
APPENDIX F

REC CHECK REPORT

Aerial Photo & Topographic Map Research

REPORT RESULTS

Report Results for:

Megan Black
UltraSystems Environmental Inc.
16431 Scientific Way
Irvine, CA 92618
2104769356 AOTO
September 13, 2022

Site Information:

Cargo Solutions-Truck Warehouse
APNs 3064-591-17, -18, -12, and -13 and
3064-631-01
Hesperia, CA 92344

Subject Site:

Client's Project #: **7187**
Address: **APNs 3064-591-17, -18, -12, and -13 and 3064-631-01**
City, State Zip: **Hesperia, CA 92344**

ERS Order #:**2104769356 AOTO****Prepared For:**

Name: **Megan Black**
Company: **UltraSystems Environmental Inc.**
Address: **16431 Scientific Way**
City, State Zip: **Irvine, CA 92618**

Date:**September 13, 2022****Prepared By:**

Name: **Ryan Cardenas**
Phone #: **(714) 669-8096**
Ext. 1001

Enclosed are the results of our.....

Aerial Photograph and Topographic Map Research

Thank you for selecting **Environmental Record Search!**

To aid you in locating your site on the imagery provided, we have placed a box over/surrounding your site.

Note: This box is not representative of your site's boundaries. It is simply a tool to assist you with the location of your site within the image. The box has been placed in the same location on each image to help you locate your site easily from year to year. If you have any problems locating your site, please call us. We are here to help.

Aerial photo years available:

2020	2016	2012	2009	2005
1994	1985	1978	1968	1952
1938				

This report includes the following USGS Topographic Map Series:

Quadrangle Name	Series	Original Scale	Contour Interval (ft)	Years
BALDY MESA	7.5 Minute	1:24,000	20'	2018, 2012, 1999, 1985, 1969, 1957
HESPERIA	7.5 Minute	1:24,000	20'	2018
HESPERIA	15 Minute	1:62,500	50'	1942, 1936, 1923, 1912, 1906

All terms, conditions, and limitations normally associated with work contracted by **ERS** and presented or associated with aerial photography are in effect at all times. This letter summary, all its information, and content have been derived from and rely upon the reviewed aerial photographs. **ERS's** research has only been based on these images; **ERS** did not perform any type of independent investigation of any type, including as to the accuracy and/or completeness of the information derived or otherwise obtained from the secondary source or sources.



Historical Aerial Photo
Year 2020

**APNs 3064-591-17, -18, -12, and -13 and 3064-631-01
Hesperia, CA**

Target Site: 34.414918, -117.392313 Job #: 2104769356





Historical Aerial Photo
Year 2016

APNs 3064-591-17, -18, -12, and -13 and 3064-631-01
Hesperia, CA

Target Site: 34.414918, -117.392313 Job #: 2104769356





Historical Aerial Photo
Year 2012

**APNs 3064-591-17, -18, -12, and -13 and 3064-631-01
Hesperia, CA**

Target Site: 34.414918, -117.392313 Job #: 2104769356





Historical Aerial Photo
Year 2008

**APNs 3064-591-17, -18, -12, and -13 and 3064-631-01
Hesperia, CA**

Target Site: 34.414918, -117.392313 Job #: 2104769356





Historical Aerial Photo
Year 2005



**APNs 3064-591-17, -18, -12, and -13 and 3064-631-01
Hesperia, CA**

Target Site: 34.414918, -117.392313 Job #: 2104769356




Historical Aerial Photo
Year 1994

APNs 3064-591-17, -18, -12, and -13 and 3064-631-01
Hesperia, CA



Target Site: 34.414918, -117.392313 Job #: 2104769356




Historical Aerial Photo
Year 1985

**APNs 3064-591-17, -18, -12, and -13 and 3064-631-01
Hesperia, CA**

Target Site: 34.414918, -117.392313 Job #: 2104769356






Historical Aerial Photo
Year 1978

**APNs 3064-591-17, -18, -12, and -13 and 3064-631-01
Hesperia, CA**



Target Site: 34.414918, -117.392313 Job #: 2104769356




Historical Aerial Photo
Year 1968

APNs 3064-591-17, -18, -12, and -13 and 3064-631-01
Hesperia, CA

Target Site: 34.414918, -117.392313 Job #: 2104769356






Historical Aerial Photo
Year 1952

**APNs 3064-591-17, -18, -12, and -13 and 3064-631-01
Hesperia, CA**

Target Site: 34.414918, -117.392313 Job #: 2104769356





Historical Aerial Photo
Year 1938



**APNs 3064-591-17, -18, -12, and -13 and 3064-631-01
Hesperia, CA**

Target Site: 34.414918, -117.392313 Job #: 2104769356




Historical Topographic Map
Year 2018

**APNs 3064-591-17, -18, -12, and -13 and 3064-631-01
Hesperia, CA**

Target Site: 34.414918, -117.392313 Job #: 2104769356






Historical Topographic Map
Year 2012

**APNs 3064-591-17, -18, -12, and -13 and 3064-631-01
Hesperia, CA**

Target Site: 34.414918, -117.392313 Job #: 2104769356






Historical Topographic Map
Year 1999

**APNs 3064-591-17, -18, -12, and -13 and 3064-631-01
Hesperia, CA**

Target Site: 34.414918, -117.392313 Job #: 2104769356





Historical Topographic Map
Year 1985

**APNs 3064-591-17, -18, -12, and -13 and 3064-631-01
Hesperia, CA**

Target Site: 34.414918, -117.392313 Job #: 2104769356






Historical Topographic Map
Year 1969

**APNs 3064-591-17, -18, -12, and -13 and 3064-631-01
Hesperia, CA**

Target Site: 34.414918, -117.392313 Job #: 2104769356






Historical Topographic Map
Year 1957

**APNs 3064-591-17, -18, -12, and -13 and 3064-631-01
Hesperia, CA**

Target Site: 34.414918, -117.392313 Job #: 2104769356






Historical Topographic Map
Year 1942

**APNs 3064-591-17, -18, -12, and -13 and 3064-631-01
Hesperia, CA**



Target Site: 34.414918, -117.392313 Job #: 2104769356




Historical Topographic Map
Year 1936

**APNs 3064-591-17, -18, -12, and -13 and 3064-631-01
Hesperia, CA**



Target Site: 34.414918, -117.392313 Job #: 2104769356




Historical Topographic Map
Year 1923

**APNs 3064-591-17, -18, -12, and -13 and 3064-631-01
Hesperia, CA**



Target Site: 34.414918, -117.392313 Job #: 2104769356




Historical Topographic Map
Year 1912

**APNs 3064-591-17, -18, -12, and -13 and 3064-631-01
Hesperia, CA**



Target Site: 34.414918, -117.392313 Job #: 2104769356



Historical Topographic Map
Year 1906

**APNs 3064-591-17, -18, -12, and -13 and 3064-631-01
Hesperia, CA**



Target Site: 34.414918, -117.392313 Job #: 2104769356

City Directory Research

REPORT RESULTS



Report Results for:

Megan Black
UltraSystems Environmental Inc.
16431 Scientific Way
Irvine, CA 92618
2104769356 CDA
September 16, 2022

Site Information:

Cargo Solutions-Truck Warehouse
APNs 3064-591-12, -13, 17, -18 and 3064-
631-01
Hesperia, CA 92344

Subject Site:

Client's Project #: **7187**
Address: **APNs 3064-591-12, -13, 17, -18 and
3064-631-01**
City, State Zip: **Hesperia, CA 92344**

ERS Order #:

2104769356 CDAC

Prepared For:

Name: **Megan Black**
Company: **UltraSystems Environmental Inc.**
Address: **16431 Scientific Way**
City, State Zip: **Irvine, CA 92618**

Date:

September 16, 2022

Prepared By:

Name: **Michael Peel**
Phone #: **(714) 669-8096**
Ext. 1002

Thank you for selecting ***Environmental Record Search!*** Enclosed are the results of our:

[**City Directory Research**](#)

The attached image files and following table represent the findings of our research of the subject site and immediate adjacent sites.

Years	Subject	Adjacent A
	8800-8900 Block of Three Flags Rd	12200-12400 Block of Poplar St
2005	•	R
2000	•	R
1996	S	R
1990	S	R

• - Street & Range Listed **N/A** - Image Not Available **R** - Range Not Listed **S** - Street Not Listed

ERS's research has been limited to the information presented in the reviewed city directories only. All terms, conditions, and limitations normally associated with work contracted by **ERS** and presented or associated with the city directories are in effect at all times. This letter summary, all its information, and content have been derived from and rely upon the reviewed city directories. **ERS's** research has only been based on these books; **ERS** did not perform any type of independent investigation of any type, including as to the accuracy and/or completeness of the information derived or otherwise obtained from the secondary source or sources.

SAN BERNARDINO			THE HAINES DIRECTORY			2005			903 TIARA AVE		
6236 LAKEY Ronald	00	0	10132 FENNER Life	00	3	DELANEY Ray	700-555-1295	-5	THUNDERBIRD RD	00	0
6287 DELANEY William	00	0	10142 WALLACE Arian	00	3	DELANEY Ray	700-555-1295	-5	92307 APPLE VALLEY	00	0
X SAPPHIRE ST			10153 TRIN Kien	00	3	34202 MARTINEZ Jorge	00	0	WALTH CODE 3.1		
6310 POLLOPS Jimmie	00	3	10152 TRIN Kien	00	3	X W MAIN ST			X TONEKAI RD		
6322 LPEZ Luis	00	0	10153 TRIN Kien	00	3	★ 0 BUS 4 RES 1 NEW			20170 COTTONWOOD	700-546-3478	2
6334 SILVERA But	00	0	10152 TRIN Kien	00	3	THUNDER MOUNTAIN			20175 MILLER Cahn	700-542-9529	+5
X WELSH CT			10152 TRIN Kien	00	3	AVE (98) 91739			20185 SKAGGS William R Jr	700-542-2019	4
6352 FANGUIN Raymond	909-569-2846	0	10152 TRIN Kien	00	3	RANCHO CUMAMONGA			20195 COTTON Linn	700-542-9815	+5
6353 FRIESTER Sandra	909-476-9623	4	10152 TRIN Kien	00	3	WALTH CODE 1			20215 LOPES Vanda	700-546-5815	+5
6359 TAYLOR Bask	00	2	10152 TRIN Kien	00	3	X KIAMACHI RD			20215 LOPES Vanda	700-546-5815	+5
6376 ALBERT Karen	00	0	10152 TRIN Kien	00	3	20215 MENDOZA Martin			20215 LOPES Vanda	700-546-5815	+5
6377 BAGAL Edward	00	3	10152 TRIN Kien	00	3	PEREZ Carmen			20215 LOPES Vanda	700-546-5815	+5
6388 KOOK	00	3	10152 TRIN Kien	00	3	20225 GUINNA Rosalba			20215 LOPES Vanda	700-546-5815	+5
6389 MCCLEARN Richard	00	3	10152 TRIN Kien	00	3	20235 PERKINS John			20215 LOPES Vanda	700-546-5815	+5
6409 DAVIS Kenneth	00	3	10152 TRIN Kien	00	3	20240 FIDLER Jerry			20215 LOPES Vanda	700-546-5815	+5
6424 GORDANO Todd	00	2	10152 TRIN Kien	00	3	20255 SCOTT Sandra			20215 LOPES Vanda	700-546-5815	+5
6425 PAPA Raphael	00	3	10152 TRIN Kien	00	3	20260 BARDOSS April			20215 LOPES Vanda	700-546-5815	+5
6440 KANZARIM Omer	00	+5	10152 TRIN Kien	00	3	20265 SHEPPARD Scott			20215 LOPES Vanda	700-546-5815	+5
6441 CARROLL Anthony	00	0	10152 TRIN Kien	00	3	20280 XXXX			20215 LOPES Vanda	700-546-5815	+5
6445 JONES Luke	909-466-9602	3	10152 TRIN Kien	00	3	20285 XXXX			20215 LOPES Vanda	700-546-5815	+5
6456 BERRY David	00	3	10152 TRIN Kien	00	3	20290 XXXX			20215 LOPES Vanda	700-546-5815	+5
X CAMEO ST			10152 TRIN Kien	00	3	20295 XXXX			20215 LOPES Vanda	700-546-5815	+5
6469 KYLE William	00	3	10152 TRIN Kien	00	3	20300 MOORE Jay			20215 LOPES Vanda	700-546-5815	+5
6483 BIRD Dennis	00	3	10152 TRIN Kien	00	3	20305 MOORE Jay			20215 LOPES Vanda	700-546-5815	+5
X JASPER ST			10152 TRIN Kien	00	3	20310 BRENEISE Denise			20215 LOPES Vanda	700-546-5815	+5
6515 CECILIO Joseph	00	3	10152 TRIN Kien	00	3	20315 COLE Marshall			20215 LOPES Vanda	700-546-5815	+5
6517 REYES Thomas	909-567-9463	3	10152 TRIN Kien	00	3	20320 RANOFF Terry			20215 LOPES Vanda	700-546-5815	+5
6565 XXXX	00	0	10152 TRIN Kien	00	3	20325 SKAGGS William R Jr			20215 LOPES Vanda	700-546-5815	+5
X TROTTERS LN			10152 TRIN Kien	00	3	20330 XXXX			20215 LOPES Vanda	700-546-5815	+5
6575 DICK James	909-544-5973	3	10152 TRIN Kien	00	3	20335 XXXX			20215 LOPES Vanda	700-546-5815	+5
6585 BECKER Carl	00	0	10152 TRIN Kien	00	3	20340 XXXX			20215 LOPES Vanda	700-546-5815	+5
6591 BAROCCA John	00	0	10152 TRIN Kien	00	3	20345 WILLIAMS Arthur Jr			20215 LOPES Vanda	700-546-5815	+5
6591 BERRA Tracey	00	0	10152 TRIN Kien	00	3	20350 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
6591 FLORESER Fred	909-589-2842	4	10152 TRIN Kien	00	3	20355 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
6591 ARBOREDA Carl	00	0	10152 TRIN Kien	00	3	20360 XXXX			20215 LOPES Vanda	700-546-5815	+5
6627 ANGEL Frederick	00	0	10152 TRIN Kien	00	3	20365 MOORE Jay			20215 LOPES Vanda	700-546-5815	+5
X NAPA CT			10152 TRIN Kien	00	3	20370 MOORE Jay			20215 LOPES Vanda	700-546-5815	+5
6633 MCLEAN Ray	00	3	10152 TRIN Kien	00	3	20375 BRENEISE Denise			20215 LOPES Vanda	700-546-5815	+5
6647 SUTTON Ronald	00	0	10152 TRIN Kien	00	3	20380 COLE Marshall			20215 LOPES Vanda	700-546-5815	+5
6661 ROTH Kelly	909-544-9184	0	10152 TRIN Kien	00	3	20385 RANOFF Terry			20215 LOPES Vanda	700-546-5815	+5
6661 ROTH Kelly	909-544-9184	0	10152 TRIN Kien	00	3	20390 SKAGGS William R Jr			20215 LOPES Vanda	700-546-5815	+5
6677 GONZALEZ Chris	00	0	10152 TRIN Kien	00	3	20395 XXXX			20215 LOPES Vanda	700-546-5815	+5
X CARNELIAN ST			10152 TRIN Kien	00	3	20400 XXXX			20215 LOPES Vanda	700-546-5815	+5
★ 0 BUS 83 RES 4 NEW			10152 TRIN Kien	00	3	20405 WILLIAMS Arthur Jr			20215 LOPES Vanda	700-546-5815	+5
THOROUGHBRED ST			10152 TRIN Kien	00	3	20410 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
(02) 91761 ONTARIO			10152 TRIN Kien	00	3	20415 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
WALTH CODE 4			10152 TRIN Kien	00	3	20420 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2815 MACIAS Sandy	00	7	10152 TRIN Kien	00	3	20425 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2821 SANCHEZ Alberto	00	0	10152 TRIN Kien	00	3	20430 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2821 VERMILION D	909-923-4187	+5	10152 TRIN Kien	00	3	20435 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2821 ALVAREZ Philip	00	0	10152 TRIN Kien	00	3	20440 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2831 ERVE Robert	00	0	10152 TRIN Kien	00	3	20445 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2831 CEA Luis	00	0	10152 TRIN Kien	00	3	20450 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2831 ACEREDIO Robert	00	0	10152 TRIN Kien	00	3	20455 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2841 TAMARCAN Wilfred	00	0	10152 TRIN Kien	00	3	20460 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2841 BEERS Ronald	00	0	10152 TRIN Kien	00	3	20465 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2841 PEREZ Nancy	00	0	10152 TRIN Kien	00	3	20470 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2851 ORIGINAL Mary	00	0	10152 TRIN Kien	00	3	20475 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2851 CARROLL David	00	0	10152 TRIN Kien	00	3	20480 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2851 WASHINGTON Kenneth	00	0	10152 TRIN Kien	00	3	20485 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2861 SANTOS Raymond	00	0	10152 TRIN Kien	00	3	20490 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2871 FLORES Dana	00	0	10152 TRIN Kien	00	3	20495 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2871 PALACIO Ricardo	00	0	10152 TRIN Kien	00	3	20500 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2871 TAYLOR Randy	00	0	10152 TRIN Kien	00	3	20505 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2881 GARIMATO Alexander	909-715-1088	3	10152 TRIN Kien	00	3	20510 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2881 COOPER Arthur	00	0	10152 TRIN Kien	00	3	20515 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2921 ROSETTE Gerald	00	0	10152 TRIN Kien	00	3	20520 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2921 GONZALEZ Jorge	00	0	10152 TRIN Kien	00	3	20525 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2931 POWELL Carl	909-947-3094	+5	10152 TRIN Kien	00	3	20530 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2931 ESCOBAR Luis C	00	0	10152 TRIN Kien	00	3	20535 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2931 GARCIA Teodoro	00	0	10152 TRIN Kien	00	3	20540 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	909-623-4673	+5	10152 TRIN Kien	00	3	20545 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20550 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20555 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20560 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20565 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20570 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20575 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20580 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20585 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20590 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20595 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20600 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20605 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20610 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20615 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20620 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20625 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20630 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20635 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20640 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20645 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20650 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20655 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20660 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20665 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20670 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20675 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20680 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20685 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20690 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20695 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20700 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20705 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20710 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20715 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20720 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20725 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20730 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20735 LLOYD Timothy			20215 LOPES Vanda	700-546-5815	+5
2941 GARCIA Carmen	00	0	10152 TRIN Kien	00	3	20740 LLOYD Timothy					

THE HAINES CROSS DIRECTORY

[illegible]

THE HAINES DIRECTORY

[illegible]

THE HAINES DIRECTORY	1990					
THE TERRACE						
THE TERRACE 92374 CONT.						
600 XXXX 00						
602 XXXX 00						
604 FISHER JAC 793-0724 9						
606 COLLINS Patricia 798-7493 9						
610 COLLINS David Jr 798-5188 9						
616 GILKINSON Gail 798-2890						
702 LOMBARD William C 793-1386						
710 LANDFRED James H 793-6104						
4 B US 30 RES 7 NEW						
THISTLE (85) 92407						
SAN BERNARDINO						
5572 BARTLEMAN Alan 887-8467 9						
0 B US 1 RES 0 NEW						
THISTLE DR (86) 91739						
ETIWAANDA						
12233 YOUNG Jeff 899-2680 6						
12244 VALLLEY WYNN W 899-2680 6						
12248 STONE Art 899-2607 6						
12286 XXXX 00						
12292 ROJO Juan 899-2496 6						
1 B US 4 RES 0 NEW						
THISTLE LN 92352						
LAKE ARROWHEAD						
26837 XXXX 00						
26869 TERRONES Richard M 337-7010						
0 B US 2 RES 0 NEW						
THOMAS N 91768						
POMONA						
SEE LOS ANGELES EASTERN						
SAN GABRIEL VALLEY						
DIRECTORY						
THOMAS S 91766						
POMONA						
SEE LOS ANGELES EASTERN						
SAN GABRIEL VALLEY						
DIRECTORY						
THOMAS AV 92374						
REDLANDS						
902 STEPHENS Michael 792-2843						
906 THOMPSON Gary 793-7888						
910 BELL Boyd 792-0506 9						
911 XXXX 00						
914 XXXX 00						
916 XXXX 00						
918 SCHENCK Steve K 792-2692						
922 XXXX 00						
923 XXXX 00						
926 GARCIA Jesse 793-8826 2						
0 B US 11 RES 0 NEW						
THOMAS CT (86) 92324						
COLTON						
12711 STEWART BUS 793-3573 6						
0 B US 1 RES 0 NEW						
THOMAS LN (82) 92399						
YUCAIPA						
12216 MARTINEZ Rodolfo R 797-3367 4						
12217 XXXX 00						
12226 LUTZ Maria 797-7825 2						
12237 BENYOLA Flo 790-1378						
12240 BENYOLA Ray 797-2535 4						
12258 XXXX 00						
12262 JET Alan 790-2163 4						
0 B US 8 RES 3 NEW						
THOMAS PL 91710						
CHINO						
12580 BRAVO LINDSEY M 981-4889 9						
12593 SILVA Gary D 825-8243						
12600 XXXX 00						
12609 TUCKER August 827-8985 8						
12610 GORCHON George 628-3126						
12629 XXXX 00						
12630 SHANZAD Farhat 628-2713 4						
12640 MARTINEZ Jackie D 628-4438						
12642 MARTINEZ Martha D 628-4438						
12649 XXXX 00						
12650 VASQUEZ Felipe 590-7495 9						
12659 XXXX 00						
12660 PECK Richard G 627-2029						
12671 HERMANOS George 628-2817 9						
1 B US 13 RES 0 NEW						
+THOMAS RD (90) 92373						
REDLANDS						
12915 WAHL Lawrence D 794-2294 4						
0 B US 1 RES 1 NEW						
THOMPSON DR 92324						
COLTON						
22206 ANDERSON Robt P 825-8327						
22210 BROWN Richard P 825-8880						
22212 CHASE Alan B 825-5327						
0 B US 3 RES 0 NEW						
THOMPSON PL 92405						
SAN BERNARDINO						
MUSCOY AREA						
209 XXXX 00						
231 HAMILTON Marion R 883-1508 9						
232 BARE Day T 881-1334 9						
243 XXXX 00						
248 DYCHOWSKI L L 882-5138						
254 XXXX 00						
267 LEWEN Joan Ellen 886-2914 4						
280 PICK Richard J 883-6531						
340 XXXX 00						
0 B US 10 RES 0 NEW						
THOMPSON RD 92347						
HINKLEY						
22214 SANDOZ Henry 253-2859						
0 B US 1 RES 0 NEW						
THOROUGHbred 91701						
ALTA LOMA						
7954 MCGUIRE Benetti 989-8101						
7980 GEARIE J C 989-8101						
7994 XXXX 00						
8006 COBLENZ Robert 989-8101						
8025 SAGER K 989-8101						
8066 JOHNSON Michael S 989-8101						
8078 XXXX 00						
8093 ANDERSON Jan 989-8101						
8117 WALTON CONSTRUCTION 989-8101						
8186 WALTON CONSTRUCTION 989-8101						
8232 FOWLER Carl 989-8101						
8330 XXXX 00						
8352 FARRINGTON Raymond 989-8101						
8377 XXXX 00						
8389 EDENS David 989-8101						
8441 XXXX 00						
8425 XXXX 00						
8440 XXXX 00						
8441 XXXX 00						
8456 LYNCH M ANESTHESIA 989-8101						
8551 REEVES Thos C 989-8101						
8575 XXXX 00						
8601 FLICKINGER Fred 989-8101						
8627 XXXX 00						
8637 MCLEAN Ray 989-8101						
8647 COBBIN R Ray 989-8101						
8661 NICOLETTS Thos 989-8101						
8677 XXXX 00						
0 B US 32 RES 2 NEW						
THOUSAND PINES RD						
92325 CRESTLINE						
302 XXXX 00						
359 RICHARD Eugene L 338-3239						
368 KALLANDER Ross 338-1451						
370 THOUSAND PINES 338-2705						
371 WILLIAMS Chiral L 338-1147 8						
400 HUNT Wm A 338-1147 8						
404 XXXX 00						
411 GROSS Clyde 338-2513						
423 WELLS Chas 338-2513						
426 WELLS Susan 338-2513						
431 GLENN Fred J 338-3572						
432 BLAND Ross 338-3572 4						
439 XXXX 00						
440 XXXX 00						
482 KODIN Maybell C 338-2779 2						
483 XXXX 00						
484 PAUL Robert 338-4068 8						
487 XXXX 00						
488 ENGLISH Sandra 338-7000 4						
490 XXXX 00						
491 CONNER Sue A 338-4359						
492 XXXX 00						
493 XXXX 00						
494 KORDICK Ken 338-3223						
510 XXXX 00						
512 XXXX 00						
514 KINER Molen 338-3216 7						
548 XXXX 00						
0 B US 32 RES 1 NEW						
THREE PALMS DR 92284						
YUCCA VALLEY						
58714 BRADLEY Thos J 355-3587						
58716 GUEST Day E 355-0502						
58718 GUEST Marjorie 355-0502						
0 B US 4 RES 0 NEW						
THRUSH 92315						
BIG BEAR LAKE						
375 RUFFNER Chas B 886-3395 4						
438 XXXX 00						
445 XXXX 00						
472 XXXX 00						
474 FREED John 886-5425 4						
475 APARTMENTS 886-5425 4						
BUCKLEY Bonnie 886-2766						
BUCKLEY Joe 886-2766						
BUCKLEY John 886-2766						
KEYS Lawrence 886-2982 9						
MASS Judy A 886-2982 9						
PICKETT Norval J 886-3826 4						
RIOGARD Richard H 886-6301 8						
STOCKWELL Ronald R 886-7148 4						
WOLLICK Esther A 886-7148 4						
476 APARTMENTS 886-3961 8						
536 ELEGANCE 886-3961 8						
HICKS HARTWICK ENG 886-3282 2						
YAGER CHAS W 886-2472 3						
573 AZEVEDO Dwayne 886-4973 4						
583 XXXX 00						
585 HERR R G 886-9173 4						
602 XXXX 00						
676 ELLIOTT Richard A 886-9140 2						
720 XXXX 00						
741 XXXX 00						
742 XXXX 00						
773 BARNEY Donald W 886-2067 4						
881 APARTMENTS 886-7991 7						
BLOOM Joyce 886-8073 9						
FREEMAN F S 886-8196 4						
JONES Ohn L 886-8114 4						
LANO Lewis A 886-8114 4						
MCLEAN Michael J 886-8114 4						
MURPHY James L 886-8114 4						
ROBERT R 886-8114 4						
861 APARTMENTS 886-9002 6						
0 B US 35 RES 10 NEW						
THRUSH 92324 COLTON						
22537 XXXX 00						
22538 XXXX 00						
22539 XXXX 00						
22540 SCOTT Woodrow W 825-0188						
THURSH 92397						
WRIGHTWOOD						
22541 XXXX 00						
22542 XXXX 00						
22543 XXXX 00						
22544 XXXX 00						
22545 VOTI David 793-2576 6						
22546 PATTON Gary 793-2576 6						
22547 XXXX 00						
22548 XXXX 00						
22549 XXXX 00						
22550 XXXX 00						
22551 XXXX 00						
22552 XXXX 00						
22553 XXXX 00						
22554 XXXX 00						
22555 XXXX 00						
22556 XXXX 00						
22557 XXXX 00						
22558 XXXX 00						
22559 XXXX 00						
22560 XXXX 00						
22561 XXXX 00						
22562 XXXX 00						
22563 XXXX 00						
22564 XXXX 00						
22565 XXXX 00						
22566 XXXX 00						
22567 XXXX 00						
22568 XXXX 00						
22569 XXXX 00						
22570 XXXX 00						
22571 XXXX 00						
22572 XXXX 00						
22573 XXXX 00						
22574 XXXX 00						
22575 XXXX 00						
22576 XXXX 00						
22577 XXXX 00						
22578 XXXX 00						
22579 XXXX 00						
22580 XXXX 00						
22581 XXXX 00						
22582 XXXX 00						
22583 XXXX 00						
22584 XXXX 00						

THE HAINES DIRECTORY

2005

737

POPLAR ST

[illegible]

ⓈDO NOT MAIL

NOT BE REPRODUCED, COPIED, ENTERED INTO A COMPUTER OR PHOTOCOPIED, IN ANY MANNER WHATSOEVER EXCEPT AS AUTHORIZED IN WRITING BY HAINES & CO., INC.

Adjacent A

12200-12400 Block of Poplar St

2005

THE HAINES			DIRECTORY			405		
PORTOLA			1990			PORTOLA		
+PONDEROSA RNCH RD (90) 92392 VICTORVILLE			POPLAR 92376 RIALTO			POPPY LN (83) 92347 HINKLEY		
14060 JUREZ John	245-4772	0	2743 XXXX	0	0	21455 BURKHOF Richard	253-2263	0
14062 JOSELL Paul	245-5550	0	2751 XXXX	0	0	0 BUB 1 RES	0 NEW	0
14062 MASSELE Allen	241-5486	0	2752 XXXX	0	0	POPPY PL 91710 CHINO		
14070 WESLEY Mary S	241-2942	0	2753 XXXX	0	0	13507 BROWN Mike	891-3169	1
14111 BASTAL S Jan	243-3659	0	2754 XXXX	0	0	13512 DARNETT Richard	241-3568	1
14112 BASTAL Wanda	243-3659	0	2755 XXXX	0	0	13520 JOHNSON Loren	627-1037	0
0 BUB 6 RES	0 NEW	0	2756 XXXX	0	0	13531 DELAPLAN Rome	627-6928	0
14062 NORTHROP D M	796-2797	0	2757 XXXX	0	0	13536 XXXX	0	0
14063 CERENOLO Lini	796-2797	0	2758 XXXX	0	0	13537 XXXX	0	0
14064 SWEET Tim S	796-2797	0	2759 XXXX	0	0	13538 XXXX	0	0
14065 HASTINGS Ralph C	796-2797	0	2760 XXXX	0	0	13539 XXXX	0	0
14066 JONSTON Geo E	796-2797	0	2761 XXXX	0	0	13540 XXXX	0	0
14067 VARGAS Aurora M	796-2797	0	2762 XXXX	0	0	13541 XXXX	0	0
14068 NELSON M Gary	796-2797	0	2763 XXXX	0	0	13542 XXXX	0	0
14069 BLUE Melvin	796-2797	0	2764 XXXX	0	0	13543 XXXX	0	0
14070 BLUE Ruth	796-2797	0	2765 XXXX	0	0	13544 XXXX	0	0
14071 XXXX	796-2797	0	2766 XXXX	0	0	13545 XXXX	0	0
14072 XXXX	796-2797	0	2767 XXXX	0	0	13546 XXXX	0	0
14073 XXXX	796-2797	0	2768 XXXX	0	0	13547 XXXX	0	0
14074 XXXX	796-2797	0	2769 XXXX	0	0	13548 XXXX	0	0
14075 XXXX	796-2797	0	2770 XXXX	0	0	13549 XXXX	0	0
14076 XXXX	796-2797	0	2771 XXXX	0	0	13550 XXXX	0	0
14077 XXXX	796-2797	0	2772 XXXX	0	0	13551 XXXX	0	0
14078 XXXX	796-2797	0	2773 XXXX	0	0	13552 XXXX	0	0
14079 XXXX	796-2797	0	2774 XXXX	0	0	13553 XXXX	0	0
14080 XXXX	796-2797	0	2775 XXXX	0	0	13554 XXXX	0	0
14081 XXXX	796-2797	0	2776 XXXX	0	0	13555 XXXX	0	0
14082 XXXX	796-2797	0	2777 XXXX	0	0	13556 XXXX	0	0
14083 XXXX	796-2797	0	2778 XXXX	0	0	13557 XXXX	0	0
14084 XXXX	796-2797	0	2779 XXXX	0	0	13558 XXXX	0	0
14085 XXXX	796-2797	0	2780 XXXX	0	0	13559 XXXX	0	0
14086 XXXX	796-2797	0	2781 XXXX	0	0	13560 XXXX	0	0
14087 XXXX	796-2797	0	2782 XXXX	0	0	13561 XXXX	0	0
14088 XXXX	796-2797	0	2783 XXXX	0	0	13562 XXXX	0	0
14089 XXXX	796-2797	0	2784 XXXX	0	0	13563 XXXX	0	0
14090 XXXX	796-2797	0	2785 XXXX	0	0	13564 XXXX	0	0
14091 XXXX	796-2797	0	2786 XXXX	0	0	13565 XXXX	0	0
14092 XXXX	796-2797	0	2787 XXXX	0	0	13566 XXXX	0	0
14093 XXXX	796-2797	0	2788 XXXX	0	0	13567 XXXX	0	0
14094 XXXX	796-2797	0	2789 XXXX	0	0	13568 XXXX	0	0
14095 XXXX	796-2797	0	2790 XXXX	0	0	13569 XXXX	0	0
14096 XXXX	796-2797	0	2791 XXXX	0	0	13570 XXXX	0	0
14097 XXXX	796-2797	0	2792 XXXX	0	0	13571 XXXX	0	0
14098 XXXX	796-2797	0	2793 XXXX	0	0	13572 XXXX	0	0
14099 XXXX	796-2797	0	2794 XXXX	0	0	13573 XXXX	0	0
14100 XXXX	796-2797	0	2795 XXXX	0	0	13574 XXXX	0	0
14101 XXXX	796-2797	0	2796 XXXX	0	0	13575 XXXX	0	0
14102 XXXX	796-2797	0	2797 XXXX	0	0	13576 XXXX	0	0
14103 XXXX	796-2797	0	2798 XXXX	0	0	13577 XXXX	0	0
14104 XXXX	796-2797	0	2799 XXXX	0	0	13578 XXXX	0	0
14105 XXXX	796-2797	0	2800 XXXX	0	0	13579 XXXX	0	0
14106 XXXX	796-2797	0	2801 XXXX	0	0	13580 XXXX	0	0
14107 XXXX	796-2797	0	2802 XXXX	0	0	13581 XXXX	0	0
14108 XXXX	796-2797	0	2803 XXXX	0	0	13582 XXXX	0	0
14109 XXXX	796-2797	0	2804 XXXX	0	0	13583 XXXX	0	0
14110 XXXX	796-2797	0	2805 XXXX	0	0	13584 XXXX	0	0
14111 XXXX	796-2797	0	2806 XXXX	0	0	13585 XXXX	0	0
14112 XXXX	796-2797	0	2807 XXXX	0	0	13586 XXXX	0	0
14113 XXXX	796-2797	0	2808 XXXX	0	0	13587 XXXX	0	0
14114 XXXX	796-2797	0	2809 XXXX	0	0	13588 XXXX	0	0
14115 XXXX	796-2797	0	2810 XXXX	0	0	13589 XXXX	0	0
14116 XXXX	796-2797	0	2811 XXXX	0	0	13590 XXXX	0	0
14117 XXXX	796-2797	0	2812 XXXX	0	0	13591 XXXX	0	0
14118 XXXX	796-2797	0	2813 XXXX	0	0	13592 XXXX	0	0
14119 XXXX	796-2797	0	2814 XXXX	0	0	13593 XXXX	0	0
14120 XXXX	796-2797	0	2815 XXXX	0	0	13594 XXXX	0	0
14121 XXXX	796-2797	0	2816 XXXX	0	0	13595 XXXX	0	0
14122 XXXX	796-2797	0	2817 XXXX	0	0	13596 XXXX	0	0
14123 XXXX	796-2797	0	2818 XXXX	0	0	13597 XXXX	0	0
14124 XXXX	796-2797	0	2819 XXXX	0	0	13598 XXXX	0	0
14125 XXXX	796-2797	0	2820 XXXX	0	0	13599 XXXX	0	0
14126 XXXX	796-2797	0	2821 XXXX	0	0	13600 XXXX	0	0
14127 XXXX	796-2797	0	2822 XXXX	0	0	13601 XXXX	0	0
14128 XXXX	796-2797	0	2823 XXXX	0	0	13602 XXXX	0	0
14129 XXXX	796-2797	0	2824 XXXX	0	0	13603 XXXX	0	0
14130 XXXX	796-2797	0	2825 XXXX	0	0	13604 XXXX	0	0
14131 XXXX	796-2797	0	2826 XXXX	0	0	13605 XXXX	0	0
14132 XXXX	796-2797	0	2827 XXXX	0	0	13606 XXXX	0	0
14133 XXXX	796-2797	0	2828 XXXX	0	0	13607 XXXX	0	0
14134 XXXX	796-2797	0	2829 XXXX	0	0	13608 XXXX	0	0
14135 XXXX	796-2797	0	2830 XXXX	0	0	13609 XXXX	0	0
14136 XXXX	796-2797	0	2831 XXXX	0	0	13610 XXXX	0	0
14137 XXXX	796-2797	0	2832 XXXX	0	0	13611 XXXX	0	0
14138 XXXX	796-2797	0	2833 XXXX	0	0	13612 XXXX	0	0
14139 XXXX	796-2797	0	2834 XXXX	0	0	13613 XXXX	0	0
14140 XXXX	796-2797	0	2835 XXXX	0	0	13614 XXXX	0	0
14141 XXXX	796-2797	0	2836 XXXX	0	0	13615 XXXX	0	0
14142 XXXX	796-2797	0	2837 XXXX	0	0	13616 XXXX	0	0
14143 XXXX	796-2797	0	2838 XXXX	0	0	13617 XXXX	0	0
14144 XXXX	796-2797	0	2839 XXXX	0	0	13618 XXXX	0	0
14145 XXXX	796-2797	0	2840 XXXX	0	0	13619 XXXX	0	0
14146 XXXX	796-2797	0	2841 XXXX	0	0	13620 XXXX	0	0
14147 XXXX	796-2797	0	2842 XXXX	0	0	13621 XXXX	0	0
14148 XXXX	796-2797	0	2843 XXXX	0	0	13622 XXXX	0	0
14149 XXXX	796-2797	0	2844 XXXX	0	0	13623 XXXX	0	0
14150 XXXX	796-2797	0	2845 XXXX	0	0	13624 XXXX	0	0
14151 XXXX	796-2797	0	2846 XXXX	0	0	13625 XXXX	0	0
14152 XXXX	796-2797	0	2847 XXXX	0	0	13626 XXXX	0	0
14153 XXXX	796-2797	0	2848 XXXX	0	0	13627 XXXX	0	0
14154 XXXX	796-2797	0	2849 XXXX	0	0	13628 XXXX	0	0
14155 XXXX	796-2797	0	2850 XXXX	0	0	13629 XXXX	0	0
14156 XXXX	796-2797	0	2851 XXXX	0	0	13630 XXXX	0	0
14157 XXXX	796-2797	0	2852 XXXX	0	0	13631 XXXX	0	0
14158 XXXX	796-2797	0	2853 XXXX	0	0	13632 XXXX	0	0
14159 XXXX	796-2797	0	2854 XXXX	0	0	13633 XXXX	0	0
14160 XXXX	796-2797	0	2855 XXXX	0	0	13634 XXXX	0	0
14161 XXXX	796-2797	0	2856 XXXX	0	0	13635 XXXX	0	0
14162 XXXX	796-2797	0	2857 XXXX	0	0	13636 XXXX	0	0
14163 XXXX	796-2797	0	2858 XXXX	0	0	13637 XXXX	0	0
14164 XXXX	796-2797	0	2859 XXXX	0	0	13638 XXXX	0	0
14165 XXXX	796-2797	0	2860 XXXX	0	0	13639 XXXX	0	0
14166 XXXX	796-2797	0	2861 XXXX	0	0	13640 XXXX	0	0
14167 XXXX	796-2797	0	2862 XXXX	0	0	13641 XXXX	0	0
14168 XXXX	796-2797	0	2863 XXXX	0	0	13642 XXXX	0	0
14169 XXXX	796-2797	0	2864 XXXX	0	0	13643 XXXX	0	0
14170 XXXX	796-2797	0	2865 XXXX	0	0	13644 XXXX	0	0
14171 XXXX	796-2797	0	2866 XXXX	0	0	13645 XXXX	0	0
14172 XXXX	796-2797	0	2867 XXXX	0	0	13646 XXXX	0	0
14173 XXXX	796-2797	0	2868 XXXX	0	0	13647 XXXX	0	0
14174 XXXX	796-2797	0	2869 XXXX	0	0	13648 XXXX	0	0
14175 XXXX	796-2797	0	2870 XXXX	0	0	13649 XXXX	0	0
14176 XXXX	796-2797	0	2871 XXXX	0	0	13650 XXXX	0	0
14177 XXXX	796-2797	0	2872 XXXX	0	0	13651 XXXX	0	0
14178 XXXX	796-2797	0	2873 XXXX	0	0	13652 XXXX	0	0
14179 XXXX	796-2797	0	2874 XXXX	0	0	13653 XXXX	0	0
14180 XXXX	796-2797	0	2875 XXXX	0	0	13654 XXXX	0	0
14181 XXXX	796-2797	0	2876 XXXX	0	0	13655 XXXX	0	0
14182 XXXX	796-2797	0	2877 XXXX	0	0	13656 XXXX	0	0
14183 XXXX	796-2797	0	2878 XXXX	0	0	13657 XXXX	0	0
14184 XXXX	796-2797	0	2879 XXXX	0	0	13658 XXXX	0	0
14185 XXXX	796-2797	0	2880 XXXX	0	0	13659 XXXX	0	0
14186 XXXX	796-2797	0	2881 XXXX	0	0	13660 XXXX	0	0
14187 XXXX	796-2797	0	2882 XXXX	0	0	13661 XXXX	0	0
14188 XXXX	796-2797	0	2883 XXXX	0	0	13662 XXXX	0	0
14189 XXXX	796-2797	0	2884 XXXX	0	0	13663 XXXX	0	0
14190 XXXX	796-2797	0	2885 XXXX	0	0	13664 XXXX	0	0
14191 XXXX	796-2797	0	2886 XXXX	0	0	13665 XXXX	0	0
14192 XXXX	796-2797	0	2887 XXXX	0	0	13666 XXXX	0	0
14193 XXXX	796-2797	0	2888 XXXX	0	0	13667 XXXX	0	0
14194 XXXX	796-2797	0	2889 XXXX	0	0	13668 XXXX	0	0
14195 XXXX	796-2797	0	2890 XXXX	0	0	13669 XXXX	0	0
14196 XXXX								

Fire Insurance Map Results

REPORT RESULTS

Report Results for:

Megan Black
UltraSystems Environmental Inc.
16431 Scientific Way
Irvine, CA 92618
2104769356 FIM
September 15, 2022

Site Information:

Cargo Solutions-Truck Warehouse
APNs 3064-591-12, -13, 17, -18 and 3064-
631-01
Hesperia, CA 92344

Subject Site:

Client's Project #: **7187**
Address: **APNs 3064-591-12, -13, 17, -18 and
3064-631-01**
City, State Zip: **Hesperia, CA 92344**

ERS Order #:

2104769356 FIM

Prepared For:

Name: **Megan Black**
Company: **UltraSystems Environmental Inc.**
Address: **16431 Scientific Way**
City, State Zip: **Irvine, CA 92618**

Date:

September 15, 2022

Prepared By:

Name: **Michael Peel**
Phone #: **(714) 669-8096
Ext. 1002**

Years Reviewed:

N/A - Coverage was not available for Hesperia

Historical Fire Insurance Map Search Result:

The review of collections and indexes has determined that no historical fire insurance maps are available within these collections and indexes for the referenced site; therefore they are not available and are considered not "reasonably ascertainable" according to ASTM standards. Environmental Record Search (ERS) certifies that a thorough search of our holdings, various other collections and indexes has been completed.

Thank you for selecting ERS.

Researched by:

Eric Kieselbach

Eric Kieselbach





RecCheck Report for : SDBA

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
Hist-CA	No Longer Listed	0.01 miles NW	3620 ft	1
SITE NAME			MAPS	ID
B & D Industrial Park			1,4	338278
ADDRESS			CITY	ZIP
Popular St & Three Flags Ave			Hesperia	92345
DETAILS				
Original Database: NPDES-SW-CA				
Last Agency Status: Listed				
Archive Date: 06/01/16				
No Longer Listed-Registered Meas ID: 338278				
Registered Meas Type: Construction				
WDID: 6B36C350089				
Received Date: 5/9/2008				
Processed Date: 12/20/2007				
Termination Date: 6/8/2010				
Status Code Name: Terminated				
Status Date: 6/16/2010				
REGION: Not Reported				
County Code: 36				
Place Size: 3				
Place Size Unit: Acres				
Facility County: San Bernardino				
Facility Contact Name: Bob Carson				
Facility Contact Title: Not Reported				
Facility Contact Phone: 999-999-9999				
Facility Contact Phone Extension: Not Reported				
Facility Contact Email Address: Not Reported				
Operator Name: Destin Steel Inc				
Operator Address: 12127 Mallcenter Blvd A 171				
Operator City: Victoville				
Operator State: California				
Operator Zip: 92392				
Operator Contact Name: Dan Higgins				
Operator Contact Title: Not Reported				

Operator Contact Phone: 909-350-1227
Operator Contact Phone Extension: Not Reported
Operator Contact Email Address: Not Reported
Operator Type: Private Business
Developer Name: Clear Water Services
Developer Address: 2990 La Jolla St
Developer City: Anaheim
Developer State: California
Developer Zip: 92806
Developer Contact Name: Bob Carson
Developer Contact Title: Not Reported
Constype Linear Utility Ind: Not Reported
Emergency Phone Number: 951-764-1243
Emergency phone Number Extension: Not Reported
Constype Aboveground Ind: Not Reported
Constype Belowground Ind: Not Reported
Constype Cable Line Ind: Not Reported
Constype Comm line Ind: Not Reported
Constype Commercial Ind: Not Reported
Constype Electrical Line Ind: Not Reported
Constype Gas Line Ind: Not Reported
Constype Industrial Ind: YES
Constype Other Description: Not Reported
Constype Other Ind: Church
Constype Recons Ind: Not Reported
Constype Residential Ind: Not Reported
Constype Transport Ind: Not Reported
Constype Utility Description: Not Reported
Constype Utility Ind: Not Reported
Constype Water Sewer Ind: Not Reported
Dir Discharge Us Water Ind: Not Reported
Receiving Water Name: Mojave River
Certifier Name: Not Reported
Certifier Title: Not Reported
Certification Date: Not Reported
Primary SIC: Not Reported
Secondary SIC: Not Reported
Tertiary SIC: Not Reported

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CERS-CA	Listed	0.03 miles S	3632 ft	2
SITE NAME			MAPS	ID
High Desert Truck and Trailer			1,4	10400761
ADDRESS			CITY	ZIP

8995 Three Flags Ave

Hesperia

92345

DETAILS

General Program & Facility Information

CERS ID: 10400761

Facility ID: FA0016142

Facility Regulator Key ID: FA0016142

Organization Code: 90363385

Business/Organization Name: Velocity Vehicle Group (VVG)

Multiple Jurisdictional Business? (Y/N): Yes

Business Origin: Letter

Count of Business CERS User Accounts: 9

Facility Count for Business: 16

Last Submittal Date (any element): 7/9/2018 8:28:02 AM

Count of Submitted Elements: 21

Remote Facility? (Y/N): No

Small Quantity Generator Facility? (Y/N): No

Local Facility Grouping: Not Reported

Facility Specific Information

Assessor Parcel Number (APN): Not Reported

Number of Employees: 15

Property Owner Name: Brad Fauvre & Conan Barker

Property Owner Phone Number: (562) 447-1203

Property Owner Mailing Address: 2429 Peck Road

Property Owner Mailing City: Whittier

Property Owner Mailing State: CA

Property Owner Mailing Zip Code: 90601

Property Owner Mailing Country: United States

Inspection Information

Aboveground Petroleum Storage Act (APSA) Last Inspection Date: Not Reported

California Accidental Release Prevention (CalARP) Last Inspection: Not Reported

Conditionally Authorized (CA) Last Inspection Date: Not Reported

Conditionally Exempt (CE) Last Inspection Date: Not Reported

Household Hazardous Waste Collection (HHW) Last Inspection Date: Not Reported

Hazardous Materials Release Response Plan (HMRRP) Last Inspection: 12/14/2016

Hazardous Waste Generator (HW) Last Inspection Date: 12/14/2016

RCRA Large Quantity Generator (HWLQG) Last Inspection Date: Not Reported

Hazardous Waste Recycler (HWRrecycler) Last Inspection Date: Not Reported

Permit By Rule (PBR) Last Inspection: Not Reported

Underground Storage Tank (UST) Last Inspection Date: Not Reported

Owner/Operator Information

Beginning Date: Not Reported

Ending Date: Not Reported

Phone Number: (909) 510-4185
Fax Number: (562) -447-1559
Supplemental Location: Not Reported
County: San Bernardino
Dun & Bradstreet D-U-N-S Number: Not Reported
SIC Code: Not Reported
NAICS Code: Not Reported
Mailing Address: 8995 Three Flags Ave.
Mailing Address City: Hesperia
Mailing Address State Code: CA
Mailing Address Zip Code: 92345
Operator Name: Ronnie Bullocks
Operator Phone Number: (909) 510-4186
Owner Name: Brad Fauvre & Conan Barker
Owner Phone: (562) 447-1203
Owner Mailing Address: 2429 Peck Road
Owner City: Whittier
Owner State: CA
Owner Zip Code: 90601
Owner Country: United States
Environmental Contact Name: Devin Beck
Environmental Contact Phone Number: 909-510-4272
Environmental Contact Mailing Address: 2429 S. Peck Rd
Environmental Contact Email Address: dbeck@vvgtruck.com
Environmental Contact City: Whittier
Environmental Contact State: CA
Environmental Contact Zip: 90601
Environmental Contact Country: United States
Primary Emergency Contact Name: Ronnie Bullocks
Primary Emergency Contact Title: Service Manager
Primary Emergency Contact Business Phone Number: (909) 510-4185
Primary Emergency Contact 24Hr Phone: (760) -948-6442
Primary Emergency Contact Pager Number: Not Reported
Secondary Emergency Contact Name: Laki Daniels
Secondary Emergency Contact Title: Assistant Manager
Secondary Emergency Contact Business Phone: (909) 510-4181
Secondary Emergency Contact 24Hr Phone: Not Reported
Secondary Emergency Contact Pager Number: Not Reported
Additional Local Collected Info: Not Reported
Identification Signed Date: Not Reported
Document Preparer Name: Devin Beck
Identification Signer Name: Devin Beck
Identification Signer Title: Safety and Environmental Manager
Billing Contact Name: Ronnie Bullocks
Billing Contact Phone: (909) 510-4186
Billing Contact Email: rbullocks@lafreightlner.com
Billing Address: 8995 Three Flags Ave.
Billing City: Hesperia
Billing State: CA
Billing Zip: 92345

Billing Country: United States

Business Owner/Operator Regulator Key: Not Reported

Business Activity Information

EPA ID: CAL000328679

Hazardous Materials On Site? (Y/N): Y

CAL ARP Regulated Substances? (Y/N): N

Own or Operator USTs? (Y/N): N

Own or Operator APSTs? (Y/N): N

Hazardous Waste Generator? (Y/N): Y

Recycles Materials? (Y/N): N

On-site HW Treatment? (Y/N): N

Financial Assurance? (Y/N): N

Remote Waste Consolidation Site? (Y/N): N

Hazardous Waste Tank Closure? (Y/N): N

RCRA Large Quantity Generator? (Y/N): N

Household Hazardous Waste (HHW) Collection? (Y/N): N

Business Activity Comment(s): Not Reported

Submittal Information

Submitted Date/Time: 4/25/2018 2:37:31 PM

Submittal Action: Accepted

BP Activities Last Updated Date: 4/10/2018 10:53:14 AM

BP Owner/Operator Last Updated Date: 4/10/2018 10:53:14 AM

Submittal Action Comment 1: ACCEPTED AS COMPLETE PENDING FIELD VERIFICATION: Thank you for the submittal.

While this submittal is being accepted as complete, the data has not been field verified and may require correction in the future. Please note, it is your responsibility to review and certify the information submitted in CERS annually. You must also update the information within 30 days of a change of owner, business address, business name, emergency contact information, inventory and/or other site conditions that could impact emergency response activity. If you have questions about using CERS, please contact the San Bernardino County Fire CERS Help Desk at (909) 386-8432. (Reviewed by Alexander Israel, aisrael@sbcfire.org or (909) 386-8401)

Submittal Action Comment 2: Not Reported

Facility Info Next Due Date: Not Reported

Biz Activities Regulator Key: Not Reported

Supplemental Geographic Information

Agency Provided Latitude: 34.41426

Agency Provided Longitude: -117.39427

Horizontal Accuracy: 50

Horizontal Collection Method: Address Matching

Geographic Reference Point: Facility Center/Centroid

Horizontal Reference Datum: WGS84 (World Geodetic System of 1984)

Data Collection Date: 5/18/2015 1:21:33 AM

Submittal Element Regulator Information

CUPA Regulator Code: 3600

Facility Info Reporting Requirement: Applicable
Facility Info Next Due Date: Not Reported
Facility Info Last Submitted Date: 7/9/2018 8:28:02 AM
Facility Info Accepted Date: 6/14/2018 10:32:11 AM
Inventory Regulator Code: 3600
Inventory Reporting Requirement: Applicable
Inventory Next Due Date: Not Reported
Inventory Last Submitted Date: 4/25/2018 2:37:31 PM
Inventory Last Accepted Date: 7/6/2018 2:57:22 PM
ER Training Regulator Code: 3600
ER Training Reporting Requirement: Applicable
ER Training Next Due Date: Not Reported
ER Training Last Submitted Date: 7/9/2018 8:28:02 AM
ER Training Last Accepted Date: 7/19/2017 1:52:19 PM
UST Regulator Code: 3600
UST Reporting Requirement: Not Applicable
UST Next Due Date: Not Reported
UST Last Submitted Date: Not Reported
UST Last Accepted Date: Not Reported
HW Treat Regulator Code: 3600
HW Treat Reporting Requirement: Not Applicable
HW Treat Next Due Date: Not Reported
HW Treat Last Submitted Date: Not Reported
HW Treat Last Accepted Date: Not Reported
RMR Regulator Code: 3600
RMR Reporting Requirement: Not Applicable
RMR Next Due Date: Not Reported
RMR Last Submitted Date: Not Reported
RMR Last Accepted Date: Not Reported
Consolidation Regulator Code: 3600
Consolidation Reporting Requirement: Not Applicable
Consolidation Next Due Date: Not Reported
Consolidation Last Submitted Date: Not Reported
Consolidation Last Accepted Date: Not Reported
Tank Closure Regulator Code: 3600
Tank Closure Reporting Requirement: Not Applicable
Tank Closure Next Due Date: Not Reported
Tank Closure Last Submitted Date: Not Reported
Tank Closure Last Accepted Date: Not Reported
APSA Regulator Code: 3600
APSA Reporting Requirement: Not Applicable
APSA Next Due Date: Not Reported
APSA Last Submitted Date: Not Reported
APSA Last Accepted Date: Not Reported
CalARP Regulator Code: 3600
CalARP Reporting Requirement: Not Applicable
CalARP Next Due Date: Not Reported
CalARP Last Submitted Date: Not Reported
CalARP Last Accepted Date: Not Reported

UST Facility and Program Information

: Not Reported

Tank & Monitoring Plan Information

: Not Reported

HMRRP & UST Violation Information

EPA ID: CAL000328679

RCRA LQG: No

Violation Date: 12/14/2016

Violation Type Number: 1010002

Class: Minor

Scheduled Return to Compliance Date: 1/13/2017

Actual Return to Compliance Date: Not Reported

Actual Return to Compliance Qualifier: Not Reported

Violation Comment: Hazardous Materials Business Plan (HMBP) submitted on CERS on 7/20/2016 was incomplete, inaccurate, and/or not current. Hazardous Materials Inventory and Facility Site Map was not complete or accurate. There were hazardous materials that was not disclosed previously. Emergency Response / Contingency and Employee Training Plan was not submitted in CERS.

Violation Category: Administration/Documentation

Violation Name: Hazardous Materials Business Plan Submittal

Violation Description: Failure to complete and electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.

Violation Citation(s): HSC 6.95 25505, 25508(a)(1)

Violation Date: 12/14/2016

Violation Type Number: 1010006

Class: Class 2

Scheduled Return to Compliance Date: 1/13/2017

Actual Return to Compliance Date: Not Reported

Actual Return to Compliance Qualifier: Not Reported

Violation Comment: There were undisclosed hazardous materials at or above reportable quantities.

Violation Category: Administration/Documentation

Violation Name: Business plan updates

Violation Description: Failure to electronically update business plan within 30 days of any one of the following events: A 100 percent or more increase in the quantity of a previously disclosed material. Any handling of a previously undisclosed hazardous materials at or above reportable quantities. A change of business address, business ownership, or business name. A substantial change in the handler's operations that requires modification to any portion of the business plan.

Violation Citation(s): HSC 6.95 25508.1(a)-(f)

HMRRP & UST Inspection Information

EPA ID: CAL000328679

RCRA LQG: No

Inspection Date: 12/14/2016

Inspection Type: Routine

Number of Class I Violations: 0

Number of Class II Violations: 1

Number of Minor Violations: 1

Significant Operational Compliance: With both Release Detection and Release Prevention

Date Returned to Compliance: Not Reported

Days Out of Compliance: 734
Violation Details Available: Yes
Inspection Comments: HANDLER INSPECTION

HMRRP & UST Enforcement Information
Type of Enforcement Action: Notice of Violation (NOV) Only
Date of Enforcement Action: 12/14/2016
Type of Formal Enforcement Action: Not Reported
Date a Referred Case Settled or Dropped: Not Reported
Docket Number: Not Reported
Final Fine or Penalty Assessed: Not Reported
Supplemental Environmental Projects Value: Not Reported
Count of Linked Class I Violations: 0
Count of Linked Class II Violations: 1
Count of Linked Minor Violations: 1
Red Tag Issued: No
Red Tag Number: Not Reported
Violations Causing Red Tag: Not Reported
Date Red Tag Affixed: Not Reported
Date Red Tag Removed: Not Reported
Enforcement Comments: Not Reported

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CRSP-CA	Listed	0.03 miles S	3632 ft	2
SITE NAME			MAPS	ID
High Desert Truck and Trailer			1,4	169689
ADDRESS			CITY	ZIP
8995 THREE FLAGS AVE			HESPERIA	92345
DETAILS				
Site Regulated Program Information Site ID: 169689 Site EI ID: 10400761 Agency Provided Latitude: 34.41426 Agency Provided Longitude: -117.39427 Program Description: Chemical Storage Facilities Program Description: Hazardous Waste Generator				

Evaluation Information

Evaluation Date: 12/14/2016

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): GENERATOR INSPECTION

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HW

Evaluation Source: CERS

Evaluation Date: 12/14/2016

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): HANDLER INSPECTION

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HMRRP

Evaluation Source: CERS

Violation Information

Violation Date: 12/14/2016

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.

Violation Note(s): Hazardous Materials Business Plan (HMBP) submitted on CERS on 7/20/2016 was incomplete, inaccurate, and/or not current. Hazardous Materials Inventory and Facility Site Map was not complete or accurate. There were hazardous materials that was not disclosed previously. Emergency Response / Contingency and Employee Training Plan was not submitted in CERS.

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

Violation Source: CERS

Violation Date: 12/14/2016

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Operations/Maintenance - General

Violation Note(s): Returned to compliance on 01/09/2017. Failure to establish a Contingency Plan (CCR 66265.51(a))

Hazardous waste contingency plan has not been establish / submitted in California Environmental Reporting System (CERS).

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 12/14/2016

Citation: HSC 6.95 25508.1(a)-(f) - California Health and Safety Code, Chapter 6.95, Section(s) 25508.1(a)-(f)

Violation Description: Failure to electronically update business plan within 30 days of any one of the following events:

A 100 percent or more increase in the quantity of a previously disclosed material.

Any handling of a previously undisclosed hazardous materials at or above reportable quantities.

A change of business address, business ownership, or business name.

A substantial change in the handler's operations that requires modification to any portion of the business plan.

Violation Note(s): There were undisclosed hazardous materials at or above reportable quantities.

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

Violation Source: CERS

Violation Date: 12/14/2016

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Operations/Maintenance - General

Violation Note(s): Returned to compliance on 01/09/2017. Failure to manage hazardous waste lawfully (CHSC 25154)

Hazardous waste was not managed lawfully. Compliance Requirement: Submit 3-weeks worth of hazardous waste weekly inspection to this Division.

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 12/14/2016

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Operations/Maintenance - General

Violation Note(s): Returned to compliance on 01/09/2017. Failure to note accumulation start date on labels (CCR 66262.34(f)(2)) Accumulation start date missing on waste oily solids container.

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 12/14/2016

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Operations/Maintenance - General

Violation Note(s): Returned to compliance on 01/09/2017. Failure to operate and maintain facility to prevent a fire, spill or release (CCR 66265.31) Observed oil accumulation in secondary containment; spills on shop floor.

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 12/14/2016

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Operations/Maintenance - General

Violation Note(s): Returned to compliance on 01/09/2017. Failure to complete hazardous waste labels (CCR 66262.34(f)(3)) Accumulation start date missing on waste oily solids container. Compliance Requirement: Submit a signed statement indicating that all hazardous waste containers have been properly labeled.

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 12/14/2016

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Training - General

Violation Note(s): Returned to compliance on 12/14/2016. Failure to train facility personnel in hazardous waste management procedures (CCR 66265.16) Employee training documentation not documented and / or available for review. Provided at end of inspection.

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 12/14/2016

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Operations/Maintenance - General

Violation Note(s): Returned to compliance on 01/09/2017. Hazardous waste accumulation time exceeded (CCR 66262.34(a))

Hazardous waste accumulation time exceeded for waste oily water. Last pick 6/4/14.

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 12/14/2016

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Operations/Maintenance - General

Violation Note(s): Returned to compliance on 01/09/2017. Failure to keep hazardous waste containers closed when not in active use (CCR 66265.173(a)) Bung caps were missing on used oil drums.

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Enforcement Information

Enforcement Action Date: 12/14/2016

Enforcement Action Type: Notice of Violation (Unified Program)

Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enforcement Action Note(s): Not Reported

Enforcement Action Division: San Bernardino County Fire Department

Enforcement Action Program: HMRRP

Enforcement Action Source: CERS

Enforcement Action Date: 12/14/2016

Enforcement Action Type: Notice of Violation (Unified Program)

Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enforcement Action Note(s): Not Reported

Enforcement Action Division: San Bernardino County Fire Department

Enforcement Action Program: HW

Enforcement Action Source: CERS

Chemical Information

: Not Reported

:Coordinate Information

: Not Reported

:

DATABASE

STATUS

DISTANCE

ELEVATION

MAP ID

FRS-US	Listed	0.03 miles S	3632 ft	2
SITE NAME			MAPS	ID
VVG FACILITY #7			1,4	110065650352
ADDRESS			CITY	ZIP
8995 THREE FLAGS AVE			HESPERIA	92345
DETAILS				
FRS Facility Detail Report URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110065650352 Create Date: 13-OCT-2015 12:56:11 Program System: CA-ENVIROVIEW Interest Type(s): STATE MASTER				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
Hist-CA	No Longer Listed	0.03 miles S	3632 ft	2
SITE NAME			MAPS	ID
Tanks Ent LLC			1,4	278713
ADDRESS			CITY	ZIP
8995 Three Flags Avenue			Hesperia	92345
DETAILS				
Original Database: NPDES-SW-CA Last Agency Status: Listed Archive Date: 06/01/16 No Longer Listed-Registered Meas ID: 278713 Registered Meas Type: Construction WDID: 6B36C335897 Received Date: 5/9/2008 Processed Date: 8/5/2005 Termination Date: 6/7/2010 Status Code Name: Terminated Status Date: 6/16/2010 REGION: Not Reported County Code: 36 Place Size: 1 Place Size Unit: Acres Facility County: San Bernardino Facility Contact Name: Rob Immerman				

Facility Contact Title: Not Reported
Facility Contact Phone: 714-904-0994
Facility Contact Phone Extension: Not Reported
Facility Contact Email Address: Not Reported
Operator Name: Tanks Ent LLC
Operator Address: 14530 Whittier Blvd
Operator City: Whittier
Operator State: California
Operator Zip: 90605
Operator Contact Name: Brian Tanklage
Operator Contact Title: Not Reported
Operator Contact Phone: 562-902-1070
Operator Contact Phone Extension: Not Reported
Operator Contact Email Address: Not Reported
Operator Type: Other
Developer Name: Facility Builders
Developer Address: 3940 E Miraloma Ave
Developer City: Anaheim
Developer State: California
Developer Zip: 92806
Developer Contact Name: Susan Thomson
Developer Contact Title: Not Reported
Constype Linear Utility Ind: Not Reported
Emergency Phone Number: 714-904-0994
Emergency phone Number Extension: Not Reported
Constype Aboveground Ind: Not Reported
Constype Belowground Ind: Not Reported
Constype Cable Line Ind: Not Reported
Constype Comm line Ind: Not Reported
Constype Commercial Ind: YES
Constype Electrical Line Ind: Not Reported
Constype Gas Line Ind: Not Reported
Constype Industrial Ind: YES
Constype Other Description: Not Reported
Constype Other Ind: Not Reported
Constype Recons Ind: Not Reported
Constype Residential Ind: Not Reported
Constype Transport Ind: Not Reported
Constype Utility Description: Not Reported
Constype Utility Ind: Not Reported
Constype Water Sewer Ind: Not Reported
Dir Discharge Us Water Ind: Not Reported
Receiving Water Name: Mojave River
Certifier Name: Susan Thomson
Certifier Title: Project Coordinator
Certification Date: 03-AUG-05 12.00.00.000000 AM
Primary SIC: Not Reported
Secondary SIC: Not Reported
Tertiary SIC: Not Reported

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
HWIS-CA	Listed	0.03 miles S	3632 ft	2
SITE NAME			MAPS	ID
HIGH DESERT TRUCK & TRAILER			1,4	CAL000320679
ADDRESS			CITY	ZIP
8995 THREE FLAGS AVE STE B&C			VICTORVILLE	92344
DETAILS				
Facility Information EPA ID: CAL000320679 Facility County: 36 Mailing Street: 2429 S PECK RD Mailing City: WHITTIER Mailing State: CA Mailing Zip: 906010000 Contact Name: DEVIN BECK Contact Phone: Not Reported Generator Details Year: 2019 TONS: Not Reported TSD EPA ID: AZR000521146 Category Code: 352 Category Description: Other organic solids Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135) Year: 2019 TONS: Not Reported TSD EPA ID: CAT080013352 Category Code: 223 Category Description: Unspecified oil-containing waste Method Description: OTHER RECOVERY OF RECLAMATION FOR REUSE INCLUDING ACID REGENERATION, ORGANICS RECOVERY ECT Year: 2019 TONS: Not Reported TSD EPA ID: CAT080013352 Category Code: 343 Category Description: Unspecified organic liquid mixture Method Description: OTHER RECOVERY OF RECLAMATION FOR REUSE INCLUDING ACID REGENERATION,				

ORGANICS RECOVERY ECT

Year: 2019

TONS: Not Reported

TSD EPA ID: AZR000515924

Category Code: 352

Category Description: Other organic solids

Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)

Year: 2019

TONS: Not Reported

TSD EPA ID: CAD097030993

Category Code: 352

Category Description: Other organic solids

Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)

Year: 2019

TONS: Not Reported

TSD EPA ID: CAT080025711

Category Code: 223

Category Description: Unspecified oil-containing waste

Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
RCRA-NON-US	Listed	0.03 miles S	3632 ft	2
SITE NAME			MAPS	ID
HIGH DESERT TRUCK & TRAILER			1,4	CAL000320679
ADDRESS			CITY	ZIP
8995 THREE FLAGS AVE STE B&C			VICTORVILLE	92344
DETAILS				
Additional details may be found online using the following link: https://enviro.epa.gov/enviro/rcrainfoquery_3.facility_information?pgm_sys_id=CAL000320679 Source Type: Implementer Generator Status: Non-Generator NAICS1: NEW CAR DEALERS Active Site Indicator: H----				

Owner Name: LOS ANGELES TRUCK SERVICE LLC
Operator Name: DEVIN BECK
In Handler Universes: Y
In a Universe: Y
Universal Waste: Y
Universal Waste Destination Facility: Y

Receive Date: 20070613
Acknowledge Flag Date: 20070613
Contact First Name: DEVIN
Contact Last Name: BECK
Contact Street 1: 2429 S. PCK RD.
Contact City: WHITTIER
Contact State: CA
Contact Zip: 90601-0000
Contact Phone: 909-510-4272
Contact E-mail Address: DBECK@VVGTRUCK.COM
Universal Waste Destination Facility: Y

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CUPA-CA	Listed	0.04 miles W	3623 ft	3
SITE NAME			MAPS	ID
THE LITZENBERGER COMPANY			1,4	FA0011408-SBD
ADDRESS			CITY	ZIP
12221 POPLAR ST 14			HESPERIA	92345

DETAILS

County: San Bernardino
Responsible Agency: San Bernardino County Fire Department
Facility ID: FA0011408
Address2: Not Reported
Owner Information: LITZENBERGER, TROY
Contact Name: TROY LITZENBERGER
Mailing Address: P.O. BOX 943, WRIGHTWOOD, CA 92397-0943
Mailing Address 2: Not Reported
Agency Provided Latitude: Not Reported
Agency Provided Longitude: Not Reported
Permit ID: PT0019744
Program Element Code: 4221
Permit Description: HAZMAT HANDLER 0-10 EMPLOYEES
Status: INACTIVE
To: 2/28/2013

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CERS-CA	Listed	0.06 miles W	3627 ft	4
SITE NAME			MAPS	ID
Superior Pool Products LLC #548A			1,4	10762693
ADDRESS			CITY	ZIP
12221 Poplar St Bldg E			Hesperia	92344
DETAILS				
General Program & Facility Information CERS ID: 10762693 Facility ID: Not Reported Facility Regulator Key ID: Not Reported Organization Code: 90713275 Business/Organization Name: Superior Pool Products LLC #548A Multiple Jurisdictional Business? (Y/N): No Business Origin: Business Count of Business CERS User Accounts: 1 Facility Count for Business: 1 Last Submittal Date (any element): Not Reported Count of Submitted Elements: 0 Remote Facility? (Y/N): No Small Quantity Generator Facility? (Y/N): No Local Facility Grouping: Not Reported Facility Specific Information Assessor Parcel Number (APN): Not Reported Number of Employees: 4 Property Owner Name: JT & LT Family LLC Property Owner Phone Number: 714-981-3623 Property Owner Mailing Address: 310 Goetz Avenue Property Owner Mailing City: Santa Ana Property Owner Mailing State: CA Property Owner Mailing Zip Code: 92707 Property Owner Mailing Country: United States Inspection Information Aboveground Petroleum Storage Act (APSA) Last Inspection Date: Not Reported California Accidental Release Prevention (CalARP) Last Inspection: Not Reported Conditionally Authorized (CA) Last Inspection Date: Not Reported				

Conditionally Exempt (CE) Last Inspection Date: Not Reported
Household Hazardous Waste Collection (HHW) Last Inspection Date: Not Reported
Hazardous Materials Release Response Plan (HMRRP) Last Inspection: Not Reported
Hazardous Waste Generator (HW) Last Inspection Date: Not Reported
RCRA Large Quantity Generator (HWLQG) Last Inspection Date: Not Reported
Hazardous Waste Recycler (HWRcyclers) Last Inspection Date: Not Reported
Permit By Rule (PBR) Last Inspection: Not Reported
Underground Storage Tank (UST) Last Inspection Date: Not Reported

Owner/Operator Information

Beginning Date: 5/2/2018
Ending Date: 5/1/2019
Phone Number: 760-981-0159
Fax Number: 760-513-9803
Supplemental Location: Not Reported
County: San Bernardino
Dun & Bradstreet D-U-N-S Number: Not Reported
SIC Code: 5091
NAICS Code: 423910
Mailing Address: 109 Northpark Blvd., Suite 123
Mailing Address City: Covington
Mailing Address State Code: LA
Mailing Address Zip Code: 70433
Operator Name: Superior Pool Products LLC
Operator Phone Number: 760-981-0159
Owner Name: Superior Pool products LLC
Owner Phone: 985-892-5521
Owner Mailing Address: 109 Northpark Blvd., Suite 400
Owner City: Covington
Owner State: LA
Owner Zip Code: 70433
Owner Country: United States
Environmental Contact Name: Annetter Niemiec
Environmental Contact Phone Number: 985-801-5714
Environmental Contact Mailing Address: 109 Northpark Blvd., Suite 123
Environmental Contact Email Address: annette.niemiec@poolcorp.com
Environmental Contact City: Covington
Environmental Contact State: LA
Environmental Contact Zip: 70433
Environmental Contact Country: United States
Primary Emergency Contact Name: Jacob Lynch
Primary Emergency Contact Title: Sales Center Manager
Primary Emergency Contact Business Phone Number: 760-981-0159
Primary Emergency Contact 24Hr Phone: 951-675-3133
Primary Emergency Contact Pager Number: Not Reported
Secondary Emergency Contact Name: Not Reported
Secondary Emergency Contact Title: Not Reported
Secondary Emergency Contact Business Phone: Not Reported
Secondary Emergency Contact 24Hr Phone: Not Reported

Secondary Emergency Contact Pager Number: Not Reported
Additional Local Collected Info: Not Reported
Identification Signed Date: Not Reported
Document Preparer Name: Annette Niemiec
Identification Signer Name: Annette Niemiec
Identification Signer Title: EPA Government Relations Coordinator
Billing Contact Name: Annette Niemiec
Billing Contact Phone: 985-801-5714
Billing Contact Email: annette.niemiec@poolcorp.com
Billing Address: 109 Northpark Blvd., Suite 123
Billing City: Covington
Billing State: LA
Billing Zip: 70433
Billing Country: United States
Business Owner/Operator Regulator Key: Not Reported

Business Activity Information

EPA ID: Not Reported
Hazardous Materials On Site? (Y/N): Y
CAL ARP Regulated Substances? (Y/N): N
Own or Operator USTs? (Y/N): N
Own or Operator APSTs? (Y/N): N
Hazardous Waste Generator? (Y/N): N
Recycles Materials? (Y/N): N
On-site HW Treatment? (Y/N): N
Financial Assurance? (Y/N): N
Remote Waste Consolidation Site? (Y/N): N
Hazardous Waste Tank Closure? (Y/N): N
RCRA Large Quantity Generator? (Y/N): N
Household Hazardous Waste (HHW) Collection? (Y/N): N
Business Activity Comment(s): Not Reported

Submittal Information

Submitted Date/Time: Not Reported
Submittal Action: Draft
BP Activities Last Updated Date: 5/2/2018 9:07:20 AM
BP Owner/Operator Last Updated Date: 5/2/2018 9:16:58 AM
Submittal Action Comment 1: Not Reported
Submittal Action Comment 2: Not Reported
Facility Info Next Due Date: Not Reported
Biz Activities Regulator Key: Not Reported

Supplemental Geographic Information

Agency Provided Latitude: 34.41542
Agency Provided Longitude: -117.39679
Horizontal Accuracy: 10
Horizontal Collection Method: Address Matching

Geographic Reference Point: Facility Center/Centroid
Horizontal Reference Datum: WGS84 (World Geodetic System of 1984)
Data Collection Date: 5/2/2018 8:43:30 AM

Submittal Element Regulator Information

CUPA Regulator Code: 3600

Facility Info Reporting Requirement: Applicable

Facility Info Next Due Date: Not Reported

Facility Info Last Submitted Date: Not Reported

Facility Info Accepted Date: Not Reported

Inventory Regulator Code: 3600

Inventory Reporting Requirement: Applicable

Inventory Next Due Date: Not Reported

Inventory Last Submitted Date: Not Reported

Inventory Last Accepted Date: Not Reported

ER Training Regulator Code: 3600

ER Training Reporting Requirement: Applicable

ER Training Next Due Date: Not Reported

ER Training Last Submitted Date: Not Reported

ER Training Last Accepted Date: Not Reported

UST Regulator Code: 3600

UST Reporting Requirement: Not Applicable

UST Next Due Date: Not Reported

UST Last Submitted Date: Not Reported

UST Last Accepted Date: Not Reported

HW Treat Regulator Code: 3600

HW Treat Reporting Requirement: Not Applicable

HW Treat Next Due Date: Not Reported

HW Treat Last Submitted Date: Not Reported

HW Treat Last Accepted Date: Not Reported

RMR Regulator Code: 3600

RMR Reporting Requirement: Not Applicable

RMR Next Due Date: Not Reported

RMR Last Submitted Date: Not Reported

RMR Last Accepted Date: Not Reported

Consolidation Regulator Code: 3600

Consolidation Reporting Requirement: Not Applicable

Consolidation Next Due Date: Not Reported

Consolidation Last Submitted Date: Not Reported

Consolidation Last Accepted Date: Not Reported

Tank Closure Regulator Code: 3600

Tank Closure Reporting Requirement: Not Applicable

Tank Closure Next Due Date: Not Reported

Tank Closure Last Submitted Date: Not Reported

Tank Closure Last Accepted Date: Not Reported

APSA Regulator Code: 3600

APSA Reporting Requirement: Not Applicable

APSA Next Due Date: Not Reported

APSA Last Submitted Date: Not Reported

APSA Last Accepted Date: Not Reported
CalARP Regulator Code: 3600
CalARP Reporting Requirement: Not Applicable
CalARP Next Due Date: Not Reported
CalARP Last Submitted Date: Not Reported
CalARP Last Accepted Date: Not Reported

UST Facility and Program Information

: Not Reported

Tank & Monitoring Plan Information

: Not Reported

HMRRP & UST Violation Information

: Not Reported

HMRRP & UST Inspection Information

: Not Reported

HMRRP & UST Enforcement Information

: Not Reported

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CRSP-CA	Listed	0.06 miles W	3627 ft	4
SITE NAME			MAPS	ID
Superior Pool Products LLC #548A			1,4	437884
ADDRESS			CITY	ZIP
12221 POPLAR ST BLDG E			HESPERIA	92344
DETAILS				
Site Regulated Program Information				
Site ID: 437884				
Site EI ID: 10762693				
Agency Provided Latitude: 34.41542				
Agency Provided Longitude: -117.39679				
Program Description: Chemical Storage Facilities				
Evaluation Information				
: Not Reported				
:Violation Information				
: Not Reported				
:Enforcement Information				
: Not Reported				

:Chemical Information
: Not Reported
:Coordinate Information
: Not Reported
:

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
AIR-DIST-CA	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
Zippy Lube			1,4	842-MD
ADDRESS			CITY	ZIP
8899 Three Flags Avenue			Hesperia	92345
DETAILS				
Note: This is an ERS assigned ID. Responsible Agency: Mohave Valley AQMD Permit Number: T010147 Facility ID: 3040 District ID: 1 Permit Type: T Permit Status Code: PTO Permit Status: Permit To Operate Permit Desc: WASTE OIL TANK Employee Assigned: 62 Address Region: Not Reported Fax Nbr: Not Reported Emission Calc: Not Reported Expired Date: 3/31/2018 11:59:59 PM Under Construction: False Last Renewal Date: Not Reported Secondary APC: Not Reported Primary APC: Not Reported Est Comp Date: Not Reported Est Start Date: Not Reported Issue Date: 9/20/2017 6:27:00 PM Application Date: 3/13/2008 Permit Printed: True Batch Update: False Permit Detail Type: S Title VPMTwo: False Confidential: False Application Nbr: 9620 SCCCode: 30630006				

Title VSOX: False
Permit ID: 9381
Title VSynthetic Minor80: False
Title VVOC: False
Title VSynthetic Minor: False
Belongs To Capacity Rating: 13
Title VPMTen: False
Title VNOX: False
Title VLead: False
Title VHS: False
Title VGHG: False
Billing Capacity: 1
Title VCO: False
Title V1200B1e: False
NSRPMTwo: False
Title V1200B1d: False
NSRVOC: False
NSRSOX: False
NSRPMTen: False
NSRHS: False
NSRNOX: False
NSRLead: False
NAICS: 811191
Agency Provided Facility Longitude: Not Reported
Agency Provided Facility Latitude: Not Reported
Title VFacility: N
FONA: True
AB2588Facility: Not Reported
Last Modified: 7/12/2012
Address Street2: Not Reported
Facility Creation Date: 12/31/1969
Expire Month: 3
Active Flag: A
auto Schedule Status Flag: Y
Inspection Status Flag: Not Reported
Inspection Time: 1
Paper Work Time: 0.5
Zone ID: 8
Expiration Month: 3
Level2Inspection: False
UTM: 473E/3808N
SIC Code: 7538
Principal Product: Waste Oil
Phone Number: 424-832-0217
Operating Weeks: 50
Operating Hours: 8
Operating Days: 5
Size Acres: 0
Number of Employees: 0
Near School: False

Facility Description: Zippy Lube
Facility Note: Not Reported
Equipment Description: 1,000 Gallon Tank; Facility Elevation is 3664 feet

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
AIR-DIST-CA	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
IRONMAN RENEWAL LLC			1,4	177957-SC
ADDRESS			CITY	ZIP
8899 THREE FLAGS			HESPERIA	92345

DETAILS
District: South Coast AQMD Compliance URL: http://www3.aqmd.gov/webappl/fim/prog/novnc.aspx?fac_id=177957 Note: For additional Facility, Equipment, Emissions, Hearing Board or Transporation Plan Information click on different tabs. Facility Id: 177957 County Code: SB County: San Bernardino Facility Status Code: A Facility Status: ACTIVE Number of Employees: 0 Location Zip Code Extension: Not Reported Facility Representative First Name: YAMIL Facility Representative Last Name: TOMASSINI Location Area Code: 951 Location Phone Number: 5202995 Location Phone Extension: Not Reported Mailing Address: 2535 ANSELMO DR Mailing City: CORONA Mailing State: CA Mailing Zip Code: 92879 Mailing Zip Code Extension: 8092 Mailing Area Code: 951 Mailing Phone Number: 5202995 Mailing Phone Extension: Not Reported Mailing Representative First Name: YAMIL Mailing Representative Last Name: TOMASSINI

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
----------	--------	----------	-----------	--------

AST-CRSP-CA	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
ZIPPY LUBE-A-TRUCK			1,4	172882
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE			HESPERIA	92344
DETAILS				
Site Regulated Program Information Site ID: 172882 EI ID: 10049617 Agency Provided Address: 8899 THREE FLAGS AVE Agency Provided Latitude: 34.413147 Agency Provided Longitude: -117.39313 Program Description: Aboveground Petroleum Storage				
Evaluation Information (2017 to present) Evaluation Date: 3/10/2020 Violations Found? (Y/N): Yes Evaluation General Type: Compliance Evaluation Inspection Evaluation Type: Routine done by local agency Evaluation Note(s): Evaluation Division: San Bernardino County Fire Department Evaluation Program: HMRRP Evaluation Source: CERS				
Evaluation Date: 3/10/2020 Violations Found? (Y/N): Yes Evaluation General Type: Compliance Evaluation Inspection Evaluation Type: Routine done by local agency Evaluation Note(s): Evaluation Division: San Bernardino County Fire Department Evaluation Program: HW Evaluation Source: CERS				
Evaluation Date: 3/10/2020 Violations Found? (Y/N): Yes Evaluation General Type: Compliance Evaluation Inspection Evaluation Type: Routine done by local agency Evaluation Note(s): Evaluation Division: San Bernardino County Fire Department Evaluation Program: APSA Evaluation Source: CERS				

Evaluation Date: 1/9/2017
Violations Found? (Y/N): Yes
Evaluation General Type: Compliance Evaluation Inspection
Evaluation Type: Routine done by local agency
Evaluation Note(s): ROUTINE HANDLER INSPECTION
Evaluation Division: San Bernardino County Fire Department
Evaluation Program: HMRRP
Evaluation Source: CERS

Evaluation Date: 1/9/2017
Violations Found? (Y/N): Yes
Evaluation General Type: Compliance Evaluation Inspection
Evaluation Type: Routine done by local agency
Evaluation Note(s): ROUTINE APSA INSPECTION
Evaluation Division: San Bernardino County Fire Department
Evaluation Program: APSA
Evaluation Source: CERS

Evaluation Date: 1/9/2017
Violations Found? (Y/N): Yes
Evaluation General Type: Compliance Evaluation Inspection
Evaluation Type: Routine done by local agency
Evaluation Note(s): ROUTINE GENERATOR INSPECTION
Evaluation Division: San Bernardino County Fire Department
Evaluation Program: HW
Evaluation Source: CERS

Violation Information (2017 to present)

Violation Date: 3/10/2020
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description: Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.
Violation Note(s): Returned to compliance on 04/08/2020. OBSERVATION: Facility failed to annually re-certify a complete business plan in CERS. Last submittal was dated 07/10/2019 (inventory element), 04/16/2018 (emergency response element) and 08/08/2018 (APSA element). CORRECTIVE ACTION: Review and certify the business plan via CERS. Your CERS ID number is 10049617.
Violation Division: San Bernardino County Fire Department
Violation Program: HMRRP
Violation Source: CERS

Violation Date: 3/10/2020
Citation: HSC 6.67 25270.4.5 (a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5 (a)
Violation Description: Failure to include in the SPCC plan an adequate description of employee training. Training shall address, at a minimum: operation and maintenance of equipment to prevent discharges; discharge procedure protocols; applicable pollution control laws, rules, and regulations; general facility operations; content of the facility SPCC plan; and annual discharge prevention briefings for oil-handling personnel to assure adequate understanding of the SPCC plan.

Violation Note(s): Returned to compliance on 10/20/2020. OBSERVATION: Facility failed to include in the SPCC plan adequate training for oil-handling personnel. CORRECTIVE ACTION: Submit a signed statement indicating that the SPCC plan has been

revised to training for oil-handling personnel.

Violation Division: San Bernardino County Fire Department

Violation Program: APSA

Violation Source: CERS

Violation Date: 3/10/2020

Citation: HSC 6.5 25201 - California Health and Safety Code, Chapter 6.5, Section(s) 25201

Violation Description: Failure to obtain a permit or grant of interim status after generator has accumulated hazardous waste on-site for longer than 90 days.

Violation Note(s): Returned to compliance on 10/20/2020. OBSERVATION: (1) 55 gallon drum and (1) 100 gallon container of used antifreeze were observed with an accumulation start date of 05/13/2017 and 06/11/2019 and a manifest/receipt demonstrating disposal within the past 90 days was not available. CORRECTIVE ACTION: Dispose of the used antifreeze and submit a copy of the manifest/receipt to the CUPA.

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 3/10/2020

Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)

Violation Description: Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.

Violation Note(s): Returned to compliance on 10/20/2020. OBSERVATION: Training documents related to hazardous materials and hazardous waste safety handling were not provided. CORRECTIVE ACTION: Conduct initial and annual employee training and maintain training records for a minimum of three years. Submit a signed statement indicating that training has been conducted and that training records will be kept on site for review.

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

Violation Source: CERS

Violation Date: 3/10/2020

Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)

Violation Description: Failure to properly close tanks when making a claim of "permanently closed."

Violation Note(s): Returned to compliance on 10/20/2020. OBSERVATION: (2) 230 gallon and (2) 240 gallon empty tanks acquired from another location have not been properly closed. CORRECTIVE ACTION: Submit photographs indicating that the tanks have been properly closed with a "permanently closed" label and the date they were closed.

Violation Division: San Bernardino County Fire Department

Violation Program: APSA

Violation Source: CERS

Violation Date: 3/10/2020

Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)

Violation Description: Failure to designate person who reports to management as accountable for discharge prevention at facility.

Violation Note(s): Returned to compliance on 10/20/2020. OBSERVATION: The designated person in charge stated in the SPCC plan, Jake Sanchez, is no longer employed at the facility and an updated person has not been assigned. CORRECTIVE ACTION: Submit a signed statement indicating that a person who reports to facility management has been designated as

accountable for discharge prevention.

Violation Division: San Bernardino County Fire Department

Violation Program: APSA

Violation Source: CERS

Violation Date: 1/9/2017

Citation: Un-Specified

Violation Description: Business Plan Program - Administration/Documentation - General Local Ordinance

Violation Note(s): Not Reported

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.67 25270.6(a)(1), 25270.6(a)(2) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.6(a)(1), 25270.6(a)(2)

Violation Description: Failure to submit a tank facility statement on or before January 1 annually unless a current Business Plan has been submitted.

Violation Note(s): Not Reported

Violation Division: San Bernardino County Fire Department

Violation Program: APSA

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Operations/Maintenance - General

Violation Note(s): Not Reported

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Operations/Maintenance - General

Violation Note(s): Not Reported

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)

Violation Description: Failure to establish and electronically submit an adequate emergency response plan and procedures for a release or threatened release of a hazardous material.

Violation Note(s): Not Reported

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Administration/Documentation - General

Violation Note(s): Not Reported

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Operations/Maintenance - General

Violation Note(s): Not Reported

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.67 25270.6(b) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.6(b)

Violation Description: Failure to pay the APSA Program fee.

Violation Note(s): Not Reported

Violation Division: San Bernardino County Fire Department

Violation Program: APSA

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)

Violation Description: Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.

Violation Note(s): Not Reported

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.5 25250.22 - California Health and Safety Code, Chapter 6.5, Section(s) 25250.22

Violation Description: Failure to properly manage used oil and/or fuel filters in accordance with the requirements.

Violation Note(s): Not Reported

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Operations/Maintenance - General

Violation Note(s): Not Reported

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit a site map with all required content.

Violation Note(s): Not Reported

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.

Violation Note(s): Not Reported

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Operations/Maintenance - General

Violation Note(s): Not Reported

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Training - General

Violation Note(s): Not Reported

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Enforcement Information

Enforcement Action Date: 1/9/2017

Enforcement Action Type: Notice of Violation (Unified Program)

Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enforcement Action Note(s): Not Reported

Enforcement Action Division: San Bernardino County Fire Department

Enforcement Action Program: HW

Enforcement Action Source: CERS

Enforcement Action Date: 1/9/2017

Enforcement Action Type: Notice of Violation (Unified Program)

Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enforcement Action Note(s): Not Reported
Enforcement Action Division: San Bernardino County Fire Department
Enforcement Action Program: HMRRP
Enforcement Action Source: CERS

Enforcement Action Date: 1/9/2017
Enforcement Action Type: Notice of Violation (Unified Program)
Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enforcement Action Note(s): Not Reported
Enforcement Action Division: San Bernardino County Fire Department
Enforcement Action Program: APSA
Enforcement Action Source: CERS

Enforcement Action Date: 11/14/2013
Enforcement Action Type: Notice of Violation (Unified Program)
Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enforcement Action Note(s): Not Reported
Enforcement Action Division: San Bernardino County Fire Department
Enforcement Action Program: HW
Enforcement Action Source: CERS

Coordinate Information
Program ID: 10049617
ENV INT Type Code: HWG
Coordinate Name: Not Reported
Reference Point Type Description: Unknown
Agency Provided Latitude: 34.413139
Agency Provided Longitude: -117.39312

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CERS-CA	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
Little Sister's Truck Wash			1,4	10128901
ADDRESS			CITY	ZIP
8899 Three Flags Ave			Hesperia	92344
DETAILS				
General Program & Facility Information CERS ID: 10128901				

Facility ID: FA0010378
Facility Regulator Key ID: FA0010378
Organization Code: 90093058
Business/Organization Name: Little Sister's Truck Wash
Multiple Jurisdictional Business? (Y/N): No
Business Origin: Business
Count of Business CERS User Accounts: 1
Facility Count for Business: 3
Last Submittal Date (any element): 2/12/2018 11:31:19 PM
Count of Submitted Elements: 18
Remote Facility? (Y/N): No
Small Quantity Generator Facility? (Y/N): No
Local Facility Grouping: Not Reported

Facility Specific Information

Assessor Parcel Number (APN): Not Reported
Number of Employees: 24
Property Owner Name: Renald Anelle
Property Owner Phone Number: 760-731-3170
Property Owner Mailing Address: 25 Rollingview Lane
Property Owner Mailing City: Fallbrook
Property Owner Mailing State: CA
Property Owner Mailing Zip Code: 92028
Property Owner Mailing Country: United States

Inspection Information

Aboveground Petroleum Storage Act (APSA) Last Inspection Date: Not Reported
California Accidental Release Prevention (CalARP) Last Inspection: Not Reported
Conditionally Authorized (CA) Last Inspection Date: Not Reported
Conditionally Exempt (CE) Last Inspection Date: Not Reported
Household Hazardous Waste Collection (HHW) Last Inspection Date: Not Reported
Hazardous Materials Release Response Plan (HMRRP) Last Inspection: 6/3/2016
Hazardous Waste Generator (HW) Last Inspection Date: 6/3/2016
RCRA Large Quantity Generator (HWLQG) Last Inspection Date: Not Reported
Hazardous Waste Recycler (HWRecycler) Last Inspection Date: Not Reported
Permit By Rule (PBR) Last Inspection: Not Reported
Underground Storage Tank (UST) Last Inspection Date: Not Reported

Owner/Operator Information

Beginning Date: Not Reported
Ending Date: Not Reported
Phone Number: 7609474448
Fax Number: 760-731-7020
Supplemental Location: Not Reported
County: San Bernardino
Dun & Bradstreet D-U-N-S Number: Not Reported
SIC Code: 7542

NAICS Code: Not Reported
Mailing Address: 25 Rollingview Lane
Mailing Address City: Fallbrook
Mailing Address State Code: CA
Mailing Address Zip Code: 92028
Operator Name: Little Sister's Truck Wash, Inc.
Operator Phone Number: 760-731-3170
Owner Name: Little Sister's Truck Wash, Inc.
Owner Phone: 760-731-3170
Owner Mailing Address: 25 Rollingview Lane
Owner City: Fallbrook
Owner State: CA
Owner Zip Code: 92028
Owner Country: United States
Environmental Contact Name: Renald J. Anelle
Environmental Contact Phone Number: 760-731-3170
Environmental Contact Mailing Address: 25 Rollingview Lane
Environmental Contact Email Address: Istwren@gmail.com
Environmental Contact City: Fallbrook
Environmental Contact State: CA
Environmental Contact Zip: 92028
Environmental Contact Country: United States
Primary Emergency Contact Name: Renald Anelle
Primary Emergency Contact Title: President
Primary Emergency Contact Business Phone Number: 760-420-8500
Primary Emergency Contact 24Hr Phone: 760-731-3170
Primary Emergency Contact Pager Number: Not Reported
Secondary Emergency Contact Name: Joe McFann
Secondary Emergency Contact Title: Senior Manager
Secondary Emergency Contact Business Phone: (760) 420-6520
Secondary Emergency Contact 24Hr Phone: (760) 420-6520
Secondary Emergency Contact Pager Number: Not Reported
Additional Local Collected Info: Not Reported
Identification Signed Date: Not Reported
Document Preparer Name: Renald Anelle
Identification Signer Name: Renald Anelle
Identification Signer Title: President
Billing Contact Name: Renald J. Anelle
Billing Contact Phone: 7607313170
Billing Contact Email: Istwren@gmail.com
Billing Address: 25 Rollingview Lane
Billing City: Fallbrook
Billing State: CA
Billing Zip: 92028
Billing Country: United States
Business Owner/Operator Regulator Key: Not Reported

Business Activity Information

EPA ID: CAL000353253

Hazardous Materials On Site? (Y/N): Y
CAL ARP Regulated Substances? (Y/N): N
Own or Operator USTs? (Y/N): N
Own or Operator APSTs? (Y/N): N
Hazardous Waste Generator? (Y/N): Y
Recycles Materials? (Y/N): N
On-site HW Treatment? (Y/N): N
Financial Assurance? (Y/N): N
Remote Waste Consolidation Site? (Y/N): N
Hazardous Waste Tank Closure? (Y/N): N
RCRA Large Quantity Generator? (Y/N): N
Household Hazardous Waste (HHW) Collection? (Y/N): N
Business Activity Comment(s): Not Reported

Submittal Information

Submitted Date/Time: 2/12/2018 11:31:19 PM

Submittal Action: Accepted

BP Activities Last Updated Date: 2/12/2018 11:29:49 PM

BP Owner/Operator Last Updated Date: 2/12/2018 11:29:49 PM

Submittal Action Comment 1: ACCEPTED AS COMPLETE PENDING FIELD VERIFICATION: Thank you for the submittal.

While this submittal is being accepted as complete, the data has not been field verified and may require correction in the future. Please note, it is your responsibility to review and certify the information submitted in CERS annually. You must also update the information within 30 days of a change of owner, business address, business name, emergency contact information, inventory and/or other site conditions that could impact emergency response activity. If you have questions about using CERS, please contact the San Bernardino County Fire CERS Help Desk at (909) 386-8432. (Reviewed by Nancy Schlotthauer, nschlotthauer@sbcfire.org or (909) 386-8401)

Submittal Action Comment 2: Not Reported

Facility Info Next Due Date: Not Reported

Biz Activities Regulator Key: Not Reported

Supplemental Geographic Information

Agency Provided Latitude: 37.271881

Agency Provided Longitude: -119.270233

Horizontal Accuracy: 10

Horizontal Collection Method: Interpolation

Geographic Reference Point: Facility Boundary

Horizontal Reference Datum: WGS84 (World Geodetic System of 1984)

Data Collection Date: 2/28/2011 5:30:00 PM

Submittal Element Regulator Information

CUPA Regulator Code: 3600

Facility Info Reporting Requirement: Applicable

Facility Info Next Due Date: Not Reported

Facility Info Last Submitted Date: 2/12/2018 11:31:19 PM

Facility Info Accepted Date: 3/15/2018 3:11:48 PM

Inventory Regulator Code: 3600

Inventory Reporting Requirement: Applicable

Inventory Next Due Date: Not Reported
Inventory Last Submitted Date: 2/12/2018 11:31:19 PM
Inventory Last Accepted Date: 3/15/2018 3:12:00 PM
ER Training Regulator Code: 3600
ER Training Reporting Requirement: Applicable
ER Training Next Due Date: Not Reported
ER Training Last Submitted Date: 2/12/2018 11:31:19 PM
ER Training Last Accepted Date: 3/15/2018 3:12:24 PM
UST Regulator Code: 3600
UST Reporting Requirement: Not Applicable
UST Next Due Date: Not Reported
UST Last Submitted Date: Not Reported
UST Last Accepted Date: Not Reported
HW Treat Regulator Code: 3600
HW Treat Reporting Requirement: Not Applicable
HW Treat Next Due Date: Not Reported
HW Treat Last Submitted Date: Not Reported
HW Treat Last Accepted Date: Not Reported
RMR Regulator Code: 3600
RMR Reporting Requirement: Not Applicable
RMR Next Due Date: Not Reported
RMR Last Submitted Date: Not Reported
RMR Last Accepted Date: Not Reported
Consolidation Regulator Code: 3600
Consolidation Reporting Requirement: Not Applicable
Consolidation Next Due Date: Not Reported
Consolidation Last Submitted Date: Not Reported
Consolidation Last Accepted Date: Not Reported
Tank Closure Regulator Code: 3600
Tank Closure Reporting Requirement: Not Applicable
Tank Closure Next Due Date: Not Reported
Tank Closure Last Submitted Date: Not Reported
Tank Closure Last Accepted Date: Not Reported
APSA Regulator Code: 3600
APSA Reporting Requirement: Not Applicable
APSA Next Due Date: Not Reported
APSA Last Submitted Date: Not Reported
APSA Last Accepted Date: Not Reported
CalARP Regulator Code: 3600
CalARP Reporting Requirement: Not Applicable
CalARP Next Due Date: Not Reported
CalARP Last Submitted Date: Not Reported
CalARP Last Accepted Date: Not Reported

UST Facility and Program Information

: Not Reported

Tank & Monitoring Plan Information

: Not Reported

HMRRP & UST Violation Information

EPA ID: CAL000353253

RCRA LQG: No

Violation Date: 6/3/2016

Violation Type Number: 1010008

Class: Class 2

Scheduled Return to Compliance Date: 7/3/2016

Actual Return to Compliance Date: 6/6/2016

Actual Return to Compliance Qualifier: Documented

Violation Comment: COMPLIANCE ACTIVITY: CERTIFICATE OF COMPLIANCE SIGNED 06/06/2016--OBSERVATION: THE BUSINESS PLAN INFORMATION LISTED IN CERS, MUST BE UPDATED BY MARCH 1 OF EVERY YEAR. CERS WAS LAST UPDATED ON 11/11/2014.COMPLIANCE REQUIREMENT: UPDATED CERS INFORMATION.

Violation Category: Administration/Documentation

Violation Name: Annual Review / Certification

Violation Description: Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.

Violation Citation(s): HSC 6.95 25508(a)(1), 25508.2

Violation Date: 7/23/2013

Violation Type Number: 1010002

Class: Minor

Scheduled Return to Compliance Date: 8/24/2013

Actual Return to Compliance Date: 7/24/2013

Actual Return to Compliance Qualifier: Documented

Violation Comment: Not Reported

Violation Category: Administration/Documentation

Violation Name: Hazardous Materials Business Plan Submittal

Violation Description: Owner/Operator failed to complete and/or submit a Hazardous Materials Business Plan when storing hazardous materials at or above the thresholds quantities of 55 gallons/500 lbs/200 cubic feet.

Violation Citation(s): 19 CCR 4 2729.2(a); HSC 6.95 25505(a)

HMRRP & UST Inspection Information

EPA ID: CAL000353253

RCRA LQG: No

Inspection Date: 6/3/2016

Inspection Type: Routine

Number of Class I Violations: 0

Number of Class II Violations: 1

Number of Minor Violations: 0

Significant Operational Compliance: With both Release Detection and Release Prevention

Date Returned to Compliance: 6/6/2016

Days Out of Compliance: 3

Violation Details Available: Yes

Inspection Comments: LITTLE SISTERS- CUPA HANDLER INSPECTION

Inspection Date: 7/23/2013

Inspection Type: Routine

Number of Class I Violations: 0

Number of Class II Violations: 0

Number of Minor Violations: 1

Significant Operational Compliance: With both Release Detection and Release Prevention

Date Returned to Compliance: 7/24/2013

Days Out of Compliance: 1

Violation Details Available: Yes

Inspection Comments: insp

HMRRP & UST Enforcement Information

Type of Enforcement Action: Notice of Violation (NOV) Only

Date of Enforcement Action: 6/3/2016

Type of Formal Enforcement Action: Not Reported

Date a Referred Case Settled or Dropped: Not Reported

Docket Number: Not Reported

Final Fine or Penalty Assessed: Not Reported

Supplemental Environmental Projects Value: Not Reported

Count of Linked Class I Violations: 0

Count of Linked Class II Violations: 1

Count of Linked Minor Violations: 0

Red Tag Issued: No

Red Tag Number: Not Reported

Violations Causing Red Tag: Not Reported

Date Red Tag Affixed: Not Reported

Date Red Tag Removed: Not Reported

Enforcement Comments: Not Reported

Enforcement Comments: Not Reported

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CERS-CA	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
ZIPPY LUBE-A-TRUCK			1,4	10049617
ADDRESS			CITY	ZIP
8899 Three Flags Ave			Hesperia	92344
DETAILS				
General Program & Facility Information				
CERS ID: 10049617				
Facility ID: FA0009125				
Facility Regulator Key ID: FA0009125				
Organization Code: 90135682				

Business/Organization Name: ZIPPY LUBE

Multiple Jurisdictional Business? (Y/N): Yes

Business Origin: Business

Count of Business CERS User Accounts: 1

Facility Count for Business: 6

Last Submittal Date (any element): 8/8/2018 10:46:18 AM

Count of Submitted Elements: 20

Remote Facility? (Y/N): No

Small Quantity Generator Facility? (Y/N): No

Local Facility Grouping: Not Reported

Facility Specific Information

Assessor Parcel Number (APN): Not Reported

Number of Employees: 2

Property Owner Name: Not Reported

Property Owner Phone Number: Not Reported

Property Owner Mailing Address: Not Reported

Property Owner Mailing City: Not Reported

Property Owner Mailing State: Not Reported

Property Owner Mailing Zip Code: Not Reported

Property Owner Mailing Country: Not Reported

Inspection Information

Aboveground Petroleum Storage Act (APSA) Last Inspection Date: 1/9/2017

California Accidental Release Prevention (CalARP) Last Inspection: Not Reported

Conditionally Authorized (CA) Last Inspection Date: Not Reported

Conditionally Exempt (CE) Last Inspection Date: Not Reported

Household Hazardous Waste Collection (HHW) Last Inspection Date: Not Reported

Hazardous Materials Release Response Plan (HMRRP) Last Inspection: 1/9/2017

Hazardous Waste Generator (HW) Last Inspection Date: 1/9/2017

RCRA Large Quantity Generator (HWLQG) Last Inspection Date: Not Reported

Hazardous Waste Recycler (HWRecycler) Last Inspection Date: Not Reported

Permit By Rule (PBR) Last Inspection: Not Reported

Underground Storage Tank (UST) Last Inspection Date: Not Reported

Owner/Operator Information

Beginning Date: Not Reported

Ending Date: Not Reported

Phone Number: 949 412-4894

Fax Number: 951-848-0713

Supplemental Location: Not Reported

County: San Bernardino

Dun & Bradstreet D-U-N-S Number: Not Reported

SIC Code: Not Reported

NAICS Code: Not Reported

Mailing Address: 8899 Three Flags Ave.

Mailing Address City: Hesperia

Mailing Address State Code: CA
Mailing Address Zip Code: 92345
Operator Name: Zippy Lube
Operator Phone Number: 949 412-5059
Owner Name: Renald Anelle
Owner Phone: 949 627-4644
Owner Mailing Address: P.O. Box 1530
Owner City: Bonsall
Owner State: CA
Owner Zip Code: 92003
Owner Country: United States
Environmental Contact Name: Christina Ross
Environmental Contact Phone Number: 951 228-8826
Environmental Contact Mailing Address: P.O. Box 7509
Environmental Contact Email Address: christina.ross@fleetcrew.com
Environmental Contact City: Laguna Niguel
Environmental Contact State: CA
Environmental Contact Zip: 92607
Environmental Contact Country: United States
Primary Emergency Contact Name: Raul Carrillo
Primary Emergency Contact Title: Manager
Primary Emergency Contact Business Phone Number: (949) 482-5197
Primary Emergency Contact 24Hr Phone: (949) 482-5197
Primary Emergency Contact Pager Number: Not Reported
Secondary Emergency Contact Name: Rodrigo Morales
Secondary Emergency Contact Title: Manager
Secondary Emergency Contact Business Phone: 949 482-5192
Secondary Emergency Contact 24Hr Phone: 949 482-5192
Secondary Emergency Contact Pager Number: Not Reported
Additional Local Collected Info: Not Reported
Identification Signed Date: Not Reported
Document Preparer Name: Christina Ross
Identification Signer Name: Christina Ross
Identification Signer Title: Environmental Contact
Billing Contact Name: A/R
Billing Contact Phone: 949 412-4894
Billing Contact Email: vivian.lam@fleetcrew.com
Billing Address: P.O. Box 7509
Billing City: Laguna Niguel
Billing State: CA
Billing Zip: 92607
Billing Country: United States
Business Owner/Operator Regulator Key: Not Reported

Business Activity Information

EPA ID: CAL000416670
Hazardous Materials On Site? (Y/N): Y
CAL ARP Regulated Substances? (Y/N): N
Own or Operator USTs? (Y/N): N

Own or Operator APSTs? (Y/N): Y
Hazardous Waste Generator? (Y/N): Y
Recycles Materials? (Y/N): N
On-site HW Treatment? (Y/N): N
Financial Assurance? (Y/N): N
Remote Waste Consolidation Site? (Y/N): N
Hazardous Waste Tank Closure? (Y/N): N
RCRA Large Quantity Generator? (Y/N): N
Household Hazardous Waste (HHW) Collection? (Y/N): N
Business Activity Comment(s): Not Reported

Submittal Information

Submitted Date/Time: 1/17/2017 12:44:16 PM

Submittal Action: Accepted

BP Activities Last Updated Date: 1/17/2017 12:44:01 PM

BP Owner/Operator Last Updated Date: 1/17/2017 12:44:01 PM

Submittal Action Comment 1: Thank you for the submittal. This submittal has been verified as complete. Please note it is your responsibility to review and certify the information submitted in CERS annually. You must also update the information within 30 days of a change of owner, business address, business name, emergency contact information, inventory and/or other site conditions that could impact emergency response activity. If you have questions about using CERS, please contact the San Bernardino County Fire CERS Help Desk at (909) 386-8432. (Reviewed by Kaniz Rahman, krahman@sbcfire.org or (909) 386-8401)

Submittal Action Comment 2: Not Reported

Facility Info Next Due Date: Not Reported

Biz Activities Regulator Key: Not Reported

Supplemental Geographic Information

Agency Provided Latitude: 34.413147

Agency Provided Longitude: -117.393135

Horizontal Accuracy: 100

Horizontal Collection Method: Interpolation

Geographic Reference Point: Facility Boundary

Horizontal Reference Datum: WGS84 (World Geodetic System of 1984)

Data Collection Date: 7/1/2010 7:32:00 PM

Submittal Element Regulator Information

CUPA Regulator Code: 3600

Facility Info Reporting Requirement: Applicable

Facility Info Next Due Date: Not Reported

Facility Info Last Submitted Date: 8/8/2018 10:46:18 AM

Facility Info Accepted Date: 1/21/2017 7:24:26 AM

Inventory Regulator Code: 3600

Inventory Reporting Requirement: Applicable

Inventory Next Due Date: Not Reported

Inventory Last Submitted Date: 7/9/2018 10:03:05 AM

Inventory Last Accepted Date: 1/21/2017 7:24:34 AM

ER Training Regulator Code: 3600

ER Training Reporting Requirement: Applicable
ER Training Next Due Date: Not Reported
ER Training Last Submitted Date: 4/16/2018 10:00:43 AM
ER Training Last Accepted Date: 1/21/2017 7:24:42 AM
UST Regulator Code: 3600
UST Reporting Requirement: Not Applicable
UST Next Due Date: Not Reported
UST Last Submitted Date: Not Reported
UST Last Accepted Date: Not Reported
HW Treat Regulator Code: 3600
HW Treat Reporting Requirement: Not Applicable
HW Treat Next Due Date: Not Reported
HW Treat Last Submitted Date: Not Reported
HW Treat Last Accepted Date: Not Reported
RMR Regulator Code: 3600
RMR Reporting Requirement: Not Applicable
RMR Next Due Date: Not Reported
RMR Last Submitted Date: Not Reported
RMR Last Accepted Date: Not Reported
Consolidation Regulator Code: 3600
Consolidation Reporting Requirement: Not Applicable
Consolidation Next Due Date: Not Reported
Consolidation Last Submitted Date: Not Reported
Consolidation Last Accepted Date: Not Reported
Tank Closure Regulator Code: 3600
Tank Closure Reporting Requirement: Not Applicable
Tank Closure Next Due Date: Not Reported
Tank Closure Last Submitted Date: Not Reported
Tank Closure Last Accepted Date: Not Reported
APSA Regulator Code: 3600
APSA Reporting Requirement: Applicable
APSA Next Due Date: Not Reported
APSA Last Submitted Date: 8/8/2018 10:46:18 AM
APSA Last Accepted Date: 1/21/2017 7:24:47 AM
CalARP Regulator Code: 3600
CalARP Reporting Requirement: Not Applicable
CalARP Next Due Date: Not Reported
CalARP Last Submitted Date: Not Reported
CalARP Last Accepted Date: Not Reported

UST Facility and Program Information

: Not Reported

Tank & Monitoring Plan Information

: Not Reported

HMRRP & UST Violation Information

EPA ID: CAL000416670

RCRA LQG: No

Violation Date: 1/9/2017

Violation Type Number: 1010004

Class: Minor

Scheduled Return to Compliance Date: 2/24/2017

Actual Return to Compliance Date: 3/30/2017

Actual Return to Compliance Qualifier: Documented

Violation Comment: The hazardous materials inventory submitted 12/16/13 is missing (1) 275 gallon tote of Diesel Exhaust Fluid.

Violation Category: Administration/Documentation

Violation Name: Hazardous materials inventory

Violation Description: Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.

Violation Citation(s): HSC 6.95 25505(a)(1), 25506, 25508(a)(1)

Violation Date: 1/9/2017

Violation Type Number: 1010005

Class: Minor

Scheduled Return to Compliance Date: 2/24/2017

Actual Return to Compliance Date: 3/30/2017

Actual Return to Compliance Qualifier: Documented

Violation Comment: The map submitted on CERS is missing adjacent streets and north orientation. Update and resubmit on CERS.

Violation Category: Administration/Documentation

Violation Name: Site map

Violation Description: Failure to complete and electronically submit a site map with all required content.

Violation Citation(s): HSC 6.95 25505(a)(2), 25508(a)(1)

Violation Date: 1/9/2017

Violation Type Number: 1010010

Class: Minor

Scheduled Return to Compliance Date: 2/24/2017

Actual Return to Compliance Date: 3/30/2017

Actual Return to Compliance Qualifier: Documented

Violation Comment: The Emergency Response (ER) Plan contains the incorrect phone number for the Local Unified Program Agency (CUPA). The correct phone number for the Emergency Response team at the CUPA is (909) 386-8425. Update the ER Plan and resubmit on CERS.

Violation Category: Administration/Documentation

Violation Name: Emergency response plan and procedures

Violation Description: Failure to establish and electronically submit an adequate emergency response plan and procedures for a release or threatened release of a hazardous material.

Violation Citation(s): HSC 6.95 25505(a)(3), 25508(a)(1)

Violation Date: 1/9/2017

Violation Type Number: 1015

Class: Minor

Scheduled Return to Compliance Date: 2/24/2017

Actual Return to Compliance Date: 3/30/2017

Actual Return to Compliance Qualifier: Documented

Violation Comment: Failure to obtain a CUPA Hazardous Materials Handler permit (SBCC 23.0602(a))CUPA permits expired on 12/31/16.

Violation Category: Administration/Documentation

Violation Name: General Local Ordinance

Violation Description: Business Plan Program - Administration/Documentation - General Local Ordinance

Violation Citation(s): Not Reported

Violation Date: 1/9/2017

Violation Type Number: 1020002

Class: Minor

Scheduled Return to Compliance Date: 2/24/2017

Actual Return to Compliance Date: 3/30/2017

Actual Return to Compliance Qualifier: Documented

Violation Comment: Not Reported

Violation Category: Training

Violation Name: Training Documentation

Violation Description: Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.

Violation Citation(s): HSC 6.95 25505(a)(4)

HMRRP & UST Inspection Information

EPA ID: CAL000416670

RCRA LQG: No

Inspection Date: 1/9/2017

Inspection Type: Routine

Number of Class I Violations: 0

Number of Class II Violations: 0

Number of Minor Violations: 5

Significant Operational Compliance: With both Release Detection and Release Prevention

Date Returned to Compliance: 3/30/2017

Days Out of Compliance: 80

Violation Details Available: Yes

Inspection Comments: ROUTINE HANDLER INSPECTION

Inspection Date: 11/14/2013

Inspection Type: Routine

Number of Class I Violations: 0

Number of Class II Violations: 0

Number of Minor Violations: 0

Significant Operational Compliance: With both Release Detection and Release Prevention

Date Returned to Compliance: Not Reported

Days Out of Compliance: 1860

Violation Details Available: No

Inspection Comments: zippy lube- hesperia/ oak hills-insp

HMRRP & UST Enforcement Information

Type of Enforcement Action: Notice of Violation (NOV) Only

Date of Enforcement Action: 1/9/2017

Type of Formal Enforcement Action: Not Reported

Date a Referred Case Settled or Dropped: Not Reported

Docket Number: Not Reported

Final Fine or Penalty Assessed: Not Reported
Supplemental Environmental Projects Value: Not Reported
Count of Linked Class I Violations: 0
Count of Linked Class II Violations: 0
Count of Linked Minor Violations: 5
Red Tag Issued: No
Red Tag Number: Not Reported
Violations Causing Red Tag: Not Reported
Date Red Tag Affixed: Not Reported
Date Red Tag Removed: Not Reported
Enforcement Comments: Not Reported

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
County-AST-CA	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
ZIPPY LUBE-A-TRUCK			1,4	FA0009125-SBD
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE B			Hesperia	92344
DETAILS				
County: San Bernardino Responsible Agency: San Bernardino Division of Environmental Health Services Facility ID: FA0009125 Address2: Not Reported Owner Information: Ren Anelle Contact Name: Not Reported Mailing Address: P.O. Box 7509, LAGUNA NIGUEL, CA 92607 Mailing Address2: Not Reported Permit ID: PT0023266 Program Element Code: 4031 Permit Description: APSA 1,320-10,000 GAL FAC CAPACITY Status: ACTIVE To: 12/31/2018				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CRSP-CA	Listed	0.06 miles S	3634 ft	5

SITE NAME	MAPS	ID
ZIPPY LUBE-A-TRUCK	1,4	172882
ADDRESS	CITY	ZIP
8899 THREE FLAGS AVE	HESPERIA	92344
DETAILS		
Site Regulated Program Information Site ID: 172882 Site EI ID: 10049617 Agency Provided Latitude: 34.413147 Agency Provided Longitude: -117.39313 Program Description: Aboveground Petroleum Storage Program Description: Chemical Storage Facilities Program Description: Hazardous Waste Generator Evaluation Information Evaluation Date: 1/9/2017 Violations Found? (Y/N): Yes Evaluation General Type: Compliance Evaluation Inspection Evaluation Type: Routine done by local agency Evaluation Note(s): ROUTINE GENERATOR INSPECTION Evaluation Division: San Bernardino County Fire Department Evaluation Program: HW Evaluation Source: CERS Evaluation Date: 1/9/2017 Violations Found? (Y/N): Yes Evaluation General Type: Compliance Evaluation Inspection Evaluation Type: Routine done by local agency Evaluation Note(s): ROUTINE APSA INSPECTION Evaluation Division: San Bernardino County Fire Department Evaluation Program: APSA Evaluation Source: CERS Evaluation Date: 1/9/2017 Violations Found? (Y/N): Yes Evaluation General Type: Compliance Evaluation Inspection Evaluation Type: Routine done by local agency Evaluation Note(s): ROUTINE HANDLER INSPECTION Evaluation Division: San Bernardino County Fire Department Evaluation Program: HMRRP Evaluation Source: CERS		

Evaluation Date: 11/14/2013
Violations Found? (Y/N): No
Evaluation General Type: Compliance Evaluation Inspection
Evaluation Type: Routine done by local agency
Evaluation Note(s): zippy lube- hesperia/ oak hills-insp
Evaluation Division: San Bernardino County Fire Department
Evaluation Program: HMRRP
Evaluation Source: CERS

Evaluation Date: 11/14/2013
Violations Found? (Y/N): No
Evaluation General Type: Compliance Evaluation Inspection
Evaluation Type: Routine done by local agency
Evaluation Note(s): zippy lube- hesperia/ oak hills-insp
Evaluation Division: San Bernardino County Fire Department
Evaluation Program: APSA
Evaluation Source: CERS

Evaluation Date: 11/14/2013
Violations Found? (Y/N): Yes
Evaluation General Type: Compliance Evaluation Inspection
Evaluation Type: Routine done by local agency
Evaluation Note(s): zippy lube- hesperia/ oak hills-insp
Evaluation Division: San Bernardino County Fire Department
Evaluation Program: HW
Evaluation Source: CERS

Violation Information

Violation Date: 1/9/2017
Citation: HSC 6.67 25270.6(a)(1), 25270.6(a)(2) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.6(a)(1), 25270.6(a)(2)
Violation Description: Failure to submit a tank facility statement on or before January 1 annually unless a current Business Plan has been submitted.

Violation Note(s): Returned to compliance on 03/30/2017. A Tank Facility Statement had not been submitted since 12/16/13.
Violation Division: San Bernardino County Fire Department
Violation Program: APSA
Violation Source: CERS

Violation Date: 1/9/2017
Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Description: Hazardous Waste Generator Program - Operations/Maintenance - General
Violation Note(s): Returned to compliance on 03/30/2017. Failure to complete hazardous waste labels (CCR 66262.34(f)(3))
Observed (1) 55 gallon drums of waste grease with an illegible hazardous waste label.
Violation Division: San Bernardino County Fire Department
Violation Program: HW
Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Operations/Maintenance - General

Violation Note(s): Returned to compliance on 03/30/2017. Failure to keep hazardous waste containers closed when not in active use (CCR 66265.173(a)) Observed (1) 15 gallon drum of used oil that was not currently in use with no lid.

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Operations/Maintenance - General

Violation Note(s): Returned to compliance on 03/30/2017. Failure to operate and maintain facility to prevent a fire, spill or release (CCR 66265.31) Failure to operate and maintain facility to prevent release/fire

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)

Violation Description: Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.

Violation Note(s): Returned to compliance on 03/30/2017.

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.67 25270.6(b) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.6(b)

Violation Description: Failure to pay the APSA Program fee.

Violation Note(s): Returned to compliance on 03/30/2017. CUPA permits expired on 12/31/16.

Violation Division: San Bernardino County Fire Department

Violation Program: APSA

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Training - General

Violation Note(s): Returned to compliance on 03/30/2017. Failure to train facility personnel in hazardous waste management procedures (CCR 66265.16) Per operator, hazardous waste management training is regularly conducted, but there was not documentation to this effect. This the site is a Large Quantity Generator (LQG), facility must provide annual hazardous waste management training.

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Administration/Documentation - General

Violation Note(s): Returned to compliance on 03/30/2017. Failure to obtain a CUPA Hazardous Waste Generator Permit (SBCC 23.0602(b)(1)) CUPA permits expired on 12/31/16.

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)

Violation Description: Failure to establish and electronically submit an adequate emergency response plan and procedures for a release or threatened release of a hazardous material.

Violation Note(s): Returned to compliance on 03/30/2017. The Emergency Response (ER) Plan contains the incorrect phone number for the Local Unified Program Agency (CUPA). The correct phone number for the Emergency Response team at the CUPA is (909) 386-8425. Update the ER Plan and resubmit on CERS.

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

Violation Source: CERS

Violation Date: 1/9/2017

Citation: Un-Specified

Violation Description: Business Plan Program - Administration/Documentation - General Local Ordinance

Violation Note(s): Returned to compliance on 03/30/2017. Failure to obtain a CUPA Hazardous Materials Handler permit (SBCC 23.0602(a)) CUPA permits expired on 12/31/16.

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Operations/Maintenance - General

Violation Note(s): Returned to compliance on 03/30/2017. Failure to label hazardous waste containers (CCR 66262.34(f)(3)) Observed (1) 55 gallon container of used oil and (1) 55 gallon drum of waste grease with no hazardous waste label.

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.

Violation Note(s): Returned to compliance on 03/30/2017. The hazardous materials inventory submitted 12/16/13 is missing (1) 275 gallon tote of Diesel Exhaust Fluid.

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.5 25250.22 - California Health and Safety Code, Chapter 6.5, Section(s) 25250.22

Violation Description: Failure to properly manage used oil and/or fuel filters in accordance with the requirements.

Violation Note(s): Returned to compliance on 03/30/2017. Observed (4) 55 gallon drums of drained used oil filters with no lid, (2) 55 gallon drained used oil filters with no labels, and (1) 55 gallon drum of drained used oil filters with a label, but no accumulation start date.

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple

Violation Description: Hazardous Waste Generator Program - Operations/Maintenance - General

Violation Note(s): Returned to compliance on 03/30/2017. Failure to note accumulation start date on labels (CCR 66262.34(f)(2)) Observed (1) 55 gallon drum of waste grease with no accumulation start date marked.

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 1/9/2017

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit a site map with all required content.

Violation Note(s): Returned to compliance on 03/30/2017. The map submitted on CERS is missing adjacent streets and north orientation. Update and resubmit on CERS.

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

Violation Source: CERS

Violation Date: 11/14/2013

Citation: HSC 6.67 Multiple - California Health and Safety Code, Chapter 6.67, Section(s) Multiple

Violation Description: Haz Waste Generator Program - Operations/Maintenance - General

Violation Note(s): Returned to compliance on 11/14/2013. Failure to label hazardous waste containers (CCR 66262.34(f)(3)) corrected on site- operator properly labeled the hazwaste drum

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 11/14/2013

Citation: HSC 6.67 Multiple - California Health and Safety Code, Chapter 6.67, Section(s) Multiple

Violation Description: Haz Waste Generator Program - Operations/Maintenance - General

Violation Note(s): Returned to compliance on 11/14/2013. Failure to note accumulation start date on labels (CCR 66262.34(f)(2)) corrected on site- operator properly labeled the hazwaste drum

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 11/14/2013

Citation: 22 CCR 16 66266.130 - California Code of Regulations, Title 22, Chapter 16, Section(s) 66266.130

Violation Description: Failure to properly handle, manage, label, and recycle used oil and fuel filters.

Violation Note(s): Returned to compliance on 11/14/2013. corrected on site- operator properly labeled marked the drained used

oil filter drum for the start date

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 11/14/2013

Citation: HSC 6.67 Multiple - California Health and Safety Code, Chapter 6.67, Section(s) Multiple

Violation Description: Haz Waste Generator Program - Operations/Maintenance - General

Violation Note(s): Returned to compliance on 11/14/2013. Failure to complete hazardous waste labels (CCR 66262.34(f)(3)) corrected on site- operator properly labeled the hazwaste drum

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Enforcement Information

Enforcement Action Date: 1/9/2017

Enforcement Action Type: Notice of Violation (Unified Program)

Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enforcement Action Note(s): Not Reported

Enforcement Action Division: San Bernardino County Fire Department

Enforcement Action Program: APSA

Enforcement Action Source: CERS

Enforcement Action Date: 1/9/2017

Enforcement Action Type: Notice of Violation (Unified Program)

Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enforcement Action Note(s): Not Reported

Enforcement Action Division: San Bernardino County Fire Department

Enforcement Action Program: HMRRP

Enforcement Action Source: CERS

Enforcement Action Date: 1/9/2017

Enforcement Action Type: Notice of Violation (Unified Program)

Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enforcement Action Note(s): Not Reported

Enforcement Action Division: San Bernardino County Fire Department

Enforcement Action Program: HW

Enforcement Action Source: CERS

Enforcement Action Date: 11/14/2013

Enforcement Action Type: Notice of Violation (Unified Program)

Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enforcement Action Note(s): Not Reported

Enforcement Action Division: San Bernardino County Fire Department

Enforcement Action Program: HW

Enforcement Action Source: CERS

Chemical Information

: Not Reported
:Coordinate Information
Program ID: 10049617
ENV INT Type Code: HMBP
Coordinate Name: Not Reported
Reference Point Type Description: Unknown
Agency Provided Latitude: 34.413139
Agency Provided Longitude: -117.393120

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CRSP-CA	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
Little Sister's Truck Wash			1,4	130941
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE			HESPERIA	92344
DETAILS				
Site Regulated Program Information Site ID: 130941 Site EI ID: 10128901 Agency Provided Latitude: 37.271881 Agency Provided Longitude: -119.27023 Program Description: Chemical Storage Facilities Program Description: Hazardous Waste Generator				
Evaluation Information Evaluation Date: 6/3/2016 Violations Found? (Y/N): No Evaluation General Type: Compliance Evaluation Inspection Evaluation Type: Routine done by local agency Evaluation Note(s): LITTLE SISTER'S TRUCK WASK- CUPA WASTE INSPECTION Evaluation Division: San Bernardino County Fire Department Evaluation Program: HW Evaluation Source: CERS Evaluation Date: 6/3/2016 Violations Found? (Y/N): Yes				

Evaluation General Type: Compliance Evaluation Inspection
Evaluation Type: Routine done by local agency
Evaluation Note(s): LITTLE SISTERS- CUPA HANDLER INSPECTION
Evaluation Division: San Bernardino County Fire Department
Evaluation Program: HMRRP
Evaluation Source: CERS

Evaluation Date: 7/23/2013

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection
Evaluation Type: Routine done by local agency
Evaluation Note(s): insp
Evaluation Division: San Bernardino County Fire Department
Evaluation Program: HW
Evaluation Source: CERS

Evaluation Date: 7/23/2013

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection
Evaluation Type: Routine done by local agency
Evaluation Note(s): insp
Evaluation Division: San Bernardino County Fire Department
Evaluation Program: HMRRP
Evaluation Source: CERS

Violation Information

Violation Date: 6/3/2016

Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Section(s) 25508.2

Violation Description: Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.

Violation Note(s): Returned to compliance on 06/06/2016. COMPLIANCE ACTIVITY: CERTIFICATE OF COMPLIANCE SIGNED 06/06/2016-- OBSERVATION: THE BUSINESS PLAN INFORMATION LISTED IN CERS, MUST BE UPDATED BY MARCH 1 OF EVERY YEAR. CERS WAS LAST UPDATED ON 11/11/2014. COMPLIANCE REQUIREMENT: UPDATED CERS INFORMATION.

Violation Division: San Bernardino County Fire Department
Violation Program: HMRRP
Violation Source: CERS

Violation Date: 7/23/2013

Citation: HSC 6.67 Multiple - California Health and Safety Code, Chapter 6.67, Section(s) Multiple

Violation Description: Haz Waste Generator Program - Administration/Documentation - General

Violation Note(s): Returned to compliance on 07/24/2013. Failure to maintain used oil disposal receipts for at least 3 years (CHSC 25160.2(b)(3))

Violation Division: San Bernardino County Fire Department
Violation Program: HW
Violation Source: CERS

Violation Date: 7/23/2013

Citation: HSC 6.95 25505(a) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)

Violation Description: Owner/Operator failed to complete and/or submit a Hazardous Materials Business Plan when storing hazardous materials at or above the thresholds quantities of 55 gallons/500 lbs/200 cubic feet.

Violation Note(s): Returned to compliance on 07/24/2013.

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

Violation Source: CERS

Enforcement Information

Enforcement Action Date: 6/3/2016

Enforcement Action Type: Notice of Violation (Unified Program)

Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enforcement Action Note(s): Not Reported

Enforcement Action Division: San Bernardino County Fire Department

Enforcement Action Program: HMRRP

Enforcement Action Source: CERS

Enforcement Action Date: 7/23/2013

Enforcement Action Type: Notice of Violation (Unified Program)

Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enforcement Action Note(s): Not Reported

Enforcement Action Division: San Bernardino County Fire Department

Enforcement Action Program: HW

Enforcement Action Source: CERS

Enforcement Action Date: 7/23/2013

Enforcement Action Type: Notice of Violation (Unified Program)

Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enforcement Action Note(s): Not Reported

Enforcement Action Division: San Bernardino County Fire Department

Enforcement Action Program: HMRRP

Enforcement Action Source: CERS

Chemical Information

: Not Reported

:Coordinate Information

Program ID: 10128901

ENV INT Type Code: HMBP

Coordinate Name: Not Reported

Reference Point Type Description: Unknown

Agency Provided Latitude: 34.413139

Agency Provided Longitude: -117.393120

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID

CUPA-CA	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
Little Sister's Truck Wash			1,4	FA0010378-SBD
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE			Hesperia	92344
DETAILS				
County: San Bernardino Responsible Agency: San Bernardino County Fire Department Facility ID: FA0010378 Address2: Not Reported Owner Information: Little Sister's Truck Wash, Inc. Contact Name: Not Reported Mailing Address: 25 Rollingview Lane, Fallbrook, CA 92028 Mailing Address 2: Not Reported Agency Provided Latitude: Not Reported Agency Provided Longitude: Not Reported Permit ID: PT0017654 Program Element Code: 4244 Permit Description: HAZARDOUS MATERIALS 11-30 CHEMICALS Status: ACTIVE To: 5/31/2019 Permit ID: PT0017973 Program Element Code: 4453 Permit Description: SMALL QUANTITY GENERATOR Status: ACTIVE To: 5/31/2019				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CUPA-CA	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
ZIPPY LUBE-A-TRUCK			1,4	FA0009125-SBD
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE B			Hesperia	92344
DETAILS				

County: San Bernardino
Responsible Agency: San Bernardino County Fire Department
Facility ID: FA0009125
Address2: Not Reported
Owner Information: Ren Anelle
Contact Name: Not Reported
Mailing Address: P.O. Box 7509, LAGUNA NIGUEL, CA 92607
Mailing Address 2: Not Reported
Agency Provided Latitude: Not Reported
Agency Provided Longitude: Not Reported
Permit ID: PT0015214
Program Element Code: 4454
Permit Description: LARGE QUANTITY GENERATOR
Status: ACTIVE
To: 12/31/2019

Permit ID: PT0015215
Program Element Code: 4243
Permit Description: HAZARDOUS MATERIALS 4-10 CHEMICALS
Status: ACTIVE
To: 12/31/2019

Permit ID: PT0023266
Program Element Code: 4031
Permit Description: APSA 1,320-10,000 GAL FAC CAPACITY
Status: ACTIVE
To: 12/31/2019

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
FRS-US	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
LITTLE SISTER'S TRUCK WASH			1,4	110066395494
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE			HESPERIA	92344

DETAILS

FRS Facility Detail Report URL:
http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110066395494
Create Date: 14-OCT-2015 11:18:47
Program System: CA-ENVIROVIEW
Interest Type(s): STATE MASTER

--

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
FRS-US	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
ZIPPY LUBE-A-TRUCK, INC.			1,4	110033211245
ADDRESS			CITY	ZIP
8899B THREE FLAGS AVENUE			HESPERIA	92345-
DETAILS				
FRS Facility Detail Report URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110033211245 Create Date: 29-FEB-2008 02:16:06 Program System: UORS Interest Type(s): STATE MASTER				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
FRS-US	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
ZIPPY LUBE-A-TRUCK			1,4	110066206484
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE			HESPERIA	92344
DETAILS				
FRS Facility Detail Report URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110066206484 Create Date: 14-OCT-2015 10:26:38 Program System: CA-ENVIROVIEW Interest Type(s): STATE MASTER				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
Hist-CA	Name Changed	0.06 miles S	3634 ft	5

SITE NAME	MAPS	ID
LITTLE SISTERS TRUCK WASH	1,4	FA0010378-SBD
ADDRESS	CITY	ZIP
8899 THREE FLAGS AVE	HESPERIA	92345
DETAILS		
Original Database: CUPA-CA Last Agency Status: Listed Archive Date: 06/04/17 Name Changed-County: San Bernardino Responsible Agency: San Bernardino County Fire Department Facility ID: FA0010378 Address2: Not Reported Owner Information: LITTLE SISTER'S TRUCK WASH Contact Name: Not Reported Mailing Address: 25 ROLLING VIEW LN, FALLBROOK, CA 92028 Mailing Address 2: Not Reported Agency Provided Latitude: Not Reported Agency Provided Longitude: Not Reported Permit ID: PT0017654 Program Element Code: 4244 Permit Description: HAZARDOUS MATERIALS 11-30 CHEMICALS Status: ACTIVE To: 5/31/2017 Permit ID: PT0017973 Program Element Code: 4453 Permit Description: SMALL QUANTITY GENERATOR Status: ACTIVE To: 5/31/2017		

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
Hist-CA	No Longer Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
IRONMAN RENEWAL DBA ZIPPY LUBE A TRUCK			1,4	CAL000344771
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE			OAK HILLS	923440497
DETAILS				

Original Database: HWIS-CA
Last Agency Status: Listed
Archive Date: 10/07/21
No Longer Listed-EPA ID: CAL000344771
Facility County: 36
Mailing Street: 2535 ANSELMO DR
Mailing City: ANSELMO
Mailing State: CA
Mailing Zip: 928798092
Contact Name: SAM MCMILLAN
Contact Phone: 9517353710

Year: 2016
TONS: 0.1
TSD EPA ID: AZD081705402
Category Code: 331
Category Description: Off-specification, aged or surplus organics
Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)

Year: 2015
TONS: 0.2
TSD EPA ID: AZD081705402
Category Code: 352
Category Description: Other organic solids
Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)

Year: 2015
TONS: 0.231
TSD EPA ID: Not Reported
Category Code: 134
Category Description: Aqueous solution with total organic residues less than 10 percent
Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)

Year: 2014
TONS: 0.22935
TSD EPA ID: CAT080013352
Category Code: 223
Category Description: Unspecified oil-containing waste
Method Description: OTHER RECOVERY OF RECLAMATION FOR REUSE INCLUDING ACID REGENERATION, ORGANICS RECOVERY ECT

Year: 2014
TONS: 0.10425
TSD EPA ID: CAD044429835
Category Code: 213
Category Description: Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR

(H131-H135)

Year: 2014

TONS: 0.375

TSD EPA ID: CAD097030993

Category Code: 352

Category Description: Other organic solids

Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)

Year: 2013

TONS: 0.52125

TSD EPA ID: CAT080013352

Category Code: 222

Category Description: Oil/water separation sludge

Method Description: OTHER RECOVERY OF RECLAMATION FOR REUSE INCLUDING ACID REGENERATION, ORGANICS RECOVERY ECT

Year: 2013

TONS: 0.4

TSD EPA ID: CAD097030993

Category Code: 352

Category Description: Other organic solids

Method Description: Not Reported

Year: 2013

TONS: 0.62935

TSD EPA ID: CAD097030993

Category Code: 491

Category Description: Unspecified sludge waste

Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)

Year: 2013

TONS: 0.265

TSD EPA ID: CAD097030993

Category Code: 352

Category Description: Other organic solids

Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)

Year: 2013

TONS: 0.2085

TSD EPA ID: CAT000613893

Category Code: 213

Category Description: Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)

Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)

Year: 2012

TONS: 0.2085

TSD EPA ID: CAT000613893

Category Code: 213

Category Description: Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)

Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)

Year: 2012

TONS: 0.22935

TSD EPA ID: CAD097030993

Category Code: 491

Category Description: Unspecified sludge waste

Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)

Year: 2012

TONS: 0.45

TSD EPA ID: CAD097030993

Category Code: 352

Category Description: Other organic solids

Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)

Year: 2010

TONS: Not Reported

TSD EPA ID: CAD097030993

Category Code: 352

Category Description: Other organic solids

Method Description: Not Reported

Year: 2010

TONS: 0.22935

TSD EPA ID: CAD097030993

Category Code: 491

Category Description: Unspecified sludge waste

Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)

Year: 2010

TONS: 0.22935

TSD EPA ID: CAD097030993

Category Code: 491

Category Description: Unspecified sludge waste

Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)

Year: 2009

TONS: 0.22935

TSD EPA ID: CAD097030993

Category Code: 491

Category Description: Unspecified sludge waste

Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
Hist-CA	No Longer Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
IRONMAN RENEWAL DBA ZIPPY LUBE A TRUCK			1,4	54FDFFFA-CAL000344771
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE			OAK HILLS	92344
DETAILS				
Previous List: HWIS-CA Archived: 4/2/2012				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
Hist-CA	No Longer Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
ANELLE MANAGEMENT SERVICES INC DBA FLEET CREW			1,4	CAL000416670
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE			HESPERIA	923440497
DETAILS				
Original Database: HWIS-CA Last Agency Status: Listed Archive Date: 10/07/21 No Longer Listed-EPA ID: CAL000416670 Facility County: 36 Mailing Street: 30025 ALICIA PKWY Mailing City: LAGUNA NIGUEL Mailing State: CA Mailing Zip: 92677 Contact Name: CRAIG PHILLIPS				

Contact Phone: 9516600400

Year: 2017

TONS: 1.665

TSD EPA ID: CAD097030993

Category Code: 352

Category Description: Other organic solids

Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)

Year: 2017

TONS: 0.22935

TSD EPA ID: CAD097030993

Category Code: 491

Category Description: Unspecified sludge waste

Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)

Year: 2017

TONS: 1.205

TSD EPA ID: AZR000515924

Category Code: 352

Category Description: Other organic solids

Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)

Year: 2016

TONS: 1.405

TSD EPA ID: AZR000515924

Category Code: 352

Category Description: Other organic solids

Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)

Year: 2016

TONS: 0.15

TSD EPA ID: NED981723513

Category Code: 213

Category Description: Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)

Method Description: INCINERATION--THERMAL DESTRUCTION OTHER THAN USE AS A FUEL

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
HWIS-CA	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
FLEETCREW			1,4	CAL000416670

ADDRESS	CITY	ZIP
8899 THREE FLAGS AVE	HESPERIA	92344
DETAILS		
Facility Information EPA ID: CAL000416670 Facility County: 36 Mailing Street: "29911 NIGUEL ROAD " Mailing City: LAGUNA NIGUEL Mailing State: CA Mailing Zip: 926070000 Contact Name: CRAIG PHILLIPS Contact Phone: Not Reported Generator Details Year: 2019 TONS: Not Reported TSD EPA ID: CAD097030993 Category Code: 352 Category Description: Other organic solids Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)		

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
RCRA-NON-US	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
LITTLE SISTERS TRUCK WASH INC			1,4	CAL000353253
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE			OAK HILLS	92344
DETAILS				
Additional details may be found online using the following link: https://enviro.epa.gov/enviro/rcrainfoquery_3.facility_information?pgm_sys_id=CAL000353253 Source Type: Implementer Generator Status: Non-Generator NAICS1: CAR WASHES Active Site Indicator: H----				

Owner Name: LITTLE SISTERS TRUCK WASH INC
Operator Name: JOE MCFANN
In Handler Universes: Y
In a Universe: Y
Universal Waste: Y
Universal Waste Destination Facility: Y

Receive Date: 20100610
Acknowledge Flag Date: 20100610
Contact First Name: JOE
Contact Last Name: MCFANN
Contact Street 1: 8899 THREE FLAGS AVE
Contact City: OAK HILLS
Contact State: CA
Contact Zip: 92344
Contact Phone: 760-947-4448
Contact FAX: 760-956-1270
Contact E-mail Address: RJA@YELLOWMAGIC.COM
Universal Waste Destination Facility: Y

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
RCRA-NON-US	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
ANELLE MANAGEMENT SERVICES INC DBA FLEET			1,4	CAL000416670
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE			HESPERIA	92344

DETAILS

Additional details may be found online using the following link:
https://enviro.epa.gov/enviro/rcrainfoquery_3.facility_information?pgm_sys_id=CAL000416670
Source Type: Implementer
Generator Status: Non-Generator
NAICS1: GENERAL AUTOMOTIVE REPAIR
Active Site Indicator: H----
Owner Name: ANELLE MGMT SRV INC DBA FLEET CREW
Operator Name: CRAIG PHILLIPS
In Handler Universes: Y
In a Universe: Y
Universal Waste: Y
Universal Waste Destination Facility: Y

Receive Date: 20160502

Acknowledge Flag Date: 20160502
Contact First Name: CRAIG
Contact Last Name: PHILLIPS
Contact Street 1: 29911 NIGUEL ROAD #7509
Contact City: LAGUNA NIGUEL
Contact State: CA
Contact Zip: 92607-0000
Contact Phone: 951-660-0400
Contact FAX: 951-848-0713
Contact E-mail Address: CRAIG.PHILLIPS@FLEETCREW.COM
Universal Waste Destination Facility: Y

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CUPA-CA	Listed	0.06 miles W	3624 ft	6
SITE NAME			MAPS	ID
DESERT DYNAMICS OFFROAD			1,4	FA0012792-SBD
ADDRESS			CITY	ZIP
12221 POPLAR ST BLDG B-10			HESPERIA	92344
DETAILS				
County: San Bernardino Responsible Agency: San Bernardino County Fire Department Facility ID: FA0012792 Address2: Not Reported Owner Information: LAWSON, DAVE Contact Name: DAVE LAWSON Mailing Address: 12221 POPLAR ST BLDG B-10, HESPERIA, CA 92344 Mailing Address 2: Not Reported Agency Provided Latitude: Not Reported Agency Provided Longitude: Not Reported Permit ID: PT0022349 Program Element Code: 4221 Permit Description: HAZMAT HANDLER 0-10 EMPLOYEES Status: INACTIVE To: 10/31/2010				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CERS-CA	Listed	0.08 miles W	3628 ft	7

SITE NAME	MAPS	ID
3M OAK HILLS	1,4	10311793
ADDRESS	CITY	ZIP
12221 POPLAR ST UNIT D20	OAK HILLS	92344
DETAILS		
General Program & Facility Information CERS ID: 10311793 Facility ID: FA0013596 Facility Regulator Key ID: FA0013596 Organization Code: 90278605 Business/Organization Name: 3M OAK HILLS Multiple Jurisdictional Business? (Y/N): No Business Origin: Seeding Count of Business CERS User Accounts: 3 Facility Count for Business: 2 Last Submittal Date (any element): 3/6/2018 12:28:21 PM Count of Submitted Elements: 21 Remote Facility? (Y/N): No Small Quantity Generator Facility? (Y/N): No Local Facility Grouping: Not Reported Facility Specific Information Assessor Parcel Number (APN): Not Reported Number of Employees: 2 Property Owner Name: Not Reported Property Owner Phone Number: Not Reported Property Owner Mailing Address: Not Reported Property Owner Mailing City: Not Reported Property Owner Mailing State: Not Reported Property Owner Mailing Zip Code: Not Reported Property Owner Mailing Country: Not Reported Inspection Information Aboveground Petroleum Storage Act (APSA) Last Inspection Date: Not Reported California Accidental Release Prevention (CalARP) Last Inspection: Not Reported Conditionally Authorized (CA) Last Inspection Date: Not Reported Conditionally Exempt (CE) Last Inspection Date: Not Reported Household Hazardous Waste Collection (HHW) Last Inspection Date: Not Reported Hazardous Materials Release Response Plan (HMRRP) Last Inspection: 9/29/2016 Hazardous Waste Generator (HW) Last Inspection Date: Not Reported RCRA Large Quantity Generator (HWLQG) Last Inspection Date: Not Reported Hazardous Waste Recycler (HWRrecycler) Last Inspection Date: Not Reported Permit By Rule (PBR) Last Inspection: Not Reported		

Underground Storage Tank (UST) Last Inspection Date: Not Reported

Owner/Operator Information

Beginning Date: Not Reported

Ending Date: Not Reported

Phone Number: (760) 949-4204

Fax Number: (760) 949-0912

Supplemental Location: Not Reported

County: San Bernardino

Dun & Bradstreet D-U-N-S Number: Not Reported

SIC Code: 3291

NAICS Code: Not Reported

Mailing Address: 8981 US HWY 395

Mailing Address City: OAK HILLS

Mailing Address State Code: CA

Mailing Address Zip Code: 92344

Operator Name: 3M Oak Hills

Operator Phone Number: (760) 949-4204

Owner Name: 3M COMPANY

Owner Phone: (760) 949-4204

Owner Mailing Address: 8981 HWY 395

Owner City: OAK HILLS

Owner State: CA

Owner Zip Code: 92344

Owner Country: United States

Environmental Contact Name: JESSE CAIN

Environmental Contact Phone Number: 760-983-9085

Environmental Contact Mailing Address: 13044 Rocky Trail Way

Environmental Contact Email Address: JCAIN@MMM.COM

Environmental Contact City: Victorville

Environmental Contact State: CA

Environmental Contact Zip: 92395

Environmental Contact Country: United States

Primary Emergency Contact Name: DAN BRAUN

Primary Emergency Contact Title: PLANT MANAGER

Primary Emergency Contact Business Phone Number: (760) 949-4204 2001

Primary Emergency Contact 24Hr Phone: (760) 881-9772

Primary Emergency Contact Pager Number: Not Reported

Secondary Emergency Contact Name: SAL BRIONES / ISMAEL MARTINEZ

Secondary Emergency Contact Title: DAY/ NIGHT SUPERVISOR

Secondary Emergency Contact Business Phone: (760) 949-4204 2043

Secondary Emergency Contact 24Hr Phone: (760) 662-0808

Secondary Emergency Contact Pager Number: (760) 983-0380

Additional Local Collected Info: Not Reported

Identification Signed Date: Not Reported

Document Preparer Name: JESSE CAIN

Identification Signer Name: Daniel Braun

Identification Signer Title: Plant Manager

Billing Contact Name: 3M COMPANY

Billing Contact Phone: (760) 949-4204
Billing Contact Email: Not Reported
Billing Address: 8981 US HWY 395
Billing City: OAK HILLS
Billing State: CA
Billing Zip: 92344
Billing Country: United States
Business Owner/Operator Regulator Key: Not Reported

Business Activity Information

EPA ID: Not Reported
Hazardous Materials On Site? (Y/N): Y
CAL ARP Regulated Substances? (Y/N): N
Own or Operator USTs? (Y/N): N
Own or Operator APSTs? (Y/N): N
Hazardous Waste Generator? (Y/N): N
Recycles Materials? (Y/N): N
On-site HW Treatment? (Y/N): N
Financial Assurance? (Y/N): N
Remote Waste Consolidation Site? (Y/N): N
Hazardous Waste Tank Closure? (Y/N): N
RCRA Large Quantity Generator? (Y/N): N
Household Hazardous Waste (HHW) Collection? (Y/N): N
Business Activity Comment(s): Not Reported

Submittal Information

Submitted Date/Time: 3/6/2018 12:28:21 PM
Submittal Action: Accepted
BP Activities Last Updated Date: 3/6/2018 12:28:15 PM
BP Owner/Operator Last Updated Date: 3/6/2018 12:28:16 PM
Submittal Action Comment 1: ACCEPTED AS COMPLETE PENDING FIELD VERIFICATION: Thank you for the submittal. While this submittal is being accepted as complete, the data has not been field verified and may require correction in the future. Please note, it is your responsibility to review and certify the information submitted in CERS annually. You must also update the information within 30 days of a change of owner, business address, business name, emergency contact information, inventory and/or other site conditions that could impact emergency response activity. If you have questions about using CERS, please contact the San Bernardino County Fire CERS Help Desk at (909) 386-8432. (Reviewed by Nancy Schlotthauer, nschlotthauer@sbcfire.org or (909) 386-8401)
Submittal Action Comment 2: Not Reported
Facility Info Next Due Date: Not Reported
Biz Activities Regulator Key: Not Reported

Supplemental Geographic Information

Agency Provided Latitude: 34.41542
Agency Provided Longitude: -117.39626
Horizontal Accuracy: 50
Horizontal Collection Method: Address Matching
Geographic Reference Point: Facility Center/Centroid

Horizontal Reference Datum: WGS84 (World Geodetic System of 1984)

Data Collection Date: 5/17/2015 11:58:10 PM

Submittal Element Regulator Information

CUPA Regulator Code: 3600

Facility Info Reporting Requirement: Applicable

Facility Info Next Due Date: Not Reported

Facility Info Last Submitted Date: 3/6/2018 12:28:21 PM

Facility Info Accepted Date: 4/20/2018 8:32:19 AM

Inventory Regulator Code: 3600

Inventory Reporting Requirement: Applicable

Inventory Next Due Date: Not Reported

Inventory Last Submitted Date: 3/6/2018 12:28:21 PM

Inventory Last Accepted Date: 4/20/2018 8:32:32 AM

ER Training Regulator Code: 3600

ER Training Reporting Requirement: Applicable

ER Training Next Due Date: Not Reported

ER Training Last Submitted Date: 3/6/2018 12:28:21 PM

ER Training Last Accepted Date: 4/20/2018 8:32:28 AM

UST Regulator Code: 3600

UST Reporting Requirement: Not Applicable

UST Next Due Date: Not Reported

UST Last Submitted Date: Not Reported

UST Last Accepted Date: Not Reported

HW Treat Regulator Code: 3600

HW Treat Reporting Requirement: Not Applicable

HW Treat Next Due Date: Not Reported

HW Treat Last Submitted Date: Not Reported

HW Treat Last Accepted Date: Not Reported

RMR Regulator Code: 3600

RMR Reporting Requirement: Not Applicable

RMR Next Due Date: Not Reported

RMR Last Submitted Date: Not Reported

RMR Last Accepted Date: Not Reported

Consolidation Regulator Code: 3600

Consolidation Reporting Requirement: Not Applicable

Consolidation Next Due Date: Not Reported

Consolidation Last Submitted Date: Not Reported

Consolidation Last Accepted Date: Not Reported

Tank Closure Regulator Code: 3600

Tank Closure Reporting Requirement: Not Applicable

Tank Closure Next Due Date: Not Reported

Tank Closure Last Submitted Date: Not Reported

Tank Closure Last Accepted Date: Not Reported

APSA Regulator Code: 3600

APSA Reporting Requirement: Not Applicable

APSA Next Due Date: Not Reported

APSA Last Submitted Date: Not Reported

APSA Last Accepted Date: Not Reported

CalARP Regulator Code: 3600
CalARP Reporting Requirement: Not Applicable
CalARP Next Due Date: Not Reported
CalARP Last Submitted Date: Not Reported
CalARP Last Accepted Date: Not Reported

UST Facility and Program Information

: Not Reported

Tank & Monitoring Plan Information

: Not Reported

HMRRP & UST Violation Information

EPA ID: Not Reported

RCRA LQG: No

Violation Date: 9/29/2016

Violation Type Number: 1010006

Class: Class 2

Scheduled Return to Compliance Date: 10/29/2016

Actual Return to Compliance Date: 10/19/2016

Actual Return to Compliance Qualifier: Documented

Violation Comment: Update submitted chemical inventory, facility site map, and emergency response plan.

Violation Category: Administration/Documentation

Violation Name: Business plan updates

Violation Description: Failure to electronically update business plan within 30 days of any one of the following events: A 100 percent or more increase in the quantity of a previously disclosed material. Any handling of a previously undisclosed hazardous materials at or above reportable quantities. A change of business address, business ownership, or business name. A substantial change in the handler's operations that requires modification to any portion of the business plan.

Violation Citation(s): HSC 6.95 25508.1(a)-(f)

HMRRP & UST Inspection Information

EPA ID: Not Reported

RCRA LQG: No

Inspection Date: 9/29/2016

Inspection Type: Routine

Number of Class I Violations: 0

Number of Class II Violations: 1

Number of Minor Violations: 0

Significant Operational Compliance: With both Release Detection and Release Prevention

Date Returned to Compliance: 10/19/2016

Days Out of Compliance: 20

Violation Details Available: Yes

Inspection Comments: HANDLER INSPECTION

HMRRP & UST Enforcement Information

Type of Enforcement Action: Notice of Violation (NOV) Only

Date of Enforcement Action: 9/29/2016

Type of Formal Enforcement Action: Not Reported

Date a Referred Case Settled or Dropped: Not Reported

Docket Number: Not Reported

Final Fine or Penalty Assessed: Not Reported

Supplemental Environmental Projects Value: Not Reported

Count of Linked Class I Violations: 0

Count of Linked Class II Violations: 1

Count of Linked Minor Violations: 0

Red Tag Issued: No

Red Tag Number: Not Reported

Violations Causing Red Tag: Not Reported

Date Red Tag Affixed: Not Reported

Date Red Tag Removed: Not Reported

Enforcement Comments: Not Reported

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CRSP-CA	Listed	0.08 miles W	3628 ft	7
SITE NAME			MAPS	ID
3M OAK HILLS			1,4	617
ADDRESS			CITY	ZIP
12221 POPLAR ST UNIT D20			OAK HILLS	92344
DETAILS				
Site Regulated Program Information Site ID: 617 Site EI ID: 10311793 Agency Provided Latitude: 34.41542 Agency Provided Longitude: -117.39626 Program Description: Chemical Storage Facilities Evaluation Information Evaluation Date: 9/29/2016 Violations Found? (Y/N): Yes Evaluation General Type: Compliance Evaluation Inspection Evaluation Type: Routine done by local agency Evaluation Note(s): HANDLER INSPECTION Evaluation Division: San Bernardino County Fire Department Evaluation Program: HMRRP Evaluation Source: CERS				

Violation Information

Violation Date: 9/29/2016

Citation: HSC 6.95 25508.1(a)-(f) - California Health and Safety Code, Chapter 6.95, Section(s) 25508.1(a)-(f)

Violation Description: Failure to electronically update business plan within 30 days of any one of the following events:

A 100 percent or more increase in the quantity of a previously disclosed material.

Any handling of a previously undisclosed hazardous materials at or above reportable quantities.

A change of business address, business ownership, or business name.

A substantial change in the handler's operations that requires modification to any portion of the business plan.

Violation Note(s): Returned to compliance on 10/19/2016. Update submitted chemical inventory, facility site map, and emergency response plan.

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

Violation Source: CERS

Enforcement Information

Enforcement Action Date: 9/29/2016

Enforcement Action Type: Notice of Violation (Unified Program)

Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enforcement Action Note(s): Not Reported

Enforcement Action Division: San Bernardino County Fire Department

Enforcement Action Program: HMRRP

Enforcement Action Source: CERS

Chemical Information

: Not Reported

:Coordinate Information

: Not Reported

:

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CUPA-CA	Listed	0.08 miles W	3628 ft	7
SITE NAME			MAPS	ID
3M OAK HILLS			1,4	FA0013596-SBD
ADDRESS			CITY	ZIP
12221 POPLAR ST UNIT D20			OAK HILLS	92344
DETAILS				
County: San Bernardino				
Responsible Agency: San Bernardino County Fire Department				
Facility ID: FA0013596				

Address2: Not Reported
Owner Information: 3M COMPANY
Contact Name: Not Reported
Mailing Address: 8981 US HWY 395, OAK HILLS, CA 92344
Mailing Address 2: Not Reported
Agency Provided Latitude: Not Reported
Agency Provided Longitude: Not Reported
Permit ID: PT0023866
Program Element Code: 4244
Permit Description: HAZARDOUS MATERIALS 11-30 CHEMICALS
Status: ACTIVE
To: 11/30/2019

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CUPA-CA	Listed	0.11 miles SW	3642 ft	8
SITE NAME			MAPS	ID
High Desert Truck and Trailer			1,4	FA0016142-SBD
ADDRESS			CITY	ZIP
8895 THREE FLAGS AVE			Hesperia	92345
DETAILS				

County: San Bernardino
Responsible Agency: San Bernardino County Fire Department
Facility ID: FA0016142
Address2: Not Reported
Owner Information: Brad Fauvre & Conan Barker
Contact Name: Not Reported
Mailing Address: 8995 Three Flags Ave., Hesperia, CA 92345
Mailing Address 2: Not Reported
Agency Provided Latitude: Not Reported
Agency Provided Longitude: Not Reported
Permit ID: PT0034884
Program Element Code: 4453
Permit Description: SMALL QUANTITY GENERATOR
Status: ACTIVE
To: 8/31/2019

Permit ID: PT0034885
Program Element Code: 4243
Permit Description: HAZARDOUS MATERIALS 4-10 CHEMICALS
Status: ACTIVE
To: 8/31/2019

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CERS-CA	Listed	0.11 miles S	3641 ft	9
SITE NAME			MAPS	ID
DIRECTV			1,4	10312237
ADDRESS			CITY	ZIP
12269 SCARBROUGH CT			HESPERIA	92345

DETAILS

General Program & Facility Information

CERS ID: 10312237
Facility ID: FA0013884
Facility Regulator Key ID: FA0013884
Organization Code: 90430663
Business/Organization Name: DIRECTV, LLC
Multiple Jurisdictional Business? (Y/N): Yes
Business Origin: Business
Count of Business CERS User Accounts: 41
Facility Count for Business: 37
Last Submittal Date (any element): Not Reported
Count of Submitted Elements: 0
Remote Facility? (Y/N): No
Small Quantity Generator Facility? (Y/N): No
Local Facility Grouping: Not Reported

Facility Specific Information

Assessor Parcel Number (APN): Not Reported
Number of Employees: 110
Property Owner Name: Not Reported
Property Owner Phone Number: Not Reported
Property Owner Mailing Address: Not Reported
Property Owner Mailing City: Not Reported
Property Owner Mailing State: Not Reported
Property Owner Mailing Zip Code: Not Reported
Property Owner Mailing Country: Not Reported

Inspection Information

Aboveground Petroleum Storage Act (APSA) Last Inspection Date: Not Reported
California Accidental Release Prevention (CalARP) Last Inspection: Not Reported
Conditionally Authorized (CA) Last Inspection Date: Not Reported

Conditionally Exempt (CE) Last Inspection Date: Not Reported
Household Hazardous Waste Collection (HHW) Last Inspection Date: Not Reported
Hazardous Materials Release Response Plan (HMRRP) Last Inspection: 8/4/2015
Hazardous Waste Generator (HW) Last Inspection Date: Not Reported
RCRA Large Quantity Generator (HWLQG) Last Inspection Date: Not Reported
Hazardous Waste Recycler (HWR) Last Inspection Date: Not Reported
Permit By Rule (PBR) Last Inspection: Not Reported
Underground Storage Tank (UST) Last Inspection Date: Not Reported

Owner/Operator Information

Beginning Date: Not Reported
Ending Date: Not Reported
Phone Number: (760) 561-1567
Fax Number: Not Reported
Supplemental Location: Not Reported
County: San Bernardino
Dun & Bradstreet D-U-N-S Number: Not Reported
SIC Code: 0
NAICS Code: Not Reported
Mailing Address: 12269 SCARBROUGH CT
Mailing Address City: HESPERIA
Mailing Address State Code: CA
Mailing Address Zip Code: 92345
Operator Name: Not Reported
Operator Phone Number: Not Reported
Owner Name: DIRECTV
Owner Phone: (760) 561-1567
Owner Mailing Address: 12269 SCARBROUGH CT
Owner City: HESPERIA
Owner State: CA
Owner Zip Code: 92345
Owner Country: United States
Environmental Contact Name: Not Reported
Environmental Contact Phone Number: Not Reported
Environmental Contact Mailing Address: Not Reported
Environmental Contact Email Address: Not Reported
Environmental Contact City: Not Reported
Environmental Contact State: Not Reported
Environmental Contact Zip: Not Reported
Environmental Contact Country: United States
Primary Emergency Contact Name: Not Reported
Primary Emergency Contact Title: Not Reported
Primary Emergency Contact Business Phone Number: Not Reported
Primary Emergency Contact 24Hr Phone: Not Reported
Primary Emergency Contact Pager Number: Not Reported
Secondary Emergency Contact Name: Not Reported
Secondary Emergency Contact Title: Not Reported
Secondary Emergency Contact Business Phone: Not Reported
Secondary Emergency Contact 24Hr Phone: Not Reported

Secondary Emergency Contact Pager Number: Not Reported

Additional Local Collected Info: Not Reported

Identification Signed Date: Not Reported

Document Preparer Name: Not Reported

Identification Signer Name: Not Reported

Identification Signer Title: Not Reported

Billing Contact Name: FACILITIES

Billing Contact Phone: (760) 561-1567

Billing Contact Email: Not Reported

Billing Address: 12269 SCARBROUGH CT

Billing City: HESPERIA

Billing State: CA

Billing Zip: 92345

Billing Country: United States

Business Owner/Operator Regulator Key: OW0011374

Business Activity Information

EPA ID: Not Reported

Hazardous Materials On Site? (Y/N): Y

CAL ARP Regulated Substances? (Y/N): Not Reported

Own or Operator USTs? (Y/N): N

Own or Operator APSTs? (Y/N): Not Reported

Hazardous Waste Generator? (Y/N): Not Reported

Recycles Materials? (Y/N): Not Reported

On-site HW Treatment? (Y/N): Not Reported

Financial Assurance? (Y/N): Not Reported

Remote Waste Consolidation Site? (Y/N): Not Reported

Hazardous Waste Tank Closure? (Y/N): Not Reported

RCRA Large Quantity Generator? (Y/N): Not Reported

Household Hazardous Waste (HHW) Collection? (Y/N): Not Reported

Business Activity Comment(s): Not Reported

Submittal Information

Submitted Date/Time: Not Reported

Submittal Action: Draft

BP Activities Last Updated Date: 11/27/2012 6:47:55 PM

BP Owner/Operator Last Updated Date: 11/27/2012 6:47:56 PM

Submittal Action Comment 1: Not Reported

Submittal Action Comment 2: Not Reported

Facility Info Next Due Date: Not Reported

Biz Activities Regulator Key: AD0013554

Supplemental Geographic Information

Agency Provided Latitude: 34.41257

Agency Provided Longitude: -117.39551

Horizontal Accuracy: 50

Horizontal Collection Method: Address Matching

Geographic Reference Point: Facility Center/Centroid
Horizontal Reference Datum: WGS84 (World Geodetic System of 1984)
Data Collection Date: 5/17/2015 11:58:31 PM

Submittal Element Regulator Information

CUPA Regulator Code: 3600

Facility Info Reporting Requirement: Not Applicable

Facility Info Next Due Date: Not Reported

Facility Info Last Submitted Date: Not Reported

Facility Info Accepted Date: Not Reported

Inventory Regulator Code: 3600

Inventory Reporting Requirement: Not Applicable

Inventory Next Due Date: Not Reported

Inventory Last Submitted Date: Not Reported

Inventory Last Accepted Date: Not Reported

ER Training Regulator Code: 3600

ER Training Reporting Requirement: Not Applicable

ER Training Next Due Date: Not Reported

ER Training Last Submitted Date: Not Reported

ER Training Last Accepted Date: Not Reported

UST Regulator Code: 3600

UST Reporting Requirement: Not Applicable

UST Next Due Date: Not Reported

UST Last Submitted Date: Not Reported

UST Last Accepted Date: Not Reported

HW Treat Regulator Code: 3600

HW Treat Reporting Requirement: Not Applicable

HW Treat Next Due Date: Not Reported

HW Treat Last Submitted Date: Not Reported

HW Treat Last Accepted Date: Not Reported

RMR Regulator Code: 3600

RMR Reporting Requirement: Not Applicable

RMR Next Due Date: Not Reported

RMR Last Submitted Date: Not Reported

RMR Last Accepted Date: Not Reported

Consolidation Regulator Code: 3600

Consolidation Reporting Requirement: Not Applicable

Consolidation Next Due Date: Not Reported

Consolidation Last Submitted Date: Not Reported

Consolidation Last Accepted Date: Not Reported

Tank Closure Regulator Code: 3600

Tank Closure Reporting Requirement: Not Applicable

Tank Closure Next Due Date: Not Reported

Tank Closure Last Submitted Date: Not Reported

Tank Closure Last Accepted Date: Not Reported

APSA Regulator Code: 3600

APSA Reporting Requirement: Not Applicable

APSA Next Due Date: Not Reported

APSA Last Submitted Date: Not Reported

APSA Last Accepted Date: Not Reported
CalARP Regulator Code: 3600
CalARP Reporting Requirement: Not Applicable
CalARP Next Due Date: Not Reported
CalARP Last Submitted Date: Not Reported
CalARP Last Accepted Date: Not Reported

UST Facility and Program Information

: Not Reported

Tank & Monitoring Plan Information

: Not Reported

HMRRP & UST Violation Information

EPA ID: Not Reported

RCRA LQG: No

Violation Date: 11/8/2013

Violation Type Number: 1010

Class: Minor

Scheduled Return to Compliance Date: 12/8/2013

Actual Return to Compliance Date: 8/4/2015

Actual Return to Compliance Qualifier: Not Resolvable

Violation Comment: Failure to obtain a CUPA Hazardous Materials Handler permit (SBCC 23.0602(a))

Violation Category: Administration/Documentation

Violation Name: General

Violation Description: Business Plan Program - Administration/Documentation - General

Violation Citation(s): 19 CCR 4 Multiple; HSC 6.95 Multiple

Violation Date: 11/8/2013

Violation Type Number: 1010002

Class: Minor

Scheduled Return to Compliance Date: 12/8/2013

Actual Return to Compliance Date: 8/4/2015

Actual Return to Compliance Qualifier: Not Resolvable

Violation Comment: Not Reported

Violation Category: Administration/Documentation

Violation Name: Hazardous Materials Business Plan Submittal

Violation Description: Owner/Operator failed to complete and/or submit a Hazardous Materials Business Plan when storing hazardous materials at or above the thresholds quantities of 55 gallons/500 lbs/200 cubic feet.

Violation Citation(s): 19 CCR 4 2729.2(a); HSC 6.95 25505(a)

HMRRP & UST Inspection Information

EPA ID: Not Reported

RCRA LQG: No

Inspection Date: 8/4/2015

Inspection Type: Other

Number of Class I Violations: 0

Number of Class II Violations: 0

Number of Minor Violations: 0

Significant Operational Compliance: Not Reported

Date Returned to Compliance: Not Reported
Days Out of Compliance: 1232
Violation Details Available: No
Inspection Comments: INSPECTION - CLOSURE

Inspection Date: 11/8/2013
Inspection Type: Routine
Number of Class I Violations: 0
Number of Class II Violations: 0
Number of Minor Violations: 2
Significant Operational Compliance: With both Release Detection and Release Prevention
Date Returned to Compliance: 8/4/2015
Days Out of Compliance: 634
Violation Details Available: Yes
Inspection Comments: inspection report

HMRRP & UST Enforcement Information
Type of Enforcement Action: Notice of Violation (NOV) Only
Date of Enforcement Action: 11/8/2013
Type of Formal Enforcement Action: Not Reported
Date a Referred Case Settled or Dropped: Not Reported
Docket Number: Not Reported
Final Fine or Penalty Assessed: Not Reported
Supplemental Environmental Projects Value: Not Reported
Count of Linked Class I Violations: 0
Count of Linked Class II Violations: 0
Count of Linked Minor Violations: 2
Red Tag Issued: No
Red Tag Number: Not Reported
Violations Causing Red Tag: Not Reported
Date Red Tag Affixed: Not Reported
Date Red Tag Removed: Not Reported
Enforcement Comments: Not Reported

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CUPA-CA	Listed	0.11 miles S	3641 ft	9
SITE NAME			MAPS	ID
CDM CONSTRUCTORS INC.			1,4	FA0008728-SBD
ADDRESS			CITY	ZIP
12269 SCARBROUGH CT			HESPERIA	92345

DETAILS
County: San Bernardino Responsible Agency: San Bernardino County Fire Department Facility ID: FA0008728 Address2: Not Reported Owner Information: CDM CONSTRUCTORS INC. Contact Name: JOYCE JACKSON Mailing Address: 12269 SCARBROUGH COURT, HESPERIA, CA 92345-0000 Mailing Address 2: Not Reported Agency Provided Latitude: Not Reported Agency Provided Longitude: Not Reported Permit ID: PT0015514 Program Element Code: 4221 Permit Description: HAZMAT HANDLER 0-10 EMPLOYEES Status: INACTIVE To: 12/31/2006 Permit ID: PT0015515 Program Element Code: 4202 Permit Description: HAZMAT HANDLER 0-10 EMPLOYEES (W/GEN PRMT) Status: INACTIVE To: 12/31/2004

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CUPA-CA	Listed	0.11 miles S	3641 ft	9
SITE NAME			MAPS	ID
DIRECTV			1,4	FA0013884-SBD
ADDRESS			CITY	ZIP
12269 SCARBROUGH CT			HESPERIA	92345
DETAILS				
County: San Bernardino Responsible Agency: San Bernardino County Fire Department Facility ID: FA0013884 Address2: Not Reported Owner Information: DIRECTV Contact Name: Not Reported Mailing Address: 12269 SCARBROUGH CT, HESPERIA, CA 92344 Mailing Address 2: Not Reported Agency Provided Latitude: Not Reported Agency Provided Longitude: Not Reported				

Permit ID: PT0024398
Program Element Code: 4241
Permit Description: HAZARDOUS MATERIALS 1-3 CHEMICALS SPECIAL
Status: INACTIVE
To: 9/30/2012

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CUPA-CA	Listed	0.11 miles S	3641 ft	9
SITE NAME			MAPS	ID
3M OAK HILLS REMOTE STORAGE			1,4	FA0012098-SBD
ADDRESS			CITY	ZIP
12269 SCARBROUGH CT			HESPERIA	92344
DETAILS				
County: San Bernardino Responsible Agency: San Bernardino County Fire Department Facility ID: FA0012098 Address2: Not Reported Owner Information: 3M COMPANY Contact Name: 3M OAK HILLS Mailing Address: 8981 US HWY 395, HESPERIA, CA 92344 Mailing Address 2: Not Reported Agency Provided Latitude: Not Reported Agency Provided Longitude: Not Reported Permit ID: PT0021294 Program Element Code: 4250 Permit Description: HAZMAT HANDLER - UNSTAFFED REMOTE FACILITY Status: INACTIVE To: 3/31/2011				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CERS-CA	Listed	0.12 miles SW	3643 ft	10
SITE NAME			MAPS	ID
RV Supply Center, Inc			1,4	10609933
ADDRESS			CITY	ZIP

8893 Three Flags Ave Ste B

Oak Hills

92344

DETAILS

General Program & Facility Information

CERS ID: 10609933

Facility ID: FA0016222

Facility Regulator Key ID: FA0016222

Organization Code: 90574786

Business/Organization Name: RV Supply Center, Inc

Multiple Jurisdictional Business? (Y/N): No

Business Origin: Business

Count of Business CERS User Accounts: 4

Facility Count for Business: 1

Last Submittal Date (any element): 4/16/2018 4:27:39 PM

Count of Submitted Elements: 20

Remote Facility? (Y/N): No

Small Quantity Generator Facility? (Y/N): No

Local Facility Grouping: Not Reported

Facility Specific Information

Assessor Parcel Number (APN): Not Reported

Number of Employees: Not Reported

Property Owner Name: 760-949-1222

Property Owner Phone Number: 760-949-1222

Property Owner Mailing Address: 8893 Three Flags Ave Ste B

Property Owner Mailing City: Oak Hills

Property Owner Mailing State: CA

Property Owner Mailing Zip Code: 92344

Property Owner Mailing Country: United States

Inspection Information

Aboveground Petroleum Storage Act (APSA) Last Inspection Date: Not Reported

California Accidental Release Prevention (CalARP) Last Inspection: Not Reported

Conditionally Authorized (CA) Last Inspection Date: Not Reported

Conditionally Exempt (CE) Last Inspection Date: Not Reported

Household Hazardous Waste Collection (HHW) Last Inspection Date: Not Reported

Hazardous Materials Release Response Plan (HMRRP) Last Inspection: 4/4/2018

Hazardous Waste Generator (HW) Last Inspection Date: 4/4/2018

RCRA Large Quantity Generator (HWLQG) Last Inspection Date: Not Reported

Hazardous Waste Recycler (HWRrecycler) Last Inspection Date: Not Reported

Permit By Rule (PBR) Last Inspection: Not Reported

Underground Storage Tank (UST) Last Inspection Date: Not Reported

Owner/Operator Information

Beginning Date: Not Reported

Ending Date: Not Reported

Phone Number: 760-949-1222
Fax Number: Not Reported
Supplemental Location: Not Reported
County: San Bernardino
Dun & Bradstreet D-U-N-S Number: Not Reported
SIC Code: Not Reported
NAICS Code: Not Reported
Mailing Address: 8893 Three Flags Ave Ste B
Mailing Address City: Oak Hills
Mailing Address State Code: CA
Mailing Address Zip Code: 92344
Operator Name: Mark Boesch
Operator Phone Number: 760-949-1222
Owner Name: Mark Boesch
Owner Phone: 760-949-1222
Owner Mailing Address: 8893 Three Flags Ave Ste B
Owner City: Oak Hills
Owner State: CA
Owner Zip Code: 92344
Owner Country: United States
Environmental Contact Name: Mark Boesch
Environmental Contact Phone Number: 760-949-1222
Environmental Contact Mailing Address: 8893 Three Flags Ave Ste B
Environmental Contact Email Address: mark@rvscinc.com
Environmental Contact City: Oak Hills
Environmental Contact State: CA
Environmental Contact Zip: 92344
Environmental Contact Country: United States
Primary Emergency Contact Name: Mark Boesch
Primary Emergency Contact Title: Owner
Primary Emergency Contact Business Phone Number: 760-949-1222
Primary Emergency Contact 24Hr Phone: 760-524-8036
Primary Emergency Contact Pager Number: Not Reported
Secondary Emergency Contact Name: Nathaniel Mark Boesch
Secondary Emergency Contact Title: Assistant manager
Secondary Emergency Contact Business Phone: 760-949-1222
Secondary Emergency Contact 24Hr Phone: 760-954-2888
Secondary Emergency Contact Pager Number: Not Reported
Additional Local Collected Info: Not Reported
Identification Signed Date: Not Reported
Document Preparer Name: Mikhail Levinson
Identification Signer Name: Mikhail Levinson
Identification Signer Title: KPA Consultant
Billing Contact Name: Mark Boesch
Billing Contact Phone: 760-949-1222
Billing Contact Email: mark@rvscinc.com
Billing Address: 8893 Three Flags Ave Ste B
Billing City: Oak Hills
Billing State: CA
Billing Zip: 92344

Billing Country: United States

Business Owner/Operator Regulator Key: Not Reported

Business Activity Information

EPA ID: CAL000307361

Hazardous Materials On Site? (Y/N): Y

CAL ARP Regulated Substances? (Y/N): N

Own or Operator USTs? (Y/N): N

Own or Operator APSTs? (Y/N): N

Hazardous Waste Generator? (Y/N): Y

Recycles Materials? (Y/N): N

On-site HW Treatment? (Y/N): N

Financial Assurance? (Y/N): N

Remote Waste Consolidation Site? (Y/N): N

Hazardous Waste Tank Closure? (Y/N): N

RCRA Large Quantity Generator? (Y/N): N

Household Hazardous Waste (HHW) Collection? (Y/N): N

Business Activity Comment(s): Not Reported

Submittal Information

Submitted Date/Time: 8/31/2017 9:39:04 AM

Submittal Action: Accepted

BP Activities Last Updated Date: 8/31/2017 9:38:58 AM

BP Owner/Operator Last Updated Date: 8/31/2017 9:38:58 AM

Submittal Action Comment 1: ACCEPTED AS COMPLETE PENDING FIELD VERIFICATION: Thank you for the submittal.

While this submittal is being accepted as complete, the data has not been field verified and may require correction in the future. Please note, it is your responsibility to review and certify the information submitted in CERS annually. You must also update the information within 30 days of a change of owner, business address, business name, emergency contact information, inventory and/or other site conditions that could impact emergency response activity. If you have questions about using CERS, please contact the San Bernardino County Fire CERS Help Desk at (909) 386-8432. (Reviewed by Rudy Valencia, rvalencia@sbcfire.org or (909) 386-8401)

Submittal Action Comment 2: Not Reported

Facility Info Next Due Date: Not Reported

Biz Activities Regulator Key: Not Reported

Supplemental Geographic Information

Agency Provided Latitude: 34.36946

Agency Provided Longitude: -117.42963

Horizontal Accuracy: 10

Horizontal Collection Method: Address Matching

Geographic Reference Point: Facility Center/Centroid

Horizontal Reference Datum: WGS84 (World Geodetic System of 1984)

Data Collection Date: 12/12/2014 2:56:39 PM

Submittal Element Regulator Information

CUPA Regulator Code: 3600

Facility Info Reporting Requirement: Applicable
Facility Info Next Due Date: Not Reported
Facility Info Last Submitted Date: 4/16/2018 4:27:39 PM
Facility Info Accepted Date: 10/3/2017 12:37:12 PM
Inventory Regulator Code: 3600
Inventory Reporting Requirement: Applicable
Inventory Next Due Date: Not Reported
Inventory Last Submitted Date: 4/16/2018 4:27:39 PM
Inventory Last Accepted Date: 10/3/2017 12:37:16 PM
ER Training Regulator Code: 3600
ER Training Reporting Requirement: Applicable
ER Training Next Due Date: Not Reported
ER Training Last Submitted Date: 4/16/2018 4:27:39 PM
ER Training Last Accepted Date: 8/23/2017 3:26:35 PM
UST Regulator Code: 3600
UST Reporting Requirement: Not Applicable
UST Next Due Date: Not Reported
UST Last Submitted Date: Not Reported
UST Last Accepted Date: Not Reported
HW Treat Regulator Code: 3600
HW Treat Reporting Requirement: Not Applicable
HW Treat Next Due Date: Not Reported
HW Treat Last Submitted Date: Not Reported
HW Treat Last Accepted Date: Not Reported
RMR Regulator Code: 3600
RMR Reporting Requirement: Not Applicable
RMR Next Due Date: Not Reported
RMR Last Submitted Date: Not Reported
RMR Last Accepted Date: Not Reported
Consolidation Regulator Code: 3600
Consolidation Reporting Requirement: Not Applicable
Consolidation Next Due Date: Not Reported
Consolidation Last Submitted Date: Not Reported
Consolidation Last Accepted Date: Not Reported
Tank Closure Regulator Code: 3600
Tank Closure Reporting Requirement: Not Applicable
Tank Closure Next Due Date: Not Reported
Tank Closure Last Submitted Date: Not Reported
Tank Closure Last Accepted Date: Not Reported
APSA Regulator Code: 3600
APSA Reporting Requirement: Not Applicable
APSA Next Due Date: Not Reported
APSA Last Submitted Date: Not Reported
APSA Last Accepted Date: Not Reported
CalARP Regulator Code: 3600
CalARP Reporting Requirement: Not Applicable
CalARP Next Due Date: Not Reported
CalARP Last Submitted Date: Not Reported
CalARP Last Accepted Date: Not Reported

UST Facility and Program Information

: Not Reported

Tank & Monitoring Plan Information

: Not Reported

HMRRP & UST Violation Information

EPA ID: CAL000307361

RCRA LQG: No

Violation Date: 4/4/2018

Violation Type Number: 1010006

Class: Minor

Scheduled Return to Compliance Date: 5/4/2018

Actual Return to Compliance Date: 4/17/2018

Actual Return to Compliance Qualifier: Documented

Violation Comment: OBSERVATION: The inventory submitted in CERS on 02/27/2018 did no reflect (1) 55 gal drum of wastse paint.CORRECTIVE ACTION: Submit the updated business plan information into the California Environmental Reporting System (CERS).

Violation Category: Administration/Documentation

Violation Name: Business plan updates

Violation Description: Failure to electronically update business plan within 30 days of any one of the following events:A 100 percent or more increase in the quantity of a previously disclosed material.Any handling of a previously undisclosed hazardous materials at or above reportable quantities. A change of business address, business ownership, or business name. A substantial change in the handler's operations that requires modification to any portion of the business plan.

Violation Citation(s): HSC 6.95 25508.1(a)-(f)

HMRRP & UST Inspection Information

EPA ID: CAL000307361

RCRA LQG: No

Inspection Date: 4/4/2018

Inspection Type: Routine

Number of Class I Violations: 0

Number of Class II Violations: 0

Number of Minor Violations: 1

Significant Operational Compliance: With both Release Detection and Release Prevention

Date Returned to Compliance: 4/17/2018

Days Out of Compliance: 13

Violation Details Available: Yes

Inspection Comments: Not Reported

HMRRP & UST Enforcement Information

: Not Reported

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CRSP-CA	Listed	0.12 miles SW	3643 ft	10

SITE NAME	MAPS	ID
RV Supply Center, Inc	1,4	277513
ADDRESS	CITY	ZIP
8893 THREE FLAGS AVE STE B	OAK HILLS	92344
DETAILS		
Site Regulated Program Information Site ID: 277513 Site EI ID: 10609933 Agency Provided Latitude: 34.36946 Agency Provided Longitude: -117.42963 Program Description: Chemical Storage Facilities Program Description: Hazardous Waste Generator Evaluation Information Evaluation Date: 4/4/2018 Violations Found? (Y/N): Yes Evaluation General Type: Compliance Evaluation Inspection Evaluation Type: Routine done by local agency Evaluation Note(s): Not Reported Evaluation Division: San Bernardino County Fire Department Evaluation Program: HW Evaluation Source: CERS Evaluation Date: 4/4/2018 Violations Found? (Y/N): Yes Evaluation General Type: Compliance Evaluation Inspection Evaluation Type: Routine done by local agency Evaluation Note(s): Not Reported Evaluation Division: San Bernardino County Fire Department Evaluation Program: HMRRP Evaluation Source: CERS Violation Information Violation Date: 4/4/2018 Citation: HSC 6.95 25508.1(a)-(f) - California Health and Safety Code, Chapter 6.95, Section(s) 25508.1(a)-(f) Violation Description: Failure to electronically update business plan within 30 days of any one of the following events: A 100 percent or more increase in the quantity of a previously disclosed material. Any handling of a previously undisclosed hazardous materials at or above reportable quantities. A change of business address, business ownership, or business name. A substantial change in the handler's operations that requires modification to any portion of the business plan. Violation Note(s): Returned to compliance on 04/17/2018. OBSERVATION: The inventory submitted in CERS on 02/27/2018		

did no reflect (1) 55 gal drum of wastse paint. CORRECTIVE ACTION: Submit the updated business plan information into the California Environmental Reporting System (CERS).

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

Violation Source: CERS

Violation Date: 4/4/2018

Citation: HSC 6.5 25250.22 - California Health and Safety Code, Chapter 6.5, Section(s) 25250.22

Violation Description: Failure to properly manage used oil and/or fuel filters in accordance with the requirements.

Violation Note(s): Returned to compliance on 04/04/2018. OBSERVATION: Observed (1) 55 gal drum of used oil filters with no labeling. This was corrected during the inspection.

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 4/4/2018

Citation: 40 CFR 1 265.31 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.31

Violation Description: Failure to maintain and operate the facility to minimize the possibility of a fire, explosion, or any unplanned sudden or non-sudden release of hazardous waste or hazardous waste constituents to air, soil, or surface water which could threaten human health or the environment.

Violation Note(s): Returned to compliance on 04/17/2018. OBSERVATION: Waste oil was observed in the secondary containment. CORRECTIVE ACTION: Submit a signed statement indicating that the secondary containment will be kept free of hazardous waste..

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 4/4/2018

Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)

Violation Description: Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Violation Note(s): Returned to compliance on 04/04/2018. OBSERVATION: Observed (1) 55 gal drum of used oil and (1) 55 gal drum of waste antifreeze with incomplete or illegible hazardous waste label. This was corrected during the inspection.

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Enforcement Information

: Not Reported

:Chemical Information

: Not Reported

:Coordinate Information

: Not Reported

:

DATABASE

STATUS

DISTANCE

ELEVATION

MAP ID

CUPA-CA	Listed	0.12 miles SW	3643 ft	10
SITE NAME			MAPS	ID
RV Supply Center, Inc			1,4	FA0016222-SBD
ADDRESS			CITY	ZIP
8893 Three Flags Ave Ste B			Oak Hills	92344
DETAILS				
County: San Bernardino Responsible Agency: San Bernardino County Fire Department Facility ID: FA0016222 Address2: Not Reported Owner Information: Mark Boesch Contact Name: Not Reported Mailing Address: 8893 Three Flags Ave Ste B, Oak Hills, CA 92344 Mailing Address 2: Not Reported Agency Provided Latitude: Not Reported Agency Provided Longitude: Not Reported Permit ID: PT0036888 Program Element Code: 4243 Permit Description: HAZARDOUS MATERIALS 4-10 CHEMICALS Status: ACTIVE To: 5/31/2019 Permit ID: PT0036889 Program Element Code: 4453 Permit Description: SMALL QUANTITY GENERATOR Status: ACTIVE To: 5/31/2019				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
Hist-Auto Repair	Listed	0.12 miles SW	3643 ft	10
SITE NAME			MAPS	ID
WINGFOOT COMMERCIAL TIRE SYSTS			1,4	16670
ADDRESS			CITY	ZIP
8893 THREE FLAGS AVE			Hesperia	92344
DETAILS				

Sic Code: 5531
Desc: Auto, Truck & Tire Service
Site Added: 2/2010

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
RCRA-NON-US	Listed	0.12 miles SW	3643 ft	10
SITE NAME			MAPS	ID
RV SUPPLY CENTER INC			1,4	CAL000307361
ADDRESS			CITY	ZIP
8893 THREE FLAGS AVE STE B			OAK HILLS	92344

DETAILS

Additional details may be found online using the following link:
https://enviro.epa.gov/enviro/rcrainfoquery_3.facility_information?pgm_sys_id=CAL000307361
Source Type: Implementer
Generator Status: Non-Generator
NAICS1: RECREATIONAL VEHICLE DEALERS
Active Site Indicator: H----
Owner Name: RV SUPPLY CENTER INC
Operator Name: MARK BOESCH
In Handler Universes: Y
In a Universe: Y
Universal Waste: Y
Universal Waste Destination Facility: Y

Receive Date: 20060526
Acknowledge Flag Date: 20060526
Contact First Name: MARK
Contact Last Name: BOESCH
Contact Street 1: 8893 THREE FLAGS AVE STE B
Contact City: OAK HILLS
Contact State: CA
Contact Zip: 92344
Contact Phone: 760-949-1222
Contact FAX: 000-000-0000
Contact E-mail Address: MARK@RVSCINC.COM
Universal Waste Destination Facility: Y

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID

CERS-CA	Listed	0.19 miles SW	3645 ft	11
SITE NAME			MAPS	ID
DOUBLE EAGLE TRANSPORTATION			1,4	10049065
ADDRESS			CITY	ZIP
12135 SCARBROUGH CT			HESPERIA	92345
DETAILS				
General Program & Facility Information CERS ID: 10049065 Facility ID: FA0008746 Facility Regulator Key ID: FA0008746 Organization Code: 90044872 Business/Organization Name: DOUBLE EAGLE TRANSPORTATION Multiple Jurisdictional Business? (Y/N): No Business Origin: Business Count of Business CERS User Accounts: 3 Facility Count for Business: 1 Last Submittal Date (any element): 12/5/2018 4:02:03 PM Count of Submitted Elements: 77 Remote Facility? (Y/N): No Small Quantity Generator Facility? (Y/N): No Local Facility Grouping: Not Reported				
Facility Specific Information Assessor Parcel Number (APN): 3.06459116e+012 Number of Employees: 133 Property Owner Name: Gerald Butcher Property Owner Phone Number: (760) 956-3770 Property Owner Mailing Address: 12135 Scarbrough Court Property Owner Mailing City: Hesperia Property Owner Mailing State: CA Property Owner Mailing Zip Code: 92344 Property Owner Mailing Country: United States				
Inspection Information Aboveground Petroleum Storage Act (APSA) Last Inspection Date: Not Reported California Accidental Release Prevention (CalARP) Last Inspection: Not Reported Conditionally Authorized (CA) Last Inspection Date: Not Reported Conditionally Exempt (CE) Last Inspection Date: Not Reported Household Hazardous Waste Collection (HHW) Last Inspection Date: Not Reported Hazardous Materials Release Response Plan (HMRRP) Last Inspection: 8/22/2018 Hazardous Waste Generator (HW) Last Inspection Date: 8/22/2018 RCRA Large Quantity Generator (HWLQG) Last Inspection Date: Not Reported				

Hazardous Waste Recycler (HWR) Last Inspection Date: Not Reported

Permit By Rule (PBR) Last Inspection: Not Reported

Underground Storage Tank (UST) Last Inspection Date: 08/28/2018

Owner/Operator Information

Beginning Date: Not Reported

Ending Date: Not Reported

Phone Number: (760) 956-3770

Fax Number: (760) 956-6362

Supplemental Location: Not Reported

County: San Bernardino

Dun & Bradstreet D-U-N-S Number: Not Reported

SIC Code: 7219

NAICS Code: 484220

Mailing Address: 12135 Scarbrough Court

Mailing Address City: Hesperia

Mailing Address State Code: CA

Mailing Address Zip Code: 92345

Operator Name: Gerald Butcher

Operator Phone Number: (760) 956-3770

Owner Name: Double Eagle Transportation Inc.

Owner Phone: (760) 956-3770

Owner Mailing Address: 12135 Scarbrough Court

Owner City: Hesperia

Owner State: CA

Owner Zip Code: 92345

Owner Country: United States

Environmental Contact Name: Tony McKinney

Environmental Contact Phone Number: (760) 956-3770

Environmental Contact Mailing Address: 12135 Scarbrough Court

Environmental Contact Email Address: safetydirector@doubleeagletrans.com

Environmental Contact City: Hesperia

Environmental Contact State: CA

Environmental Contact Zip: 92344

Environmental Contact Country: United States

Primary Emergency Contact Name: Tony McKinney

Primary Emergency Contact Title: Safety Director

Primary Emergency Contact Business Phone Number: (760) 956-3770

Primary Emergency Contact 24Hr Phone: (760) 265-0433

Primary Emergency Contact Pager Number: Not Reported

Secondary Emergency Contact Name: Jerry Wheeler

Secondary Emergency Contact Title: Operations Manager

Secondary Emergency Contact Business Phone: (760) 956-3770

Secondary Emergency Contact 24Hr Phone: (760) 964-2721

Secondary Emergency Contact Pager Number: (760) 956-3770

Additional Local Collected Info: Not Reported

Identification Signed Date: Not Reported

Document Preparer Name: Jerry Wheeler

Identification Signer Name: Jerry Wheeler

Identification Signer Title: Safety Director
Billing Contact Name: Gerald Butcher
Billing Contact Phone: (760) 956-3770
Billing Contact Email: jerry2Xeagle@AOL.com
Billing Address: 12135 Scarbrough Court
Billing City: Hesperia
Billing State: CA
Billing Zip: 92345
Billing Country: United States
Business Owner/Operator Regulator Key: Not Reported

Business Activity Information

EPA ID: CAL000225630
Hazardous Materials On Site? (Y/N): Y
CAL ARP Regulated Substances? (Y/N): N
Own or Operator USTs? (Y/N): Y
Own or Operator APSTs? (Y/N): N
Hazardous Waste Generator? (Y/N): Y
Recycles Materials? (Y/N): N
On-site HW Treatment? (Y/N): N
Financial Assurance? (Y/N): N
Remote Waste Consolidation Site? (Y/N): N
Hazardous Waste Tank Closure? (Y/N): N
RCRA Large Quantity Generator? (Y/N): N
Household Hazardous Waste (HHW) Collection? (Y/N): N
Business Activity Comment(s): Not Reported

Submittal Information

Submitted Date/Time: 7/31/2018 12:08:14 PM
Submittal Action: Accepted
BP Activities Last Updated Date: 7/31/2018 12:01:42 PM
BP Owner/Operator Last Updated Date: 7/31/2018 12:01:42 PM
Submittal Action Comment 1: ACCEPTED AS COMPLETE PENDING FIELD VERIFICATION: Thank you for the submittal. While this submittal is being accepted as complete, the data has not been field verified and may require correction in the future. Please note, it is your responsibility to review and certify the information submitted in CERS annually. You must also update the information within 30 days of a change of owner, business address, business name, emergency contact information, inventory and/or other site conditions that could impact emergency response activity. If you have questions about using CERS, please contact the San Bernardino County Fire CERS Help Desk at (909) 386-8432. (Reviewed by Nancy Schlotthauer, nschlotthauer@sbcfire.org or (909) 386-8401)
Submittal Action Comment 2: No changes
Facility Info Next Due Date: Not Reported
Biz Activities Regulator Key: Not Reported

Supplemental Geographic Information

Agency Provided Latitude: 34.41259
Agency Provided Longitude: -117.398056
Horizontal Accuracy: 100

Horizontal Collection Method: Interpolation
Geographic Reference Point: Facility Boundary
Horizontal Reference Datum: WGS84 (World Geodetic System of 1984)
Data Collection Date: 7/1/2010 7:55:00 PM

Submittal Element Regulator Information

CUPA Regulator Code: 3600
Facility Info Reporting Requirement: Applicable
Facility Info Next Due Date: Not Reported
Facility Info Last Submitted Date: 12/5/2018 4:02:03 PM
Facility Info Accepted Date: 9/24/2018 1:50:54 PM
Inventory Regulator Code: 3600
Inventory Reporting Requirement: Applicable
Inventory Next Due Date: Not Reported
Inventory Last Submitted Date: 12/5/2018 4:02:03 PM
Inventory Last Accepted Date: 4/2/2018 12:46:24 PM
ER Training Regulator Code: 3600
ER Training Reporting Requirement: Applicable
ER Training Next Due Date: Not Reported
ER Training Last Submitted Date: 10/24/2018 2:13:58 PM
ER Training Last Accepted Date: 4/2/2018 12:46:19 PM
UST Regulator Code: 3600
UST Reporting Requirement: Applicable
UST Next Due Date: Not Reported
UST Last Submitted Date: 11/01/2018
UST Last Accepted Date: 09/24/2018
HW Treat Regulator Code: 3600
HW Treat Reporting Requirement: Not Applicable
HW Treat Next Due Date: Not Reported
HW Treat Last Submitted Date: Not Reported
HW Treat Last Accepted Date: Not Reported
RMR Regulator Code: 3600
RMR Reporting Requirement: Not Applicable
RMR Next Due Date: Not Reported
RMR Last Submitted Date: Not Reported
RMR Last Accepted Date: Not Reported
Consolidation Regulator Code: 3600
Consolidation Reporting Requirement: Not Applicable
Consolidation Next Due Date: Not Reported
Consolidation Last Submitted Date: Not Reported
Consolidation Last Accepted Date: Not Reported
Tank Closure Regulator Code: 3600
Tank Closure Reporting Requirement: Not Applicable
Tank Closure Next Due Date: Not Reported
Tank Closure Last Submitted Date: Not Reported
Tank Closure Last Accepted Date: Not Reported
APSA Regulator Code: 3600
APSA Reporting Requirement: Not Applicable
APSA Next Due Date: Not Reported

APSA Last Submitted Date: Not Reported
APSA Last Accepted Date: Not Reported
CalARP Regulator Code: 3600
CalARP Reporting Requirement: Not Applicable
CalARP Next Due Date: Not Reported
CalARP Last Submitted Date: Not Reported
CalARP Last Accepted Date: Not Reported

UST Facility and Program Information

BOE Number: 44039735
Type of Action: Confirmed/Updated Information
UST Facility Type: Motor Vehicle Fueling
Permit Holder Notification Information: Facility Owner
Total Number of USTs: 1
Indian or Trust Land: No
Supervisor of Division, Section, or Office: Not Reported
Tank Owner Name: Double Eagle Transportation
Tank Owner Phone: 760-956-3770
Tank Owner Mailing Address: 12135 Scarbrough Court
Tank Owner City: Hesperia
Tank Owner State: CA
Tank Owner ZIP Code: 92344
Tank Owner Country: United States
Tank Owner Type: Non-Government
Tank Operator Name: Double Eagle Transportation
Tank Operator Phone: 760-956-3770
Tank Operator Mailing Address: 12135 Scarbrough Court
Tank Operator City: Hesperia
Tank Operator State: CA
Tank Operator ZIP Code: 92344
Tank Operator Country: United States
Self-Insured?: No
Guarantee?: No
Insurance?: No
Surety Bond?: No
Letter of Credit?: No
Exemption?: No
State Fund and CFO letter?: Yes
State Fund and CD?: No
Local Government Mechanism?: No
Other?: No
Other Description: Not Reported
Date Submitted to CERS: 7/31/2018 12:08:14 PM
Date Accepted by Regulator: 9/24/2018 1:51:09 PM
Regulator Comment: Thank you for the submittal. This submittal has been verified as complete. Please note it is your responsibility to review and certify the information submitted in CERS annually. If you have questions about using CERS, please contact the San Bernardino County Fire CERS Help Desk at (909) 386-8432. (Reviewed by Amanda Nesbit, ICC 8750403-UI, anesbit@sbcfire.org or (909) 386-8419.)
Regulator Agent Name: SCHLOTTHAUER, NANCY

Regulator Name: San Bernardino County Fire Department

Regulator Type: CUPA

Tank & Monitoring Plan Information

Tank ID #: 20K1

Type of Action: Confirmed/Updated Information

Tank Manufacturer: owens corning

Tank Configuration: A Stand-alone Tank

Tank Capacity (In Gallons): 20000

Date UST System Installed: 05-01-1999

Date UST Permanently Closed: Not Reported

Date Existing UST Discovered: Not Reported

Number of Compartments in the Unit: 1

Additional Description: Not Reported

Tank Use: Motor Vehicle Fueling

Specify Other Tank Use: Not Reported

Tank Contents: Diesel

Specify Other Petroleum: Not Reported

Specify Other Non-Petroleum: Not Reported

Type of Tank: Double Wall

Tank Primary Containment Construction: Fiberglass

Tank Construction - Other Primary Containment Construction: Not Reported

Tank Construction - Tank Secondary Containment Construction: Fiberglass

Tank Construction - Other Secondary Containment Construction: Not Reported

Audible/Visual Alarms: No

Ball Float: No

Fill Tube Shut-Off Valve: Yes

Exempt: No

Piping Construction: Double-walled

Piping System Type: Pressure

Primary Containment Construction: Fiberglass

Other Primary Containment Construction: Not Reported

Secondary Containment Construction: Fiberglass

Other Secondary Containment Construction: Not Reported

Piping/Turbine Containment Sump: Single-walled

Vent Piping Construction - Primary Containment Construction: Fiberglass

Vent Piping Const - Other Primary Containment Construction: Not Reported

Vent Piping Construction - Secondary Containment Construction: None

Vent Piping Const - Other Secondary Containment Construction: Not Reported

Vent Piping Transition Sumps: None

VR Piping Const - Primary Containment Construction: None

VR Piping Const - Other Primary Containment Construction: Not Reported

VR Piping Const - Secondary Containment Construction: None

VR Piping Const - Other Secondary Containment Construction: Not Reported

Riser/Fill Piping Const - Primary Containment Const: Steel

Riser/Fill Piping Const - Other Primary Containment Const: Not Reported

Riser/Fill Piping Const - Secondary Containment Const: Fiberglass

Riser/Fill Piping Const - Other Secondary Containment Const: Not Reported

Spill Bucket Installed: Yes

Striker Plate / Bottom Protector Installed: Yes
Containment Sump: Yes
Construction Type: Single-walled
Construction Material: Steel
Other Construction Material: Not Reported
Sacrificial Anode: No
Impressed Current: No
Isolation: Yes
Monitoring Equipment Serviced: Annually
Other Frequency of Monitoring Equipment Service: Not Reported
Site Plot Plan Submitted: Site Plan Previously Submitted
Continuous Electronic Tank Monitoring: Yes
Tank Secondary Containment System: Dry
Electronic Monitor Panel Manufacturer: Veeder Root
Electronic Monitor Panel Model #: TLS-300C
Tank Monitoring - Leak Sensor Manufacturer: Veeder Root
Tank Monitoring - Leak Sensor Model #: 409
Automatic Tank Gauging: No
ATG Panel Manufacturer: Not Reported
ATG Model #: Not Reported
In-Tank Probe Manufacturer: Not Reported
In-tank Probe Model #: Not Reported
Tank Leak Test Frequency: Not Reported
Other Leak Test Frequency: Not Reported
Programmed Tank Tests: Not Reported
Other Programmed Tests: Not Reported
Monthly Statistical Inventory Reconciliation: No
Weekly Manual Tank Gauge: No
Tank Gauging Test Period: Not Reported
Tank Integrity Testing: No
Tank Integrity Testing Frequency: Not Reported
Other Tank Integrity Testing Frequency: Not Reported
Other Monitoring: No
Specify Other Monitoring: Not Reported
Continuous Monitoring of Piping Secondary Containment: Yes
Piping Secondary Containment: Dry
Panel Manufacturer: Veeder Root
Panel Model #: TLS-300C
Piping Secondary Containment - Leak Sensor Manufacturer: Veeder Root
Piping Secondary Containment - Leak Sensor Model #: 208
Leak Alarm Triggers Automatic Pump Shutdown: Yes
Failure/Disconnect Triggers Pump Shutdown: Yes
Mechanical Line Leak Detector Performs 3 GPH Leak Test: Yes
MLLD Manufacturer: Vapor Less
MLLD Model #: LD2000
Electronic Line Leak Detector Performs 3 GPH Leak Test: No
ELLD Manufacturer: Not Reported
ELLD Model #: Not Reported
ELLD Programmed In-Line Testing: 0.2 GPH
ELLD Triggers Automatic Pump Shutdown: Not Reported

ELLD Failure/Disconnect Triggers Automatic Shutdown: Not Reported

Pipeline Integrity Testing: No

Pipeline Integrity Testing Frequency: Not Reported

Other Pipeline Integrity Testing Frequency: Not Reported

Visual Pipeline Monitoring: No

Visual Pipeline Monitoring Frequency: Not Reported

Suction Piping Meets Exemption Criteria: No

No Regulated Piping Is Connected To The Tank System: No

Other Pipeline Monitoring: No

Other Pipeline Monitoring Description: Not Reported

UDC Monitoring: Float and Chain Assembly

Other UDC Monitoring: Not Reported

UDC Panel Manufacturer: N/A

UDC Panel Model #: N/A

UDC Leak Sensor Manufacturer: Bravo

UDC Leak Sensor Model #: N/A

Detection of Leak into UDC Triggers Audible and Visual Alarms: No

UDC Leak Alarm Triggers Automatic Pump Shutdown: No

Fail/Discon UDC Monitor System Triggers Automatic Pump Shutdown: No

UDC Monitoring Stops Flow of Product at Dispenser: Yes

UDC Construction: Single-walled

UDC Secondary Containment Monitoring: Not Reported

Leak Within Sec Cnt of UDC Causes Audible & Visual Alarms: Not Reported

ELD Testing: No

Secondary Containment Testing: Yes

Spill Bucket Testing: Yes

Alarm Logs: Yes

Visual Inspection Records: Yes

Tank Integrity Testing Results: No

SIR Testing Results: No

Tank Gauging Results: No

ATG Testing Results: No

Corrosion Protection Logs: No

Equipment Maintenance and Calibration Records: Yes

Personnel w/ UST Monitor Responsibility Familiar w/ Training Doc: Yes

UST Monitoring Plan: Not Reported

Operating Manuals: Not Reported

CA UST Regulations: Not Reported

CA UST Law: Not Reported

SWRCB Handbook for Tank Owners - Manual and SIR: Not Reported

SWRCB Publication: Understanding Automatic Tank Gauging Systems: Not Reported

Other Training Documents: Not Reported

Other Training Documents Description: Not Reported

Designated Operator Training: Yes

Comments and Additional Information: fill sup is monitored by -208 sensor

Name of First Person Having Responsibility: Bob Derrick

Title of First Person Having Responsibility: Dispatch Manager

Name of Second Person Having Responsibility: Jerry Wheeler

Title of Second Person Having Responsibility: Safety Director

Signature Representation: Facility Owner/Operator

Signature Date: Not Reported
Applicant Name: Gerald Butcher
Applicant Title: Owner
Date Submitted to CERS: 7/31/2018 12:08:14 PM
Date Accepted by Regulator: 9/24/2018 1:51:09 PM
Regulator Agent Name: SCHLOTTHAUER, NANCY
Regulator Name: San Bernardino County Fire Department
Regulator Type: CUPA

HMRRP & UST Violation Information

EPA ID: CAL000225630

RCRA LQG: No

Violation Date: 8/22/2018

Violation Type Number: 1010004

Class: Minor

Scheduled Return to Compliance Date: 9/21/2018

Actual Return to Compliance Date: Not Reported

Actual Return to Compliance Qualifier: Not Reported

Violation Comment: OBSERVATION: The facility hazardous material inventory lacks the listing of waste coolant and drained used oil filters, and also has inaccurate quantity amounts for "DEF", oil/absorbent and spent fuel filter waste, and gear oil. CORRECTIVE ACTION: Submit an accurate and complete hazardous materials inventory into the California Environmental Reporting System (CERS).

Violation Category: Administration/Documentation

Violation Name: Hazardous materials inventory

Violation Description: Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.

Violation Citation(s): HSC 6.95 25505(a)(1), 25506, 25508(a)(1)

Violation Date: 8/22/2018

Violation Type Number: 1010005

Class: Minor

Scheduled Return to Compliance Date: 9/21/2018

Actual Return to Compliance Date: Not Reported

Actual Return to Compliance Qualifier: Not Reported

Violation Comment: OBSERVATION: The facility map lacks the listing of storm and sewer drains. CORRECTIVE ACTION: Submit an accurate and complete site map into the California Environmental Reporting System (CERS).

Violation Category: Administration/Documentation

Violation Name: Site map

Violation Description: Failure to complete and electronically submit a site map with all required content.

Violation Citation(s): HSC 6.95 25505(a)(2), 25508(a)(1)

HMRRP & UST Inspection Information

EPA ID: CAL000225630

RCRA LQG: No

Inspection Date: 8/22/2018

Inspection Type: Routine

Number of Class I Violations: 0

Number of Class II Violations: 0

Number of Minor Violations: 2
Significant Operational Compliance: With both Release Detection and Release Prevention
Date Returned to Compliance: Not Reported
Days Out of Compliance: 118
Violation Details Available: Yes
Inspection Comments: Not Reported

Inspection Date: 4/23/2015
Inspection Type: Routine
Number of Class I Violations: 0
Number of Class II Violations: 0
Number of Minor Violations: 0
Significant Operational Compliance: With both Release Detection and Release Prevention
Date Returned to Compliance: Not Reported
Days Out of Compliance: 1335
Violation Details Available: No
Inspection Comments: INSPECTION - BP

Inspection Date: 9/2/2014
Inspection Type: Routine
Number of Class I Violations: 0
Number of Class II Violations: 0
Number of Minor Violations: 0
Significant Operational Compliance: With both Release Detection and Release Prevention
Date Returned to Compliance: Not Reported
Days Out of Compliance: 1568
Violation Details Available: No
Inspection Comments: UST FIELD INSPECTION AND CERS CONSULT WITH OPERATORS

Inspection Date: 9/5/2013
Inspection Type: Routine
Number of Class I Violations: 0
Number of Class II Violations: 0
Number of Minor Violations: 0
Significant Operational Compliance: With both Release Detection and Release Prevention
Date Returned to Compliance: Not Reported
Days Out of Compliance: 1930
Violation Details Available: No
Inspection Comments: UST HANDLER INSPECTION

HMRRP & UST Enforcement Information
: Not Reported

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
County-UST-CA	Listed	0.19 miles SW	3645 ft	11

SITE NAME	MAPS	ID
DOUBLE EAGLE TRANSPORTATION	1,4	FA0008746-SBD
ADDRESS	CITY	ZIP
12135 SCARBROUGH CT	HESPERIA	92345
DETAILS		
County: San Bernardino Responsible Agency: San Bernardino Division of Environmental Health Services Facility ID: FA0008746 Address2: Not Reported Owner Info: Double Eagle Transportation Inc. Contact Name: GERALD BUTCHER Mailing Address: 12135 Scarbrough Court, Hesperia, CA 92345 Mailing Address2: Not Reported Permit ID: PT0016928 Program Element Code: 4104 Permit Description: REGULAR UST ANNUAL INSPECTION (PER TANK) Status: ACTIVE To: 8/31/2019		

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CRSP-CA	Listed	0.19 miles SW	3645 ft	11
SITE NAME			MAPS	ID
DOUBLE EAGLE TRANSPORTATION			1,4	391724
ADDRESS			CITY	ZIP
12135 SCARBROUGH CT			HESPERIA	92345
DETAILS				
Site Regulated Program Information Site ID: 391724 Site EI ID: 10049065 Agency Provided Latitude: 34.41259 Agency Provided Longitude: -117.39805 Program Description: Chemical Storage Facilities Program Description: Hazardous Waste Generator				

Program Description: Underground Storage Tank

Evaluation Information

Evaluation Date: 8/28/2018

Violations Found? (Y/N): No

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): Not Reported

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: UST

Evaluation Source: CERS

Evaluation Date: 8/22/2018

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): Not Reported

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HW

Evaluation Source: CERS

Evaluation Date: 8/22/2018

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): Not Reported

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HMRRP

Evaluation Source: CERS

Evaluation Date: 8/29/2017

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): ANNUAL UST INSPECTION AND CERS REVIEW

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: UST

Evaluation Source: CERS

Evaluation Date: 8/29/2017

Violations Found? (Y/N): No

Evaluation General Type: Other/Unknown

Evaluation Type: Other, not routine, done by local agency

Evaluation Note(s): SB 989 TESTING

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: UST

Evaluation Source: CERS

Evaluation Date: 8/30/2016

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): DOUBLE EAGLE HESPERIA

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: UST

Evaluation Source: CERS

Evaluation Date: 9/1/2015

Violations Found? (Y/N): No

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): DOUBLE EAGLE- UST INSPECTION & MONITORING CERTIFICATION

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: UST

Evaluation Source: CERS

Evaluation Date: 4/23/2015

Violations Found? (Y/N): No

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): INSPECTION - BP

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HMRRP

Evaluation Source: CERS

Evaluation Date: 4/23/2015

Violations Found? (Y/N): No

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): INSPECTION - HW

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HW

Evaluation Source: CERS

Evaluation Date: 1/28/2015

Violations Found? (Y/N): Yes

Evaluation General Type: Other/Unknown

Evaluation Type: Other, not routine, done by local agency

Evaluation Note(s): FOLLOW UP INSPECTION FOR VIOLATIONS CITED ON ANNUAL MONITORING CERTIFICATION
9/2/14 .

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: UST

Evaluation Source: CERS

Evaluation Date: 9/2/2014

Violations Found? (Y/N): No

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): UST FIELD INSPECTION AND CERS CONSULT WITH OPERATORS

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HMRRP

Evaluation Source: CERS

Evaluation Date: 9/2/2014

Violations Found? (Y/N): No

Evaluation General Type: Other/Unknown

Evaluation Type: Other, not routine, done by local agency

Evaluation Note(s): UST FIELD INSPECTION-TRIENNIAL SECONDARY CONTAINMENT TESTING WITH ABEL VERGARA. FAILURES FOUND DURING TESTING. VIOLATIONS ATTACHED TO ANNUAL INSPECTION (C16) DAR

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: UST

Evaluation Source: CERS

Evaluation Date: 9/2/2014

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): UST FIELD INSPECTION-ANNUAL MONITORING SYSTEM CERTIFICATION (SINGLE TANK) W/ABEL VERGARA

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: UST

Evaluation Source: CERS

Evaluation Date: 9/5/2013

Violations Found? (Y/N): No

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): UST MONIORING CERTIFICATION

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: UST

Evaluation Source: CERS

Evaluation Date: 9/5/2013

Violations Found? (Y/N): No

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): UST HANDLER INSPECTION

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HMRRP

Evaluation Source: CERS

Violation Information

Violation Date: 8/22/2018

Citation: 22 CCR 15 66265.16 - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.16

Violation Description: Failure to provide employees with hazardous waste training program of class room instructions or on-the-job training within the first six months after the date of their employment or assignment to a facility, or to a new position at a facility and annually thereafter. Training records on current personnel shall be kept until closure of the facility and for former employees the record shall be kept for at least three years from the date the employee last worked at the facility. The records

shall include the following: the job title for each position at the facility related to hazardous waste management, and the name of the employee filling each job; a written job description for each position, duties of facility personnel assigned to each position, and a written description of the type and amount of both introductory and continuing training that will be given to each person filling a position.

Violation Note(s): OBSERVATION: Documented training of personnel was not available at the time of inspection.

CORRECTIVE ACTION: Locate training documentation or conduct training with applicable personnel and document it. Submit the signed Certificate of Compliance to show proof of compliance regarding this violation.

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 8/22/2018

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit a site map with all required content.

Violation Note(s): OBSERVATION: The facility map lacks the listing of storm and sewer drains. CORRECTIVE ACTION: Submit an accurate and complete site map into the California Environmental Reporting System (CERS).

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

Violation Source: CERS

Violation Date: 8/22/2018

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.

Violation Note(s): OBSERVATION: The facility hazardous material inventory lacks the listing of waste coolant and drained used oil filters, and also has inaccurate quantity amounts for "DEF", oil/absorbent and spent fuel filter waste, and gear oil. CORRECTIVE ACTION: Submit an accurate and complete hazardous materials inventory into the California Environmental Reporting System (CERS).

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

Violation Source: CERS

Violation Date: 8/22/2018

Citation: 22 CCR 15 66265.192(a) - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.192(a)

Violation Description: Failure to obtain and maintain a written assessment reviewed and certified by an independent, qualified, professional engineer prior to placing the tank system in service. The written assessment shall state that, the new hazardous waste tank system has sufficient structural integrity, is acceptable for the transferring, storing and treating of hazardous waste, and that the tanks and containment system including the foundation, structural support, seams, connections, and pressure controls (if applicable) are suitably designed to meet the regulation.

Violation Note(s): OBSERVATION: A written hazardous waste tank assessment has not been obtained for the used oil aboveground storage tank system prior to placing system into service. CORRECTIVE ACTION: Obtain a written hazardous waste tank system assessment for the used oil tank system in accordance with 22 CCR 15 66265.192 and submit a copy to the CUPA.

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 8/22/2018

Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)

Violation Description: Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Violation Note(s): Returned to compliance on 08/22/2018. OBSERVATION: Two 55-gallon containers of hazardous waste spent paper filters located in the outside storage area near the used oil "ast" were observed without the required hazardous waste label. CORRECTIVE ACTION: Submit the signed Certificate of Compliance to the CUPA showing that the container listed above has been properly labeled. This violation was corrected during the inspection. CB

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 8/29/2017

Citation: 23 CCR 16 2712 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712

Violation Description: Failure to comply with any of the applicable requirements of the permit issued for the operation of the UST system.

Violation Note(s): Returned to compliance on 08/29/2018. OBSERVED FLOAT AND CHAIN ASSEMBLY AT DISPENSER #1 DID NOT FUNCTION PROPERLY WHEN TESTED. DID NOT ACTIVATE SHEAR VALVE WHEN TESTED. COMPLIANCE REQUIREMENT: REPAIR AND SCHEDULE WITNESSED RETEST OF FLOAT AND CHAIN ASSEMBLY AT UDC #1 WITHIN 7 (SEVEN) DAYS.

Violation Division: San Bernardino County Fire Department

Violation Program: UST

Violation Source: CERS

Violation Date: 8/30/2016

Citation: HSC 6.7 Multiple - California Health and Safety Code, Chapter 6.7, Section(s) Multiple

Violation Description: UST Program - Administration/Documentation - General - Must include violation description, proper statute and regulation citation in the "comment" section.

Violation Note(s): Returned to compliance on 09/02/2016. Failure to have a written monitoring program with monitoring procedures and response plan (CHSC 25286(a)) OBSERVATIONS: THE TANK INFORMATION PAGE SHOW THAT THE TANK IS A FLUID CONTAINMENT TANK, WHEN IT IS AN OWEN CORNING TANK. THIS WAS ALSO CONFIRMED BY THE TECHNICIAN. THE UST RESPONSE PLAN NEEDS TO BE UPDATED WITH THE NEW RESPONSIBLE PERSONS AND SECTION V NEEDS TO BE COMPLETED. COMPLIANCE REQUIREMENT: UPDATE THE TANK INFORMATION PAGE AND RESPONSE PLAN IN CERS. INFORM THE INSPECTOR ONCE COMPLETED.

Violation Division: San Bernardino County Fire Department

Violation Program: UST

Violation Source: CERS

Violation Date: 1/28/2015

Citation: HSC 6.7 25292.1(a) - California Health and Safety Code, Chapter 6.7, Section(s) 25292.1(a)

Violation Description: Failure to operate the UST system to prevent spills and/or overfills.

Violation Note(s): Returned to compliance on 04/23/2015. SHEAR VALVE #1 AT MAIN DISPENSER FAILED TO CEASE FUEL DISPENSING WHEN TESTED FOR FUNCTIONALITY. COMPLIANCE REQUIREMENT: IMMEDIATELY CEASE OPERATION OF MAIN DISPENSER #1. REPAIR SHEAR VALVE AND ENSURE PROPER FUNCTIONALITY OF EQUIPMENT PRIOR TO OPERATION. CONTACT THIS DIVISION PRIOR TO REPAIRS AND TO DETERMINE IF A PERMIT WILL BE REQUIRED FOR REPAIR. SUBMIT COPIES OF REPAIR RECORDS. SUBMIT SIGNED CERTIFICATE OF COMPLIANCE WITH COPIES OF WORK ORDERS AND REPAIRS WITHIN 7 (SEVEN) DAYS. FINAL INSPECTION ON

APPROVED UST MODIFICATION. JMAY

Violation Division: San Bernardino County Fire Department

Violation Program: UST

Violation Source: CERS

Violation Date: 1/28/2015

Citation: HSC 6.7 29291(b) - California Health and Safety Code, Chapter 6.7, Section(s) 29291(b)

Violation Description: Failure of the UST system to be designed and constructed with a monitoring system capable of detecting the entry of the hazardous substance stored in the primary containment into the secondary containment.

Violation Note(s): Returned to compliance on 04/23/2015. SHEAR VALVE #1 AT MAIN DISPENSER FAILED TO CEASE FUEL DISPENSING WHEN TESTED FOR FUNCTIONALITY. COMPLIANCE REQUIREMENT: IMMEDIATELY CEASE OPERATION OF MAIN DISPENSER #1. REPAIR SHEAR VALVE AND ENSURE PROPER FUNCTIONALITY OF EQUIPMENT PRIOR TO OPERATION. CONTACT THIS DIVISION PRIOR TO REPAIRS AND TO DETERMINE IF A PERMIT WILL BE REQUIRED FOR REPAIR. SUBMIT COPIES OF REPAIR RECORDS. SUBMIT SIGNED CERTIFICATE OF COMPLIANCE WITH COPIES OF WORK ORDERS AND REPAIRS WITHIN 7 (SEVEN) DAYS. FINAL INSPECTION ON APPROVED UST MODIFICATION. JMAY

Violation Division: San Bernardino County Fire Department

Violation Program: UST

Violation Source: CERS

Violation Date: 1/28/2015

Citation: HSC 6.7 25299 - California Health and Safety Code, Chapter 6.7, Section(s) 25299

Violation Description: Failure to comply with one or more of the operating permit conditions.

Violation Note(s): Returned to compliance on 04/23/2015. SHEAR VALVE #1 AT MAIN DISPENSER FAILED TO CEASE FUEL DISPENSING WHEN TESTED FOR FUNCTIONALITY. COMPLIANCE REQUIREMENT: IMMEDIATELY CEASE OPERATION OF MAIN DISPENSER #1. REPAIR SHEAR VALVE AND ENSURE PROPER FUNCTIONALITY OF EQUIPMENT PRIOR TO OPERATION. CONTACT THIS DIVISION PRIOR TO REPAIRS AND TO DETERMINE IF A PERMIT WILL BE REQUIRED FOR REPAIR. SUBMIT COPIES OF REPAIR RECORDS. SUBMIT SIGNED CERTIFICATE OF COMPLIANCE WITH COPIES OF WORK ORDERS AND REPAIRS WITHIN 7 (SEVEN) DAYS. FINAL INSPECTION ON APPROVED UST MODIFICATION. JMAY

Violation Division: San Bernardino County Fire Department

Violation Program: UST

Violation Source: CERS

Violation Date: 9/2/2014

Citation: HSC 6.7 25292.1(a) - California Health and Safety Code, Chapter 6.7, Section(s) 25292.1(a)

Violation Description: Failure to operate the UST system to prevent spills and/or overfills.

Violation Note(s): Returned to compliance on 04/23/2015. THE SYSTEM CURRENTLY HAS SEVERAL SECONDARY CONTAINMENT FAILURES AND DOES NOT MEET STANDARDS TO PREVENT THE THREAT OF RELEASE TO THE ENVIRONMENT. REQUIREMENT: SUBMIT PLANS FOR REPAIR WITHIN 30 DAYS (SEE DESCRIPTION FOR VIOLATION #329). FINAL INSPECTION ON APPROVED UST MODIFICATION. JMAY

Violation Division: San Bernardino County Fire Department

Violation Program: UST

Violation Source: CERS

Violation Date: 9/2/2014

Citation: HSC 6.7 29291(b) - California Health and Safety Code, Chapter 6.7, Section(s) 29291(b)

Violation Description: Failure of the UST system to be designed and constructed with a monitoring system capable of detecting the entry of the hazardous substance stored in the primary containment into the secondary containment.

Violation Note(s): Returned to compliance on 01/21/2015. THE SYSTEM IS NOT CURRENTLY OPERATED TO MEET

DESIGN AND CONSTRUCTION REQUIREMENTS DUE TO MULTIPLE SECONDARY CONTAINMENT FAILURES.
REQUIREMENT: IMMEDIATELY DETERMINE THE SOURCE OF FAILURE(S) AND CONTACT THIS DEPARTMENT WITH RESULTS UPON COMPLETION. IF NECESSARY, SUBMIT PLANS AND OBTAIN A UST MODIFICATION PERMIT FOR REPAIRS. FOR PERMITTABLE REPAIRS, COMPLETE PLANS SHALL BE SUBMITTED FOR REVIEW WITHIN 30 DAYS.
Violation Division: San Bernardino County Fire Department
Violation Program: UST
Violation Source: CERS

Violation Date: 9/2/2014
Citation: HSC 6.7 25290.1(h), 25290.2(g), 25291(f), 25292(e) - California Health and Safety Code, Chapter 6.7, Section(s) 25290.1(h), 25290.2(g), 25291(f), 25292(e)
Violation Description: Failure to install line leak detector.

Violation Note(s): Returned to compliance on 09/02/2014. THE MECHANICAL LEAK DETECTOR FAILED TO RECOGNIZE THE SIMULATED LEAK WHEN TESTED. REQUIREMENT: THE LEAK DETECTOR WAS REPLACED WHILE ONSITE WITH LIKE-FOR-LIKE EQUIPMENT. THE OLD VMI WAS REPLACED WITH A NEW VMI LD2000 AND RETESTED BY THE TECHNICIAN. THE NEW MLLD PASSED. VIOLATION CORRECTED.
Violation Division: San Bernardino County Fire Department
Violation Program: UST
Violation Source: CERS

Enforcement Information

Enforcement Action Date: 8/30/2016
Enforcement Action Type: Notice of Violation (Unified Program)
Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enforcement Action Note(s): Not Reported
Enforcement Action Division: San Bernardino County Fire Department
Enforcement Action Program: UST
Enforcement Action Source: CERS

Enforcement Action Date: 1/28/2015
Enforcement Action Type: Notice of Violation (Unified Program)
Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enforcement Action Note(s): Not Reported
Enforcement Action Division: San Bernardino County Fire Department
Enforcement Action Program: UST
Enforcement Action Source: CERS

Enforcement Action Date: 9/2/2014
Enforcement Action Type: Notice of Violation (Unified Program)
Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enforcement Action Note(s): Not Reported
Enforcement Action Division: San Bernardino County Fire Department
Enforcement Action Program: UST
Enforcement Action Source: CERS

Chemical Information

: Not Reported

:Coordinate Information

: Not Reported

:

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CUPA-CA	Listed	0.19 miles SW	3645 ft	11
SITE NAME			MAPS	ID
DOUBLE EAGLE TRANSPORTATION			1,4	FA0008746-SBD
ADDRESS			CITY	ZIP
12135 SCARBROUGH CT			HESPERIA	92345
DETAILS				
County: San Bernardino Responsible Agency: San Bernardino County Fire Department Facility ID: FA0008746 Address2: Not Reported Owner Information: Double Eagle Transportation Inc. Contact Name: GERALD BUTCHER Mailing Address: 12135 Scarbrough Court, Hesperia, CA 92345 Mailing Address 2: Not Reported Agency Provided Latitude: Not Reported Agency Provided Longitude: Not Reported Permit ID: PT0016926 Program Element Code: 4454 Permit Description: LARGE QUANTITY GENERATOR Status: ACTIVE To: 8/31/2019 Permit ID: PT0016927 Program Element Code: 4243 Permit Description: HAZARDOUS MATERIALS 4-10 CHEMICALS Status: ACTIVE To: 8/31/2019 Permit ID: PT0016928 Program Element Code: 4104 Permit Description: REGULAR UST ANNUAL INSPECTION (PER TANK) Status: ACTIVE To: 8/31/2019				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
DryCleaners-CA	Listed	0.19 miles SW	3645 ft	11
SITE NAME			MAPS	ID
DOUBLE EAGLE TRANSPORTATION			1,4	CAL000225630
ADDRESS			CITY	ZIP
12135 SCARBOROUGH CT			HESPERIA	923450000
DETAILS				
EPA ID: CAL000225630 Create Date: 12/18/2001 Facility Act Ind: y Inact Date: Not Reported Facility Street2: Not Reported County: San Bernardino Latitude: 0 Longitude: 0 Mailing Name: Not Reported Facility Mailing Address: 12135 SCARBROUGH CT Facility Mailing Address 2: Not Reported Facility Mailing City: OAK HILLS Facility Mailing State: CA Facility Mailing Zip Code: 923449200 Region Code: 4 Owner Name: JERRY BUTCHER Owner Address: 12135 SCARBROUGH CT Owner Address2: Not Reported Owner City: OAK HILLS Owner State: CA Owner Zip Code: 923449200 Owner Phone Number: 7609563770 Owner Fax Number: 7609566362 Contact Name: TONY MCKINNEY Contact Address: 12135 SCARBROUGH COURT Contact Address2: Not Reported Contact City: HESPERIA Contact State: CA Contact Zip Code: 92344 Contact Phone Number: 7609563770 NAICS Code: 81232 NAICS Description: Drycleaning and Laundry Services (except Coin-Operated) SIC Code: 7211 SIC Description: Power Laundries, Family and Commercial Reason: SIC/NAICS				

NAICS Code: 812331
NAICS Description: Linen Supply
SIC Code: 7213
SIC Description: Linen Supply
Reason: SIC/NAICS

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
RCRA-NON-US	Listed	0.19 miles SW	3645 ft	11
SITE NAME			MAPS	ID
DOUBLE EAGLE TRANSPORTATION			1,4	CAL000225630
ADDRESS			CITY	ZIP
12135 SCARBOROUGH CT			HESPERIA	92345
DETAILS				

Additional details may be found online using the following link:
https://enviro.epa.gov/enviro/rcrainfoquery_3.facility_information?pgm_sys_id=CAL000225630
Source Type: Implementer
Generator Status: Non-Generator
NAICS1: GENERAL FREIGHT TRUCKING
Active Site Indicator: H----
Owner Name: JERRY BUTCHER
Operator Name: TONY MCKINNEY
In Handler Universes: Y
In a Universe: Y
Universal Waste: Y
Universal Waste Destination Facility: Y

Receive Date: 20011218
Acknowledge Flag Date: 20011218
Contact First Name: TONY
Contact Last Name: MCKINNEY
Contact Street 1: 12135 SCARBROUGH COURT
Contact City: HESPERIA
Contact State: CA
Contact Zip: 92344
Contact Phone: 760-956-3770
Contact FAX: 760-956-6362
Contact E-mail Address: SAFETYDIRECTOR@DOUBLEEAGLETRANS.COM
Universal Waste Destination Facility: Y

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
UST-CA	Listed	0.19 miles SW	3645 ft	11
SITE NAME			MAPS	ID
DOUBLE EAGLE TRANSPORTATION			1,4	243095
ADDRESS			CITY	ZIP
12135 SCARBROUGH CT			HESPERIA	92345
DETAILS				
More Information on Site? Go to Following Link: http://geotracker.waterboards.ca.gov/search.asp CERSID: 10049065 Global ID: FA0008746 COUNTY: San Bernardino Permitting Agency: San Bernardino County Fire Department Agency Provided Latitude: 34.41259 Agency Provided Longitude: -117.398056 PROJECT TYPE: Not Reported RB Case Number: Not Reported LOC Case Number: Not Reported Case Worker: Not Reported MTBE DATE: Not Reported GW CONC (PPB): Not Reported MATRIX: Not Reported				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
UST-CRSP-CA	Listed	0.19 miles SW	3645 ft	11
SITE NAME			MAPS	ID
DOUBLE EAGLE TRANSPORTATION			1,4	391724
ADDRESS			CITY	ZIP
12135 SCARBROUGH CT			HESPERIA	92345
DETAILS				
Site Regulated Program Information Site ID: 391724 EI ID: 10049065 Agency Provided Address: 12135 SCARBROUGH CT				

Agency Provided Latitude: 34.41259

Agency Provided Longitude: -117.39805

Program Description: Underground Storage Tank

Evaluation Information (2017 to present)

Evaluation Date: 11/9/2021

Violations Found? (Y/N): No

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s):

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HMRRP

Evaluation Source: CERS

Evaluation Date: 11/9/2021

Violations Found? (Y/N): No

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s):

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HW

Evaluation Source: CERS

Evaluation Date: 8/17/2021

Violations Found? (Y/N): No

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): Annual UST inspection with MC and OPE

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: UST

Evaluation Source: CERS

Evaluation Date: 8/17/2020

Violations Found? (Y/N): No

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): Annual UST inspection with monitoring certification.

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: UST

Evaluation Source: CERS

Evaluation Date: 8/21/2019

Violations Found? (Y/N): No

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): UST INSPECTION & UST MONITORING CERTIFICATION

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: UST

Evaluation Source: CERS

Evaluation Date: 8/21/2019

Violations Found? (Y/N): No

Evaluation General Type: Other/Unknown

Evaluation Type: Other, not routine, done by local agency

Evaluation Note(s): UST OVERFILL INSPECTION

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: UST

Evaluation Source: CERS

Evaluation Date: 8/28/2018

Violations Found? (Y/N): No

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s):

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: UST

Evaluation Source: CERS

Evaluation Date: 8/22/2018

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s):

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HMRRP

Evaluation Source: CERS

Evaluation Date: 8/22/2018

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s):

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HW

Evaluation Source: CERS

Evaluation Date: 8/29/2017

Violations Found? (Y/N): No

Evaluation General Type: Other/Unknown

Evaluation Type: Other, not routine, done by local agency

Evaluation Note(s): SB 989 TESTING

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: UST

Evaluation Source: CERS

Evaluation Date: 8/29/2017

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency
Evaluation Note(s): ANNUAL UST INSPECTION AND CERS REVIEW
Evaluation Division: San Bernardino County Fire Department
Evaluation Program: UST
Evaluation Source: CERS

Violation Information (2017 to present)

Violation Date: 8/22/2018

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.

Violation Note(s): Returned to compliance on 12/05/2018. OBSERVATION: The facility hazardous material inventory lacks the listing of waste coolant and drained used oil filters, and also has inaccurate quantity amounts for "DEF", oil/absorbent and spent fuel filter waste, and gear oil. CORRECTIVE ACTION: Submit an accurate and complete hazardous materials inventory into the California Environmental Reporting System (CERS). Updated Business Plan hazardous material inventory was submitted to the "CERS" database on 12/5/2018. CB

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

Violation Source: CERS

Violation Date: 8/22/2018

Citation: 22 CCR 15 66265.192(a) - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.192(a)

Violation Description: Failure to obtain and maintain a written assessment reviewed and certified by an independent, qualified, professional engineer prior to placing the tank system in service. The written assessment shall state that, the new hazardous waste tank system has sufficient structural integrity, is acceptable for the transferring, storing and treating of hazardous waste, and that the tanks and containment system including the foundation, structural support, seams, connections, and pressure controls (if applicable) are suitably designed to meet the regulation.

Violation Note(s): OBSERVATION: A written hazardous waste tank assessment has not been obtained for the used oil aboveground storage tank system prior to placing system into service. CORRECTIVE ACTION: Obtain a written hazardous waste tank system assessment for the used oil tank system in accordance with 22 CCR 15 66265.192 and submit a copy to the CUPA.

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 8/22/2018

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit a site map with all required content.

Violation Note(s): Returned to compliance on 09/06/2018. OBSERVATION: The facility map lacks the listing of storm and sewer drains. CORRECTIVE ACTION: Submit an accurate and complete site map into the California Environmental Reporting System (CERS). Updated Business Plan submitted to the "CERS" database on 9/6/2018. CB

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

Violation Source: CERS

Violation Date: 8/22/2018

Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)

Violation Description: Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Violation Note(s): Returned to compliance on 08/22/2018. OBSERVATION: Two 55-gallon containers of hazardous waste spent paper filters located in the outside storage area near the used oil "ast" were observed without the required hazardous waste label. CORRECTIVE ACTION: Submit the signed Certificate of Compliance to the CUPA showing that the container listed above has been properly labeled. This violation was corrected during the inspection. CB

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 8/22/2018

Citation: 22 CCR 15 66265.16 - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.16

Violation Description: Failure to provide employees with hazardous waste training program of class room instructions or on-the-job training within the first six months after the date of their employment or assignment to a facility, or to a new position at a facility and annually thereafter. Training records on current personnel shall be kept until closure of the facility and for former employees the record shall be kept for at least three years from the date the employee last worked at the facility. The records shall include the following: the job title for each position at the facility related to hazardous waste management, and the name of the employee filling each job; a written job description for each position, duties of facility personnel assigned to each position, and a written description of the type and amount of both introductory and continuing training that will be given to each person filling a position.

Violation Note(s): OBSERVATION: Documented training of personnel was not available at the time of inspection.

CORRECTIVE ACTION: Locate training documentation or conduct training with applicable personnel and document it. Submit the signed Certificate of Compliance to show proof of compliance regarding this violation.

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 8/29/2017

Citation: 23 CCR 16 2712 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712

Violation Description: Failure to comply with any of the applicable requirements of the permit issued for the operation of the UST system.

Violation Note(s): Not Reported

Violation Division: San Bernardino County Fire Department

Violation Program: UST

Violation Source: CERS

Enforcement Information

Enforcement Action Date: 8/30/2016

Enforcement Action Type: Notice of Violation (Unified Program)

Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enforcement Action Note(s): Not Reported

Enforcement Action Division: San Bernardino County Fire Department

Enforcement Action Program: UST

Enforcement Action Source: CERS

Enforcement Action Date: 1/28/2015
Enforcement Action Type: Notice of Violation (Unified Program)
Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enforcement Action Note(s): Not Reported
Enforcement Action Division: San Bernardino County Fire Department
Enforcement Action Program: UST
Enforcement Action Source: CERS

Enforcement Action Date: 9/2/2014
Enforcement Action Type: Notice of Violation (Unified Program)
Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enforcement Action Note(s): Not Reported
Enforcement Action Division: San Bernardino County Fire Department
Enforcement Action Program: UST
Enforcement Action Source: CERS

Coordinate Information

: Not Reported

:

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
AST-CRSP-CA	Listed	0.21 miles S	3649 ft	12
SITE NAME			MAPS	ID
BEST LUBE TRUCK SERVICE & REPAIRS LLC			1,4	11970
ADDRESS			CITY	ZIP
8853 THREE FLAGS AVE STE C			HESPERIA	92344
DETAILS				
Site Regulated Program Information Site ID: 11970 EI ID: 10402582 Agency Provided Address: 8853 THREE FLAGS AVE STE C Agency Provided Latitude: 34.41111 Agency Provided Longitude: -117.39383 Program Description: Aboveground Petroleum Storage Evaluation Information (2017 to present) Evaluation Date: 11/4/2021 Violations Found? (Y/N): Yes Evaluation General Type: Compliance Evaluation Inspection				

Evaluation Type: Routine done by local agency

Evaluation Note(s):

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HMRRP

Evaluation Source: CERS

Evaluation Date: 11/4/2021

Violations Found? (Y/N): No

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s):

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HW

Evaluation Source: CERS

Evaluation Date: 2/13/2019

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s):

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HMRRP

Evaluation Source: CERS

Evaluation Date: 2/13/2019

Violations Found? (Y/N): No

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s):

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: APSA

Evaluation Source: CERS

Evaluation Date: 2/13/2019

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s):

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HW

Evaluation Source: CERS

Violation Information (2017 to present)

Violation Date: 11/4/2021

Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Section(s) 25508.2

Violation Description: Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.

Violation Note(s): Returned to compliance on 12/08/2021. OBSERVATION: The facility Hazardous Materials Business Plan was last certified via CERS on 3/2/2020. Your CERS ID number is 10402582. CORRECTIVE ACTION: Review and certify the

Hazardous Materials Business Plan electronically via CERS.

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

Violation Source: CERS

Violation Date: 2/13/2019

Citation: 22 CCR 15 66265.16 - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.16

Violation Description: Failure to provide employees with hazardous waste training program of class room instructions or on-the-job training within the first six months after the date of their employment or assignment to a facility, or to a new position at a facility and annually thereafter. Training records on current personnel shall be kept until closure of the facility and for former employees the record shall be kept for at least three years from the date the employee last worked at the facility. The records shall include the following: the job title for each position at the facility related to hazardous waste management, and the name of the employee filling each job; a written job description for each position, duties of facility personnel assigned to each position, and a written description of the type and amount of both introductory and continuing training that will be given to each person filling a position.

Violation Note(s): Returned to compliance on 03/13/2019. OBSERVATION: As demonstrated by the number and type of hazardous waste violations observed at the time of inspection, personnel are not adequately trained to perform their duties in a way that ensures the facility's compliance with hazardous waste laws and regulations, and/or employee training records have not been kept or do not contain all required information. CORRECTIVE ACTION: Conduct training with applicable personnel and document it according to the requirements of 22 CCR 15 66265.16(d). Submit the signed Certificate of Compliance to this Agency to show that the listed violation was corrected. Signed C of C proof of compliance statement received by email on 3/13/2019. CB

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 2/13/2019

Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)

Violation Description: Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Violation Note(s): Returned to compliance on 03/13/2019. OBSERVATION: Two used oil aboveground storage tanks (AST's) and a bulk container of waste coolant at the facility hazardous waste storage area lacked the required hazardous waste labeling; provide hazardous waste labels on the actual "AST's" or containers. CORRECTIVE ACTION: Properly label all hazardous waste containers and or "AST's" and submit the signed Certificate of Compliance to this Agency to show that the listed violation has been corrected. Signed C of C proof of compliance statement received by email on 3/13/2019. CB

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 2/13/2019

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.

Violation Note(s): Returned to compliance on 03/25/2019. OBSERVATION: Failure to accurately complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities; The following listed hazardous materials were not disclosed on the facility Business Plan: 2 - 55-gallon containers of oil/absorbent and paper oil filter waste. CORRECTIVE ACTION: Submit an accurate and complete hazardous materials

inventory via CERS and submit the signed Certificate of Compliance to this Agency to show proof that the listed violation has been corrected. "BP" update submitted to "CERS" database on 3/25/2019. CB

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

Violation Source: CERS

Violation Date: 2/13/2019

Citation: 22 CCR 15 66265.31 - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.31

Violation Description: Failure to maintain and operate the facility to minimize the possibility of a fire, explosion, or any unplanned sudden or non-sudden release of hazardous waste or hazardous waste constituents to air, soil, or surface water which could threaten human health or the environment.

Violation Note(s): Returned to compliance on 03/13/2019. OBSERVATION: Pooled liquid waste was observed on the floor of the secondary containment structure at the facility hazardous waste storage area. Note: liquid waste in secondary containment structures should be removed within 24 hours. CORRECTIVE ACTION: Properly clean up the the liquid waste and lawfully manage and dispose of any hazardous waste, and submit the signed Certificate of Compliance to this Agency to show that the listed violation has been corrected. Signed C of C proof oc compliance statement received by email on 3/13/2019. CB

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 2/13/2019

Citation: 22 CCR 15 66265.195(c) - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.195(c)

Violation Description: Failure to conduct and document inspections of hazardous waste tank systems each operating day and retain records of those inspections at the facility.

Violation Note(s): Returned to compliance on 03/13/2019. OBSERVATION: Daily inspections of the used oil "AST's" have not been conducted and documented. CORRECTIVE ACTION: Conduct daily tank inspections on the used oil "AST's" and submit the signed Certificate of Compliance to this Agency to show that the listed violation has been corrected. Signed C of C proof oc compliance statement received by email on 3/13/2019. CB

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Enforcement Information

Enforcement Action Date: 1/25/2016

Enforcement Action Type: Notice of Violation (Unified Program)

Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enforcement Action Note(s): Not Reported

Enforcement Action Division: San Bernardino County Fire Department

Enforcement Action Program: HMRRP

Enforcement Action Source: CERS

Enforcement Action Date: 1/25/2016

Enforcement Action Type: Notice of Violation (Unified Program)

Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enforcement Action Note(s): Not Reported

Enforcement Action Division: San Bernardino County Fire Department

Enforcement Action Program: APSA

Enforcement Action Source: CERS

Enforcement Action Date: 1/25/2016
Enforcement Action Type: Notice of Violation (Unified Program)
Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enforcement Action Note(s): Not Reported
Enforcement Action Division: San Bernardino County Fire Department
Enforcement Action Program: HW
Enforcement Action Source: CERS

Coordinate Information

: Not Reported

:

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CERS-CA	Listed	0.21 miles S	3649 ft	12
SITE NAME			MAPS	ID
BEST LUBE TRUCK SERVICE & REPAIRS LLC			1,4	10402582
ADDRESS			CITY	ZIP
8853 Three Flags Ave Ste C			Hesperia	92344

DETAILS

General Program & Facility Information

CERS ID: 10402582

Facility ID: FA0014891

Facility Regulator Key ID: FA0014891

Organization Code: 90364402

Business/Organization Name: BEST LUBE TRUCK SERVICE & REPAIRS LLC

Multiple Jurisdictional Business? (Y/N): No

Business Origin: Business

Count of Business CERS User Accounts: 1

Facility Count for Business: 1

Last Submittal Date (any element): 3/1/2018 7:42:32 PM

Count of Submitted Elements: 15

Remote Facility? (Y/N): No

Small Quantity Generator Facility? (Y/N): No

Local Facility Grouping: Not Reported

Facility Specific Information

Assessor Parcel Number (APN): Not Reported

Number of Employees: 5

Property Owner Name: Not Reported

Property Owner Phone Number: Not Reported

Property Owner Mailing Address: Not Reported
Property Owner Mailing City: Not Reported
Property Owner Mailing State: Not Reported
Property Owner Mailing Zip Code: Not Reported
Property Owner Mailing Country: Not Reported

Inspection Information

Aboveground Petroleum Storage Act (APSA) Last Inspection Date: 1/25/2016
California Accidental Release Prevention (CalARP) Last Inspection: Not Reported
Conditionally Authorized (CA) Last Inspection Date: Not Reported
Conditionally Exempt (CE) Last Inspection Date: Not Reported
Household Hazardous Waste Collection (HHW) Last Inspection Date: Not Reported
Hazardous Materials Release Response Plan (HMRRP) Last Inspection: 1/25/2016
Hazardous Waste Generator (HW) Last Inspection Date: 1/25/2016
RCRA Large Quantity Generator (HVLQG) Last Inspection Date: Not Reported
Hazardous Waste Recycler (HWRrecycler) Last Inspection Date: Not Reported
Permit By Rule (PBR) Last Inspection: Not Reported
Underground Storage Tank (UST) Last Inspection Date: Not Reported

Owner/Operator Information

Beginning Date: Not Reported
Ending Date: Not Reported
Phone Number: (760) 244-8033
Fax Number: (760) 244-8599
Supplemental Location: Not Reported
County: San Bernardino
Dun & Bradstreet D-U-N-S Number: Not Reported
SIC Code: 7538
NAICS Code: Not Reported
Mailing Address: 8853 Three Flags Ave Ste C
Mailing Address City: Hesperia
Mailing Address State Code: CA
Mailing Address Zip Code: 92344
Operator Name: Angelica Jimenez
Operator Phone Number: (661)400-4753
Owner Name: Francisco Jimenez
Owner Phone: (661) 400-4587
Owner Mailing Address: 37123 Calle Real St
Owner City: Palmdale
Owner State: CA
Owner Zip Code: 93550
Owner Country: United States
Environmental Contact Name: Francisco Jimenez
Environmental Contact Phone Number: (661) 400-4587
Environmental Contact Mailing Address: 37123 Calle Real St
Environmental Contact Email Address: Bestlubeservice@hotmail.com
Environmental Contact City: Palmdale
Environmental Contact State: CA

Environmental Contact Zip: 93550
Environmental Contact Country: United States
Primary Emergency Contact Name: Francisco Jimenez
Primary Emergency Contact Title: Owner
Primary Emergency Contact Business Phone Number: (760) 244-8033
Primary Emergency Contact 24Hr Phone: (661) 400-4587
Primary Emergency Contact Pager Number: Not Reported
Secondary Emergency Contact Name: Angelica Jimenez
Secondary Emergency Contact Title: Secretary/Owner's Daughter
Secondary Emergency Contact Business Phone: Not Reported
Secondary Emergency Contact 24Hr Phone: (661) 400-4753
Secondary Emergency Contact Pager Number: Not Reported
Additional Local Collected Info: Not Reported
Identification Signed Date: Not Reported
Document Preparer Name: ANGELICA JIMENEZ
Identification Signer Name: ANGELICA JIMENEZ
Identification Signer Title: Secretary
Billing Contact Name: Francisco Jimenez
Billing Contact Phone: (760) 244-8033
Billing Contact Email: Bestlubeservice@hotmail.com
Billing Address: 8853 Three Flags Ave Ste C
Billing City: Hesperia
Billing State: CA
Billing Zip: 92344
Billing Country: United States
Business Owner/Operator Regulator Key: Not Reported

Business Activity Information

EPA ID: CAL000372624
Hazardous Materials On Site? (Y/N): Y
CAL ARP Regulated Substances? (Y/N): N
Own or Operator USTs? (Y/N): N
Own or Operator APSTs? (Y/N): Y
Hazardous Waste Generator? (Y/N): Y
Recycles Materials? (Y/N): N
On-site HW Treatment? (Y/N): N
Financial Assurance? (Y/N): N
Remote Waste Consolidation Site? (Y/N): N
Hazardous Waste Tank Closure? (Y/N): N
RCRA Large Quantity Generator? (Y/N): Y
Household Hazardous Waste (HHW) Collection? (Y/N): N
Business Activity Comment(s): Not Reported

Submittal Information

Submitted Date/Time: 2/28/2017 7:44:21 PM
Submittal Action: Accepted
BP Activities Last Updated Date: 2/24/2017 1:00:46 PM
BP Owner/Operator Last Updated Date: 2/24/2017 1:00:46 PM

Submittal Action Comment 1: ACCEPTED AS COMPLETE PENDING FIELD VERIFICATION: Thank you for the submittal. While this submittal is being accepted as complete, the data has not been field verified and may require correction in the future. Please note, it is your responsibility to review and certify the information submitted in CERS annually. You must also update the information within 30 days of a change of owner, business address, business name, emergency contact information, inventory and/or other site conditions that could impact emergency response activity. If you have questions about using CERS, please contact the San Bernardino County Fire CERS Help Desk at (909) 386-8432. (Reviewed by Rudy Valencia, rvalencia@sbcfire.org or (909) 386-8401)

Submittal Action Comment 2: Not Reported

Facility Info Next Due Date: Not Reported

Biz Activities Regulator Key: Not Reported

Supplemental Geographic Information

Agency Provided Latitude: 34.41111

Agency Provided Longitude: -117.39383

Horizontal Accuracy: 300

Horizontal Collection Method: Address Matching

Geographic Reference Point: Facility Center/Centroid

Horizontal Reference Datum: WGS84 (World Geodetic System of 1984)

Data Collection Date: 5/18/2015 1:23:02 AM

Submittal Element Regulator Information

CUPA Regulator Code: 3600

Facility Info Reporting Requirement: Applicable

Facility Info Next Due Date: Not Reported

Facility Info Last Submitted Date: 3/1/2018 7:42:32 PM

Facility Info Accepted Date: 6/23/2017 1:05:05 PM

Inventory Regulator Code: 3600

Inventory Reporting Requirement: Applicable

Inventory Next Due Date: Not Reported

Inventory Last Submitted Date: 3/1/2018 7:42:32 PM

Inventory Last Accepted Date: 6/23/2017 1:05:47 PM

ER Training Regulator Code: 3600

ER Training Reporting Requirement: Applicable

ER Training Next Due Date: Not Reported

ER Training Last Submitted Date: 3/1/2018 7:42:32 PM

ER Training Last Accepted Date: 6/23/2017 1:05:44 PM

UST Regulator Code: 3600

UST Reporting Requirement: Not Applicable

UST Next Due Date: Not Reported

UST Last Submitted Date: Not Reported

UST Last Accepted Date: Not Reported

HW Treat Regulator Code: 3600

HW Treat Reporting Requirement: Not Applicable

HW Treat Next Due Date: Not Reported

HW Treat Last Submitted Date: Not Reported

HW Treat Last Accepted Date: Not Reported

RMR Regulator Code: 3600

RMR Reporting Requirement: Not Applicable

RMR Next Due Date: Not Reported
RMR Last Submitted Date: Not Reported
RMR Last Accepted Date: Not Reported
Consolidation Regulator Code: 3600
Consolidation Reporting Requirement: Not Applicable
Consolidation Next Due Date: Not Reported
Consolidation Last Submitted Date: Not Reported
Consolidation Last Accepted Date: Not Reported
Tank Closure Regulator Code: 3600
Tank Closure Reporting Requirement: Not Applicable
Tank Closure Next Due Date: Not Reported
Tank Closure Last Submitted Date: Not Reported
Tank Closure Last Accepted Date: Not Reported
APSA Regulator Code: 3600
APSA Reporting Requirement: Applicable
APSA Next Due Date: Not Reported
APSA Last Submitted Date: 3/1/2018 7:42:32 PM
APSA Last Accepted Date: 6/23/2017 1:05:48 PM
CalARP Regulator Code: 3600
CalARP Reporting Requirement: Not Applicable
CalARP Next Due Date: Not Reported
CalARP Last Submitted Date: Not Reported
CalARP Last Accepted Date: Not Reported

UST Facility and Program Information

: Not Reported

Tank & Monitoring Plan Information

: Not Reported

HMRRP & UST Violation Information

EPA ID: CAL000372624

RCRA LQG: Yes

Violation Date: 1/25/2016

Violation Type Number: 1010002

Class: Minor

Scheduled Return to Compliance Date: 2/24/2016

Actual Return to Compliance Date: 3/10/2016

Actual Return to Compliance Qualifier: Documented

Violation Comment: Not Reported

Violation Category: Administration/Documentation

Violation Name: Hazardous Materials Business Plan Submittal

Violation Description: Failure to complete and/or electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.

Violation Citation(s): 19 CCR 6.95 25505; HSC 6.95 25508(a)(1), 25508(d)

Violation Date: 1/25/2016

Violation Type Number: 1010008

Class: Class 2

Scheduled Return to Compliance Date: 2/24/2016

Actual Return to Compliance Date: 3/10/2016

Actual Return to Compliance Qualifier: Documented
Violation Comment: Not Reported
Violation Category: Administration/Documentation
Violation Name: Annual Review / Certification
Violation Description: Failure to annually review and electronically certify that the business plan is complete, accurate, and up-to-date.
Violation Citation(s): HSC 6.95 25508(c), 25508.2

HMRRP & UST Inspection Information
EPA ID: CAL000372624
RCRA LQG: Yes
Inspection Date: 1/25/2016
Inspection Type: Routine
Number of Class I Violations: 0
Number of Class II Violations: 1
Number of Minor Violations: 1
Significant Operational Compliance: With both Release Detection and Release Prevention
Date Returned to Compliance: 3/10/2016
Days Out of Compliance: 45
Violation Details Available: Yes
Inspection Comments: INSPECTION OF BEST LUBE TRUCK SERVICE & REPAIRS LLC IN HESPERIA.

HMRRP & UST Enforcement Information
Type of Enforcement Action: Notice of Violation (NOV) Only
Date of Enforcement Action: 1/25/2016
Type of Formal Enforcement Action: Not Reported
Date a Referred Case Settled or Dropped: Not Reported
Docket Number: Not Reported
Final Fine or Penalty Assessed: Not Reported
Supplemental Environmental Projects Value: Not Reported
Count of Linked Class I Violations: 0
Count of Linked Class II Violations: 1
Count of Linked Minor Violations: 1
Red Tag Issued: No
Red Tag Number: Not Reported
Violations Causing Red Tag: Not Reported
Date Red Tag Affixed: Not Reported
Date Red Tag Removed: Not Reported
Enforcement Comments: Not Reported

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
County-AST-CA	Listed	0.21 miles S	3649 ft	12

SITE NAME	MAPS	ID
BEST LUBE TRUCK SERVICE & REPAIRS LLC	1,4	FA0014891-SBD
ADDRESS	CITY	ZIP
8853 THREE FLAGS AVE UNIT C	Hesperia	92344
DETAILS		
County: San Bernardino Responsible Agency: San Bernardino Division of Environmental Health Services Facility ID: FA0014891 Address2: Not Reported Owner Information: Francisco Jimenez Contact Name: FRANCISCO JIMENEZ Mailing Address: 8853 Three Flags Ave Ste C, Hesperia, CA 92344 Mailing Address2: Not Reported Permit ID: PT0031853 Program Element Code: 4031 Permit Description: APSA 1,320-10,000 GAL FAC CAPACITY Status: ACTIVE To: 2/28/2019		

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CRSP-CA	Listed	0.21 miles S	3649 ft	12
SITE NAME			MAPS	ID
BEST LUBE TRUCK SERVICE & REPAIRS LLC			1,4	11970
ADDRESS			CITY	ZIP
8853 THREE FLAGS AVE STE C			HESPERIA	92344
DETAILS				
Site Regulated Program Information Site ID: 11970 Site EI ID: 10402582 Agency Provided Latitude: 34.41111 Agency Provided Longitude: -117.39383 Program Description: Aboveground Petroleum Storage Program Description: Chemical Storage Facilities				

Program Description: Hazardous Waste Generator

Program Description: RCRA LQ HW Generator

Evaluation Information

Evaluation Date: 1/25/2016

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): INSPECTION OF BEST LUBE TRUCK SERVICE & REPAIRS LLC IN HESPERIA.

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: APSA

Evaluation Source: CERS

Evaluation Date: 1/25/2016

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): INSPECTION OF BEST LUBE TRUCK SERVICE & REPAIRS LLC IN HESPERIA.

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HMRRP

Evaluation Source: CERS

Evaluation Date: 1/25/2016

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): INSPECTION OF BEST LUBE TRUCK SERVICE & REPAIRS LLC IN HESPERIA.

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HW

Evaluation Source: CERS

Violation Information

Violation Date: 1/25/2016

Citation: HSC 6.5 Multiple Sections - California Health and Safety Code, Chapter 6.5, Section(s) Multiple Sections

Violation Description: Haz Waste Generator Program - Operations/Maintenance - General

Violation Note(s): Returned to compliance on 02/24/2016. Failure to keep hazardous waste containers closed when not in active use (CCR 66265.173(a))

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 1/25/2016

Citation: HSC 6.5 Multiple Sections - California Health and Safety Code, Chapter 6.5, Section(s) Multiple Sections

Violation Description: Haz Waste Generator Program - Operations/Maintenance - General

Violation Note(s): Returned to compliance on 02/24/2016. Failure to label hazardous waste containers (CCR 66262.34(f)(3))

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 1/25/2016

Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple

Violation Description: Haz Waste Generator Program - Training - General

Violation Note(s): Returned to compliance on 03/10/2016. Failure to train facility personnel in hazardous waste management procedures (CCR 66265.16)

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 1/25/2016

Citation: HSC 6.5 Multiple Sections - California Health and Safety Code, Chapter 6.5, Section(s) Multiple Sections

Violation Description: Haz Waste Generator Program - Operations/Maintenance - General

Violation Note(s): Returned to compliance on 02/24/2016. Failure to complete hazardous waste labels (CCR 66262.34(f)(3))

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 1/25/2016

Citation: HSC 6.5 Multiple Sections - California Health and Safety Code, Chapter 6.5, Section(s) Multiple Sections

Violation Description: Haz Waste Generator Program - Operations/Maintenance - General

Violation Note(s): Returned to compliance on 02/24/2016. Failure to operate and maintain facility to prevent a fire, spill or release (CCR 66265.31)

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 1/25/2016

Citation: HSC 6.95 25508(d) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(d)

Violation Description: Failure to complete and/or electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.

Violation Note(s): Returned to compliance on 03/10/2016.

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

Violation Source: CERS

Violation Date: 1/25/2016

Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)

Violation Description: Failure to prepare and implement a Spill Prevention Control and Countermeasure (SPCC) Plan .

Violation Note(s): Returned to compliance on 03/10/2016.

Violation Division: San Bernardino County Fire Department

Violation Program: APSA

Violation Source: CERS

Violation Date: 1/25/2016

Citation: 22 CCR 16 66266.130 - California Code of Regulations, Title 22, Chapter 16, Section(s) 66266.130

Violation Description: Failure to properly handle, manage, label, and recycle used oil and fuel filters.

Violation Note(s): Returned to compliance on 02/24/2016.

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 1/25/2016

Citation: HSC 6.5 Multiple Sections - California Health and Safety Code, Chapter 6.5, Section(s) Multiple Sections

Violation Description: Haz Waste Generator Program - Operations/Maintenance - General

Violation Note(s): Returned to compliance on 02/24/2016. Failure to note accumulation start date on labels (CCR 66262.34(f)(2))

Violation Division: San Bernardino County Fire Department

Violation Program: HW

Violation Source: CERS

Violation Date: 1/25/2016

Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Section(s) 25508.2

Violation Description: Failure to annually review and electronically certify that the business plan is complete, accurate, and up-to-date.

Violation Note(s): Returned to compliance on 03/10/2016.

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

Violation Source: CERS

Enforcement Information

Enforcement Action Date: 1/25/2016

Enforcement Action Type: Notice of Violation (Unified Program)

Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enforcement Action Note(s): Not Reported

Enforcement Action Division: San Bernardino County Fire Department

Enforcement Action Program: HW

Enforcement Action Source: CERS

Enforcement Action Date: 1/25/2016

Enforcement Action Type: Notice of Violation (Unified Program)

Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enforcement Action Note(s): Not Reported

Enforcement Action Division: San Bernardino County Fire Department

Enforcement Action Program: HMRRP

Enforcement Action Source: CERS

Enforcement Action Date: 1/25/2016

Enforcement Action Type: Notice of Violation (Unified Program)

Enforcement Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection

Enforcement Action Note(s): Not Reported
Enforcement Action Division: San Bernardino County Fire Department
Enforcement Action Program: APSA
Enforcement Action Source: CERS

Chemical Information
: Not Reported
:Coordinate Information
: Not Reported
:

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CUPA-CA	Listed	0.21 miles S	3649 ft	12
SITE NAME			MAPS	ID
BEST LUBE TRUCK SERVICE & REPAIRS LLC			1,4	FA0014891-SBD
ADDRESS			CITY	ZIP
8853 THREE FLAGS AVE UNIT C			Hesperia	92344
DETAILS				
County: San Bernardino Responsible Agency: San Bernardino County Fire Department Facility ID: FA0014891 Address2: Not Reported Owner Information: Francisco Jimenez Contact Name: FRANCISCO JIMENEZ Mailing Address: 8853 Three Flags Ave Ste C, Hesperia, CA 92344 Mailing Address 2: Not Reported Agency Provided Latitude: Not Reported Agency Provided Longitude: Not Reported Permit ID: PT0025928 Program Element Code: 4243 Permit Description: HAZARDOUS MATERIALS 4-10 CHEMICALS Status: ACTIVE To: 2/28/2020 Permit ID: PT0025929 Program Element Code: 4454 Permit Description: LARGE QUANTITY GENERATOR Status: ACTIVE To: 2/28/2020 Permit ID: PT0031853				

Program Element Code: 4031
Permit Description: APSA 1,320-10,000 GAL FAC CAPACITY
Status: ACTIVE
To: 2/28/2020

Permit ID: PT0037301
Program Element Code: 4300
Permit Description: RCRA LQG GENERAL ACTIVITY(NB)
Status: FEE EXEMPT
To: 2/28/2018

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
Hist-Auto Repair	Listed	0.21 miles S	3649 ft	12
SITE NAME			MAPS	ID
CAJON TIRE SVC			1,4	17338
ADDRESS			CITY	ZIP
8853 THREE FLAGS AVE B			Hesperia	92344
DETAILS				
Sic Code: 5531 Desc: Auto, Truck & Tire Service Site Added: 2/2010				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
Hist-Auto Repair	Listed	0.21 miles S	3649 ft	12
SITE NAME			MAPS	ID
WEST COAST TIRES & TRUCK RPR			1,4	23876
ADDRESS			CITY	ZIP
8853 THREE FLAGS AVE B			Hesperia	92344
DETAILS				
Sic Code: 5531 Desc: Auto, Truck & Tire Service Site Added: 2/2010				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
RCRA-NON-US	Listed	0.21 miles S	3649 ft	12
SITE NAME			MAPS	ID
BEST LUBE TRUCK SERVICE & REPAIRS LLC			1,4	CAL000372624
ADDRESS			CITY	ZIP
8853 THREE FLAGS AVE UNIT C			HESPERIA	92345
DETAILS				
Additional details may be found online using the following link: https://enviro.epa.gov/enviro/rcrainfoquery_3.facility_information?pgm_sys_id=CAL000372624 Source Type: Implementer Generator Status: Non-Generator NAICS1: GENERAL AUTOMOTIVE REPAIR Active Site Indicator: H---- Owner Name: FRANCISCO A JIMENEZ Operator Name: ANGELICA N JIMENEZ In Handler Universes: Y In a Universe: Y Universal Waste: Y Universal Waste Destination Facility: Y Receive Date: 20120313 Acknowledge Flag Date: 20120313 Contact First Name: ANGELICA Contact Last Name: N JIMENEZ Contact Street 1: 37123 CALLE REAL ST Contact City: PALMDALE Contact State: CA Contact Zip: 93550 Contact Phone: 661-400-4753 Contact FAX: 760-244-8599 Contact E-mail Address: BESTLUBESERVICE@HOTMAIL.COM Universal Waste Destination Facility: Y				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
School-Other-CA	NO ACTION REQUIRED	0.48 miles SE	3598 ft	13
SITE NAME			MAPS	ID

NEW MESQUITE TRAILS WEST ELEMENTARY SCHOOL	1,4	70000125
ADDRESS	CITY	ZIP
12850 MUSCATEL STREET	HESPERIA	92345
DETAILS		
URL: http://www.envirostor.dtsc.ca.gov/public/profile_report.asp?global_id=70000125 Envirostor ID: 70000125 Agency Provided Address: 12850 MUSCATEL STREET County: SAN BERNARDINO Site Type: SCHOOL INVESTIGATION Site Type Detailed: SCHOOL Acres: 7 Assessor's Parcel Number: 3064-631-07 National Priorities List: NO Lead Agency: SMBRP Project Manager: Not Reported Supervisor: SHAHIR HADDAD Division Branch: SOUTHERN CALIFORNIA SCHOOLS & BROWNFIELDS OUTREACH Site Code: 404669 Assembly: 33 Senate: 21 Congressional District: 8 Special Program: Not Reported Status: NO ACTION REQUIRED Status Date: 11/16/2005 Past Uses: NONE Restricted Use: NO Funding: SCHOOL DISTRICT Regulatory Agencies Involved: SMBRP Potential Contamination of Concern: NONE SPECIFIED,31000 Confirmed Contamination of Concern: NONE SPECIFIED Potential Media Affected: NMA Site Management Requirements: NONE SPECIFIED Agency Provided Latitude: 34.4124988 Agency Provided Longitude: -117.3818021 Description: The details below (if any) are all either Future, Scheduled, and/or Completed Activities on the site Area Name: PROJECT WIDE Sub Area Name: Not Reported Document Type: COST RECOVERY CLOSEOUT MEMO Due Date: Not Reported Completed Date: 11/16/2005 Activity Comments: Not Reported Description: The details below (if any) are all either Future, Scheduled, and/or Completed Activities on the site Area Name: PROJECT WIDE Sub Area Name: Not Reported Document Type: PHASE 1		

Due Date: Not Reported
Completed Date: 11/16/2005
Activity Comments: PHASE I REVIEW COMPLETE.

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
LUST-Closed-CA	COMPLETED - CASE CLOSED	0.5 miles SW	3678 ft	14
SITE NAME			MAPS	ID
PILOT #381			1,4	T0607144072
ADDRESS			CITY	ZIP
8701 HIGHWAY 395			HESPERIA	92345
DETAILS				
Sites Details URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607144072 Global ID: T0607144072 Case Type: LUST CLEANUP SITE Status: COMPLETED - CASE CLOSED Agency Provided Address: 8701 HIGHWAY 395 Status Date: 3/18/2009 Cleanup Fund Case: NO Lead Agency: SAN BERNARDINO COUNTY Case Worker: JC Local Agency: SAN BERNARDINO COUNTY Resolution Case Number: 6B3601044T Location Case Number: T06071 File Location: Not Reported Potential Contaminants of Concern: DIESEL Potential Media Affected: UNDER INVESTIGATION Site History: Not Reported Begin Date: 6/11/2007 How Discovered: OTHER MEANS How Discovered Description: LEAK IN PRODUCT LINES OBSERVED WHEN PRESSURIZED FOR TESTING. THERE WAS NO LEAKING OBSERVED DURING NORMAL OPERATIONS. A LEAK IN AND IN-LINE VALVE IN A SUMP WAS OBSERVED. PILOT HAS ORDERED PARTS FOR REPAIR. Stop Method: OTHER MEANS Stop Method Description: Not Reported Agency Provided Latitude: 34.4099215 Agency Provided Longitude: -117.3991492				
Regulatory Activities Details				

Action Date: 6/11/2007

Action Type: Other

Action: Leak Began

Action Date: 6/11/2007

Action Type: Other

Action: Leak Discovery

Action Date: 6/21/2007

Action Type: Other

Action: Leak Reported

Action Date: 11/15/2007

Action Type: ENFORCEMENT

Action: Closure/No Further Action Letter

Action Date: 11/15/2007

Action Type: ENFORCEMENT

Action: Staff Letter

Status History Details

Status Date: 3/18/2009

Status: COMPLETED - CASE CLOSED

Status Date: 2/5/2009

Status: OPEN - INACTIVE

Status Date: 11/15/2007

Status: COMPLETED - CASE CLOSED

Status Date: 6/11/2007

Status: OPEN - CASE BEGIN DATE

Status Date: 6/11/2007

Status: OPEN - VERIFICATION MONITORING

Contact Details

Note: Contacts were last updated in 2021

Contact Type: REGIONAL BOARD CASEWORKER

Contact Name: TAMMY LUNDQUIST

Organization Name: LAHONTAN RWQCB (REGION 6T)

Contact Address: 2501 LAKE TAHOE BLVD.

Contact City: SOUTH LAKE TAHOE

Contact Email: TAMMY.LUNDQUIST@WATERBOARDS.CA.GOV

Contact Phone Number: 5305425400

Methyl tertiary-butyl ether/Region Details

: Not Reported

RecCheck

The Standard for ASTM/AAI Radius Searches

(One Mile Environmental Records Search, Exceeds ASTM 1527/1528 and EPA All Appropriate Inquiry)

Area Report Results

REPORT RESULTS



Site Location:

Apns 3064-591-12, -13, 17, -18 And 3064-631-01
Hesperia, CA 92344
(N 34-24-54, W 117-23-32) NAD83

Client:

UltraSystems Environmental Inc.

TABLE OF CONTENTS

<u>EXECUTIVE SUMMARY</u>	<u>1</u>
<u>SUMMARY OF OCCURRENCES</u>	<u>3</u>
<u>POTENTIAL AREAS OF CONCERN/CONTAMINATION SUMMARY</u>	<u>9</u>
<u>DATABASE OCCURRENCE SUMMARY</u>	<u>9</u>
<u>SITE LOCATION TOPOGRAPHIC MAP</u>	<u>18</u>
<u>SITE LOCATION MAP</u>	<u>19</u>
<u>1-MILE RADIUS STREET MAP W/OCCURRENCES (MAP1)</u>	<u>20</u>
<u>GRID LAYOUT MAP KEY</u>	<u>21</u>
<u>GRID MAP 101</u>	<u>22</u>
<u>GRID MAP 102</u>	<u>23</u>
<u>GRID MAP 103</u>	<u>24</u>
<u>GRID MAP 104</u>	<u>25</u>
<u>GRID MAP 105</u>	<u>26</u>
<u>GRID MAP 106</u>	<u>27</u>
<u>GRID MAP 107</u>	<u>28</u>
<u>GRID MAP 108</u>	<u>29</u>
<u>GRID MAP 109</u>	<u>30</u>
<u>1-MILE TOPOGRAPHIC MAP W/OCCURRENCES (MAP4)</u>	<u>31</u>
<u>AGENCY DIFFERENCES IN MAPPED LOCATIONS (MAP5)</u>	<u>32</u>
<u>SUMMARY OF AGENCY DIFFERENCES</u>	<u>33</u>
<u>MAPPED AIR PERMITS WITH POTENTIAL DISPERSION (MAP6)</u>	<u>35</u>
<u>LISTED OCCURRENCE DETAILS</u>	<u>36</u>
<u>RECORDS SOURCES SEARCHED</u>	<u>92</u>
<u>UN-MAPPABLE OCCURRENCES</u>	<u>107</u>
<u>DISCLAIMER, LIMITS AND LIABILITIES</u>	<u>108</u>

EXECUTIVE SUMMARY

INFORMATION ON THE REQUESTED LOCATION

Site Address:	Apns 3064-591-12, -13, 17, -18 And 3064-631-01 Hesperia, CA 92344
Client Project Name/Number:	Cargo Solutions-Truck Warehouse 7187
Coordinates:	N 34-24-54, W 117-23-32 (NAD 83) 34.4149538155935, -117.392229114202
Date of Report	September 15, 2022
ERS Project Number:	2104769356
Subject Site Listed on the following lists:	Not Listed
Subject Site Listed as Map ID#:	N/A
USGS 7.5 Minute Quad Map:	Baldy Mesa (Date Unavailable)
Subject Site Located within a Potential Area of Concern:	No
Township, Section and Range:	Township: 04N Range: 05W Section: 22 Baseline: San Bernardino
Site Elevation: (feet above or below (-) mean sea level)	Approximately 3618 ft near the center of the area.
Flood Zone: (Digital Flood Insurance Rate Maps - DFIRMs) Only available digital data is provided	Panel: 06071C6475H, Effective Date: 8/28/2008 Zone X - Area of minimal flood hazard, usually depicted on FIRMs as above the 500-year flood level.
Fire Insurance Map Coverage:	There may be coverage of your site.
Radon Information:	EPA Radon Zone: 2 (Predicted avg for county: 2 to 4 pCi/L) For zip code 92344: Number of tests per zip code: 1 Number of tests where radon is > 4 pCi/L: 0 Percentage of test where radon is > 4 pCi/L: 0.00% Other Information: Not Reported
Search Radius Expansion Size: (In Miles)	0

Soil Type: (USDA Soil Survey Geographic Database) (SSURGO)	Map Unit Name: HESPERIA LOAMY FINE SAND, 2 TO 5 PERCENT SLOPES Map Unit Type: Consociation Drainage Class - Dominant Condition: Well drained General Information: Coarse-loamy, mixed, nonacid, thermic Xeric Torriorthents Top 3 Map Unit Components are below (if available): Component Name: Wrightwood, Cajon, Hesperia Component Percentage: 5%, 5%, 85% Hydric: No, No, No
Zip Codes Searched for "Un-Mappable" Sites:	Not Researched
Occurrence Count:	62

SUMMARY OF OCCURRENCES

MAP ID	ID/SITE NAME	ADDRESS	DATABASE	STATUS	DISTANCE (MILES)	ELEV DIFF (FEET)
1 Maps: 1, 4	338278 B & D Industrial Park	Popular St & Three Flags Ave Hesperia	Hist-CA	No Longer Listed	0.01 NW	N/A
2 Maps: 1, 4	10400761 High Desert Truck and Trailer	8995 Three Flags Ave Hesperia	CERS-CA	Listed	0.03 S	N/A
2 Maps: 1, 4	169689 High Desert Truck and Trailer	8995 THREE FLAGS AVE HESPERIA	CRSP-CA	Listed	0.03 S	N/A
2 Maps: 1, 4	110065650352 VVG FACILITY #7	8995 THREE FLAGS AVE HESPERIA	FRS-US	Listed	0.03 S	N/A
2 Maps: 1, 4	278713 Tanks Ent LLC	8995 Three Flags Avenue Hesperia	Hist-CA	No Longer Listed	0.03 S	N/A
2 Maps: 1, 4	CAL000320679 HIGH DESERT TRUCK & TRAILER	8995 THREE FLAGS AVE STE B&C VICTORVILLE	HWIS-CA	Listed	0.03 S	N/A
2 Maps: 1, 4	CAL000320679 HIGH DESERT TRUCK & TRAILER	8995 THREE FLAGS AVE STE B&C VICTORVILLE	RCRA-NON-US	Listed	0.03 S	N/A
3 Maps: 1, 4	FA0011408-SBD THE LITZENBERGER COMPANY	12221 POPLAR ST 14 HESPERIA	CUPA-CA	Listed	0.04 W	N/A
4 Maps: 1, 4	10762693 Superior Pool Products LLC #548A	12221 Poplar St Bldg E Hesperia	CERS-CA	Listed	0.06 W	N/A
4 Maps: 1, 4	437884 Superior Pool Products LLC #548A	12221 POPLAR ST BLDG E HESPERIA	CRSP-CA	Listed	0.06 W	N/A
5 Maps: 1, 4	842-MD Zippy Lube	8899 Three Flags Avenue Hesperia	AIR-DIST-CA	Listed	0.06 S	N/A
5 Maps: 1, 4	177957-SC IRONMAN RENEWAL LLC	8899 THREE FLAGS HESPERIA	AIR-DIST-CA	Listed	0.06 S	N/A

MAP ID	ID/SITE NAME	ADDRESS	DATABASE	STATUS	DISTANCE (MILES)	ELEV DIFF (FEET)
5 Maps: 1, 4	172882 ZIPPY LUBE-A- TRUCK	8899 THREE FLAGS AVE HESPERIA	AST-CRSP-CA	Listed	0.06 S	N/A
5 Maps: 1, 4	10128901 Little Sister's Truck Wash	8899 Three Flags Ave Hesperia	CERS-CA	Listed	0.06 S	N/A
5 Maps: 1, 4	10049617 ZIPPY LUBE-A- TRUCK	8899 Three Flags Ave Hesperia	CERS-CA	Listed	0.06 S	N/A
5 Maps: 1, 4	FA0009125-SBD ZIPPY LUBE-A- TRUCK	8899 THREE FLAGS AVE B Hesperia	County-AST-CA	Listed	0.06 S	N/A
5 Maps: 1, 4	172882 ZIPPY LUBE-A- TRUCK	8899 THREE FLAGS AVE HESPERIA	CRSP-CA	Listed	0.06 S	N/A
5 Maps: 1, 4	130941 Little Sister's Truck Wash	8899 THREE FLAGS AVE HESPERIA	CRSP-CA	Listed	0.06 S	N/A
5 Maps: 1, 4	FA0010378-SBD Little Sister's Truck Wash	8899 THREE FLAGS AVE Hesperia	CUPA-CA	Listed	0.06 S	N/A
5 Maps: 1, 4	FA0009125-SBD ZIPPY LUBE-A- TRUCK	8899 THREE FLAGS AVE B Hesperia	CUPA-CA	Listed	0.06 S	N/A
5 Maps: 1, 4	110066395494 LITTLE SISTER'S TRUCK WASH	8899 THREE FLAGS AVE HESPERIA	FRS-US	Listed	0.06 S	N/A
5 Maps: 1, 4	110033211245 ZIPPY LUBE-A- TRUCK, INC.	8899B THREE FLAGS AVENUE HESPERIA	FRS-US	Listed	0.06 S	N/A
5 Maps: 1, 4	110066206484 ZIPPY LUBE-A- TRUCK	8899 THREE FLAGS AVE HESPERIA	FRS-US	Listed	0.06 S	N/A
5 Maps: 1, 4	FA0010378-SBD LITTLE SISTERS TRUCK WASH	8899 THREE FLAGS AVE HESPERIA	Hist-CA	Name Changed	0.06 S	N/A
5 Maps: 1, 4	CAL000344771 IRONMAN RENEWAL DBA ZIPPY LUBE A TRUCK	8899 THREE FLAGS AVE OAK HILLS	Hist-CA	No Longer Listed	0.06 S	N/A

MAP ID	ID/SITE NAME	ADDRESS	DATABASE	STATUS	DISTANCE (MILES)	ELEV DIFF (FEET)
5 Maps: 1, 4	54FDFFA-CAL000344771 IRONMAN RENEWAL DBA ZIPPY LUBE A TRUCK	8899 THREE FLAGS AVE OAK HILLS	Hist-CA	No Longer Listed	0.06 S	N/A
5 Maps: 1, 4	CAL000416670 ANELLE MANAGEMENT SERVICES INC DBA FLEET CREW	8899 THREE FLAGS AVE HESPERIA	Hist-CA	No Longer Listed	0.06 S	N/A
5 Maps: 1, 4	CAL000416670 FLEETCREW	8899 THREE FLAGS AVE HESPERIA	HWIS-CA	Listed	0.06 S	N/A
5 Maps: 1, 4	CAL000353253 LITTLE SISTERS TRUCK WASH INC	8899 THREE FLAGS AVE OAK HILLS	RCRA-NON-US	Listed	0.06 S	N/A
5 Maps: 1, 4	CAL000416670 ANELLE MANAGEMENT SERVICES INC DBA FLEET	8899 THREE FLAGS AVE HESPERIA	RCRA-NON-US	Listed	0.06 S	N/A
6 Maps: 1, 4	FA0012792-SBD DESERT DYNAMICS OFFROAD	12221 POPLAR ST BLDG B-10 HESPERIA	CUPA-CA	Listed	0.06 W	N/A
7 Maps: 1, 4	10311793 3M OAK HILLS	12221 POPLAR ST UNIT D20 OAK HILLS	CERS-CA	Listed	0.08 W	N/A
7 Maps: 1, 4	617 3M OAK HILLS	12221 POPLAR ST UNIT D20 OAK HILLS	CRSP-CA	Listed	0.08 W	N/A
7 Maps: 1, 4	FA0013596-SBD 3M OAK HILLS	12221 POPLAR ST UNIT D20 OAK HILLS	CUPA-CA	Listed	0.08 W	N/A
8 Maps: 1, 4	FA0016142-SBD High Desert Truck and Trailer	8895 THREE FLAGS AVE Hesperia	CUPA-CA	Listed	0.11 SW	N/A
9 Maps: 1, 4	10312237 DIRECTV	12269 SCARBROUGH CT HESPERIA	CERS-CA	Listed	0.11 S	N/A
9 Maps: 1, 4	FA0008728-SBD CDM CONSTRUCTORS INC.	12269 SCARBROUGH CT HESPERIA	CUPA-CA	Listed	0.11 S	N/A

MAP ID	ID/SITE NAME	ADDRESS	DATABASE	STATUS	DISTANCE (MILES)	ELEV DIFF (FEET)
9 Maps: 1, 4	FA0013884-SBD DIRECTV	12269 SCARBROUGH CT HESPERIA	CUPA-CA	Listed	0.11 S	N/A
9 Maps: 1, 4	FA0012098-SBD 3M OAK HILLS REMOTE STORAGE	12269 SCARBROUGH CT HESPERIA	CUPA-CA	Listed	0.11 S	N/A
10 Maps: 1, 4	10609933 RV Supply Center, Inc	8893 Three Flags Ave Ste B Oak Hills	CERS-CA	Listed	0.12 SW	N/A
10 Maps: 1, 4	277513 RV Supply Center, Inc	8893 THREE FLAGS AVE STE B OAK HILLS	CRSP-CA	Listed	0.12 SW	N/A
10 Maps: 1, 4	FA0016222-SBD RV Supply Center, Inc	8893 Three Flags Ave Ste B Oak Hills	CUPA-CA	Listed	0.12 SW	N/A
10 Maps: 1, 4	16670 WINGFOOT COMMERCIAL TIRE SYSTS	8893 THREE FLAGS AVE Hesperia	Hist-Auto Repair	Listed	0.12 SW	N/A
10 Maps: 1, 4	CAL000307361 RV SUPPLY CENTER INC	8893 THREE FLAGS AVE STE B OAK HILLS	RCRA-NON-US	Listed	0.12 SW	N/A
11 Maps: 1, 4	10049065 DOUBLE EAGLE TRANSPORTATIO N	12135 SCARBROUGH CT HESPERIA	CERS-CA	Listed	0.19 SW	N/A
11 Maps: 1, 4	FA0008746-SBD DOUBLE EAGLE TRANSPORTATIO N	12135 SCARBROUGH CT HESPERIA	County-UST-CA	Listed	0.19 SW	N/A
11 Maps: 1, 4	391724 DOUBLE EAGLE TRANSPORTATIO N	12135 SCARBROUGH CT HESPERIA	CRSP-CA	Listed	0.19 SW	N/A
11 Maps: 1, 4	FA0008746-SBD DOUBLE EAGLE TRANSPORTATIO N	12135 SCARBROUGH CT HESPERIA	CUPA-CA	Listed	0.19 SW	N/A
11 Maps: 1, 4	CAL000225630 DOUBLE EAGLE TRANSPORTATIO N	12135 SCARBOROUGH CT HESPERIA	DryCleaners-CA	Listed	0.19 SW	N/A

MAP ID	ID/SITE NAME	ADDRESS	DATABASE	STATUS	DISTANCE (MILES)	ELEV DIFF (FEET)
11 Maps: 1, 4	CAL000225630 DOUBLE EAGLE TRANSPORTATIO N	12135 SCARBOROUGH CT HESPERIA	RCRA-NON-US	Listed	0.19 SW	N/A
11 Maps: 1, 4	243095 DOUBLE EAGLE TRANSPORTATIO N	12135 SCARBROUGH CT HESPERIA	UST-CA	Listed	0.19 SW	N/A
11 Maps: 1, 4	391724 DOUBLE EAGLE TRANSPORTATIO N	12135 SCARBROUGH CT HESPERIA	UST-CRSP-CA	Listed	0.19 SW	N/A
12 Maps: 1, 4	11970 BEST LUBE TRUCK SERVICE & REPAIRS LLC	8853 THREE FLAGS AVE STE C HESPERIA	AST-CRSP-CA	Listed	0.21 S	N/A
12 Maps: 1, 4	10402582 BEST LUBE TRUCK SERVICE & REPAIRS LLC	8853 Three Flags Ave Ste C Hesperia	CERS-CA	Listed	0.21 S	N/A
12 Maps: 1, 4	FA0014891-SBD BEST LUBE TRUCK SERVICE & REPAIRS LLC	8853 THREE FLAGS AVE UNIT C Hesperia	County-AST-CA	Listed	0.21 S	N/A
12 Maps: 1, 4	11970 BEST LUBE TRUCK SERVICE & REPAIRS LLC	8853 THREE FLAGS AVE STE C HESPERIA	CRSP-CA	Listed	0.21 S	N/A
12 Maps: 1, 4	FA0014891-SBD BEST LUBE TRUCK SERVICE & REPAIRS LLC	8853 THREE FLAGS AVE UNIT C Hesperia	CUPA-CA	Listed	0.21 S	N/A
12 Maps: 1, 4	17338 CAJON TIRE SVC	8853 THREE FLAGS AVE B Hesperia	Hist-Auto Repair	Listed	0.21 S	N/A
12 Maps: 1, 4	23876 WEST COAST TIRES & TRUCK RPR	8853 THREE FLAGS AVE B Hesperia	Hist-Auto Repair	Listed	0.21 S	N/A
12 Maps: 1, 4	CAL000372624 BEST LUBE TRUCK SERVICE & REPAIRS LLC	8853 THREE FLAGS AVE UNIT C HESPERIA	RCRA-NON-US	Listed	0.21 S	N/A

MAP ID	ID/SITE NAME	ADDRESS	DATABASE	STATUS	DISTANCE (MILES)	ELEV DIFF (FEET)
13 Maps: 1 , 4	70000125 NEW MESQUITE TRAILS WEST ELEMENTARY SCHOOL	12850 MUSCATEL STREET HESPERIA	School-Other-CA	NO ACTION REQUIRED	0.48 SE	N/A
14 Maps: 1 , 4	T0607144072 PILOT #381	8701 HIGHWAY 395 HESPERIA	LUST-Closed-CA	COMPLETED - CASE CLOSED	0.5 SW	N/A

POTENTIAL AREAS OF CONCERN/CONTAMINATION SUMMARY

DATABASE SEARCHED	SUBJECT SITE WITHIN POTENTIAL AREA OF CONCERN	AREAS FOUND WITHIN 1-MILE RADIUS
NPL-R9-US	No	0
MethaneLF-CA	No	0
LA-LF-CA	No	0
Military-Bases-US	No	0
SGV-Deep-Plumes-CA	No	0
SGV-Shallow-Plumes-Puente-Valley-CA	No	0
SGV-Shallow-Plumes-CA	No	0

DATABASE OCCURRENCE SUMMARY

HIGH RISK* OCCURRENCES IDENTIFIED IN REQUESTED SEARCH RADIUS		
DATABASE SEARCHED	DISTANCE SEARCHED (MILES)	HIGH RISK OCCURRENCES FOUND
CERCLIS-US	0.5	0
CorAct-Open-CA	0.5	0
County-LUST-Open-CA	0.5	0
County-SLIC-Open-CA	0.5	0
Eval-Hist-Active-CA	0.5	0
Hist-UST-Cleanup-CA	0.5	0
LUST-Open-CA	0.5	0
Military-Active-CA	1	0
NPL-US	1	0
Proposed-NPL-US	1	0
Response-CA	1	0
SAA-Agreements-US	1	0
School-Active-CA	0.5	0
SLIC-Open-CA	0.5	0
State-Response-Active-CA	1	0
Superfund-Active-CA	1	0
Tribal-LUST-Open-Reg10	0.5	0
Tribal-LUST-Open-Reg4	0.5	0
Tribal-LUST-Open-Reg9	0.5	0
Tribal-LUST-Reg7	0.5	0
VCP-Active-CA	0.5	0

* For the purposes of this report, "high risk" occurrences are those that have known contamination and have not received a "case closed" or "no further action" status from the agency that maintains the records.

ASTM/AAI STANDARD RECORD SOURCES SUMMARY

STANDARD ENVIRONMENTAL RECORD SOURCES	ASTM MIN. SEARCH DIST. / ERS SEARCH DIST.	ERS DATABASE NAME	TOTAL LISTINGS	MAP ID #'S
---------------------------------------	---	-------------------	----------------	------------

	(MILES)			
Federal NPL site list	1.0 / 1.0	NPL-US	0	None Listed
		Proposed-NPL-US	0	None Listed
Federal Delisted NPL site list	0.5 / 1.0	Delisted-NPL-US	0	None Listed
Federal CERCLIS list	0.5 / 0.5	CERCLIS-US	0	None Listed
Federal CERCLIS NFRAP site list	0.5 / 0.5	CERCLIS-Archived-US	0	None Listed
Federal RCRA CORRACTS facilities list	1.0 / 1.0	RCRA-COR-US	0	None Listed
Federal RCRA non-CORRACTS TSD facilities list	0.5 / 0.5	RCRA-TSDF-US	0	None Listed
Federal RCRA generators list	Property and adjoining properties / 0.25	RCRA-CESQG-US	0	None Listed
		RCRA-LQG-US	0	None Listed
		RCRA-NON-US	6	2 , 5 , 5 , 10 , 11 , 12
		RCRA-SQG-US	0	None Listed
Federal Inst/Eng control registries	Property Only / 0.25	Controls-RCRA-US	0	None Listed
		Controls-US	0	None Listed
		Hist-US-EC	0	None Listed
		Hist-US-IC	0	None Listed
		LIENS-US	0	None Listed
Federal ERNS list	Property Only / 0.0625	ERNS-US	0	None Listed
State and Tribal-Equivalent NPL	1.0 / 1.0	Response-CA	0	None Listed
		State-Response-Active-CA	0	None Listed
		State-Response-NFA-CA	0	None Listed
		State-Response-Other-CA	0	None Listed
State and Tribal-Equivalent CERCLIS	0.5 / 0.5	Superfund-Active-CA	0	None Listed
		Superfund-NFA-CA	0	None Listed
		Superfund-Other-CA	0	None Listed
State and Tribal landfill and/or solid waste disposal sites	0.5 / 0.5	County-SWF-CA	0	None Listed
		Debris-US	0	None Listed
		Hist-Dumps-US	0	None Listed
		Land-Disposal-CA	0	None Listed
		SWIS-CA	0	None Listed
		SWLF-US	0	None Listed
		Tribal-ODI-US	0	None Listed
		County-LUST-CA	0	None Listed
State and Tribal Leaking Storage Tank Lists	0.5 / 0.5	County-LUST-Closed-CA	0	None Listed
		County-LUST-Open-CA	0	None Listed
		Hist-UST-Cleanup-CA	0	None Listed

		LUST-Closed-CA	1	14
		LUST-Open-CA	0	None Listed
		Tribal-LUST-Closed-Reg4	0	None Listed
		Tribal-LUST-Closed-Reg9	0	None Listed
		Tribal-LUST-Open-Reg10	0	None Listed
		Tribal-LUST-Open-Reg4	0	None Listed
		Tribal-LUST-Open-Reg9	0	None Listed
		Tribal-LUST-Reg1	0	None Listed
		Tribal-LUST-Reg7	0	None Listed
		AST-CA	0	None Listed
State and Tribal Registered Storage Tank Lists	Property and adjoining properties / 0.25	AST-CRSP-CA	2	5, 12
		City-AST-CA	0	None Listed
		City-UST-CA	0	None Listed
		County-AST-CA	2	5, 12
		County-UST-CA	1	11
		FEMA-UST-US	0	None Listed
		Hist-UST-CA	0	None Listed
		Tribal-UST-Reg1	0	None Listed
		Tribal-UST-Reg10	0	None Listed
		Tribal-UST-Reg4	0	None Listed
		Tribal-UST-Reg7	0	None Listed
		Tribal-UST-Reg9	0	None Listed
		UST-Abandoned-CA	0	None Listed
		UST-CA	1	11
		UST-Closed-CA	0	None Listed
		USTComp-CA	0	None Listed
		UST-CRSP-CA	1	11
		UST-Priority-CA	0	None Listed
		UST-Proposed-CA	0	None Listed
State and Tribal Inst/Eng Control Registries	Property Only / 0.5	Controls-CA	0	None Listed
		Deed-CA	0	None Listed
		Hist-Controls-CA	0	None Listed
		HWMP-Controls-CA	0	None Listed
		Liens-CA	0	None Listed
State and Tribal Voluntary Cleanup Sites	0.5 / 0.5	Military-Active-CA	0	None Listed
		Military-NFA-CA	0	None Listed
		Military-Other-CA	0	None Listed
		School-Active-CA	0	None Listed
		School-NFA-CA	0	None Listed
		School-Other-CA	1	13
		Tribal-VCP-US	0	None Listed
		VCP-Active-CA	0	None Listed

State and Tribal Brownfield Sites	0.5 / 0.5	VCP-NFA-CA	0	None Listed
		VCP-Other-CA	0	None Listed
		BF-MOA-CA	0	None Listed
		BF-Tribal-US	0	None Listed

FEDERAL ASTM/AAI DATABASES							
DATABASE SEARCHED	DISTANCE SEARCHED	SUBJECT SITE	0.125 MILES	0.25 MILES	0.5 MILES	1.0 MILES	TOTAL
BF-Tribal-US	0.5	0	0	0	0	-	0
BF-US	0.5	0	0	0	0	-	0
CERCLIS-Archived-US	0.5	0	0	0	0	-	0
CERCLIS-US	0.5	0	0	0	0	-	0
Controls-RCRA-US	0.5	0	0	0	0	-	0
Controls-US	0.5	0	0	0	0	-	0
Debris-US	0.5	0	0	0	0	-	0
Delisted-NPL-US	1	0	0	0	0	0	0
ERNS-US	0.0625	0	0	-	-	-	0
FEMA-UST-US	0.25	0	0	0	-	-	0
FTTS-ENF-US	0.25	0	0	0	-	-	0
Hist-Dumps-US	0.5	0	0	0	0	-	0
Hist-US-EC	0.5	0	0	0	0	-	0
Hist-US-IC	0.5	0	0	0	0	-	0
HMIS-US	0.0625	0	0	-	-	-	0
LIENS-US	0.0625	0	0	-	-	-	0
NPL-US	1	0	0	0	0	0	0
PADS-US	0.0625	0	0	-	-	-	0
PCB-US	0.25	0	0	0	-	-	0
Proposed-NPL-US	1	0	0	0	0	0	0
RCRA-CESQG-US	0.25	0	0	0	-	-	0
RCRA-COR-US	1	0	0	0	0	0	0
RCRA-LQG-US	0.25	0	0	0	-	-	0
RCRA-NON-US	0.25	0	4	2	-	-	6
RCRA-SQG-US	0.25	0	0	0	-	-	0
RCRA-TSDF-US	0.5	0	0	0	0	-	0
SAA-Agreements-US	1	0	0	0	0	0	0
SWLF-US	0.5	0	0	0	0	-	0
Tribal-LUST-Closed-Reg4	0.5	0	0	0	0	-	0
Tribal-LUST-Closed-Reg9	0.5	0	0	0	0	-	0
Tribal-LUST-Open-Reg10	0.5	0	0	0	0	-	0
Tribal-LUST-Open-Reg4	0.5	0	0	0	0	-	0
Tribal-LUST-Open-Reg9	0.5	0	0	0	0	-	0
Tribal-LUST-Reg1	0.5	0	0	0	0	-	0
Tribal-LUST-Reg7	0.5	0	0	0	0	-	0
Tribal-ODI-US	0.5	0	0	0	0	-	0
Tribal-UST-Reg1	0.25	0	0	0	-	-	0
Tribal-UST-Reg10	0.25	0	0	0	-	-	0
Tribal-UST-Reg4	0.25	0	0	0	-	-	0
Tribal-UST-Reg7	0.25	0	0	0	-	-	0
Tribal-UST-Reg9	0.25	0	0	0	-	-	0
Tribal-VCP-US	0.5	0	0	0	0	-	0

STATE ASTM/AAI DATABASES

DATABASE SEARCHED	DISTANCE SEARCHED	SUBJECT SITE	0.125 MILES	0.25 MILES	0.5 MILES	1.0 MILES	TOTAL
AST-CA	0.25	0	0	0	-	-	0
AST-CRSP-CA	0.25	0	1	1	-	-	2
BF-MOA-CA	0.5	0	0	0	0	-	0
BZ-HazWaste-CA	0.5	0	0	0	0	-	0
CERS-CA	0.25	0	7	2	-	-	9
CHMIRS-CA	0.0625	0	0	-	-	-	0
City-AST-CA	0.25	0	0	0	-	-	0
City-CUPA-CA	0.25	0	0	0	-	-	0
City-Others-CA	0.25	0	0	0	-	-	0
City-UST-CA	0.25	0	0	0	-	-	0
Controls-CA	0.5	0	0	0	0	-	0
CorAct-Closed-CA	0.5	0	0	0	0	-	0
CorAct-Open-CA	0.5	0	0	0	0	-	0
CorAct-Other-CA	0.5	0	0	0	0	-	0
CORTESE-CA	0.25	0	0	0	-	-	0
County-AST-CA	0.25	0	1	1	-	-	2
County-Hist-CA	0.25	0	0	0	-	-	0
County-LUST-CA	0.5	0	0	0	0	-	0
County-LUST-Closed-CA	0.5	0	0	0	0	-	0
County-LUST-Open-CA	0.5	0	0	0	0	-	0
County-Others-CA	0.25	0	0	0	-	-	0
County-SLIC-Closed-CA	0.25	0	0	0	-	-	0
County-SLIC-Open-CA	0.5	0	0	0	0	-	0
County-SML-CA	0.5	0	0	0	0	-	0
County-SWF-CA	0.5	0	0	0	0	-	0
County-UST-CA	0.25	0	0	1	-	-	1
CRSP-CA	0.25	0	6	2	-	-	8
CUPA-CA	0.25	0	10	2	-	-	12
Deed-CA	0.5	0	0	0	0	-	0
ENF-CA	0.25	0	0	0	-	-	0
ENF-SMARTS-CA	0.25	0	0	0	-	-	0
ENF-Wastewater-CA	0.25	0	0	0	-	-	0
Eval-Hist-Active-CA	0.5	0	0	0	0	-	0
Eval-Hist-NFA-CA	0.5	0	0	0	0	-	0
Eval-Hist-Other-CA	0.5	0	0	0	0	-	0
HazWaste-CA	0.25	0	0	0	-	-	0
Hist-Controls-CA	0.5	0	0	0	0	-	0
Hist-Cort-CA	0.25	0	0	0	-	-	0
HIST-R4-CA	0.25	0	0	0	-	-	0
HIST-SLIC-CV-CLOSED-CA	0.5	0	0	0	0	-	0
HIST-SLIC-CV-OPEN-CA	0.5	0	0	0	0	-	0
Hist-UST-CA	0.25	0	0	0	-	-	0
Hist-UST-Cleanup-CA	0.5	0	0	0	0	-	0
Hist-WIP-Active-CA	0.5	0	0	0	0	-	0
Hist-WIP-Backlog-CA	0.5	0	0	0	0	-	0
Hist-WIP-Historical-CA	0.5	0	0	0	0	-	0
HWIS-CA	0.0625	0	2	-	-	-	2
HWMP-Controls-CA	0.5	0	0	0	0	-	0
ICE-CA	0.25	0	0	0	-	-	0
Land-Disposal-CA	0.5	0	0	0	0	-	0
Liens-CA	0.0625	0	0	-	-	-	0
LUST-Closed-CA	0.5	0	0	0	1	-	1
LUST-Open-CA	0.5	0	0	0	0	-	0
Manifest2-RI	0.0625	0	0	-	-	-	0
Military-Active-CA	1	0	0	0	0	0	0
Military-NFA-CA	0.5	0	0	0	0	-	0
Military-Other-CA	1	0	0	0	0	0	0

STATE ASTM/AAI DATABASES

DATABASE SEARCHED	DISTANCE SEARCHED	SUBJECT SITE	0.125 MILES	0.25 MILES	0.5 MILES	1.0 MILES	TOTAL
PR-MOA-CA	0.25	0	0	0	-	-	0
Response-CA	1	0	0	0	0	0	0
School-Active-CA	0.5	0	0	0	0	-	0
School-NFA-CA	0.5	0	0	0	0	-	0
School-Other-CA	0.5	0	0	0	1	-	1
SLIC-Closed-CA	0.5	0	0	0	0	-	0
SLIC-Open-CA	0.5	0	0	0	0	-	0
SML-CA	0.5	0	0	0	0	-	0
State-Response-Active-CA	1	0	0	0	0	0	0
State-Response-NFA-CA	0.5	0	0	0	0	-	0
State-Response-Other-CA	0.5	0	0	0	0	-	0
Superfund-Active-CA	1	0	0	0	0	0	0
Superfund-NFA-CA	1	0	0	0	0	0	0
Superfund-Other-CA	1	0	0	0	0	0	0
SWIS-CA	0.5	0	0	0	0	-	0
SWRCY-CA	0.5	0	0	0	0	-	0
UST-Abandoned-CA	0.25	0	0	0	-	-	0
UST-CA	0.25	0	0	1	-	-	1
UST-Closed-CA	0.25	0	0	0	-	-	0
USTComp-CA	0.25	0	0	0	-	-	0
UST-CRSP-CA	0.25	0	0	1	-	-	1
UST-Priority-CA	0.5	0	0	0	0	-	0
UST-Proposed-CA	0.25	0	0	0	-	-	0
VCP-Active-CA	0.5	0	0	0	0	-	0
VCP-NFA-CA	0.5	0	0	0	0	-	0
VCP-Other-CA	0.5	0	0	0	0	-	0

SUPPLEMENTAL DATABASES


DATABASE SEARCHED	DISTANCE SEARCHED	SUBJECT SITE	0.125 MILES	0.25 MILES	0.5 MILES	1.0 MILES	TOTAL
Air-CA	0.25	0	0	0	-	-	0
AIR-DIST-CA	0.25	0	2	0	-	-	2
BioFuel-US	0.25	0	0	0	-	-	0
CAF-CA	0.25	0	0	0	-	-	0
CDL-CA	0.0625	0	0	-	-	-	0
CDL-US	0.0625	0	0	-	-	-	0
CHWF-CA	0.5	0	0	0	0	-	0
Cleaners-CA	0.25	0	0	0	-	-	0
Coal-Ash-Dams-US	0.5	0	0	0	0	-	0
County-BI-CA	0.25	0	0	0	-	-	0
Dams-CA	0.25	0	0	0	-	-	0
DPR-CA	0.25	0	0	0	-	-	0
DryCleaners-CA	0.25	0	0	1	-	-	1
EGRID-US	0.5	0	0	0	0	-	0
EPA-Watch-List-US	0.25	0	0	0	-	-	0
FA-HW-CA	0.0625	0	0	-	-	-	0
FA-HW-US	0.0625	0	0	-	-	-	0
FA-SWF-CA	0.0625	0	0	-	-	-	0
FRS-US	0.0625	0	4	-	-	-	4
FTTS-INSP-US	0.0625	0	0	-	-	-	0
FUDS-US	1	0	0	0	0	0	0
FUSRAP-US	0.25	0	0	0	-	-	0
Haulers-CA	0.0625	0	0	-	-	-	0

SUPPLEMENTAL DATABASES							
DATABASE SEARCHED	DISTANCE SEARCHED	SUBJECT SITE	0.125 MILES	0.25 MILES	0.5 MILES	1.0 MILES	TOTAL
Hist-AFS2-US	0.25	0	0	0	-	-	0
Hist-AFS-US	0.25	0	0	0	-	-	0
Hist-AST-CA	0.25	0	0	0	-	-	0
Hist-AWS-CA	0.25	0	0	0	-	-	0
Hist-CA	0.0625	0	6	-	-	-	6
Hist-CalFID-CA	0.25	0	0	0	-	-	0
Hist-CALSITES-CA	0.25	0	0	0	-	-	0
Hist-CERCLIS-NFRAP-US	0.25	0	0	0	-	-	0
Hist-CERCLIS-US	0.25	0	0	0	-	-	0
Hist-City-UST-CA	0.25	0	0	0	-	-	0
Hist-Deed-CA	0.25	0	0	0	-	-	0
Hist-DTG-CA	0.25	0	0	0	-	-	0
Hist-ERNS-US	0.0625	0	0	-	-	-	0
Hist-FIFRA-US	0.25	0	0	0	-	-	0
Hist-FINDS-US	0.0625	0	0	-	-	-	0
Hist-HWS-CA	0.25	0	0	0	-	-	0
Hist-LUSTIS-CA	0.25	0	0	0	-	-	0
HIST-MLTS-US	0.25	0	0	0	-	-	0
HIST-MTBE-CA	0.25	0	0	0	-	-	0
Hist-NPL-US	0.25	0	0	0	-	-	0
Hist-Orange-County-LF-CA	0.25	0	0	0	-	-	0
Historical-CA	0.5	0	0	0	0	-	0
Hist-Prop65-CA	0.25	0	0	0	-	-	0
Hist-RCRIS-US	0.25	0	0	0	-	-	0
Hist-Regional-LUST-CA	0.25	0	0	0	-	-	0
Hist-Regional-Other-CA	0.25	0	0	0	-	-	0
Hist-Regional-SLIC-CA	0.25	0	0	0	-	-	0
Hist-Regional-Spills-CA	0.25	0	0	0	-	-	0
Hist-Regional-SWLF-CA	0.25	0	0	0	-	-	0
Hist-Regional-UST-CA	0.25	0	0	0	-	-	0
Hist-SCL-CA	0.25	0	0	0	-	-	0
Hist-SWIS-CA	0.25	0	0	0	-	-	0
Hist-ToxicPits-CA	0.25	0	0	0	-	-	0
Hist-TRIS-US	0.25	0	0	0	-	-	0
Hist-US	0.0625	0	0	-	-	-	0
Hist-USGS-WaterWells-CA	0.0625	0	0	-	-	-	0
Hist-USTReg-CA	0.25	0	0	0	-	-	0
Hist-WaterWells-US	0.0625	0	0	-	-	-	0
Hist-WMUDS-CA	0.25	0	0	0	-	-	0
HWT-CA	0.25	0	0	0	-	-	0
ICIS-Air-US	0.0625	0	0	-	-	-	0
ICIS-FEC-US	0.0625	0	0	-	-	-	0
ICIS-NPDES-US	0.0625	0	0	-	-	-	0
LA-Waste-Haulers-CA	0.0625	0	0	-	-	-	0
Lead-Smelter-2-US	0.25	0	0	0	-	-	0
Lead-US	0.25	0	0	0	-	-	0
LMOP-US	0.5	0	0	0	0	-	0
Mines2-CA	0.0625	0	0	-	-	-	0
Mines-CA	0.0625	0	0	-	-	-	0
Mines-CDMG-CA	0.0625	0	0	-	-	-	0
MINES-US	0.0625	0	0	-	-	-	0
MLTS-US	0.0625	0	0	-	-	-	0
Mortgage-CA	0.25	0	0	0	-	-	0
MRDS-US	0.25	0	0	0	-	-	0
MWMP-CA	0.25	0	0	0	-	-	0

SUPPLEMENTAL DATABASES							
DATABASE SEARCHED	DISTANCE SEARCHED	SUBJECT SITE	0.125 MILES	0.25 MILES	0.5 MILES	1.0 MILES	TOTAL
NCI-CA	0.25	0	0	0	-	-	0
NEI-LF-CA	0.25	0	0	0	-	-	0
NPDES-CA	0.0625	0	0	-	-	-	0
NPDES-SW-CA	0.0625	0	0	-	-	-	0
OGM-CA	0.0625	0	0	-	-	-	0
OGW-CA	0.0625	0	0	-	-	-	0
OSCF-CA	0.5	0	0	0	0	-	0
PCS-US	0.25	0	0	0	-	-	0
Perch1-CA	0.25	0	0	0	-	-	0
Perch2-CA	0.25	0	0	0	-	-	0
Project-CA	0.25	0	0	0	-	-	0
RADINFO-US	0.0625	0	0	-	-	-	0
RFG-Lab-US	0.25	0	0	0	-	-	0
RMP-US	0.0625	0	0	-	-	-	0
ROD-US	0.5	0	0	0	0	-	0
SDWIS-US	0.25	0	0	0	-	-	0
SP-CA	0.25	0	0	0	-	-	0
Spills-SSO-CA	0.25	0	0	0	-	-	0
SSTS-US	0.0625	0	0	-	-	-	0
TierPer-CA	0.25	0	0	0	-	-	0
TOMS-CA	0.0625	0	0	-	-	-	0
Tribal-Air-US	0.25	0	0	0	-	-	0
TRIS2000-US	0.0625	0	0	-	-	-	0
TRIS2010-US	0.0625	0	0	-	-	-	0
TRIS80-US	0.0625	0	0	-	-	-	0
TRIS90-US	0.0625	0	0	-	-	-	0
TSCA-US	0.0625	0	0	-	-	-	0
UIC2-CA	0.0625	0	0	-	-	-	0
UIC-CA	0.0625	0	0	-	-	-	0
UMTRA-US	0.0625	0	0	-	-	-	0
USGS-Waterwells-US	0.0625	0	0	-	-	-	0
Vapor-Intrusions-US	0.5	0	0	0	0	-	0
WDR-CA	0.25	0	0	0	-	-	0

PROPRIETARY HISTORIC DATABASES							
DATABASE SEARCHED	DISTANCE SEARCHED	SUBJECT SITE	0.125 MILES	0.25 MILES	0.5 MILES	1.0 MILES	TOTAL
Hist-Agriculture	0.0625	0	0	-	-	-	0
Hist-Auto Dealers	0.0625	0	0	-	-	-	0
Hist-Auto Repair	0.25	0	1	2	-	-	3
Hist-Chemical Manufacturing	0.0625	0	0	-	-	-	0
Hist-Chemical-Storage	0.0625	0	0	-	-	-	0
Hist-Cleaners	0.25	0	0	0	-	-	0
Hist-Convenience	0.0625	0	0	-	-	-	0
Hist-Disposal-Recycle	0.0625	0	0	-	-	-	0
Hist-Food-Processors	0.0625	0	0	-	-	-	0
Hist-Gun-Ranges	0.0625	0	0	-	-	-	0
Hist-Machine Shop	0.0625	0	0	-	-	-	0
Hist-Manufacturing	0.0625	0	0	-	-	-	0
Hist-Metal Plating	0.0625	0	0	-	-	-	0
Hist-Mining	0.0625	0	0	-	-	-	0
Hist-Mortuaries	0.0625	0	0	-	-	-	0
Hist-Oil-Gas	0.0625	0	0	-	-	-	0

PROPRIETARY HISTORIC DATABASES							
DATABASE SEARCHED	DISTANCE SEARCHED	SUBJECT SITE	0.125 MILES	0.25 MILES	0.5 MILES	1.0 MILES	TOTAL
Hist-OilGas-Refiners	0.0625	0	0	-	-	-	0
Hist-Other	0.0625	0	0	-	-	-	0
Hist-Paint-Stores	0.0625	0	0	-	-	-	0
Hist-Petroleum	0.0625	0	0	-	-	-	0
Hist-Post-Offices	0.0625	0	0	-	-	-	0
Hist-Printers	0.0625	0	0	-	-	-	0
Hist-Rental	0.0625	0	0	-	-	-	0
Hist-RV-Dealers	0.0625	0	0	-	-	-	0
Hist-Salvage	0.0625	0	0	-	-	-	0
Hist-Service Stations	0.25	0	0	0	-	-	0
Hist-Steel-Metals	0.0625	0	0	-	-	-	0
Hist-Textile	0.0625	0	0	-	-	-	0
Hist-Transportation	0.0625	0	0	-	-	-	0
Hist-Trucking	0.0625	0	0	-	-	-	0
Hist-Vehicle-Parts	0.0625	0	0	-	-	-	0
Hist-Vehicle-Washing	0.0625	0	0	-	-	-	0



SITE LOCATION TOPOGRAPHIC MAP

U.S. Geological Survey. Baldy Mesa (Date Unavailable) Quadrangle, 7.5 Minute Series


UltraSystems Environmental Inc.	Apns 3064-591-12, -13, 17, -18 And 3064-631-01 Hesperia, CA 92344	FIGURE: 1 JOB: 7187 DATE: 9/15/2022
---------------------------------	---	---



SITE LOCATION MAP


UltraSystems Environmental Inc.	Apns 3064-591-12, -13, 17, -18 And 3064-631-01 Hesperia, CA 92344	FIGURE: 2 JOB: 7187 DATE: 9/15/2022
---------------------------------	---	---

1-MILE RADIUS STREET MAP W/OCCURRENCES (MAP1)




All plotted occurrences represent approximate locations based on geographic information provided by the respective agency. Actual locations may vary due to numerous reasons such as: the size of the property, accuracy of the provided location, accuracy of the software used to determine the location, etc. **Occurrences are shown in three colors** to give a visual indication of the potential risk of the listed occurrence based on the type of list and the current status of the occurrence. Occurrences shown in **RED** are locations with known contamination that have not received a "case closed" or "no further action" status. Occurrences shown in **YELLOW** have been listed by the respective agency, but do not always represent an environmental risk. The detailed status information and description of the listing should be reviewed for further information. Occurrences shown in **GREEN** are occurrences that have active permits or have had contamination in the past but have received a "case closed" or "no further action" status and therefore, do not likely present an environmental risk.

GRID LAYOUT MAP KEY




All plotted occurrences represent approximate locations based on geographic information provided by the respective agency. Actual locations may vary due to numerous reasons such as: the size of the property, accuracy of the provided location, accuracy of the software used to determine the location, etc. **Occurrences are shown in three colors** to give a visual indication of the potential risk of the listed occurrence based on the type of list and the current status of the occurrence. Occurrences shown in **RED** are locations with known contamination that have not received a "case closed" or "no further action" status. Occurrences shown in **YELLOW** have been listed by the respective agency, but do not always represent an environmental risk. The detailed status information and description of the listing should be reviewed for further information. Occurrences shown in **GREEN** are occurrences that have active permits or have had contamination in the past but have received a "case closed" or "no further action" status and therefore, do not likely present an environmental risk.

GRID MAP 101



All plotted occurrences represent approximate locations based on geographic information provided by the respective agency. Actual locations may vary due to numerous reasons such as: the size of the property, accuracy of the provided location, accuracy of the software used to determine the location, etc. **Occurrences are shown in three colors** to give a visual indication of the potential risk of the listed occurrence based on the type of list and the current status of the occurrence. Occurrences shown in **RED** are locations with known contamination that have not received a "case closed" or "no further action" status. Occurrences shown in **YELLOW** have been listed by the respective agency, but do not always represent an environmental risk. The detailed status information and description of the listing should be reviewed for further information. Occurrences shown in **GREEN** are occurrences that have active permits or have had contamination in the past but have received a "case closed" or "no further action" status and therefore, do not likely present an environmental risk.

GRID MAP 102




Sources: Esri, HERE, Garmin, USGS, Intermap, INCREMENTAL, Navteq, Esri Japan, METI, Esri China (Hong Kong), Esri Korea, Esri (Thailand), NGCC, (c) OpenStreetMap contributors, and the GIS User Community

Legend

Federal NPL	Federal RCRA non-CORRACTS TSD	Federal Emergency Release Reports	State/Tribal UST	ERS Supplemental Govt Sources
Federal Delisted NPL	Federal RCRA Generators	Emergency Release Reports	State/Tribal Brownfield	ERS Exclusive Historic Sources
Federal CERCLIS	Federal UST	State/Tribal NPL	State/Tribal Inst/Eng Controls	
Federal CERCLIS NFRAP	Federal Inst/Eng Controls	State/Tribal CERCLIS Equivalent	State/Tribal Landfill/Solid Waste	
Federal LUST	Federal Brownfield	State/Tribal LUST	State/Tribal RCRA Equivalent	
Federal RCRA CORRACTS	Federal ERNS	State/Tribal Voluntary Cleanup Sites	State/Tribal ASTM Other	

All plotted occurrences represent approximate locations based on geographic information provided by the respective agency. Actual locations may vary due to numerous reasons such as: the size of the property, accuracy of the provided location, accuracy of the software used to determine the location, etc. **Occurrences are shown in three colors** to give a visual indication of the potential risk of the listed occurrence based on the type of list and the current status of the occurrence. Occurrences shown in **RED** are locations with known contamination that have not received a "case closed" or "no further action" status. Occurrences shown in **YELLOW** have been listed by the respective agency, but do not always represent an environmental risk. The detailed status information and description of the listing should be reviewed for further information. Occurrences shown in **GREEN** are occurrences that have active permits or have had contamination in the past but have received a "case closed" or "no further action" status and therefore, do not likely present an environmental risk.

GRID MAP 103




Sources: Esri, HERE, Garmin, USGS, Intermap, INCREMENTAL, Navteq, Esri Japan, METI, Esri China (Hong Kong), Esri Korea, Esri (Thailand), NGCC, (c) OpenStreetMap contributors, and the GIS User Community

Legend

Federal NPL	Federal RCRA non-CORRACTS TSD	Federal Emergency Release Reports	State/Tribal UST	ERS Supplemental Govt Sources
Federal Delisted NPL	Federal RCRA Generators	Emergency Release Reports	State/Tribal Brownfield	ERS Exclusive Historic Sources
Federal CERCLIS	Federal UST	State/Tribal NPL	State/Tribal Inst/Eng Controls	
Federal CERCLIS NFRAP	Federal Inst/Eng Controls	State/Tribal CERCLIS Equivalent	State/Tribal Landfill/Solid Waste	
Federal LUST	Federal Brownfield	State/Tribal LUST	State/Tribal RCRA Equivalent	
Federal RCRA CORRACTS	Federal ERNS	State/Tribal Voluntary Cleanup Sites	State/Tribal ASTM Other	


All plotted occurrences represent approximate locations based on geographic information provided by the respective agency. Actual locations may vary due to numerous reasons such as: the size of the property, accuracy of the provided location, accuracy of the software used to determine the location, etc. **Occurrences are shown in three colors** to give a visual indication of the potential risk of the listed occurrence based on the type of list and the current status of the occurrence. Occurrences shown in **RED** are locations with known contamination that have not received a "case closed" or "no further action" status. Occurrences shown in **YELLOW** have been listed by the respective agency, but do not always represent an environmental risk. The detailed status information and description of the listing should be reviewed for further information. Occurrences shown in **GREEN** are occurrences that have active permits or have had contamination in the past but have received a "case closed" or "no further action" status and therefore, do not likely present an environmental risk.

GRID MAP 104



All plotted occurrences represent approximate locations based on geographic information provided by the respective agency. Actual locations may vary due to numerous reasons such as: the size of the property, accuracy of the provided location, accuracy of the software used to determine the location, etc. **Occurrences are shown in three colors** to give a visual indication of the potential risk of the listed occurrence based on the type of list and the current status of the occurrence. Occurrences shown in **RED** are locations with known contamination that have not received a "case closed" or "no further action" status. Occurrences shown in **YELLOW** have been listed by the respective agency, but do not always represent an environmental risk. The detailed status information and description of the listing should be reviewed for further information. Occurrences shown in **GREEN** are occurrences that have active permits or have had contamination in the past but have received a "case closed" or "no further action" status and therefore, do not likely present an environmental risk.

GRID MAP 105




All plotted occurrences represent approximate locations based on geographic information provided by the respective agency. Actual locations may vary due to numerous reasons such as: the size of the property, accuracy of the provided location, accuracy of the software used to determine the location, etc. **Occurrences are shown in three colors** to give a visual indication of the potential risk of the listed occurrence based on the type of list and the current status of the occurrence. Occurrences shown in **RED** are locations with known contamination that have not received a "case closed" or "no further action" status. Occurrences shown in **YELLOW** have been listed by the respective agency, but do not always represent an environmental risk. The detailed status information and description of the listing should be reviewed for further information. Occurrences shown in **GREEN** are occurrences that have active permits or have had contamination in the past but have received a "case closed" or "no further action" status and therefore, do not likely present an environmental risk.

GRID MAP 106




All plotted occurrences represent approximate locations based on geographic information provided by the respective agency. Actual locations may vary due to numerous reasons such as: the size of the property, accuracy of the provided location, accuracy of the software used to determine the location, etc. **Occurrences are shown in three colors** to give a visual indication of the potential risk of the listed occurrence based on the type of list and the current status of the occurrence. Occurrences shown in **RED** are locations with known contamination that have not received a "case closed" or "no further action" status. Occurrences shown in **YELLOW** have been listed by the respective agency, but do not always represent an environmental risk. The detailed status information and description of the listing should be reviewed for further information. Occurrences shown in **GREEN** are occurrences that have active permits or have had contamination in the past but have received a "case closed" or "no further action" status and therefore, do not likely present an environmental risk.

GRID MAP 107



All plotted occurrences represent approximate locations based on geographic information provided by the respective agency. Actual locations may vary due to numerous reasons such as: the size of the property, accuracy of the provided location, accuracy of the software used to determine the location, etc. **Occurrences are shown in three colors** to give a visual indication of the potential risk of the listed occurrence based on the type of list and the current status of the occurrence. Occurrences shown in **RED** are locations with known contamination that have not received a "case closed" or "no further action" status. Occurrences shown in **YELLOW** have been listed by the respective agency, but do not always represent an environmental risk. The detailed status information and description of the listing should be reviewed for further information. Occurrences shown in **GREEN** are occurrences that have active permits or have had contamination in the past but have received a "case closed" or "no further action" status and therefore, do not likely present an environmental risk.

GRID MAP 108




All plotted occurrences represent approximate locations based on geographic information provided by the respective agency. Actual locations may vary due to numerous reasons such as: the size of the property, accuracy of the provided location, accuracy of the software used to determine the location, etc. **Occurrences are shown in three colors** to give a visual indication of the potential risk of the listed occurrence based on the type of list and the current status of the occurrence. Occurrences shown in **RED** are locations with known contamination that have not received a "case closed" or "no further action" status. Occurrences shown in **YELLOW** have been listed by the respective agency, but do not always represent an environmental risk. The detailed status information and description of the listing should be reviewed for further information. Occurrences shown in **GREEN** are occurrences that have active permits or have had contamination in the past but have received a "case closed" or "no further action" status and therefore, do not likely present an environmental risk.

GRID MAP 109



All plotted occurrences represent approximate locations based on geographic information provided by the respective agency. Actual locations may vary due to numerous reasons such as: the size of the property, accuracy of the provided location, accuracy of the software used to determine the location, etc. **Occurrences are shown in three colors** to give a visual indication of the potential risk of the listed occurrence based on the type of list and the current status of the occurrence. Occurrences shown in **RED** are locations with known contamination that have not received a "case closed" or "no further action" status. Occurrences shown in **YELLOW** have been listed by the respective agency, but do not always represent an environmental risk. The detailed status information and description of the listing should be reviewed for further information. Occurrences shown in **GREEN** are occurrences that have active permits or have had contamination in the past but have received a "case closed" or "no further action" status and therefore, do not likely present an environmental risk.


1-MILE TOPOGRAPHIC MAP W/OCCURRENCES (MAP4)



All plotted occurrences represent approximate locations based on geographic information provided by the respective agency. Actual locations may vary due to numerous reasons such as: the size of the property, accuracy of the provided location, accuracy of the software used to determine the location, etc. Occurrences are shown in three colors to give a visual indication of the potential risk of the listed occurrence based on the type of list and the current status of the occurrence. Occurrences shown in **RED** are locations with known contamination that have not received a "case closed" or "no further action" status. Occurrences shown in **YELLOW** have been listed by the respective agency, but do not always represent an environmental risk. The detailed status information and description of the listing should be reviewed for further information. Occurrences shown in **GREEN** are occurrences that have active permits or have had contamination in the past but have received a "case closed" or "no further action" status and therefore, do not likely present an environmental risk.

AGENCY DIFFERENCES IN MAPPED LOCATIONS (MAP5)

Note: Occurrences on this map have agency provided coordinates which differ significantly from geocoded locations.



This "AGENCY DIFFERENCES IN MAPPED LOCATIONS (MAP 4)" is fully protected against reproduction in any way, shape or form by ERS Environmental Record Search. ALL applicable laws, copyrights, pending copyrights, trademarks, and any and all applicable Federal and State laws apply at all times. These protections include the concept, procedures, processes, layout, vision, color scheme, mapping layout, legends, data, any and all verbiage, and the entire concept.


SUMMARY OF AGENCY DIFFERENCES

MAP ID	ID / SITE NAME	ADDRESS / DATABASE	AGENCY COORDINATES	DISTANCE (MILES)	DIRECTION
2	10400761 High Desert Truck and Trailer	8995 Three Flags Ave CERS-CA	-117.39427, 34.41426	0.02	S
2	169689 High Desert Truck and Trailer	8995 THREE FLAGS AVE CRSP-CA	-117.39427, 34.41426	0.02	S
2	110065650352 VVG FACILITY #7	8995 THREE FLAGS AVE FRS-US	-117.39427, 34.41426	0.02	S
4	10762693 Superior Pool Products LLC #548A	12221 Poplar St Bldg E CERS-CA	-117.39679, 34.41542	0.11	W
4	437884 Superior Pool Products LLC #548A	12221 POPLAR ST BLDG E CRSP-CA	-117.39679, 34.41542	0.11	W
5	110033211245 ZIPPY LUBE-A-TRUCK, INC.	8899B THREE FLAGS AVENUE FRS-US	-117.39496, 34.41445	0.01	SW
9	10312237 DIRECTV	12269 SCARBROUGH CT CERS-CA	-117.39551, 34.41257	0.14	S
11	10049065 DOUBLE EAGLE TRANSPORTATION	12135 SCARBROUGH CT CERS-CA	-117.39806, 34.41259	0.23	SW
11	391724 DOUBLE EAGLE TRANSPORTATION	12135 SCARBROUGH CT CRSP-CA	-117.39805, 34.41259	0.23	SW
11	243095 DOUBLE EAGLE TRANSPORTATION	12135 SCARBROUGH CT UST-CA	-117.39806, 34.41259	0.23	SW
11	391724 DOUBLE EAGLE TRANSPORTATION	12135 SCARBROUGH CT UST-CRSP-CA	-117.39805, 34.41259	0.23	SW
14	T0607144072 PILOT #381	8701 HIGHWAY 395 LUST-Closed-CA	-117.39915, 34.40992	0.4	SW
15	10758478 Verizon Wireless: Highway 395	8853 Three Flags Ave CERS-CA	-117.39383, 34.41123	0.19	S
16	435257 Verizon Wireless: Highway 395	8853 THREE FLAGS AVE CRSP-CA	-117.39383, 34.41123	0.19	S

MAP ID	ID / SITE NAME	ADDRESS / DATABASE	AGENCY COORDINATES	DISTANCE (MILES)	DIRECTION
17	495979 STANDARD ABRASIVES	8981 STATE HIGHWAY 395 CRSP-CA	-117.39914, 34.416	0.24	W
18	T0607100957 TIMOTHY LANE	8685 US HIGHWAY 395 LUST-Closed-CA	-117.39916, 34.40964	0.42	SW

MAPPED AIR PERMITS WITH POTENTIAL DISPERSION (MAP6)

Note: Occurrences on this map are reported in Air Quality databases. Potential air plumes are drawn in the direction of the prevailing wind.



All plotted occurrences represent approximate locations based on geographic information provided by the respective agency/source. Actual locations may vary due to numerous reasons such as: the size of the property, accuracy of the provided location, accuracy of the software used to determine the location, etc. Potential air dispersion plumes are depicted to graphically show the direction contaminants may travel based on prevailing wind data and provide a visual screening tool only. Actual direction will vary especially by season. Depending on the actual contaminate, amount released, and other variables, the distance from the source the contaminate may travel can and will vary. Interpretation and review of all the actual relevant data by an environmental professional is recommended before making any decisions, conclusions or otherwise based on the map depictions, air data, and potential air dispersion plumes.

This "MAPPED AIR PERMITS WITH POTENTIAL DISPERSION (MAP 6)" is fully protected against reproduction in any way, shape or form by ERS Environmental Record Search. ALL applicable laws, copyrights, pending copyrights, trademarks, and any and all applicable Federal and State laws apply at all times. These protections include the concept, procedures, processes, layout, vision, color scheme, mapping layout, legends, data, any and all verbiage, and the entire concept.

LISTED OCCURRENCE DETAILS

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
Hist-CA	No Longer Listed	0.01 miles NW	3620 ft	1
SITE NAME			MAPS	ID
B & D Industrial Park			1 , 4	338278
ADDRESS			CITY	ZIP
Popular St & Three Flags Ave			Hesperia	92345
DETAILS				
Original Database: NPDES-SW-CA Last Agency Status: Listed Archive Date: 06/01/16 No Longer Listed-Registered Meas ID: 338278 Registered Meas Type: Construction WDID: 6B36C350089 Received Date: 5/9/2008 Processed Date: 12/20/2007 Termination Date: 6/8/2010 Status Code Name: Terminated Status Date: 6/16/2010 REGION: Not Reported County Code: 36 Place Size: 3 Place Size Unit: Acres Facility County: San Bernardino Facility Contact Name: Bob Carson Facility Contact Title: Not Reported Facility Contact Phone: 999-999-9999 Facility Contact Phone Extension: Not Reported Facility Contact Email Address: Not Reported Operator Name: Destin Steel Inc Operator Address: 12127 Mallcenter Blvd A 171 Operator City: Victorville Operator State: California Operator Zip: 92392 Operator Contact Name: Dan Higgins More Details Link				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CERS-CA	Listed	0.03 miles S	3632 ft	2
SITE NAME			MAPS	ID
High Desert Truck and Trailer			1 , 4	10400761
ADDRESS			CITY	ZIP
8995 Three Flags Ave			Hesperia	92345
DETAILS				
General Program & Facility Information CERS ID: 10400761 Facility ID: FA0016142 Facility Regulator Key ID: FA0016142 Organization Code: 90363385 Business/Organization Name: Velocity Vehicle Group (VVG) Multiple Jurisdictional Business? (Y/N): Yes Business Origin: Letter Count of Business CERS User Accounts: 9 Facility Count for Business: 16 Last Submittal Date (any element): 7/9/2018 8:28:02 AM Count of Submitted Elements: 21 Remote Facility? (Y/N): No Small Quantity Generator Facility? (Y/N): No Local Facility Grouping: Not Reported Facility Specific Information Assessor Parcel Number (APN): Not Reported Number of Employees: 15 Property Owner Name: Brad Fauvre & Conan Barker Property Owner Phone Number: (562) 447-1203 Property Owner Mailing Address: 2429 Peck Road Property Owner Mailing City: Whittier Property Owner Mailing State: CA Property Owner Mailing Zip Code: 90601 Property Owner Mailing Country: United States More Details Link				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CRSP-CA	Listed	0.03 miles S	3632 ft	2
SITE NAME			MAPS	ID
High Desert Truck and Trailer			1 , 4	169689
ADDRESS			CITY	ZIP
8995 THREE FLAGS AVE			HESPERIA	92345
DETAILS				
Site Regulated Program Information Site ID: 169689 Site EI ID: 10400761 Agency Provided Latitude: 34.41426 Agency Provided Longitude: -117.39427 Program Description: Chemical Storage Facilities Program Description: Hazardous Waste Generator Evaluation Information Evaluation Date: 12/14/2016 Violations Found? (Y/N): Yes Evaluation General Type: Compliance Evaluation Inspection Evaluation Type: Routine done by local agency Evaluation Note(s): GENERATOR INSPECTION Evaluation Division: San Bernardino County Fire Department Evaluation Program: HW Evaluation Source: CERS Evaluation Date: 12/14/2016 Violations Found? (Y/N): Yes Evaluation General Type: Compliance Evaluation Inspection Evaluation Type: Routine done by local agency Evaluation Note(s): HANDLER INSPECTION Evaluation Division: San Bernardino County Fire Department More Details Link				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
FRS-US	Listed	0.03 miles S	3632 ft	2
SITE NAME			MAPS	ID
VVG FACILITY #7			1 , 4	110065650352
ADDRESS			CITY	ZIP
8995 THREE FLAGS AVE			HESPERIA	92345
DETAILS				
FRS Facility Detail Report URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110065650352 Create Date: 13-OCT-2015 12:56:11 Program System: CA-ENVIROVIEW Interest Type(s): STATE MASTER				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
Hist-CA	No Longer Listed	0.03 miles S	3632 ft	2
SITE NAME			MAPS	ID
Tanks Ent LLC			1 , 4	278713
ADDRESS			CITY	ZIP
8995 Three Flags Avenue			Hesperia	92345

DETAILS

Original Database: NPDES-SW-CA
 Last Agency Status: Listed
 Archive Date: 06/01/16
 No Longer Listed-Registered Meas ID: 278713
 Registered Meas Type: Construction
 WDID: 6B36C335897
 Received Date: 5/9/2008
 Processed Date: 8/5/2005
 Termination Date: 6/7/2010
 Status Code Name: Terminated
 Status Date: 6/16/2010
 REGION: Not Reported
 County Code: 36
 Place Size: 1
 Place Size Unit: Acres
 Facility County: San Bernardino
 Facility Contact Name: Rob Immerman
 Facility Contact Title: Not Reported
 Facility Contact Phone: 714-904-0994
 Facility Contact Phone Extension: Not Reported
 Facility Contact Email Address: Not Reported
 Operator Name: Tanks Ent LLC
 Operator Address: 14530 Whittier Blvd
 Operator City: Whittier
 Operator State: California
 Operator Zip: 90605
 Operator Contact Name: Brian Tanklage

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
HWIS-CA	Listed	0.03 miles S	3632 ft	2
SITE NAME			MAPS	ID
HIGH DESERT TRUCK & TRAILER			1 , 4	CAL000320679
ADDRESS			CITY	ZIP
8995 THREE FLAGS AVE STE B&C			VICTORVILLE	92344

DETAILS

Facility Information

EPA ID: CAL000320679
 Facility County: 36
 Mailing Street: 2429 S PECK RD
 Mailing City: WHITTIER
 Mailing State: CA
 Mailing Zip: 906010000
 Contact Name: DEVIN BECK
 Contact Phone: Not Reported

Generator Details

Year: 2019
 TONS: Not Reported
 TSD EPA ID: AZR000521146
 Category Code: 352
 Category Description: Other organic solids
 Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)

Year: 2019

TONS: Not Reported
 TSD EPA ID: CAT080013352
 Category Code: 223

Category Description: Unspecified oil-containing waste

Method Description: OTHER RECOVERY OF RECLAMATION FOR REUSE INCLUDING ACID REGENERATION, ORGANICS RECOVERY ECT

Year: 2019

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
RCRA-NON-US	Listed	0.03 miles S	3632 ft	2
SITE NAME			MAPS	ID
HIGH DESERT TRUCK & TRAILER			1 , 4	CAL000320679
ADDRESS			CITY	ZIP
8995 THREE FLAGS AVE STE B&C			VICTORVILLE	92344

DETAILS

Additional details may be found online using the following link:

https://enviro.epa.gov/enviro/rcrainfoquery_3.facility_information?pgm_sys_id=CAL000320679

Source Type: Implementer

Generator Status: Non-Generator

NAICS1: NEW CAR DEALERS

Active Site Indicator: H----

Owner Name: LOS ANGELES TRUCK SERVICE LLC

Operator Name: DEVIN BECK

In Handler Universes: Y

In a Universe: Y

Universal Waste: Y

Universal Waste Destination Facility: Y

Receive Date: 20070613

Acknowledge Flag Date: 20070613

Contact First Name: DEVIN

Contact Last Name: BECK

Contact Street 1: 2429 S. PCK RD.

Contact City: WHITTIER

Contact State: CA

Contact Zip: 90601-0000

Contact Phone: 909-510-4272

Contact E-mail Address: DBECK@VVGTRUCK.COM

Universal Waste Destination Facility: Y

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CUPA-CA	Listed	0.04 miles W	3623 ft	3
SITE NAME			MAPS	ID
THE LITZENBERGER COMPANY			1 , 4	FA0011408-SBD
ADDRESS			CITY	ZIP
12221 POPLAR ST 14			HESPERIA	92345

DETAILS

County: San Bernardino
 Responsible Agency: San Bernardino County Fire Department
 Facility ID: FA0011408
 Address2: Not Reported
 Owner Information: LITZENBERGER, TROY
 Contact Name: TROY LITZENBERGER
 Mailing Address: P.O. BOX 943, WRIGHTWOOD, CA 92397-0943
 Mailing Address 2: Not Reported
 Agency Provided Latitude: Not Reported
 Agency Provided Longitude: Not Reported
 Permit ID: PT0019744
 Program Element Code: 4221
 Permit Description: HAZMAT HANDLER 0-10 EMPLOYEES
 Status: INACTIVE
 To: 2/28/2013

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CERS-CA	Listed	0.06 miles W	3627 ft	4
SITE NAME			MAPS	ID
Superior Pool Products LLC #548A			1 , 4	10762693
ADDRESS			CITY	ZIP
12221 Poplar St Bldg E			Hesperia	92344

DETAILS

General Program & Facility Information

CERS ID: 10762693
 Facility ID: Not Reported
 Facility Regulator Key ID: Not Reported
 Organization Code: 90713275
 Business/Organization Name: Superior Pool Products LLC #548A
 Multiple Jurisdictional Business? (Y/N): No
 Business Origin: Business
 Count of Business CERS User Accounts: 1
 Facility Count for Business: 1
 Last Submittal Date (any element): Not Reported
 Count of Submitted Elements: 0
 Remote Facility? (Y/N): No
 Small Quantity Generator Facility? (Y/N): No
 Local Facility Grouping: Not Reported

Facility Specific Information

Assessor Parcel Number (APN): Not Reported
 Number of Employees: 4
 Property Owner Name: JT & LT Family LLC
 Property Owner Phone Number: 714-981-3623
 Property Owner Mailing Address: 310 Goetz Avenue
 Property Owner Mailing City: Santa Ana
 Property Owner Mailing State: CA
 Property Owner Mailing Zip Code: 92707
 Property Owner Mailing Country: United States

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CRSP-CA	Listed	0.06 miles W	3627 ft	4
SITE NAME			MAPS	ID
Superior Pool Products LLC #548A			1 , 4	437884
ADDRESS			CITY	ZIP
12221 POPLAR ST BLDG E			HESPERIA	92344

DETAILS

Site Regulated Program Information

Site ID: 437884

Site EI ID: 10762693

Agency Provided Latitude: 34.41542

Agency Provided Longitude: -117.39679

Program Description: Chemical Storage Facilities

Evaluation Information

: Not Reported

: Violation Information

: Not Reported

: Enforcement Information

: Not Reported

: Chemical Information

: Not Reported

: Coordinate Information

: Not Reported

:

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
AIR-DIST-CA	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
Zippy Lube			1, 4	842-MD
ADDRESS			CITY	ZIP
8899 Three Flags Avenue			Hesperia	92345

DETAILS

Note: This is an ERS assigned ID.
 Responsible Agency: Mohave Valley AQMD
 Permit Number: T010147
 Facility ID: 3040
 District ID: 1
 Permit Type: T
 Permit Status Code: PTO
 Permit Status: Permit To Operate
 Permit Desc: WASTE OIL TANK
 Employee Assigned: 62
 Address Region: Not Reported
 Fax Nbr: Not Reported
 Emission Calc: Not Reported
 Expired Date: 3/31/2018 11:59:59 PM
 Under Construction: False
 Last Renewal Date: Not Reported
 Secondary APC: Not Reported
 Primary APC: Not Reported
 Est Comp Date: Not Reported
 Est Start Date: Not Reported
 Issue Date: 9/20/2017 6:27:00 PM
 Application Date: 3/13/2008
 Permit Printed: True
 Batch Update: False
 Permit Detail Type: S
 Title VPMTwo: False
 Confidential: False

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
AIR-DIST-CA	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
IRONMAN RENEWAL LLC			1 , 4	177957-SC
ADDRESS			CITY	ZIP
8899 THREE FLAGS			HESPERIA	92345

DETAILS

District: South Coast AQMD
 Compliance URL:
http://www3.aqmd.gov/webappl/fim/prog/novnc.aspx?fac_id=177957
 Note: For additional Facility, Equipment, Emissions, Hearing Board or Transporation Plan Information click on different tabs.
 Facility Id: 177957
 County Code: SB
 County: San Bernardino
 Facility Status Code: A
 Facility Status: ACTIVE
 Number of Employees: 0
 Location Zip Code Extension: Not Reported
 Facility Representative First Name: YAMIL
 Facility Representative Last Name: TOMASSINI
 Location Area Code: 951
 Location Phone Number: 5202995
 Location Phone Extension: Not Reported
 Mailing Address: 2535 ANSELMO DR
 Mailing City: CORONA
 Mailing State: CA
 Mailing Zip Code: 92879
 Mailing Zip Code Extension: 8092
 Mailing Area Code: 951
 Mailing Phone Number: 5202995
 Mailing Phone Extension: Not Reported
 Mailing Representative First Name: YAMIL
 Mailing Representative Last Name: TOMASSINI

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
AST-CRSP-CA	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
ZIPPY LUBE-A-TRUCK			1 , 4	172882
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE			HESPERIA	92344

DETAILS

Site Regulated Program Information

Site ID: 172882

EI ID: 10049617

Agency Provided Address: 8899 THREE FLAGS AVE

Agency Provided Latitude: 34.413147

Agency Provided Longitude: -117.39313

Program Description: Aboveground Petroleum Storage

Evaluation Information (2017 to present)

Evaluation Date: 3/10/2020

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s):

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HMRRP

Evaluation Source: CERS

Evaluation Date: 3/10/2020

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s):

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HW

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CERS-CA	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
Little Sister's Truck Wash			1 , 4	10128901
ADDRESS			CITY	ZIP
8899 Three Flags Ave			Hesperia	92344

DETAILS

General Program & Facility Information

CERS ID: 10128901
 Facility ID: FA0010378
 Facility Regulator Key ID: FA0010378
 Organization Code: 90093058
 Business/Organization Name: Little Sister's Truck Wash
 Multiple Jurisdictional Business? (Y/N): No
 Business Origin: Business
 Count of Business CERS User Accounts: 1
 Facility Count for Business: 3
 Last Submittal Date (any element): 2/12/2018 11:31:19 PM
 Count of Submitted Elements: 18
 Remote Facility? (Y/N): No
 Small Quantity Generator Facility? (Y/N): No
 Local Facility Grouping: Not Reported

Facility Specific Information

Assessor Parcel Number (APN): Not Reported
 Number of Employees: 24
 Property Owner Name: Renald Anelle
 Property Owner Phone Number: 760-731-3170
 Property Owner Mailing Address: 25 Rollingview Lane
 Property Owner Mailing City: Fallbrook
 Property Owner Mailing State: CA
 Property Owner Mailing Zip Code: 92028
 Property Owner Mailing Country: United States

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CERS-CA	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
ZIPPY LUBE-A-TRUCK			1 , 4	10049617
ADDRESS			CITY	ZIP
8899 Three Flags Ave			Hesperia	92344

DETAILS

General Program & Facility Information

CERS ID: 10049617
 Facility ID: FA0009125
 Facility Regulator Key ID: FA0009125
 Organization Code: 90135682
 Business/Organization Name: ZIPPY LUBE
 Multiple Jurisdictional Business? (Y/N): Yes
 Business Origin: Business
 Count of Business CERS User Accounts: 1
 Facility Count for Business: 6
 Last Submittal Date (any element): 8/8/2018 10:46:18 AM
 Count of Submitted Elements: 20
 Remote Facility? (Y/N): No
 Small Quantity Generator Facility? (Y/N): No
 Local Facility Grouping: Not Reported

Facility Specific Information

Assessor Parcel Number (APN): Not Reported
 Number of Employees: 2
 Property Owner Name: Not Reported
 Property Owner Phone Number: Not Reported
 Property Owner Mailing Address: Not Reported
 Property Owner Mailing City: Not Reported
 Property Owner Mailing State: Not Reported
 Property Owner Mailing Zip Code: Not Reported
 Property Owner Mailing Country: Not Reported

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
County-AST-CA	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
ZIPPY LUBE-A-TRUCK			1 , 4	FA0009125-SBD
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE B			Hesperia	92344

DETAILS

County: San Bernardino
 Responsible Agency: San Bernardino Division of Environmental Health Services
 Facility ID: FA0009125
 Address2: Not Reported
 Owner Information: Ren Anelle
 Contact Name: Not Reported
 Mailing Address: P.O. Box 7509, LAGUNA NIGUEL, CA 92607
 Mailing Address2: Not Reported
 Permit ID: PT0023266
 Program Element Code: 4031
 Permit Description: APSA 1,320-10,000 GAL FAC CAPACITY
 Status: ACTIVE
 To: 12/31/2018

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CRSP-CA	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
ZIPPY LUBE-A-TRUCK			1 , 4	172882
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE			HESPERIA	92344

DETAILS

Site Regulated Program Information

Site ID: 172882

Site EI ID: 10049617

Agency Provided Latitude: 34.413147

Agency Provided Longitude: -117.39313

Program Description: Aboveground Petroleum Storage

Program Description: Chemical Storage Facilities

Program Description: Hazardous Waste Generator

Evaluation Information

Evaluation Date: 1/9/2017

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): ROUTINE GENERATOR INSPECTION

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HW

Evaluation Source: CERS

Evaluation Date: 1/9/2017

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CRSP-CA	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
Little Sister's Truck Wash			1 , 4	130941
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE			HESPERIA	92344

DETAILS

Site Regulated Program Information

Site ID: 130941

Site EI ID: 10128901

Agency Provided Latitude: 37.271881

Agency Provided Longitude: -119.27023

Program Description: Chemical Storage Facilities

Program Description: Hazardous Waste Generator

Evaluation Information

Evaluation Date: 6/3/2016

Violations Found? (Y/N): No

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): LITTLE SISTER'S TRUCK WASH- CUPA WASTE INSPECTION

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HW

Evaluation Source: CERS

Evaluation Date: 6/3/2016

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): LITTLE SISTERS- CUPA HANDLER INSPECTION

Evaluation Division: San Bernardino County Fire Department

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CUPA-CA	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
Little Sister's Truck Wash			1 , 4	FA0010378-SBD
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE			Hesperia	92344

DETAILS

County: San Bernardino
 Responsible Agency: San Bernardino County Fire Department
 Facility ID: FA0010378
 Address2: Not Reported
 Owner Information: Little Sister's Truck Wash, Inc.
 Contact Name: Not Reported
 Mailing Address: 25 Rollingview Lane, Fallbrook, CA 92028
 Mailing Address 2: Not Reported
 Agency Provided Latitude: Not Reported
 Agency Provided Longitude: Not Reported
 Permit ID: PT0017654
 Program Element Code: 4244
 Permit Description: HAZARDOUS MATERIALS 11-30 CHEMICALS
 Status: ACTIVE
 To: 5/31/2019

 Permit ID: PT0017973
 Program Element Code: 4453
 Permit Description: SMALL QUANTITY GENERATOR
 Status: ACTIVE
 To: 5/31/2019

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CUPA-CA	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
ZIPPY LUBE-A-TRUCK			1 , 4	FA0009125-SBD
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE B			Hesperia	92344

DETAILS

County: San Bernardino
 Responsible Agency: San Bernardino County Fire Department
 Facility ID: FA0009125
 Address2: Not Reported
 Owner Information: Ren Anelle
 Contact Name: Not Reported
 Mailing Address: P.O. Box 7509, LAGUNA NIGUEL, CA 92607
 Mailing Address 2: Not Reported
 Agency Provided Latitude: Not Reported
 Agency Provided Longitude: Not Reported
 Permit ID: PT0015214
 Program Element Code: 4454
 Permit Description: LARGE QUANTITY GENERATOR
 Status: ACTIVE
 To: 12/31/2019

Permit ID: PT0015215
 Program Element Code: 4243
 Permit Description: HAZARDOUS MATERIALS 4-10 CHEMICALS
 Status: ACTIVE
 To: 12/31/2019

Permit ID: PT0023266
 Program Element Code: 4031
 Permit Description: APSA 1,320-10,000 GAL FAC CAPACITY
 Status: ACTIVE
 To: 12/31/2019

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
FRS-US	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
LITTLE SISTER'S TRUCK WASH			1, 4	110066395494
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE			HESPERIA	92344
DETAILS				
FRS Facility Detail Report URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110066395494 Create Date: 14-OCT-2015 11:18:47 Program System: CA-ENVIROVIEW Interest Type(s): STATE MASTER				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
FRS-US	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
ZIPPY LUBE-A-TRUCK, INC.			1 , 4	110033211245
ADDRESS			CITY	ZIP
8899B THREE FLAGS AVENUE			HESPERIA	92345-
DETAILS				
FRS Facility Detail Report URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110033211245 Create Date: 29-FEB-2008 02:16:06 Program System: UORS Interest Type(s): STATE MASTER				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
FRS-US	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
ZIPPY LUBE-A-TRUCK			1 , 4	110066206484
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE			HESPERIA	92344
DETAILS				
FRS Facility Detail Report URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110066206484 Create Date: 14-OCT-2015 10:26:38 Program System: CA-ENVIROVIEW Interest Type(s): STATE MASTER				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
Hist-CA	Name Changed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
LITTLE SISTERS TRUCK WASH			<u>1</u> , <u>4</u>	FA0010378-SBD
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE			HESPERIA	92345
DETAILS				
Original Database: CUPA-CA Last Agency Status: Listed Archive Date: 06/04/17 Name Changed-County: San Bernardino Responsible Agency: San Bernardino County Fire Department Facility ID: FA0010378 Address2: Not Reported Owner Information: LITTLE SISTER'S TRUCK WASH Contact Name: Not Reported Mailing Address: 25 ROLLING VIEW LN, FALLBROOK, CA 92028 Mailing Address 2: Not Reported Agency Provided Latitude: Not Reported Agency Provided Longitude: Not Reported Permit ID: PT0017654 Program Element Code: 4244 Permit Description: HAZARDOUS MATERIALS 11-30 CHEMICALS Status: ACTIVE To: 5/31/2017 Permit ID: PT0017973 Program Element Code: 4453 Permit Description: SMALL QUANTITY GENERATOR Status: ACTIVE To: 5/31/2017				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
Hist-CA	No Longer Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
IRONMAN RENEWAL DBA ZIPPY LUBE A TRUCK			<u>1</u> , <u>4</u>	CAL000344771
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE			OAK HILLS	923440497

DETAILS

Original Database: HWIS-CA
 Last Agency Status: Listed
 Archive Date: 10/07/21
 No Longer Listed-EPA ID: CAL000344771
 Facility County: 36
 Mailing Street: 2535 ANSELMO DR
 Mailing City: ANSELMO
 Mailing State: CA
 Mailing Zip: 928798092
 Contact Name: SAM MCMILLAN
 Contact Phone: 9517353710

Year: 2016
 TONS: 0.1
 TSD EPA ID: AZD081705402
 Category Code: 331
 Category Description: Off-specification, aged or surplus organics
 Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)

Year: 2015
 TONS: 0.2
 TSD EPA ID: AZD081705402
 Category Code: 352
 Category Description: Other organic solids
 Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)

Year: 2015

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
Hist-CA	No Longer Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
IRONMAN RENEWAL DBA ZIPPY LUBE A TRUCK			1 , 4	54FDFFFA-CAL000344771
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE			OAK HILLS	92344
DETAILS				
Previous List: HWIS-CA Archived: 4/2/2012				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
Hist-CA	No Longer Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
ANELLE MANAGEMENT SERVICES INC DBA FLEET CREW			1, 4	CAL000416670
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE			HESPERIA	923440497
DETAILS				
Original Database: HWIS-CA Last Agency Status: Listed Archive Date: 10/07/21 No Longer Listed-EPA ID: CAL000416670 Facility County: 36 Mailing Street: 30025 ALICIA PKWY Mailing City: LAGUNA NIGUEL Mailing State: CA Mailing Zip: 92677 Contact Name: CRAIG PHILLIPS Contact Phone: 9516600400 Year: 2017 TONS: 1.665 TSD EPA ID: CAD097030993 Category Code: 352 Category Description: Other organic solids Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135) Year: 2017 TONS: 0.22935 TSD EPA ID: CAD097030993 Category Code: 491 Category Description: Unspecified sludge waste Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135) Year: 2017 More Details Link				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
HWIS-CA	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
FLEETCREW			1 , 4	CAL000416670
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE			HESPERIA	92344
DETAILS				
Facility Information EPA ID: CAL000416670 Facility County: 36 Mailing Street: "29911 NIGUEL ROAD " Mailing City: LAGUNA NIGUEL Mailing State: CA Mailing Zip: 926070000 Contact Name: CRAIG PHILLIPS Contact Phone: Not Reported Generator Details Year: 2019 TONS: Not Reported TSD EPA ID: CAD097030993 Category Code: 352 Category Description: Other organic solids Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/RECOVERY (H010-H129) OR (H131-H135)				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
RCRA-NON-US	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
LITTLE SISTERS TRUCK WASH INC			1 , 4	CAL000353253
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE			OAK HILLS	92344

DETAILS

Additional details may be found online using the following link:

https://enviro.epa.gov/enviro/rcrainfoquery_3.facility_information?pgm_sys_id=CAL000353253

Source Type: Implementer
 Generator Status: Non-Generator
 NAICS1: CAR WASHES
 Active Site Indicator: H----
 Owner Name: LITTLE SISTERS TRUCK WASH INC
 Operator Name: JOE MCFANN
 In Handler Universes: Y
 In a Universe: Y
 Universal Waste: Y
 Universal Waste Destination Facility: Y

Receive Date: 20100610
 Acknowledge Flag Date: 20100610
 Contact First Name: JOE
 Contact Last Name: MCFANN
 Contact Street 1: 8899 THREE FLAGS AVE
 Contact City: OAK HILLS
 Contact State: CA
 Contact Zip: 92344
 Contact Phone: 760-947-4448
 Contact FAX: 760-956-1270
 Contact E-mail Address: RJA@YELLOWMAGIC.COM
 Universal Waste Destination Facility: Y

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
RCRA-NON-US	Listed	0.06 miles S	3634 ft	5
SITE NAME			MAPS	ID
ANELLE MANAGEMENT SERVICES INC DBA FLEET			1 , 4	CAL000416670
ADDRESS			CITY	ZIP
8899 THREE FLAGS AVE			HESPERIA	92344

DETAILS

Additional details may be found online using the following link:

https://enviro.epa.gov/enviro/rcrainfoquery_3.facility_information?pgm_sys_id=CAL000416670

Source Type: Implementer

Generator Status: Non-Generator

NAICS1: GENERAL AUTOMOTIVE REPAIR

Active Site Indicator: H----

Owner Name: ANELLE MGMT SRV INC DBA FLEET CREW

Operator Name: CRAIG PHILLIPS

In Handler Universes: Y

In a Universe: Y

Universal Waste: Y

Universal Waste Destination Facility: Y

Receive Date: 20160502

Acknowledge Flag Date: 20160502

Contact First Name: CRAIG

Contact Last Name: PHILLIPS

Contact Street 1: 29911 NIGUEL ROAD #7509

Contact City: LAGUNA NIGUEL

Contact State: CA

Contact Zip: 92607-0000

Contact Phone: 951-660-0400

Contact FAX: 951-848-0713

Contact E-mail Address: CRAIG.PHILLIPS@FLEETCREW.COM

Universal Waste Destination Facility: Y

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CUPA-CA	Listed	0.06 miles W	3624 ft	6
SITE NAME			MAPS	ID
DESERT DYNAMICS OFFROAD			1 , 4	FA0012792-SBD
ADDRESS			CITY	ZIP
12221 POPLAR ST BLDG B-10			HESPERIA	92344

DETAILS

County: San Bernardino
 Responsible Agency: San Bernardino County Fire Department
 Facility ID: FA0012792
 Address2: Not Reported
 Owner Information: LAWSON, DAVE
 Contact Name: DAVE LAWSON
 Mailing Address: 12221 POPLAR ST BLDG B-10, HESPERIA, CA 92344
 Mailing Address 2: Not Reported
 Agency Provided Latitude: Not Reported
 Agency Provided Longitude: Not Reported
 Permit ID: PT0022349
 Program Element Code: 4221
 Permit Description: HAZMAT HANDLER 0-10 EMPLOYEES
 Status: INACTIVE
 To: 10/31/2010

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CERS-CA	Listed	0.08 miles W	3628 ft	7
SITE NAME			MAPS	ID
3M OAK HILLS			1 , 4	10311793
ADDRESS			CITY	ZIP
12221 POPLAR ST UNIT D20			OAK HILLS	92344

DETAILS

General Program & Facility Information

CERS ID: 10311793
 Facility ID: FA0013596
 Facility Regulator Key ID: FA0013596
 Organization Code: 90278605
 Business/Organization Name: 3M OAK HILLS
 Multiple Jurisdictional Business? (Y/N): No
 Business Origin: Seeding
 Count of Business CERS User Accounts: 3
 Facility Count for Business: 2
 Last Submittal Date (any element): 3/6/2018 12:28:21 PM
 Count of Submitted Elements: 21
 Remote Facility? (Y/N): No
 Small Quantity Generator Facility? (Y/N): No
 Local Facility Grouping: Not Reported

Facility Specific Information

Assessor Parcel Number (APN): Not Reported
 Number of Employees: 2
 Property Owner Name: Not Reported
 Property Owner Phone Number: Not Reported
 Property Owner Mailing Address: Not Reported
 Property Owner Mailing City: Not Reported
 Property Owner Mailing State: Not Reported
 Property Owner Mailing Zip Code: Not Reported
 Property Owner Mailing Country: Not Reported

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CRSP-CA	Listed	0.08 miles W	3628 ft	7
SITE NAME			MAPS	ID
3M OAK HILLS			1 , 4	617
ADDRESS			CITY	ZIP
12221 POPLAR ST UNIT D20			OAK HILLS	92344

DETAILS

Site Regulated Program Information

Site ID: 617

Site EI ID: 10311793

Agency Provided Latitude: 34.41542

Agency Provided Longitude: -117.39626

Program Description: Chemical Storage Facilities

Evaluation Information

Evaluation Date: 9/29/2016

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): HANDLER INSPECTION

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HMRRP

Evaluation Source: CERS

Violation Information

Violation Date: 9/29/2016

Citation: HSC 6.95 25508.1(a)-(f) - California Health and Safety Code, Chapter 6.95, Section(s) 25508.1(a)-(f)

Violation Description: Failure to electronically update business plan within 30 days of any one of the following events:

A 100 percent or more increase in the quantity of a previously disclosed material.

Any handling of a previously undisclosed hazardous materials at or above reportable quantities.

A change of business address, business ownership, or business name.

A substantial change in the handler's operations that requires modification to any portion of the business plan.

Violation Note(s): Returned to compliance on 10/19/2016. Update submitted chemical inventory, facility site map, and emergency response plan.

Violation Division: San Bernardino County Fire Department

Violation Program: HMRRP

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CUPA-CA	Listed	0.08 miles W	3628 ft	7
SITE NAME			MAPS	ID
3M OAK HILLS			1 , 4	FA0013596-SBD
ADDRESS			CITY	ZIP
12221 POPLAR ST UNIT D20			OAK HILLS	92344

DETAILS

County: San Bernardino
 Responsible Agency: San Bernardino County Fire Department
 Facility ID: FA0013596
 Address2: Not Reported
 Owner Information: 3M COMPANY
 Contact Name: Not Reported
 Mailing Address: 8981 US HWY 395, OAK HILLS, CA 92344
 Mailing Address 2: Not Reported
 Agency Provided Latitude: Not Reported
 Agency Provided Longitude: Not Reported
 Permit ID: PT0023866
 Program Element Code: 4244
 Permit Description: HAZARDOUS MATERIALS 11-30 CHEMICALS
 Status: ACTIVE
 To: 11/30/2019

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CUPA-CA	Listed	0.11 miles SW	3642 ft	8
SITE NAME			MAPS	ID
High Desert Truck and Trailer			1 , 4	FA0016142-SBD
ADDRESS			CITY	ZIP
8895 THREE FLAGS AVE			Hesperia	92345

DETAILS

County: San Bernardino
 Responsible Agency: San Bernardino County Fire Department
 Facility ID: FA0016142
 Address2: Not Reported
 Owner Information: Brad Fauvre & Conan Barker
 Contact Name: Not Reported
 Mailing Address: 8995 Three Flags Ave., Hesperia, CA 92345
 Mailing Address 2: Not Reported
 Agency Provided Latitude: Not Reported
 Agency Provided Longitude: Not Reported
 Permit ID: PT0034884
 Program Element Code: 4453
 Permit Description: SMALL QUANTITY GENERATOR
 Status: ACTIVE
 To: 8/31/2019

 Permit ID: PT0034885
 Program Element Code: 4243
 Permit Description: HAZARDOUS MATERIALS 4-10 CHEMICALS
 Status: ACTIVE
 To: 8/31/2019

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CERS-CA	Listed	0.11 miles S	3641 ft	9
SITE NAME			MAPS	ID
DIRECTV			1 , 4	10312237
ADDRESS			CITY	ZIP
12269 SCARBROUGH CT			HESPERIA	92345

DETAILS

General Program & Facility Information

CERS ID: 10312237
 Facility ID: FA0013884
 Facility Regulator Key ID: FA0013884
 Organization Code: 90430663
 Business/Organization Name: DIRECTV, LLC
 Multiple Jurisdictional Business? (Y/N): Yes
 Business Origin: Business
 Count of Business CERS User Accounts: 41
 Facility Count for Business: 37
 Last Submittal Date (any element): Not Reported
 Count of Submitted Elements: 0
 Remote Facility? (Y/N): No
 Small Quantity Generator Facility? (Y/N): No
 Local Facility Grouping: Not Reported

Facility Specific Information

Assessor Parcel Number (APN): Not Reported
 Number of Employees: 110
 Property Owner Name: Not Reported
 Property Owner Phone Number: Not Reported
 Property Owner Mailing Address: Not Reported
 Property Owner Mailing City: Not Reported
 Property Owner Mailing State: Not Reported
 Property Owner Mailing Zip Code: Not Reported
 Property Owner Mailing Country: Not Reported

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CUPA-CA	Listed	0.11 miles S	3641 ft	9
SITE NAME			MAPS	ID
CDM CONSTRUCTORS INC.			1 , 4	FA0008728-SBD
ADDRESS			CITY	ZIP
12269 SCARBROUGH CT			HESPERIA	92345

DETAILS

County: San Bernardino
 Responsible Agency: San Bernardino County Fire Department
 Facility ID: FA0008728
 Address2: Not Reported
 Owner Information: CDM CONSTRUCTORS INC.
 Contact Name: JOYCE JACKSON
 Mailing Address: 12269 SCARBROUGH COURT, HESPERIA, CA 92345-0000
 Mailing Address 2: Not Reported
 Agency Provided Latitude: Not Reported
 Agency Provided Longitude: Not Reported
 Permit ID: PT0015514
 Program Element Code: 4221
 Permit Description: HAZMAT HANDLER 0-10 EMPLOYEES
 Status: INACTIVE
 To: 12/31/2006

Permit ID: PT0015515
 Program Element Code: 4202
 Permit Description: HAZMAT HANDLER 0-10 EMPLOYEES (W/GEN PRMT)
 Status: INACTIVE
 To: 12/31/2004

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CUPA-CA	Listed	0.11 miles S	3641 ft	9
SITE NAME			MAPS	ID
DIRECTV			1 , 4	FA0013884-SBD
ADDRESS			CITY	ZIP
12269 SCARBROUGH CT			HESPERIA	92345

DETAILS
County: San Bernardino Responsible Agency: San Bernardino County Fire Department Facility ID: FA0013884 Address2: Not Reported Owner Information: DIRECTV Contact Name: Not Reported Mailing Address: 12269 SCARBROUGH CT, HESPERIA, CA 92344 Mailing Address 2: Not Reported Agency Provided Latitude: Not Reported Agency Provided Longitude: Not Reported Permit ID: PT0024398 Program Element Code: 4241 Permit Description: HAZARDOUS MATERIALS 1-3 CHEMICALS SPECIAL Status: INACTIVE To: 9/30/2012

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CUPA-CA	Listed	0.11 miles S	3641 ft	9
SITE NAME			MAPS	ID
3M OAK HILLS REMOTE STORAGE			1 , 4	FA0012098-SBD
ADDRESS			CITY	ZIP
12269 SCARBROUGH CT			HESPERIA	92344
DETAILS				
County: San Bernardino Responsible Agency: San Bernardino County Fire Department Facility ID: FA0012098 Address2: Not Reported Owner Information: 3M COMPANY Contact Name: 3M OAK HILLS Mailing Address: 8981 US HWY 395, HESPERIA, CA 92344 Mailing Address 2: Not Reported Agency Provided Latitude: Not Reported Agency Provided Longitude: Not Reported Permit ID: PT0021294 Program Element Code: 4250 Permit Description: HAZMAT HANDLER - UNSTAFFED REMOTE FACILITY Status: INACTIVE To: 3/31/2011				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CERS-CA	Listed	0.12 miles SW	3643 ft	10
SITE NAME			MAPS	ID
RV Supply Center, Inc			1 , 4	10609933
ADDRESS			CITY	ZIP
8893 Three Flags Ave Ste B			Oak Hills	92344
DETAILS				
General Program & Facility Information CERS ID: 10609933 Facility ID: FA0016222 Facility Regulator Key ID: FA0016222 Organization Code: 90574786 Business/Organization Name: RV Supply Center, Inc Multiple Jurisdictional Business? (Y/N): No Business Origin: Business Count of Business CERS User Accounts: 4 Facility Count for Business: 1 Last Submittal Date (any element): 4/16/2018 4:27:39 PM Count of Submitted Elements: 20 Remote Facility? (Y/N): No Small Quantity Generator Facility? (Y/N): No Local Facility Grouping: Not Reported Facility Specific Information Assessor Parcel Number (APN): Not Reported Number of Employees: Not Reported Property Owner Name: 760-949-1222 Property Owner Phone Number: 760-949-1222 Property Owner Mailing Address: 8893 Three Flags Ave Ste B Property Owner Mailing City: Oak Hills Property Owner Mailing State: CA Property Owner Mailing Zip Code: 92344 Property Owner Mailing Country: United States More Details Link				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CRSP-CA	Listed	0.12 miles SW	3643 ft	10
SITE NAME			MAPS	ID
RV Supply Center, Inc			1 , 4	277513
ADDRESS			CITY	ZIP
8893 THREE FLAGS AVE STE B			OAK HILLS	92344
DETAILS				
Site Regulated Program Information Site ID: 277513 Site EI ID: 10609933 Agency Provided Latitude: 34.36946 Agency Provided Longitude: -117.42963 Program Description: Chemical Storage Facilities Program Description: Hazardous Waste Generator Evaluation Information Evaluation Date: 4/4/2018 Violations Found? (Y/N): Yes Evaluation General Type: Compliance Evaluation Inspection Evaluation Type: Routine done by local agency Evaluation Note(s): Not Reported Evaluation Division: San Bernardino County Fire Department Evaluation Program: HW Evaluation Source: CERS Evaluation Date: 4/4/2018 Violations Found? (Y/N): Yes Evaluation General Type: Compliance Evaluation Inspection Evaluation Type: Routine done by local agency Evaluation Note(s): Not Reported Evaluation Division: San Bernardino County Fire Department More Details Link				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CUPA-CA	Listed	0.12 miles SW	3643 ft	10
SITE NAME			MAPS	ID
RV Supply Center, Inc			1, 4	FA0016222-SBD
ADDRESS			CITY	ZIP
8893 Three Flags Ave Ste B			Oak Hills	92344
DETAILS				
County: San Bernardino Responsible Agency: San Bernardino County Fire Department Facility ID: FA0016222 Address2: Not Reported Owner Information: Mark Boesch Contact Name: Not Reported Mailing Address: 8893 Three Flags Ave Ste B, Oak Hills, CA 92344 Mailing Address 2: Not Reported Agency Provided Latitude: Not Reported Agency Provided Longitude: Not Reported Permit ID: PT0036888 Program Element Code: 4243 Permit Description: HAZARDOUS MATERIALS 4-10 CHEMICALS Status: ACTIVE To: 5/31/2019 Permit ID: PT0036889 Program Element Code: 4453 Permit Description: SMALL QUANTITY GENERATOR Status: ACTIVE To: 5/31/2019				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
Hist-Auto Repair	Listed	0.12 miles SW	3643 ft	10
SITE NAME			MAPS	ID
WINGFOOT COMMERCIAL TIRE SYSTS			1, 4	16670
ADDRESS			CITY	ZIP
8893 THREE FLAGS AVE			Hesperia	92344

DETAILS
Sic Code: 5531 Desc: Auto, Truck & Tire Service Site Added: 2/2010

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
RCRA-NON-US	Listed	0.12 miles SW	3643 ft	10
SITE NAME			MAPS	ID
RV SUPPLY CENTER INC			1, 4	CAL000307361
ADDRESS			CITY	ZIP
8893 THREE FLAGS AVE STE B			OAK HILLS	92344

DETAILS
Additional details may be found online using the following link: https://enviro.epa.gov/enviro/rcrainfoquery_3.facility_information?pgm_sys_id=CAL000307361 Source Type: Implementer Generator Status: Non-Generator NAICS1: RECREATIONAL VEHICLE DEALERS Active Site Indicator: H---- Owner Name: RV SUPPLY CENTER INC Operator Name: MARK BOESCH In Handler Universes: Y In a Universe: Y Universal Waste: Y Universal Waste Destination Facility: Y Receive Date: 20060526 Acknowledge Flag Date: 20060526 Contact First Name: MARK Contact Last Name: BOESCH Contact Street 1: 8893 THREE FLAGS AVE STE B Contact City: OAK HILLS Contact State: CA Contact Zip: 92344 Contact Phone: 760-949-1222 Contact FAX: 000-000-0000 Contact E-mail Address: MARK@RVSCINC.COM Universal Waste Destination Facility: Y More Details Link

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CERS-CA	Listed	0.19 miles SW	3645 ft	11
SITE NAME			MAPS	ID
DOUBLE EAGLE TRANSPORTATION			1, 4	10049065
ADDRESS			CITY	ZIP
12135 SCARBROUGH CT			HESPERIA	92345
DETAILS				
General Program & Facility Information CERS ID: 10049065 Facility ID: FA0008746 Facility Regulator Key ID: FA0008746 Organization Code: 90044872 Business/Organization Name: DOUBLE EAGLE TRANSPORTATION Multiple Jurisdictional Business? (Y/N): No Business Origin: Business Count of Business CERS User Accounts: 3 Facility Count for Business: 1 Last Submittal Date (any element): 12/5/2018 4:02:03 PM Count of Submitted Elements: 77 Remote Facility? (Y/N): No Small Quantity Generator Facility? (Y/N): No Local Facility Grouping: Not Reported Facility Specific Information Assessor Parcel Number (APN): 3.06459116e+012 Number of Employees: 133 Property Owner Name: Gerald Butcher Property Owner Phone Number: (760) 956-3770 Property Owner Mailing Address: 12135 Scarbrough Court Property Owner Mailing City: Hesperia Property Owner Mailing State: CA Property Owner Mailing Zip Code: 92344 Property Owner Mailing Country: United States More Details Link				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
County-UST-CA	Listed	0.19 miles SW	3645 ft	11
SITE NAME			MAPS	ID
DOUBLE EAGLE TRANSPORTATION			1 , 4	FA0008746-SBD
ADDRESS			CITY	ZIP
12135 SCARBROUGH CT			HESPERIA	92345
DETAILS				
County: San Bernardino Responsible Agency: San Bernardino Division of Environmental Health Services Facility ID: FA0008746 Address2: Not Reported Owner Info: Double Eagle Transportation Inc. Contact Name: GERALD BUTCHER Mailing Address: 12135 Scarbrough Court, Hesperia, CA 92345 Mailing Address2: Not Reported Permit ID: PT0016928 Program Element Code: 4104 Permit Description: REGULAR UST ANNUAL INSPECTION (PER TANK) Status: ACTIVE To: 8/31/2019				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CRSP-CA	Listed	0.19 miles SW	3645 ft	11
SITE NAME			MAPS	ID
DOUBLE EAGLE TRANSPORTATION			1 , 4	391724
ADDRESS			CITY	ZIP
12135 SCARBROUGH CT			HESPERIA	92345

DETAILS

Site Regulated Program Information

Site ID: 391724

Site EI ID: 10049065

Agency Provided Latitude: 34.41259

Agency Provided Longitude: -117.39805

Program Description: Chemical Storage Facilities

Program Description: Hazardous Waste Generator

Program Description: Underground Storage Tank

Evaluation Information

Evaluation Date: 8/28/2018

Violations Found? (Y/N): No

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): Not Reported

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: UST

Evaluation Source: CERS

Evaluation Date: 8/22/2018

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CUPA-CA	Listed	0.19 miles SW	3645 ft	11
SITE NAME			MAPS	ID
DOUBLE EAGLE TRANSPORTATION			1 , 4	FA0008746-SBD
ADDRESS			CITY	ZIP
12135 SCARBROUGH CT			HESPERIA	92345

DETAILS

County: San Bernardino
 Responsible Agency: San Bernardino County Fire Department
 Facility ID: FA0008746
 Address2: Not Reported
 Owner Information: Double Eagle Transportation Inc.
 Contact Name: GERALD BUTCHER
 Mailing Address: 12135 Scarbrough Court, Hesperia, CA 92345
 Mailing Address 2: Not Reported
 Agency Provided Latitude: Not Reported
 Agency Provided Longitude: Not Reported
 Permit ID: PT0016926
 Program Element Code: 4454
 Permit Description: LARGE QUANTITY GENERATOR
 Status: ACTIVE
 To: 8/31/2019

Permit ID: PT0016927
 Program Element Code: 4243
 Permit Description: HAZARDOUS MATERIALS 4-10 CHEMICALS
 Status: ACTIVE
 To: 8/31/2019

Permit ID: PT0016928
 Program Element Code: 4104
 Permit Description: REGULAR UST ANNUAL INSPECTION (PER TANK)
 Status: ACTIVE
 To: 8/31/2019

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
DryCleaners-CA	Listed	0.19 miles SW	3645 ft	11
SITE NAME			MAPS	ID
DOUBLE EAGLE TRANSPORTATION			1, 4	CAL000225630
ADDRESS			CITY	ZIP
12135 SCARBOROUGH CT			HESPERIA	923450000

DETAILS

EPA ID: CAL000225630
 Create Date: 12/18/2001
 Facility Act Ind: y
 Inact Date: Not Reported
 Facility Street2: Not Reported
 County: San Bernardino
 Latitude: 0
 Longitude: 0
 Mailing Name: Not Reported
 Facility Mailing Address: 12135 SCARBROUGH CT
 Facility Mailing Address 2: Not Reported
 Facility Mailing City: OAK HILLS
 Facility Mailing State: CA
 Facility Mailing Zip Code: 923449200
 Region Code: 4
 Owner Name: JERRY BUTCHER
 Owner Address: 12135 SCARBROUGH CT
 Owner Address2: Not Reported
 Owner City: OAK HILLS
 Owner State: CA
 Owner Zip Code: 923449200
 Owner Phone Number: 7609563770
 Owner Fax Number: 7609566362
 Contact Name: TONY MCKINNEY
 Contact Address: 12135 SCARBROUGH COURT
 Contact Address2: Not Reported
 Contact City: HESPERIA

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
RCRA-NON-US	Listed	0.19 miles SW	3645 ft	11
SITE NAME			MAPS	ID
DOUBLE EAGLE TRANSPORTATION			1 , 4	CAL000225630
ADDRESS			CITY	ZIP
12135 SCARBOROUGH CT			HESPERIA	92345

DETAILS

Additional details may be found online using the following link:

https://enviro.epa.gov/enviro/rcrainfoquery_3.facility_information?pgm_sys_id=CAL000225630

Source Type: Implementer

Generator Status: Non-Generator

NAICS1: GENERAL FREIGHT TRUCKING

Active Site Indicator: H----

Owner Name: JERRY BUTCHER

Operator Name: TONY MCKINNEY

In Handler Universes: Y

In a Universe: Y

Universal Waste: Y

Universal Waste Destination Facility: Y

Receive Date: 20011218

Acknowledge Flag Date: 20011218

Contact First Name: TONY

Contact Last Name: MCKINNEY

Contact Street 1: 12135 SCARBROUGH COURT

Contact City: HESPERIA

Contact State: CA

Contact Zip: 92344

Contact Phone: 760-956-3770

Contact FAX: 760-956-6362

Contact E-mail Address: SAFETYDIRECTOR@DOUBLEEAGLETRANS.COM

Universal Waste Destination Facility: Y

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
UST-CA	Listed	0.19 miles SW	3645 ft	11
SITE NAME			MAPS	ID
DOUBLE EAGLE TRANSPORTATION			1 , 4	243095
ADDRESS			CITY	ZIP
12135 SCARBROUGH CT			HESPERIA	92345

DETAILS

More Information on Site? Go to Following Link:
<http://geotracker.waterboards.ca.gov/search.asp>
 CERSID: 10049065
 Global ID: FA0008746
 COUNTY: San Bernardino
 Permitting Agency: San Bernardino County Fire Department
 Agency Provided Latitude: 34.41259
 Agency Provided Longitude: -117.398056
 PROJECT TYPE: Not Reported
 RB Case Number: Not Reported
 LOC Case Number: Not Reported
 Case Worker: Not Reported
 MTBE DATE: Not Reported
 GW CONC (PPB): Not Reported
 MATRIX: Not Reported

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
UST-CRSP-CA	Listed	0.19 miles SW	3645 ft	11
SITE NAME			MAPS	ID
DOUBLE EAGLE TRANSPORTATION			1 , 4	391724
ADDRESS			CITY	ZIP
12135 SCARBROUGH CT			HESPERIA	92345

DETAILS

Site Regulated Program Information

Site ID: 391724

EI ID: 10049065

Agency Provided Address: 12135 SCARBROUGH CT

Agency Provided Latitude: 34.41259

Agency Provided Longitude: -117.39805

Program Description: Underground Storage Tank

Evaluation Information (2017 to present)

Evaluation Date: 11/9/2021

Violations Found? (Y/N): No

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s):

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HMRRP

Evaluation Source: CERS

Evaluation Date: 11/9/2021

Violations Found? (Y/N): No

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s):

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HW

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
AST-CRSP-CA	Listed	0.21 miles S	3649 ft	12
SITE NAME			MAPS	ID
BEST LUBE TRUCK SERVICE & REPAIRS LLC			1, 4	11970
ADDRESS			CITY	ZIP
8853 THREE FLAGS AVE STE C			HESPERIA	92344

DETAILS

Site Regulated Program Information

Site ID: 11970

EI ID: 10402582

Agency Provided Address: 8853 THREE FLAGS AVE STE C

Agency Provided Latitude: 34.41111

Agency Provided Longitude: -117.39383

Program Description: Aboveground Petroleum Storage

Evaluation Information (2017 to present)

Evaluation Date: 11/4/2021

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s):

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HMRRP

Evaluation Source: CERS

Evaluation Date: 11/4/2021

Violations Found? (Y/N): No

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s):

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: HW

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CERS-CA	Listed	0.21 miles S	3649 ft	12
SITE NAME			MAPS	ID
BEST LUBE TRUCK SERVICE & REPAIRS LLC			1, 4	10402582
ADDRESS			CITY	ZIP
8853 Three Flags Ave Ste C			Hesperia	92344

DETAILS

General Program & Facility Information

CERS ID: 10402582
 Facility ID: FA0014891
 Facility Regulator Key ID: FA0014891
 Organization Code: 90364402
 Business/Organization Name: BEST LUBE TRUCK SERVICE & REPAIRS LLC
 Multiple Jurisdictional Business? (Y/N): No
 Business Origin: Business
 Count of Business CERS User Accounts: 1
 Facility Count for Business: 1
 Last Submittal Date (any element): 3/1/2018 7:42:32 PM
 Count of Submitted Elements: 15
 Remote Facility? (Y/N): No
 Small Quantity Generator Facility? (Y/N): No
 Local Facility Grouping: Not Reported

Facility Specific Information

Assessor Parcel Number (APN): Not Reported
 Number of Employees: 5
 Property Owner Name: Not Reported
 Property Owner Phone Number: Not Reported
 Property Owner Mailing Address: Not Reported
 Property Owner Mailing City: Not Reported
 Property Owner Mailing State: Not Reported
 Property Owner Mailing Zip Code: Not Reported
 Property Owner Mailing Country: Not Reported

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
County-AST-CA	Listed	0.21 miles S	3649 ft	12
SITE NAME			MAPS	ID
BEST LUBE TRUCK SERVICE & REPAIRS LLC			1 , 4	FA0014891-SBD
ADDRESS			CITY	ZIP
8853 THREE FLAGS AVE UNIT C			Hesperia	92344

DETAILS

County: San Bernardino
 Responsible Agency: San Bernardino Division of Environmental Health Services
 Facility ID: FA0014891
 Address2: Not Reported
 Owner Information: Francisco Jimenez
 Contact Name: FRANCISCO JIMENEZ
 Mailing Address: 8853 Three Flags Ave Ste C, Hesperia, CA 92344
 Mailing Address2: Not Reported
 Permit ID: PT0031853
 Program Element Code: 4031
 Permit Description: APSA 1,320-10,000 GAL FAC CAPACITY
 Status: ACTIVE
 To: 2/28/2019

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CRSP-CA	Listed	0.21 miles S	3649 ft	12
SITE NAME			MAPS	ID
BEST LUBE TRUCK SERVICE & REPAIRS LLC			1 , 4	11970
ADDRESS			CITY	ZIP
8853 THREE FLAGS AVE STE C			HESPERIA	92344

DETAILS

Site Regulated Program Information

Site ID: 11970

Site EI ID: 10402582

Agency Provided Latitude: 34.41111

Agency Provided Longitude: -117.39383

Program Description: Aboveground Petroleum Storage

Program Description: Chemical Storage Facilities

Program Description: Hazardous Waste Generator

Program Description: RCRA LQ HW Generator

Evaluation Information

Evaluation Date: 1/25/2016

Violations Found? (Y/N): Yes

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: Routine done by local agency

Evaluation Note(s): INSPECTION OF BEST LUBE TRUCK SERVICE & REPAIRS LLC IN HESPERIA.

Evaluation Division: San Bernardino County Fire Department

Evaluation Program: APSA

Evaluation Source: CERS

Evaluation Date: 1/25/2016

Violations Found? (Y/N): Yes

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
CUPA-CA	Listed	0.21 miles S	3649 ft	12
SITE NAME			MAPS	ID
BEST LUBE TRUCK SERVICE & REPAIRS LLC			1, 4	FA0014891-SBD
ADDRESS			CITY	ZIP
8853 THREE FLAGS AVE UNIT C			Hesperia	92344

DETAILS

County: San Bernardino
 Responsible Agency: San Bernardino County Fire Department
 Facility ID: FA0014891
 Address2: Not Reported
 Owner Information: Francisco Jimenez
 Contact Name: FRANCISCO JIMENEZ
 Mailing Address: 8853 Three Flags Ave Ste C, Hesperia, CA 92344
 Mailing Address 2: Not Reported
 Agency Provided Latitude: Not Reported
 Agency Provided Longitude: Not Reported
 Permit ID: PT0025928
 Program Element Code: 4243
 Permit Description: HAZARDOUS MATERIALS 4-10 CHEMICALS
 Status: ACTIVE
 To: 2/28/2020

Permit ID: PT0025929
 Program Element Code: 4454
 Permit Description: LARGE QUANTITY GENERATOR
 Status: ACTIVE
 To: 2/28/2020

Permit ID: PT0031853
 Program Element Code: 4031
 Permit Description: APSA 1,320-10,000 GAL FAC CAPACITY
 Status: ACTIVE
 To: 2/28/2020

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
Hist-Auto Repair	Listed	0.21 miles S	3649 ft	12
SITE NAME			MAPS	ID
CAJON TIRE SVC			1 , 4	17338
ADDRESS			CITY	ZIP
8853 THREE FLAGS AVE B			Hesperia	92344
DETAILS				
Sic Code: 5531 Desc: Auto, Truck & Tire Service Site Added: 2/2010				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
Hist-Auto Repair	Listed	0.21 miles S	3649 ft	12
SITE NAME			MAPS	ID
WEST COAST TIRES & TRUCK RPR			1 , 4	23876
ADDRESS			CITY	ZIP
8853 THREE FLAGS AVE B			Hesperia	92344
DETAILS				
Sic Code: 5531 Desc: Auto, Truck & Tire Service Site Added: 2/2010				

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
RCRA-NON-US	Listed	0.21 miles S	3649 ft	12
SITE NAME			MAPS	ID
BEST LUBE TRUCK SERVICE & REPAIRS LLC			1 , 4	CAL000372624
ADDRESS			CITY	ZIP
8853 THREE FLAGS AVE UNIT C			HESPERIA	92345

DETAILS

Additional details may be found online using the following link:

https://enviro.epa.gov/enviro/rcrainfoquery_3.facility_information?pgm_sys_id=CAL000372624

Source Type: Implementer

Generator Status: Non-Generator

NAICS1: GENERAL AUTOMOTIVE REPAIR

Active Site Indicator: H----

Owner Name: FRANCISCO A JIMENEZ

Operator Name: ANGELICA N JIMENEZ

In Handler Universes: Y

In a Universe: Y

Universal Waste: Y

Universal Waste Destination Facility: Y

Receive Date: 20120313

Acknowledge Flag Date: 20120313

Contact First Name: ANGELICA

Contact Last Name: N JIMENEZ

Contact Street 1: 37123 CALLE REAL ST

Contact City: PALMDALE

Contact State: CA

Contact Zip: 93550

Contact Phone: 661-400-4753

Contact FAX: 760-244-8599

Contact E-mail Address: BESTLUBESERVICE@HOTMAIL.COM

Universal Waste Destination Facility: Y

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
School-Other-CA	NO ACTION REQUIRED	0.48 miles SE	3598 ft	13
SITE NAME			MAPS	ID
NEW MESQUITE TRAILS WEST ELEMENTARY SCHOOL			1 , 4	70000125
ADDRESS			CITY	ZIP
12850 MUSCATEL STREET			HESPERIA	92345

DETAILS

URL:
http://www.envirostor.dtsc.ca.gov/public/profile_report.asp?global_id=70000125
 Envirostor ID: 70000125
 Agency Provided Address: 12850 MUSCATEL STREET
 County: SAN BERNARDINO
 Site Type: SCHOOL INVESTIGATION
 Site Type Detailed: SCHOOL
 Acres: 7
 Assessor's Parcel Number: 3064-631-07
 National Priorities List: NO
 Lead Agency: SMBRP
 Project Manager: Not Reported
 Supervisor: SHAHIR HADDAD
 Division Branch: SOUTHERN CALIFORNIA SCHOOLS & BROWNFIELDS OUTREACH
 Site Code: 404669
 Assembly: 33
 Senate: 21
 Congressional District: 8
 Special Program: Not Reported
 Status: NO ACTION REQUIRED
 Status Date: 11/16/2005
 Past Uses: NONE
 Restricted Use: NO
 Funding: SCHOOL DISTRICT
 Regulatory Agencies Involved: SMBRP
 Potential Contamination of Concern: NONE SPECIFIED,31000
 Confirmed Contamination of Concern: NONE SPECIFIED

[More Details Link](#)

DATABASE	STATUS	DISTANCE	ELEVATION	MAP ID
LUST-Closed-CA	COMPLETED - CASE CLOSED	0.5 miles SW	3678 ft	14
SITE NAME			MAPS	ID
PILOT #381			1 , 4	T0607144072
ADDRESS			CITY	ZIP
8701 HIGHWAY 395			HESPERIA	92345

DETAILS

Sites Details

URL:

http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607144072

Global ID: T0607144072

Case Type: LUST CLEANUP SITE

Status: COMPLETED - CASE CLOSED

Agency Provided Address: 8701 HIGHWAY 395

Status Date: 3/18/2009

Cleanup Fund Case: NO

Lead Agency: SAN BERNARDINO COUNTY

Case Worker: JC

Local Agency: SAN BERNARDINO COUNTY

Resolution Case Number: 6B3601044T

Location Case Number: T06071

File Location: Not Reported

Potential Contaminants of Concern: DIESEL

Potential Media Affected: UNDER INVESTIGATION

Site History: Not Reported

Begin Date: 6/11/2007

How Discovered: OTHER MEANS

How Discovered Description: LEAK IN PRODUCT LINES OBSERVED WHEN PRESSURIZED FOR TESTING. THERE WAS NO LEAKING OBSERVED DURING NORMAL OPERATIONS. A LEAK IN AND IN-LINE VALVE IN A SUMP WAS OBSERVED. PILOT HAS ORDERED PARTS FOR REPAIR.

Stop Method: OTHER MEANS

Stop Method Description: Not Reported

Agency Provided Latitude: 34.4099215

Agency Provided Longitude: -117.3991492

[More Details Link](#)

RECORDS SOURCES SEARCHED

ABREVIATION	DATABASE FULLNAME	DATABASE CATEGORY	DATABASE DETAILS LINK	TOTAL LISTINGS
Air-CA	Air Permits with Emissions	ERS Supplemental Govt Sources	Click Here	None Found
AIR-DIST-CA	Air Pollution Control District	ERS Supplemental Govt Sources	Click Here	2
AST-CA	Historical Aboveground Storage Tanks	State/Tribal UST	Click Here	None Found
AST-CRSP-CA	Aboveground Storage Tanks	State/Tribal UST	Click Here	2
BF-MOA-CA	Brownfield MOA Sites (aka Considered Brownfield Sites, SWRCB MOA, Brownfield Memorandum of Agreement)	State/Tribal Brownfield	Click Here	None Found
BF-Tribal-US	Historical Tribal Brownfields	Federal Brownfield	Click Here	None Found
BF-US	Brownfields Sites	Federal Brownfields	Click Here	None Found
BioFuel-US	Bio Diesel Fuel	ERS Supplemental Govt Sources	Click Here	None Found
BZ-HazWaste-CA	Border Zone or Hazardous Waste Property	State/Tribal ASTM Other Med	Click Here	None Found
CAF-CA	Confined Animal Facilities	ERS Supplemental Govt Sources	Click Here	None Found
CDL-CA	Clandestine Drug Labs	ERS Supplemental Govt Sources	Click Here	None Found
CDL-US	National Clandestine Drug Lab Register	ERS Supplemental Govt Sources	Click Here	None Found
CERCLIS-Archived-US	CERCLIS sites that have been archived	Federal CERCLIS NFRAP	Click Here	None Found
CERCLIS-US	Comprehensive Environmental Response, Compensation, and Liability Information System	Federal CERCLIS	Click Here	None Found
CERS-CA	California Environmental Reporting System (CERS)	State/Tribal ASTM Other Med	Click Here	9
CHMIRS-CA	California Hazardous Material Incident Report System	Emergency Release Reports	Click Here	None Found
CHWF-CA	Commercial Offsite Hazardous Waste Facilities	ERS Supplemental Govt Sources	Click Here	None Found
City-AST-CA	Underground Storage Tanks	State/Tribal UST	Click Here	None Found
City-CUPA-CA	Certified Unified Program Agency	State/Tribal ASTM Other Med	Click Here	None Found
City-Others-CA	Hazardous Material Facilities	State/Tribal ASTM Other Med	Click Here	None Found

ABREVIATION	DATABASE FULLNAME	DATABASE CATEGORY	DATABASE DETAILS LINK	TOTAL LISTINGS
City-UST-CA	City Agency Underground Storage Tanks	State/Tribal UST	Click Here	None Found
Cleaners-CA	Cleaners	ERS Supplemental Govt Sources	Click Here	None Found
Coal-Ash-Dams-US	Coal Ash Contaminated Sites and Hazard Dams	ERS Supplemental Govt Sources	Click Here	None Found
Controls-CA	California sites with Deed Restrictions or other Controls	State/Tribal Inst/Eng Controls	Click Here	None Found
Controls-RCRA-US	RCRA Institutional and Engineering Controls Summary (aka Federal RCRA with Controls)	Federal Institutional/Engineering Controls	Click Here	None Found
Controls-US	US CERCLA Sites with Controls (aka US IC/EC, Institutional/Engineering List Controls, Land Use Controls)	Federal Institutional/Engineering Controls	Click Here	None Found
CorAct-Closed-CA	Corrective Action Sites	State/Tribal ASTM Other Low	Click Here	None Found
CorAct-Open-CA	Corrective Action Sites	State/Tribal ASTM Other High	Click Here	None Found
CorAct-Other-CA	Corrective Action Sites	State/Tribal ASTM Other Low	Click Here	None Found
CORTESE-CA	Cortese Hazardous Waste & Substances Sites List	State/Tribal ASTM Other Med	Click Here	None Found
County-AST-CA	Aboveground Storage Tanks	State/Tribal UST	Click Here	2
County-BI-CA	Business Inventory	ERS Supplemental Govt Sources	Click Here	None Found
County-Hist-CA	Historic Environmental County Listings	State/Tribal ASTM Other Med	Click Here	None Found
County-LUST-CA	County Agency Leaking Underground Storage Tanks	State/Tribal LUST	Click Here	None Found
County-LUST-Closed-CA	County Agency Leaking Underground Storage Tanks, Closed Cases	State/Tribal LUST	Click Here	None Found
County-LUST-Open-CA	County Agency Leaking Underground Storage Tanks, Open Cases	State/Tribal LUST	Click Here	None Found
County-Others-CA	Environmental Related Databases	State/Tribal ASTM Other Med	Click Here	None Found
County-SLIC-Closed-CA	County SLIC Sites	Emergency Release Reports	Click Here	None Found
County-SLIC-Open-CA	County SLIC Sites	Emergency Release Reports	Click Here	None Found

ABREVIATION	DATABASE FULLNAME	DATABASE CATEGORY	DATABASE DETAILS LINK	TOTAL LISTINGS
County-SML-CA	County Site Mitigation Unit List	State/Tribal ASTM Other Med	Click Here	None Found
County-SWF-CA	County Solid Waste Facilities	State/Tribal Landfill/Solid Waste	Click Here	None Found
County-UST-CA	County Agency Underground Storage Tanks	State/Tribal UST	Click Here	1
CRSP-CA	Cal EPA Regulated Site Portal	State/Tribal ASTM Other Med	Click Here	8
CUPA-CA	Certified Unified Program Agency	State/Tribal ASTM Other Med	Click Here	12
Dams-CA	California Dams	ERS Supplemental Govt Sources	Click Here	None Found
Debris-US	Historical Debris Sites	Federal Solid Waste	Click Here	None Found
Deed-CA	Deed Restrictions/Land Use Restrictions	State/Tribal Inst/Eng Controls	Click Here	None Found
Delisted-NPL-US	Delisted NPL Sites	Federal Delisted NPL	Click Here	None Found
DPR-CA	Pesticide Regulation Licenses	ERS Supplemental Govt Sources	Click Here	None Found
DryCleaners-CA	Dry Cleaner Facilities	ERS Supplemental Govt Sources	Click Here	1
EGRID-US	Emissions & Generation Resource Facilities	ERS Supplemental Govt Sources	Click Here	None Found
ENF-CA	Enforcement Actions Data	State/Tribal ASTM Other Med	Click Here	None Found
ENF-SMARTS-CA	Storm Water Enforcement Actions	State/Tribal ASTM Other Med	Click Here	None Found
ENF-Wastewater-CA	Wastewater Enforcement Actions	State/Tribal ASTM Other Med	Click Here	None Found
EPA-Watch-List-US	Historical EPA Watch List	ERS Supplemental Govt Sources	Click Here	None Found
ERNS-US	Emergency Response Notification System	Federal ERNS	Click Here	None Found
Eval-Hist-Active-CA	EnviroStor Evaluation History Sites	State/Tribal ASTM Other	Click Here	None Found
Eval-Hist-NFA-CA	EnviroStor Database Evaluation History NFA Sites	State/Tribal ASTM Other	Click Here	None Found
Eval-Hist-Other-CA	EnviroStor Database Evaluation History NFA Sites	State/Tribal ASTM Other	Click Here	None Found

ABREVIATION	DATABASE FULLNAME	DATABASE CATEGORY	DATABASE DETAILS LINK	TOTAL LISTINGS
FA-HW-CA	Financial Assurance, Hazardous Waste	ERS Supplemental Govt Sources	Click Here	None Found
FA-HW-US	Financial Assurance, Hazardous Waste	ERS Supplemental Govt Sources	Click Here	None Found
FA-SWF-CA	Financial Assurance, Solid Waste Facilities	ERS Supplemental Govt Sources	Click Here	None Found
FEMA-UST-US	Historical FEMA Underground Storage Tanks	Federal UST	Click Here	None Found
FRS-US	Facility Registry Index (FINDS)	ERS Supplemental Govt Sources	Click Here	4
FTTS-ENF-US	Historical FIFRA/TSCA Tracking System (FTTS) Enforcement Actions	Federal ASTM Other	Click Here	None Found
FTTS-INSP-US	Historical FIFRA/TSCA Tracking System (FTTS) Inspections	ERS Supplemental Govt Sources	Click Here	None Found
FUDS-US	Formerly Used Defense Sites	ERS Supplemental Govt Sources	Click Here	None Found
FUSRAP-US	Formerly Utilized Sites Remedial Action Program Sites	ERS Supplemental Govt Sources	Click Here	None Found
Haulers-CA	Registered Waste Tire Haulers Listing	ERS Supplemental Govt Sources	Click Here	None Found
HazWaste-CA	Hazardous Waste Facilities	State/Tribal ASTM Other Med	Click Here	None Found
Hist-AFS2-US	Historical Air Facility System for Clean Air Act stationary sources	ERS Supplemental Govt Sources	Click Here	None Found
Hist-AFS-US	Historical Air Facility System for Clean Air Act stationary sources	ERS Supplemental Govt Sources	Click Here	None Found
Hist-Agriculture	Historical Ranches/Farms, Livestock/Agriculture	ERS Exclusive Historic Sources	Click Here	None Found
Hist-AST-CA	Historical Aboveground Storage Tanks	ERS Supplemental Govt Sources	Click Here	None Found
Hist-Auto Dealers	Historical Auto and Truck Dealers	ERS Exclusive Historic Sources	Click Here	None Found
Hist-Auto Repair	Historical Automotive Repair	ERS Exclusive Historic Sources	Click Here	3
Hist-AWS-CA	Historical Annual Workplan Sites	ERS Supplemental Govt Sources	Click Here	None Found
Hist-CA	Previously Listed California Sites	ERS Supplemental Govt Sources	Click Here	6
Hist-CalFID-CA	Historical Facility Inventory Database	ERS Supplemental Govt Sources	Click Here	None Found
Hist-CALSITES-CA	Historical Calsites Database	ERS Supplemental Govt Sources	Click Here	None Found

ABREVIATION	DATABASE FULLNAME	DATABASE CATEGORY	DATABASE DETAILS LINK	TOTAL LISTINGS
Hist-CERCLIS-NFRAP-US	Historical CERCLIS-NFRAP	ERS Supplemental Govt Sources	Click Here	None Found
Hist-CERCLIS-US	Historical CERCLIS Sites	ERS Supplemental Govt Sources	Click Here	None Found
Hist-Chemical Manufacturing	Historical Manufacturing and Distribution of Chemicals, Gases, and/or Solids	ERS Exclusive Historic Sources	Click Here	None Found
Hist-Chemical-Storage	Historical Chemical/Hazardous Use Storage	ERS Exclusive Historic Sources	Click Here	None Found
Hist-City-UST-CA	Historical Underground Storage Tanks	ERS Supplemental Govt Sources	Click Here	None Found
Hist-Cleaners	Historical Laundry, Cleaners, and Dry Cleaning Services	ERS Exclusive Historic Sources	Click Here	None Found
Hist-Controls-CA	Historical Restricted Use Sites	State/Tribal Inst/Eng Controls	Click Here	None Found
Hist-Convenience	Historical Convenience Store with Possible Gas	ERS Exclusive Historic Sources	Click Here	None Found
Hist-Cort-CA	Historical Cortese list	State/Tribal ASTM Other Med	Click Here	None Found
Hist-Deed-CA	Historical Deed Restriction Properties	ERS Supplemental Govt Sources	Click Here	None Found
Hist-Disposal-Recycle	Historical Hazardous Disposal/Recycle and Dumps/Waste	ERS Exclusive Historic Sources	Click Here	None Found
Hist-DTG-CA	Depth to Groundwater	ERS Supplemental Govt Sources	Click Here	None Found
Hist-Dumps-US	Historical Dumps Inventory of 1985	Federal Solid Waste	Click Here	None Found
Hist-ERNS-US	Historical Emergency Response Notification System (ERNS)	ERS Supplemental Govt Sources	Click Here	None Found
Hist-FIFRA-US	Historical Case Administration Data from National Compliance Database (Federal Insecticide, Fungicide, and Rodenticide Act)	ERS Supplemental Govt Sources	Click Here	None Found
Hist-FINDS-US	Historical Facility Index System	ERS Supplemental Govt Sources	Click Here	None Found
Hist-Food-Processors	Historical Food Processing Manufacturers	ERS Exclusive Historic Sources	Click Here	None Found
Hist-Gun-Ranges	Historical Gun Ranges/Clubs	ERS Exclusive Historic Sources	Click Here	None Found
Hist-HWS-CA	Historical Cortese List-Hazardous Waste Substance Site List	ERS Supplemental Govt Sources	Click Here	None Found

ABREVIATION	DATABASE FULLNAME	DATABASE CATEGORY	DATABASE DETAILS LINK	TOTAL LISTINGS
Hist-LUSTIS-CA	Historical Lust Information System (LUSTIS)	ERS Supplemental Govt Sources	Click Here	None Found
Hist-Machine Shop	Historical Machine Shops, Welding, Machine Repair	ERS Exclusive Historic Sources	Click Here	None Found
Hist-Manufacturing	Historical Sources US: Manufacturing	ERS Exclusive Historic Sources	Click Here	None Found
Hist-Metal Plating	Historical Metal Plating	ERS Exclusive Historic Sources	Click Here	None Found
Hist-Mining	Historical Mining Operations	ERS Exclusive Historic Sources	Click Here	None Found
HIST-MLTS-US	Historical Material Licensing Tracking System	ERS Supplemental Govt Sources	Click Here	None Found
Hist-Mortuaries	Historical Crematories/Mortuaries	ERS Exclusive Historic Sources	Click Here	None Found
HIST-MTBE-CA	Historical Sites With MTBE (Methyl Tertiary-Butyl Ether) Contamination	ERS Supplemental Govt Sources	Click Here	None Found
Hist-NPL-US	Historical National Priority List	ERS Supplemental Govt Sources	Click Here	None Found
Hist-Oil-Gas	Historical Oil and Gas Well Related Facilities	ERS Exclusive Historic Sources	Click Here	None Found
Hist-OilGas-Refiners	Historical Oil/Gas Refiners/Manufacturers/Plants	ERS Exclusive Historic Sources	Click Here	None Found
Hist-Orange-County-LF-CA	Historical Orange County Landfills	ERS Supplemental Govt Sources	Click Here	None Found
Historical-CA	Historical Sites	ERS Supplemental Govt Sources	Click Here	None Found
Hist-Other	Historical Environmental Facilities	ERS Exclusive Historic Sources	Click Here	None Found
Hist-Paint-Stores	Historical Paint Stores	ERS Exclusive Historic Sources	Click Here	None Found
Hist-Petroleum	Historical Petroleum Refining/ Manufacturing/ Chemicals	ERS Exclusive Historic Sources	Click Here	None Found
Hist-Post-Offices	Historical Post Offices	ERS Exclusive Historic Sources	Click Here	None Found
Hist-Printers	Historical Printers and Publishers	ERS Exclusive Historic Sources	Click Here	None Found
Hist-Prop65-CA	Historical Prop 65 Sites	ERS Supplemental Govt Sources	Click Here	None Found
HIST-R4-CA	Historical sites	State/Tribal ASTM Other Med	Click Here	None Found

ABREVIATION	DATABASE FULLNAME	DATABASE CATEGORY	DATABASE DETAILS LINK	TOTAL LISTINGS
Hist-RCRIS-US	Historical EPA's Resource Conservation and Recovery Act	ERS Supplemental Govt Sources	Click Here	None Found
Hist-Regional-LUST-CA	Historical Leaking Underground Storage Tanks	ERS Supplemental Govt Sources	Click Here	None Found
Hist-Regional-Other-CA	Historical Toxic Lists, Site Mitigation, and Groundwater Cleanup Program	ERS Supplemental Govt Sources	Click Here	None Found
Hist-Regional-SLIC-CA	Historical Spills and Leak Sites	ERS Supplemental Govt Sources	Click Here	None Found
Hist-Regional-Spills-CA	Historical Industrial Cleanup Sites	ERS Supplemental Govt Sources	Click Here	None Found
Hist-Regional-SWLF-CA	Historical County Landfills and Transfer Stations	ERS Supplemental Govt Sources	Click Here	None Found
Hist-Regional-UST-CA	Historical Underground Storage Tanks	ERS Supplemental Govt Sources	Click Here	None Found
Hist-Rental	Historical Rental Equipment & Yards	ERS Exclusive Historic Sources	Click Here	None Found
Hist-RV-Dealers	Historical Trailer and Recreational Vehicle Dealers	ERS Exclusive Historic Sources	Click Here	None Found
Hist-Salvage	Historical Vehicle Salvage Yards or Wreckers	ERS Exclusive Historic Sources	Click Here	None Found
Hist-SCL-CA	Historical California Cerclis Sites	ERS Supplemental Govt Sources	Click Here	None Found
Hist-Service Stations	Historical Service Stations/Vehicle Fueling	ERS Exclusive Historic Sources	Click Here	None Found
HIST-SLIC-CV-CLOSED-CA	Historical Central Valley Spills and Leak Sites	Emergency Release Reports	Click Here	None Found
HIST-SLIC-CV-OPEN-CA	Historical Central Valley Spills and Leak Sites	Emergency Release Reports	Click Here	None Found
Hist-Steel-Metals	Historical Steel Mills/Manufacturers/Foundries/Smelters	ERS Exclusive Historic Sources	Click Here	None Found
Hist-SWIS-CA	Historical Solid Waste Information System (SWIS)	ERS Supplemental Govt Sources	Click Here	None Found
Hist-Textile	Historical Textile Mills/Manufacturers	ERS Exclusive Historic Sources	Click Here	None Found
Hist-ToxicPits-CA	Historical Toxic Pits Cleanup Facilities	ERS Supplemental Govt Sources	Click Here	None Found
Hist-Transportation	Historical Transportation Facilities	ERS Exclusive Historic Sources	Click Here	None Found

ABREVIATION	DATABASE FULLNAME	DATABASE CATEGORY	DATABASE DETAILS LINK	TOTAL LISTINGS
Hist-TRIS-US	Historical Toxic Release Inventory System	ERS Supplemental Govt Sources	Click Here	None Found
Hist-Trucking	Historical Trucking, Shipping, Delivery, and/or Storage	ERS Exclusive Historic Sources	Click Here	None Found
Hist-US	Historical Previously Listed Federal Sites	ERS Supplemental Govt Sources	Click Here	None Found
Hist-US-EC	Historical Engineering Controls Sites (aka US EC, Engineering Controls, Land Use Controls)	Federal Institutional/Engineering Controls	Click Here	None Found
Hist-USGS-WaterWells-CA	Historical Ground Water Site Inventory for California	ERS Supplemental Govt Sources	Click Here	None Found
Hist-US-IC	Historical Sites with Institutional Controls (aka US IC, Institutional Controls, Land Use Controls)	Federal Institutional/Engineering Controls	Click Here	None Found
Hist-UST-CA	Historical Hazardous Substance Storage Infirmary (aka Historical Underground Storage Tanks)	State/Tribal UST	Click Here	None Found
Hist-UST-Cleanup-CA	Historic UST Cases Recommended for Closure under UST Cleanup Fund 5 Year Review (aka UST Cleanup Fund Cases)	State/Tribal LUST	Click Here	None Found
Hist-USTReg-CA	Historical Underground Storage Tank Registrations Database	ERS Supplemental Govt Sources	Click Here	None Found
Hist-Vehicle-Parts	Historical Vehicle Parts	ERS Exclusive Historic Sources	Click Here	None Found
Hist-Vehicle-Washing	Historical Vehicle/Truck Washing Facilities	ERS Exclusive Historic Sources	Click Here	None Found
Hist-WaterWells-US	Historical Public Community Water Supply/Well Head Protection Database	ERS Supplemental Govt Sources	Click Here	None Found
Hist-WIP-Active-CA	Historical Well Investigation Program Case List, Active Sites (aka WIP)	State/Tribal ASTM Other Med	Click Here	None Found
Hist-WIP-Backlog-CA	Historical Well Investigation Program Case List, Backlog Sites (aka WIP)	State/Tribal ASTM Other Med	Click Here	None Found
Hist-WIP-Historical-CA	Historical Well Investigation Program Case List, Historical Sites (aka WIP)	State/Tribal ASTM Other Low	Click Here	None Found
Hist-WMUDS-CA	Historical Waste Management Unit Database System	ERS Supplemental Govt Sources	Click Here	None Found
HMIS-US	Hazardous Materials Information System	Federal Emergency Release Reports	Click Here	None Found
HWIS-CA	Hazardous Waste Information Summary	State/Tribal RCRA Equivalent	Click Here	2

ABREVIATION	DATABASE FULLNAME	DATABASE CATEGORY	DATABASE DETAILS LINK	TOTAL LISTINGS
HWMP-Controls-CA	Hazardous Waste Management Program Facility Sites with Deed / Land Use Restriction	State/Tribal Inst/Eng Controls	Click Here	None Found
HWT-CA	Hazardous Waste Transporters	ERS Supplemental Govt Sources	Click Here	None Found
ICE-CA	Inspection, Compliance, and Enforcement	State/Tribal ASTM Other Med	Click Here	None Found
ICIS-Air-US	Integrated Compliance Information System for Air	ERS Supplemental Govt Sources	Click Here	None Found
ICIS-FEC-US	Integrated Compliance Information System for Federal Enforcement Data	ERS Supplemental Govt Sources	Click Here	None Found
ICIS-NPDES-US	National Pollutant Discharge Elimination System (NPDES)	ERS Supplemental Govt Sources	Click Here	None Found
LA-LF-CA	Los Angeles County Landfills	State/Tribal Solid Waste	Click Here	None Found
Land-Disposal-CA	Geotracker - Land Disposal Sites (aka Landfills, LDS)	State/Tribal Landfill/Solid Waste	Click Here	None Found
LA-Waste-Haulers-CA	Waste Haulers	ERS Supplemental Govt Sources	Click Here	None Found
Lead-Smelter-2-US	Historical Lead Smelter Sites	ERS Supplemental Govt Sources	Click Here	None Found
Lead-US	Lead Smelter Sites	ERS Supplemental Govt Sources	Click Here	None Found
Liens-CA	Environmental Liens	State/Tribal Inst/Eng Controls	Click Here	None Found
LIENS-US	Superfund Liens	Federal Institutional/Engineering Controls	Click Here	None Found
LMOP-US	Landfill Methane Outreach Program	ERS Supplemental Govt Sources	Click Here	None Found
LUST-Closed-CA	Geotracker - Leaking Underground Storage Tanks, Closed Cases	State/Tribal LUST	Click Here	1
LUST-Open-CA	Geotracker - Leaking Underground Storage Tanks, Open Cases	State/Tribal LUST	Click Here	None Found
Manifest2-RI	Hazardous Waste Manifest	State/Tribal RCRA Equivalent	Click Here	None Found
MethaneLF-CA	Methane Producing Landfills	State/Tribal Other	Click Here	None Found
Military-Active-CA	EnviroStor Database Military Active Sites (aka MCS)	State/Tribal Voluntary Cleanup Sites	Click Here	None Found
Military-Bases-US	Military Base Boundaries	ERS Supplemental Govt Sources	Click Here	None Found

ABREVIATION	DATABASE FULLNAME	DATABASE CATEGORY	DATABASE DETAILS LINK	TOTAL LISTINGS
Military-NFA-CA	EnviroStor Database Military Active Sites (aka MCS)	State/Tribal Voluntary Cleanup Sites	Click Here	None Found
Military-Other-CA	EnviroStor Database Military Active Sites (aka MCS)	State/Tribal Voluntary Cleanup Sites	Click Here	None Found
Mines2-CA	California Mines	ERS Supplemental Govt Sources	Click Here	None Found
Mines-CA	Historical Death Valley Mines	ERS Supplemental Govt Sources	Click Here	None Found
Mines-CDMG-CA	California Division of Mines and Geology	ERS Supplemental Govt Sources	Click Here	None Found
MINES-US	Mines Master Index File	ERS Supplemental Govt Sources	Click Here	None Found
MLTS-US	Material Licensing Tracking System	ERS Supplemental Govt Sources	Click Here	None Found
Mortgage-CA	Cal Mortgage Facilities	ERS Supplemental Govt Sources	Click Here	None Found
MRDS-US	Mineral Resources Data System (MRDS)	ERS Supplemental Govt Sources	Click Here	None Found
MWMP-CA	Medical Waste Management Program	ERS Supplemental Govt Sources	Click Here	None Found
NCI-CA	Non-Case Information	ERS Supplemental Govt Sources	Click Here	None Found
NEI-LF-CA	Historical NEI (National Emission Inventory) Landfill Point Sources	ERS Supplemental Govt Sources	Click Here	None Found
NPDES-CA	National Pollutant Discharge Elimination System	ERS Supplemental Govt Sources	Click Here	None Found
NPDES-SW-CA	Notice of Intent Data	ERS Supplemental Govt Sources	Click Here	None Found
NPL-R9-US	NPL Region 9 Site Boundaries	Federal NPL	Click Here	None Found
NPL-US	National Priorities List	Federal NPL	Click Here	None Found
OGM-CA	Oil and Gas Monitoring	ERS Supplemental Govt Sources	Click Here	None Found
OGW-CA	California Oil and Gas Wells	ERS Supplemental Govt Sources	Click Here	None Found
OSCF-CA	Orphan Site Cleanup Fund	ERS Supplemental Govt Sources	Click Here	None Found
PADS-US	PCB Registration Database System	Federal ASTM Other	Click Here	None Found
PCB-US	PCB Transformers	Federal ASTM Other	Click Here	None Found
PCS-US	Historical Permit Compliance System for Clean Water Act	ERS Supplemental Govt Sources	Click Here	None Found
Perch1-CA	Perchlorate Confirmed Contaminant Sites	ERS Supplemental Govt Sources	Click Here	None Found

ABREVIATION	DATABASE FULLNAME	DATABASE CATEGORY	DATABASE DETAILS LINK	TOTAL LISTINGS
Perch2-CA	Perchlorate Confirmed Contaminant Sites	ERS Supplemental Govt Sources	Click Here	None Found
PR-MOA-CA	Polanco Redevelopment MOA Sites	State/Tribal ASTM Other Med	Click Here	None Found
Project-CA	Project - Multipurpose Site Type	ERS Supplemental Govt Sources	Click Here	None Found
Proposed-NPL-US	Proposed NPL Sites	Federal NPL	Click Here	None Found
RADINFO-US	Radiation Information Database	ERS Supplemental Govt Sources	Click Here	None Found
RCRA-CESQG-US	Resource Conservation and Recovery Act, Conditionally Exempt Small Quantity Generators (aka RCRA CESQG)	Federal RCRA Generators	Click Here	None Found
RCRA-COR-US	Resource Conservation and Recovery Act, - Corrective Actions (aka RCRA CORRACTS)	Federal RCRA CORRACTS	Click Here	None Found
RCRA-LQG-US	Resource Conservation and Recovery Act, Large Quantity Generators (aka RCRA LQG)	Federal RCRA Generators	Click Here	None Found
RCRA-NON-US	Resource Conservation and Recovery Act, Non-Hazardous Generators (aka RCRA Non-Haz, RCRA NonGen, RCRA No longer Regulated)	Federal RCRA Generators	Click Here	6
RCRA-SQG-US	Resource Conservation and Recovery Act, Small Quantity Generators (aka RCRA SQG)	Federal RCRA Generators	Click Here	None Found
RCRA-TSDF-US	Resource Conservation and Recovery Act -, Treatment, Storage, and Disposal Facilities (aka RCRA TSD, RCRA TSDF)	Federal RCRA non-CORRACTS TSD	Click Here	None Found
Response-CA	State Response Sites and National Priorities List (NPL)	State/Tribal NPL	Click Here	None Found
RFG-Lab-US	Reformulated Gasoline (RFG)	ERS Supplemental Govt Sources	Click Here	None Found
RMP-US	Risk Management Plans	ERS Supplemental Govt Sources	Click Here	None Found
ROD-US	Records of Decision	ERS Supplemental Govt Sources	Click Here	None Found
SAA-Agreements-US	Sites with Superfund Alternative Approach Agreements	Federal ASTM Other	Click Here	None Found

ABREVIATION	DATABASE FULLNAME	DATABASE CATEGORY	DATABASE DETAILS LINK	TOTAL LISTINGS
School-Active-CA	EnviroStor Database School Active Sites (aka School Property Evaluation Program, SCH)	State/Tribal Voluntary Cleanup Sites	Click Here	None Found
School-NFA-CA	EnviroStor Database School Active Sites (aka School Property Evaluation Program, SCH)	State/Tribal Voluntary Cleanup Sites	Click Here	None Found
School-Other-CA	EnviroStor Database School Active Sites (aka School Property Evaluation Program, SCH)	State/Tribal Voluntary Cleanup Sites	Click Here	1
SDWIS-US	Safe Drinking Water Information System	ERS Supplemental Govt Sources	Click Here	None Found
SGV-Deep-Plumes-CA	San Gabriel Valley Deep Plumes	State/Tribal Solid Waste	Click Here	None Found
SGV-Shallow-Plumes-CA	San Gabriel Valley Shallow Plumes	State/Tribal Solid Waste	Click Here	None Found
SGV-Shallow-Plumes-Puente-Valley-CA	Puente Valley Shallow Plumes	State/Tribal Solid Waste	Click Here	None Found
SLIC-Closed-CA	Geotracker - The Spills, Leaks, Investigation & Cleanup (SLIC), Closed Cases	Emergency Release Reports	Click Here	None Found
SLIC-Open-CA	Geotracker -Spills, Leaks, Investigation & Cleanup (SLIC), Open Cases	Emergency Release Reports	Click Here	None Found
SML-CA	Site Mitigation List	State/Tribal ASTM Other Med	Click Here	None Found
SP-CA	Sampling Points	ERS Supplemental Govt Sources	Click Here	None Found
Spills-SSO-CA	Sanitary Sewer System	ERS Supplemental Govt Sources	Click Here	None Found
SSTS-US	Section 7 Tracking System	ERS Supplemental Govt Sources	Click Here	None Found
State-Response-Active-CA	EnviroStor State Response Active Sites	State/Tribal NPL	Click Here	None Found
State-Response-NFA-CA	EnviroStor State Response NFA Sites	State/Tribal NPL	Click Here	None Found
State-Response-Other-CA	EnviroStor State Response Other Sites	State/Tribal NPL	Click Here	None Found

ABREVIATION	DATABASE FULLNAME	DATABASE CATEGORY	DATABASE DETAILS LINK	TOTAL LISTINGS
Superfund-Active-CA	Envirostor Superfund Active Sites (aka BEAP, CalSites, Brownfields and Environmental Restoration Program)	State/Tribal CERCLIS Equivalent	Click Here	None Found
Superfund-NFA-CA	EnviroStor Superfund NFA Sites (aka BEAP, CalSites, Brownfields and Environmental Restoration Program)	State/Tribal CERCLIS Equivalent	Click Here	None Found
Superfund-Other-CA	EnviroStor Superfund Sites (aka BEAP, CalSites, Brownfields and Environmental Restoration Program)	State/Tribal CERCLIS Equivalent	Click Here	None Found
SWIS-CA	Solid Waste Information System	State/Tribal Landfill/Solid Waste	Click Here	None Found
SWLF-US	Solid Waste Facilities	Federal Solid Waste	Click Here	None Found
SWRCY-CA	Beverage Container Recycler Database	State/Tribal ASTM Other Med	Click Here	None Found
TierPer-CA	Tiered Permits	ERS Supplemental Govt Sources	Click Here	None Found
TOMS-CA	Topographically Occurring Mine Symbols	ERS Supplemental Govt Sources	Click Here	None Found
Tribal-Air-US	Tribal Air Permitted Facilities	ERS Supplemental Govt Sources	Click Here	None Found
Tribal-LUST-Closed-Reg4	Tribal Leaking Underground Storage Tanks, Region 4, Closed Cases (aka Indian LUST)	Federal LUST	Click Here	None Found
Tribal-LUST-Closed-Reg9	Tribal Leaking Underground Storage Tanks, Region 9 (aka Indian LUST)	Federal LUST	Click Here	None Found
Tribal-LUST-Open-Reg10	Tribal Leaking Underground Storage Tanks (aka Indian LUST)	Federal LUST	Click Here	None Found
Tribal-LUST-Open-Reg4	Tribal Leaking Underground Storage Tanks, Region 4, Open Cases (aka Indian LUST)	Federal LUST	Click Here	None Found
Tribal-LUST-Open-Reg9	Tribal Leaking Underground Storage Tanks , Region 9 (aka Indian LUST)	Federal LUST	Click Here	None Found
Tribal-LUST-Reg1	Tribal Leaking Underground Storage Tanks (aka Indian LUST)	Federal LUST	Click Here	None Found
Tribal-LUST-Reg7	Tribal Leaking Underground Storage Tanks, Region 7 (aka Indian LUST)	Federal LUST	Click Here	None Found
Tribal-ODI-US	Tribal Open Dump Sites	Federal Solid Waste	Click Here	None Found
Tribal-UST-Reg1	Tribal Underground Storage Tanks (aka INDIAN UST)	Federal UST	Click Here	None Found
Tribal-UST-Reg10	Tribal Underground Storage Tanks (aka Indian UST)	Federal UST	Click Here	None Found

ABREVIATION	DATABASE FULLNAME	DATABASE CATEGORY	DATABASE DETAILS LINK	TOTAL LISTINGS
Tribal-UST-Reg4	Tribal Underground Storage Tanks (aka INDIAN UST)	Federal UST	Click Here	None Found
Tribal-UST-Reg7	Tribal Underground Storage Tanks, Region 7 (aka UST)	Federal UST	Click Here	None Found
Tribal-UST-Reg9	Tribal Underground Storage Tanks (aka Tribal UST)	Federal UST	Click Here	None Found
Tribal-VCP-US	Tribal VCP	Federal Tribal VCP	Click Here	None Found
TRIS2000-US	Historical Toxics Release Inventory System	ERS Supplemental Govt Sources	Click Here	None Found
TRIS2010-US	Toxics Release Inventory System	ERS Supplemental Govt Sources	Click Here	None Found
TRIS80-US	Historical Toxics Release Inventory System	ERS Supplemental Govt Sources	Click Here	None Found
TRIS90-US	Historical Toxics Release Inventory System	ERS Supplemental Govt Sources	Click Here	None Found
TSCA-US	Toxics Substance Control Sites	ERS Supplemental Govt Sources	Click Here	None Found
UIC2-CA	Injection Wells	ERS Supplemental Govt Sources	Click Here	None Found
UIC-CA	Underground Injection Control Wells	ERS Supplemental Govt Sources	Click Here	None Found
UMTRA-US	Historical Uranium Mill Tailings Remedial Action Sites	ERS Supplemental Govt Sources	Click Here	None Found
USGS-Waterwells-US	Ground Water Site Inventory	ERS Supplemental Govt Sources	Click Here	None Found
UST-Abandoned-CA	Abandoned UST Initiative (aka Inventory of Abandoned Tank Sites)	State/Tribal UST	Click Here	None Found
UST-CA	Geotracker - Underground Storage Tanks	State/Tribal UST	Click Here	1
UST-Closed-CA	UST Case Closure Review Denials and Approved Orders (aka Closure of Underground Storage Tank (UST) Cases)	State/Tribal UST	Click Here	None Found
USTComp-CA	Previously Abandoned Tanks Now in Compliance (aka Compliance UST)	State/Tribal UST	Click Here	None Found
UST-CRSP-CA	Underground Storage Tanks	State/Tribal UST	Click Here	1
UST-Priority-CA	UST Cleanup Fund Priority List	State/Tribal UST	Click Here	None Found
UST-Proposed-CA	Proposed Closure of UST Cases (aka UST Proposed for Closure)	State/Tribal UST	Click Here	None Found

ABREVIATION	DATABASE FULLNAME	DATABASE CATEGORY	DATABASE DETAILS LINK	TOTAL LISTINGS
Vapor-Intrusions-US	Vapor Intrusion Database	ERS Supplemental Govt Sources	Click Here	None Found
VCP-Active-CA	EnviroStor VCP Active Sites	State/Tribal Voluntary Cleanup Sites	Click Here	None Found
VCP-NFA-CA	EnviroStor Database VCP NFA Listing	State/Tribal Voluntary Cleanup Sites	Click Here	None Found
VCP-Other-CA	EnviroStor VCP Other Sites	State/Tribal Voluntary Cleanup Sites	Click Here	None Found
WDR-CA	Waste Discharge Requirements	ERS Supplemental Govt Sources	Click Here	None Found

UN-MAPPABLE OCCURRENCES

The following occurrences were not mapped primarily due to incomplete or inaccurate address information. All of the following occurrences were determined to share the same zip code as the area searched. General status information is given with each occurrence along with any address information entered by the agency responsible for the list.

ID	Facility Name	Address	Database	Status
No "un-mapped" sites requested.				

DISCLAIMER, LIMITS AND LIABILITIES

All of the data presented in this report was garnered from public information maintained by governmental agencies. **Environmental Record Search (ERS)** cannot ensure that the data, which has been entered and maintained by others, is complete and/or accurate. Any, and all omissions, errors, negligence, accidentally or otherwise within the data received by **ERS** is assumed to be caused by others and **ERS** cannot and does not assume, take, or acknowledge any liability whatsoever for their respective data. The extrapolation of the mapped locations is based solely on the accuracy of the data provided by others. Prior to relying completely on any mapped location within this report, its accuracy should be verified using other means such as further documentation or a field visit. **ERS** makes no representation, warranty or guaranty, express or implied regarding the accuracy of the data entered and maintained by others or the suitability of the data received from others in this report for a certain task or interpretation.

The data presented in this report should only be interpreted by an experienced environmental professional, as per EPA definition, that completely understands the potential inaccuracy of the data derived from others, the possible existence of contaminated occurrences that have not been listed, and the possibility that the governmental database misrepresents the actual status of an occurrence or listing. Prior to relying completely on any of the data within this report, an environmental professional should verify the accuracy of the information presented unless one of ERS's Environmental Professionals has interpreted the data and/or report.

It is important that the reader and/or end user of this information realize that the data gathered has not been verified for its accuracy or completeness in any way by **ERS**. With billions of records, this is an impossible task for any Company. As much as possible, the data is presented unchanged and unaltered to represent the actual data produced by these agencies. This insures the integrity of the data for the end user.

ERS does however stand behind its representation of the data, any manually plotted occurrences, any risk determinations and all other items directly under its control. This report does comply (as far as the data is reasonably ascertainable as outlined in both the following standards) with section 8.2.1 of ASTM 1527-13 – Standard Environmental Record Sources and EPA's 40 CFR Part 312, All Appropriate Inquiries. **ERS** does ensure that the data is accurately reproduced from the original source. **ERS** backs the reporting of the data with \$3,000,000 of General and Environmental Professional Liability (errors and omissions) Insurance!

The **ERS** logo, name, report design, presentation, maps, tables, etc., are the exclusive property of **ERS** and its parent company and affiliates. Except as provided below, information or images contained in this report may not be reproduced or distributed in whole or in part by any means without the prior written permission from **ERS**. United States and international copyright laws protect any and all reports produced by **ERS**.

The person or entity that purchased this report may make up to five (5) copies of the entire report or any part of it for archival purposes or to include as part of another report. All copyright information must remain intact and not be modified in any way.

Environmental Record Search (ERS) and their respective products/reports (i.e. RecCheck, LenderCheck, Environmental Screen, etc.) as well as their respective business operations, are **NOT** associated in any way with nor related to, First American Commercial Real Estate, Inc. (FACRES) and/or the First American Family of Companies.

Maps throughout this report were created using ArcGIS® software by ESRI. ArcGIS® and ArcMap™ are the intellectual property of ESRI and are used herein under license. Copyright © ESRI. All rights reserved. For more information about ESRI® software, please visit www.esri.com. Topographic imagery used in maps throughout this report are Copyright © 2011 National Geographic Society. Street and aerial "hybrid" imagery used in maps throughout this report are Copyright © 2010 Microsoft Corporation and its data suppliers.